| | LICENSEE EVENT REPORT |
|---------------|--|
| 4 | CONTROL BLOCK: [] [] (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION) |
| 0 1 7 8 | G A E I H 2 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5 6 |
| CON'T 0 1 7 8 | REPORT L 6 0 5 0 0 0 3 6 6 7 1 0 1 4 8 2 8 1 1 0 9 8 2 9 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10 On 10-14-82, with Unit 2 operating at full load, the "B" Drywell Hydro- |
| 0 3 | gen and Oxygen Analyzer was found inoperative while performing normal |
| 0 4 | monthly surveillance test. Tech. Specs. Table 3.3.6.4-1, item 9 requires |
| 0 5 | both analyzers to be operable. A 30-day LCO was initiated per ACTION a. |
| 0 6 | of Tech. Specs. 3.3.6.4. The "A" analyzer remained operable. The health |
| 0 7 | and safety of the public were not affected by this non-repetitive event. |
| 0 8 7 8 | SYSTEM CAUSE CAUSE COMP. VALVE |
| 0 9 | PB 10 E 12 B 13 P U M P X X 14 SUBCODE |
| | TO LER/RO REPORT NO. LER/RO REPORT NO. SEQUENTIAL REPORT NO. 1 1 6 0 3 LL 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 |
| | ACTION FUTURE COMPONENT SUBMITTED FORM SUB. PRIME COMP. COMPONENT MANUFACTURER ACTION ON PLANT METHOD HOURS 22 ATTACHMENT FORM SUB. SUPPLIER MANUFACTURER ACTION FUTURE COMPONENT SUBMITTED FORM SUB. PRIME COMP. COMPONENT MANUFACTURER ACTION FUTURE COMPONENT SUBMITTED FORM SUB. PRIME COMP. COMPONENT MANUFACTURER ACTION FUTURE COMPONENT SUBMITTED FORM SUB. PRIME COMP. COMPONENT MANUFACTURER ACTION ON PLANT METHOD HOURS 22 ATTACHMENT FORM SUB. PRIME COMP. COMPONENT MANUFACTURER ACTION ON PLANT METHOD HOURS 22 ATTACHMENT FORM SUB. PRIME COMP. SUPPLIER MANUFACTURER ACTION ON PLANT METHOD HOURS 22 ATTACHMENT FORM SUB. PRIME COMP. SUPPLIER MANUFACTURER ACTION ON PLANT METHOD HOURS 22 ATTACHMENT FORM SUB. PRIME COMP. SUPPLIER MANUFACTURER ACTION ON PLANT METHOD HOURS 22 ATTACHMENT FORM SUB. PRIME COMP. SUPPLIER MANUFACTURER ACTION ON PLANT METHOD HOURS 22 ATTACHMENT FORM SUB. PRIME COMP. SUPPLIER MANUFACTURER ACTION ON PLANT METHOD HOURS 22 ATTACHMENT FORM SUB. PRIME COMP. SUPPLIER MANUFACTURER ACTION ON PLANT METHOD HOURS 22 ATTACHMENT FORM SUB. PRIME COMP. SUPPLIER MANUFACTURER ACTION ON PLANT METHOD HOURS 22 ATTACHMENT FORM SUB. PRIME COMP. SUPPLIER MANUFACTURER ACTION ON PLANT METHOD HOURS 22 ATTACHMENT FORM SUB. PRIME COMP. SUPPLIER MANUFACTURER ACTION ON PLANT METHOD HOURS 22 ATTACHMENT FORM SUB. PRIME COMP. SUPPLIER MANUFACTURER ACTION ON PLANT METHOD HOURS 22 ATTACHMENT FORM SUB. PRIME COMP. SUPPLIER MANUFACTURER ACTION ON PLANT METHOD HOURS 22 ATTACHMENT FORM SUPPLIER MANUFACTURER ACTION ON PLANT METHOD HOURS 22 ATTACHMENT FORM SUPPLIER MANUFACTURER FORM SUPPLIER FORM SUP |
| 10 | This event was caused by the failure of the diaphragm capscrew on the |
| 111 | sample pump's connecting rod. The capscrew was replaced, and the "B" |
| 1 2 | analyzer was successfully recalibrated per the "COMSIP DELPHI MODEL K-1V |
| 1 3 | HYDROGEN ANALYZER FT&C" Procedure. The analyzer was returned to service |
| 1 4 | on 10/23/82. No additional corrective action was deemed necessary |
| 1 5 | STATUS SPOWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 E 28 0 9 9 29 NA B 31 Surveillance Test 9 10 12 13 44 45 46 80 |
| A | CTIVITY CONTENT ELEASED OF RELEASE AMOUNT OF ACTIVITY (35) Z (33) Z (34) NA NA NA NA NA NA NA N |
| 1 7 8 | PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39) 0 0 0 37 Z 38 NA 9 PERSONNEL INJURIES 13 80 |
| 1 8 | NUMBER DESCRIPTION (41) NA |
| 1 9 | Z 42 DESCRIPTION S PDR |
| 20 | PUBLICITY NRC USE ONLY SSUED DESCRIPTION 45 NA NA |
| | NAME OF PREPARER S. B. Tipps PHONE (912) 367-7851 |