LICENSEE EVENT REPORT
CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 G A E I H 2 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5 6 E CAT 58
CON'T O 1 SOURCE 60 O 5 0 0 0 3 6 6 0 1 1 7 8 2 8 1 1 1 1 1 8 2 9 EVENT DESCRIF FION AND PROBABLE CONSEQUENCES 10 O 2 During the performance of the "CORE SPRAY PUMP DISCHARGE PRESSURE INTER-
O[3] LOCK INSTRUMENT FT&C" procedure, the "A" instrument of Channel "A" did
o[4] [not trip at greater than or equal to 100 psig. (Actual trip occurred at
[0]5 95 psig.) as required by Item 4.3 of Tech. Specs. Table 3.3.3-2. The
o 6 redundant instrument, "B", and redundant Channel, "B", were operable.
The health and safety of the public were not affected by this non-
0 8 repetitive event.
SYSTEM CAUSE CAUSE CODE COD
[1 0 Setpoint drift in the core spray pump discharge pressure instrument was
[1] [the cause of the event. The trip was then set at 103 psig. The instru-
[1] [ment was satisfactorily calibrated and functionally tested per the
[1]3 ["CORE SPRAY PUMP DISCHARGE PRESSURE INTERLOCK INSTRUMENT FT&C" procedure
and returned to service on 10/17/82.
FACILITY STATUS POWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 1 3 E 28 0 9 9 29 NA B 31 Surveillance Test 7 8 9 ACTIVITY CONTENT RELEASE OF RELEASE AMOUNT OF ACTIVITY 35 NA NA NA
7 8 9 10 11 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39) NA
PERSONNEL INJURIES NUMBER DESCRIPTION 41 NA PERSONNEL INJURIES NUMBER DESCRIPTION 41 NA NA PERSONNEL INJURIES NUMBER DESCRIPTION 41 NA PERSONNEL INJURIES NUMBER DESCRIPTION 41 NA 80 LOSS OF OR DAMAGE TO FACILITY 43
NA 8211230104 8211111 PDR ADDCK 05000366 PDR NRC USE ONLY
NA NA (912) 367-7851 9
NAME OF PREPARER S. B. Tipps (912) 367-7851