

SUPPLEMENTARY INFORMATION

REPORT NO: 50-302/82-066/03L-0
FACILITY: Crystal River Unit #3
REPORT DATE: November 17, 1982
OCCURRENCE DATE: October 19, 1982

IDENTIFICATION OF OCCURRENCE:

Routine surveillance of the 33' wind speed channel indicated that it was inoperable. Technical Specifications 3.3.3.4 requires that this channel be operable.

CONDITIONS PRIOR TO OCCURRENCE:

MODE 5 (COLD SHUTDOWN)

DESCRIPTION OF OCCURRENCE:

At 1045, on October 19, 1982, routine surveillance indicated that the 33' wind speed channel was inoperable. The affected channel was recalibrated and returned to operability by 1600.

DESIGNATION OF APPARENT CAUSE:

The wind speed channel inoperability was caused by instrument drift.

ANALYSIS OF OCCURRENCE:

Because the wind speed channel was only marginally out of specifications, it was determined that emergency dose assessment calculations error would not be affected significantly. There was no effect on public health or safety.

CORRECTIVE ACTION:

The wind speed channel was recalibrated and returned to service.

FAILURE DATA:

This was the second time the 33' wind speed channel was inoperable due to instrument drift. This is the twenty-third report under Technical Specification 3.3.3.4.