



Attachment

Licensee Event Report 82-032/01T-0

During an outage from the startup testing program, a temporary surveillance was run, during which the Standby Gas Treatment System was to have actuated. Neither train of the SGTS operated as designed. The "A" train never started and the "B" train operated a short period of time, then tripped-off. This was determined reportable per 6.9.1.8.e.

Review of the event disclosed the following scenario. The lead SGTS fan (the "A" train) did not start because a loss of off-site power was simulated which caused the radiation monitor on the SGTS exhaust to fail high. The SGTS "B" train then started, but stopped after receiving a trip signal from the delta temperature sensor across the heater switch. The sensor assumed the heater had failed.

The station was in Operational Condition 4 at the time, therefore, neither SGTS was required, nor was any immediate corrective action taken.

To prevent recurrence, the high radiation trip and the swap-over logic will be eliminated. This will prevent loss of the "A" train in a similiar event. Further, the heater delta temperature trip switch was retimed to 200 seconds to prevent an early trip during cold weather.