	U. 3. (NUCLEAR RESIDEATORY COMMISSION COMMIS
	CONTROL BLOCK
1	A L B R F 3 2 0 0 - 0 0 0 0 - 0 0 3 4 1 11 1 1 1 1 3 5 CAT 3 5
1 8	SOURCE LLG 0 5 0 0 0 2 9 6 7 1 10 1 8 8 2 3 1 1 1 1 6 8 2 6 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (1)
IJ	During normal operation, while performing SI 4.1.A-7 on unit 3, reactor low water
D	level switch (LIS-3-203D switch #1) as-found calibration was 537.03 inches.
1	T.S. Table 3.2.A trip level setting is 538 inches above vessel zero. See
5	supplemental information sheet for switch functions. There was no effect on
3	public health and safety. Redundant switches were available and operable.
7	
] ]	SYSTEM CODE CODE SUBCODE COMPONENT CODE SUBCODE SUBCOD
7	Level indicating switch, LIS-3-203D switch #1 CAM was rubbing the actuator arm.
7	The Barton model 288 switch was repaired, recalibrated, functionally tested, and
7	returned to service. This is considered a random event and no further recurrence
	Control is required.    Control is required.
	TOTAL CONTROL OF ACTIVITY TO ASSOCIATE ASSOCIATE ASSOCIATED ASSOCI
4	Ol Ol Ol Z C NA
į.	NA  STOP CONTROL MARKET AND

8211230284 821116 PDR ADDCK 05000296 PDR NINC LISE OTH Y

MANE OF PROPERTY Bobby J. Irby

(205) 729-0841

## LER SUPPLEMENTAL INFORMATION

Reported Under Technical Specification 6.7.2.b.(2) Date Due NRC 11/17/82

## Event Marrative:

Units 1 and 3 were operating normally at 98-percent power; unit 2 was in a refueling outage. Only unit 3 was affected by this event. While performing Surveillance Instruction 4.1.A-7 (Reactor Protection System Reactor Water Level), level-indicating switch, LIS-3-203D switch 1, operated at 537.03 inches. The limit in Technical Specification Table 3.2.A. is 538 inches. Actuation below the trip setting does the following: a) scrams the reactor; b) isolates reactor water cleanup system; c) closes the drywell vent purge and sump isolation valve; d) initiates TIP withdrawal; e) initiates standby gas treatment; f) initiates RHR isolation signal trip and (g) initiates reactor building main vent isolation.

The Barton model 288 switch's CAM was rubbing the actuator arm. The switch was repaired, recalibrated, functionally tested, and returned to service. There was no effect on public health and safety. Redundant switches were available and operable. This is considered a random event and no further recurrence control is required.

\* Previous Similar Events:

None.

Retention: Period - Lifetime; Responsibility - Document Control Supervisor
\*Revision: