

November 15, 1982

James G. Keppler
Regional Administrator
Directorate of Regulatory Operations
Region III
U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Dear Sir:

Reportable Occurrence Report #82-124/03L-0 Docket #050-373 is being submitted to your office in accordance with LaSalle County Nuclear Power Station Technical Specification 6.6.B.2.(b), conditions leading to operation in a degraded mode permitted by a limiting condition for operation or plant shutdown required by a limiting condition for operation.

M. Diduid
G. J. Diederich
Superintendent
LaSalle County Station

GJD/GW/Irw

Enclosure

cc: Director of Inspection & Enforcement Director of Management Information & Program Control U.S. NRC Document Management Branch Inpo-Records Center File/NRC

IE22

1. LER NUMBER: 82-124/03L-0

II. LASALLE COUNTY STATION: Unit 1

111. DOCKET NUMBER: 050-373

IV. EVENT DESCRIPTION:

Technical Specification 3.3.7.10 requires the Lake Blowdown Flow Instrumentation to be operable. On October 16, 1982 the Lake Blowdown Flow Recorder was giving incorrect readings.

V. PROBABLE CONSEQUENCES OF THE OCCURRENCE:

Flow estimates were taken every 4 hours while discharging per Technical Specification 3.3.7.10. Safe operation of the Unit was maintained at all times.

VI. CAUSE:

The Lake Blowdown Flow Instrument probe was found to be plugged preventing the correct signal from being transmitted. The probe continues to plug up within a day from the time it is cleared. The probe was manufactured by Diederich Standards in Bouider, Colorado.

VII. CORRECTIVE ACTIONS:

Modification M-1-0-82-125 was written to modify the existing system. Several alternatives to this problem have been proposed by Sargent & Lundy. AIR 1-82-58035 has been generated to track the completion of the modification. This problem has occurred previously as referenced in LER 82-122/03L-0.

Prepared by: Diane L. Kay