

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | N | C | B | E | P | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | _____ | 5
7 8 9 14 15 25 26 57 58

CON'T
01 | L | 6 | 0 | 5 | 0 | - | 0 | 3 | 2 | 5 | 7 | 1 | 0 | 1 | 8 | 8 | 2 | 8 | 1 | 1 | 1 | 5 | 8 | 2 | 9
7 8 60 61 68 69 74 75 80

02 | During plant operation routine surveillance revealed that primary containment at-
03 | mosphere oxygen analyzer, 1-CAC-AT-1263-2, indicated a drywell oxygen concentration of
04 | .5% while redundant instrument, 1-CAC-AT-1259-2, indicated an expected drywell oxygen
05 | concentration of 2.8%. This event did not affect the health and safety of the
06 | public.
07 | Technical Specifications 3.3.5.3, 3.6.6.4, 6.9.1.9b

09 | S | E | 11 | E | 12 | A | 13 | I | N | S | T | R | U | 14 | P | 15 | Z | 16
9 10 11 12 13 18 19 20

17 | 8 | 2 | 1 | 0 | 7 | 0 | 3 | L | 0
21 22 23 24 26 27 28 29 30 31 32
18 | X | 19 | Z | 20 | Z | 21 | 0 | 0 | 0 | 0 | N | 23 | Y | 24 | N | 25 | B | 1 | 3 | 5 | 26
33 34 35 36 37 40 41 42 43 44 47

10 | 1263-2 was determined to be showing erroneous indications due to oscillations of the
11 | analyzer magnetic unit output resulting from an unstable bridge amplifier output. The
12 | magnetic unit output exciter light was adjusted and the bridge amplifier circuitry
13 | tubes were switched. The analyzer, Model No. F3M3, was then calibrated and returned
14 | to service. These type CAC analyzers will be replaced in accordance with an approved
15 | plant modification.

15 | E | 28 | 0 | 5 | 7 | 29 | NA | A | 31 | Operator Surveillance
7 8 9 10 12 13 44 45 46 80

16 | Z | 33 | Z | 34 | NA | NA
7 8 9 10 11 44 45 80

17 | 0 | 0 | 0 | 37 | Z | 38 | NA
7 8 9 11 12 13 80

18 | 0 | 0 | 0 | 40 | NA
7 8 9 11 12 80

19 | Z | 42 | NA
7 8 9 10 80

20 | N | 44 | _____
7 8 9 10 80

8211230350 821115
PDR ADOCK 05000325
S PDR

NAME OF PREPARER: M. J. Pastva, Jr. PHONE: 919-457-9521