LICENSEE EVENT REPORT

EIGENSEE EVENT REPORT
CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 N J S G S 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 1 0 57 CAT 58 5.
CON'T O 1 SOURCE LIG O 5 0 0 0 3 1 1 7 1 0 3 1 8 2 8 1 1 1 0 8 2 9 TO 1 SOURCE SO 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80
EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10 On December 31, 1982, during routine operation, an operator discovered a small service
water leak of approximately 0.25 GPM on No. 23 Containment Fan Coil Unit (CFCU). The
leak was isolated and prompt notification was made to the NRC by telephone. Action
Statement 3.6.2.3a was already in force due to low service water flow. Both contain-
0 6 ment spray systems were operable throughout the occurrence. The event constituted
abnormal degradation of the containment in accordance with Technical Specification
018 6.9.1.8.c.
SYSTEM CODE SUBCODE SU
LER RO EVENT YEAR SEQUENTIAL REPORT NO. 17 REPORT NUMBER 8 2 1 2 8 0 1 T 0
ACTION FUTURE EFFECT SHUTDOWN HOURS 22 ATTACHMENT NPRD-4 PRIME COMP. COMPONENT METHOD HOURS 22 SUBMITTED FORM SUB. SUPPLIER MANUFACTURER
B (8) F (9) Z (20) Z (21) O O O O Y (23) Y (24) A (25) W 1 2 O (26)
The leakage was due to erosion of a CFCU cooling coil by silt in the service water.
The failed coil was blanked off, and the leakage was stopped. New design cooling
1 2 coils will be installed during the next refueling.
13
14 !
FACILITY STATUS 1 5 E 28 0 8 2 29 NA A 31 Operator Observation
RELEASED OF RELEASE AMOUNT OF ACTIVITY 35 1 6 Z 33 Z 34 NA PERSONNEL EXPOSURES AMOUNT OF ACTIVITY 35 NA NA BO 10 11 10 11 10 11 10 11 10 11 10 11 10 11 10 11 10 10 11 10 1
NUMBER OF STATE OF SCRIPTION (39) NA NA NA
PERSONNEL INJURIES NUMBER DESCRIPTION 1 1 H d ol d 40 NA
LOSS OF DR DAMAGE TO FACILITY 43 SEZ11230434 821110 PDR ADDCK 05000311 PDR
PUBLICITY ISSUED DESCRIPTION 45
210 N 44 NA 68 69. 80 5
NAME OF PREPARER R. Frahm 809/935-6000 Ext. 3078