



**CENTERIOR
ENERGY**

PERRY NUCLEAR POWER PLANT

10 CENTER ROAD
PERRY, OHIO 44081
(216) 259-3737

Mail Address:
PO. BOX 97
PERRY, OHIO 44081

Michael D. Lyster
VICE PRESIDENT - NUCLEAR

February 19, 1991
PY-CEI/NRR-1312 L

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, D. C. 20555

Perry Nuclear Power Plant
Docket No. 50-440
LER 90-025-02

Gentlemen:

Enclosed is Revision 2 to LER 90-025 for the Perry Nuclear Power Plant. The purpose of this revision is to correct MSIV as-found leakage data presented in LER 90-025-01 and to provide an evaluation of 10CFR100 doses using the actual local leak rate test results.

Calculational errors were discovered in the as-found Local Leak Rate Test data provided in LER 90-025-01 for two of the main steam line penetrations. These errors have been corrected and the LER has been updated with the revised LLRT values. Following discussions with the NRC Staff at a meeting on February 7, 1991, a re-evaluation of the impact of these leaking MSIV's on the 10CFR100 design basis analysis presented in USAK Table 15.6-15 has been performed. The conclusion of this evaluation is that overall leakage is still well within 10CFR100 limits. Therefore, the as-found MSIV leakage from this event is not considered to be safety significant.

Please feel free to contact me should you desire any additional information.

Sincerely,

Frank Stead for
Michael D. Lyster

Enclosure: LER 90-025-02

MDL:SC:njc

cc: NRC Project Manager
NRC Resident Inspector Office

U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Operating Companies
Cleveland Electric Illumination

9102250258 910219
PDR ADOCK 05000440
S PDR

*IE22
111*

LICENSEE EVENT REPORT (LER)

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST 900 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20545, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)		DOCKET NUMBER (2)	PAGE (3)
Perry Nuclear Power Plant, Unit 1		0 5 0 0 0 4 4 1 0 1	OF 0 7

TITLE (4) Local Leak Rate Tests Result in Exceeding Allowable Primary Containment Leakage Rates for Main Steam Lines A, B, C and D.

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)		
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES		DOCKET NUMBER(S)
0	9	16	90	90	025	02	02	1991			0 5 0 0 0
THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR 5. (Check one or more of the following) (11)											

OPERATING MODE (9)	5	20.402(a)	20.406(a)	90.73(a)(2)(iv)	73.71(b)
POWER LEVEL (10)	0 0 0	20.406(a)(1)(ii)	90.36(a)(1)	90.73(a)(2)(v)	73.71(c)
		20.406(a)(1)(iii)	90.36(a)(2)	90.73(a)(2)(vi)	OTHER (Specify in Abstract below and in Text, NRC Form 308A)
		20.406(a)(1)(iv)	90.73(a)(2)(ii)	90.73(a)(2)(vii)(A)	
		20.406(a)(1)(v)	90.73(a)(2)(iii)	90.73(a)(2)(vii)(B)	
		20.406(a)(1)(vi)	90.73(a)(2)(iv)	90.73(a)(2)(ix)	

LICENSEE CONTACT FOR THIS LER (12)

NAME	TELEPHONE NUMBER
Henry L. Hegrat, Compliance Engineer, Extension 6855	211 6 215 9 1-13 1713 17

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFAC TURE	REPORTABLE TO NRRDS	CAUSE	SYSTEM	COMPONENT	MANUFAC TURE	REPORTABLE TO NRRDS
C4	SIB	IISIV	A15185	N	C4	SIB	IISIV	B131510	N
C4	SIB	IISIV	R131410	N					

SUPPLEMENTAL REPORT EXPECTED (14)

YES (If yes, complete EXPECTED SUBMISSION DATE) NO

EXPECTED SUBMISSION DATE (15)	MONTH	DAY	YEAR

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

During the period September 16-17, 1990, following shutdown and cooldown of the Perry Nuclear Power Plant, Unit 1 for the second refueling outage, Local Leak Rate Testing (LLRT) of the Main Steam Isolation Valves (MSIV) was conducted. All four of the Main Steam line (MSL) penetrations exhibited leakage in excess of the Technical Specification 3.6.1.2(c) limit of 25 scfh when tested at P₈ (11.31 psig). Several of the MSIV's had not been fast closed following the reactor shutdown. The MSL's were tested again following the opening and fast closing of each MSIV and were still found to be leaking in excess of Technical Specification requirements. The cause of these failures was inadequate seating contact on the outboard MSIV's, pilot valve seat damage on the A and D inboard MSIV's, leaky on all four outboard MSIV drain valves and leaky on the B and D MSL MSIV Leakage Control System (LCS) isolation valves.

As a result of these failures, six of eight MSIV's, all four outboard MSIV drain valves and the B and D MSL MSIV-LCS isolation valves were reworked. All of the MSL's have been tested satisfactorily. Modifications to enhance proper seating of the MSIV's are being purchased. These modifications include poppet anti-rotation devices, nose cone improvements and stem/cover modifications to minimize vibration of the poppet when the MSIV is open. They will be installed on any MSIV's requiring rework during the next refueling outage. In the interim, the MSIV's will be cycled quarterly which should help to minimize the buildup of the oxide layer on the valve seats. Evaluations are being performed to improve the leak tightness of the MSIV-LCS isolation valves and the outboard MSIV drain valves.

LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST 500 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (F-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20545, AND TO THE PAPERWORK REDUCTION PROJECT (3180-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)

DOCKET NUMBER (2)

LER NUMBER (3)

PAGE (3)

Perry Nuclear Power Plant, Unit 1

0 5 0 0 0 4 4 0 9 0 - 0 2 5 - 0 2 0 2 OF 0 7

TEXT (If more space is required, use additional NRC Form 388A (1) (17))

During the period September 16-17, 1990, it was determined that the primary containment leakage rate through the four Main Steam lines (MSL) as defined by Technical Specification 3.6.1.2(c) had been exceeded. At the time of these events, the plant was in Operational Condition 5 (Refuel) in a planned refueling outage which began on September 7, 1990. Reactor coolant temperature ranged between 85 degrees F and 98 degrees F at atmospheric pressure.

On September 16, Type C Local Leak Rate Testing (LLRT) of the MSL penetrations was initiated. Each MSL penetration is bounded by four isolation valves (ISV); the inboard and outboard Main Steam Isolation Valves (MSIV), the MSIV Leakage Control System (MSIV-LCS) steam tunnel isolation valve and the outboard MSIV drain valve.

Prior to these initial tests, the MSIV's had been stroked as follows on September 7 in order to control plant cooldown:

1B21-F0022 (Inboard MSIV's)

- A - slow closed - opened - slow closed
- B - slow closed
- C - slow closed - failed to remain closed - closed later on 9/8/90, speed unknown
- D - fast closed - opened - slow closed

1B21-F028 (Outboard MSIV's)

- A - slow closed - opened - slow closed - opened - slow closed
- B - slow closed - failed to remain closed - closed later, fast closed
- C - slow closed
- D - fast closed - opened - slow closed - opened - slow closed

The failures of 1B21-F022C and -F028B to remain closed are described in LER 90-021-01.

The results of the preliminary leak rate testing completed on September 17, were as follows: A MSL - unable to measure, B MSL - 2058 standard liters per minute (SLM) (estimated), C MSL - 6822 SLM (estimated) and D MSL - 34.35 SLM. All four of the MSL penetrations had thus exceeded their Technical Specification 3.6.1.2(c) limit of 25 scfh, which is equivalent to 11.8 SLM, when tested at P (11.31 psig). During this initial testing it was determined that the MSIV LCS^a isolation valves in MSL's B and D were leaking as was the A outboard MSIV drain valve.

MSL LLRT's are normally performed following single fast closures of the MSIV's while the plant is still hot, which is representative of a post-accident closure. Because of the various methods used to close the MSIV's prior to the initial testing, all eight of the MSIV's were reopened and fast closed, and a second

LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST 500 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (F-930) U.S. NUCLEAR REGULATORY COMMISSION WASHINGTON, DC 20546 AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104) OFFICE OF MANAGEMENT AND BUDGET WASHINGTON, DC 20503.

FACILITY NAME (1) Perry Nuclear Power Plant, Unit 1	DOCKET NUMBER (2) 0500044090	LER NUMBER (8)			PAGE (3) 03 OF 07
		YEAR	PROSEQUENTIAL NUMBER	REVISION NUMBER	
		90	025	02	

TEXT IF MORE SPACE IS REQUIRED, USE ADDITIONAL NRC Form 3884 (11)

round of MSL, LLRT's was performed. A nitrogen overpressure of 145 psig (approx. 25 psig in excess of the closing instrument air pressure) was applied to the actuators of the inboard MSIVs to counteract the upward force placed upon the inboard MSIV poppets when the volume between the two MSIV's is pressurized for testing. Additionally the leaking MSIV-LCS valves (E32-F001 E and N) on the B and D MSL's were plugged.

The results of the second round of testing, which occurred between September 28 and 30, were as follows: A MSL-288 SLM (estimated), B MSL-1598 SLM (estimated), C MSL-873 SLM (estimated) and D MSL-45 SLM. By placing a backpressure downstream of 1B21-F028D, it was determined that 1B21-F022D had a leakage rate of 14.21 SLM. This followup testing verified that all four MSL's leaked in excess of their Technical Specification limits.

The causes of the MSL penetration leakage were as follows: All four outboard MSIV's (F028) displayed poor seating contact between their poppets and valve seats. The upper half to one-third of the valve seat was not in contact with the poppet on each valve. The A and D inboard MSIV's (F022) leaked through the pilot poppet seats. All MSIV's inspected displayed a slight oxide layer on the valve seating surfaces. All four outboard MSIV drain valves (F067) leaked by their seats and the B and D MSL MSIV-LCS isolation valves (E32-F001) leaked by their seats. These valves were all repaired and followup LLRT's were satisfactorily performed on all four penetrations between November 1 and November 12, 1990. Table 1 provides the as-found and as-left leakage, the identified problems and the corrective actions taken for each valve. In addition to the corrective actions identified in Table 1, the six MSIV's that were disassembled were cleaned and their seats polished. All 16 springs on the B outboard MSIV were removed and checked for degradation. All checked out satisfactorily.

In addition to the data presented in Table 1, several other factors contributed to the leak rate test failures of the MSL penetrations. The MSIV-LCS isolation valves (E32-F001) have a history of leaking. During the last outage, a seal ring modification was made to correct body to bonnet leakage. This modification has proven effective. An evaluation is being performed to improve the seat leak tightness of these valves. The outboard MSIV drain valves (B21-F067) experienced their first failures since startup in 1989 when F067A was found to have seat indications and a damaged disc and F067B had a nick in the seat. All four of the F067 valves required refurbishment this outage. With this history in hand, it could be reasonably concluded that these valves have a leak tight life expectancy of four to five years, and the solution may simply be to rework or replace these valves periodically. These as well as other possible modifications or solutions for ensuring that the F067 valves remain leak tight are being evaluated.

LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 500 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (F-830), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3160-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (5)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
Perry Nuclear Power Plant, Unit 1	0 5 0 0 0 4 4 0	9 0	- 0 2 5	- 0 2	0 4	OF 0 7

TEXT IF more space is required, use additional NRC Form 366A (1/77)

Another possible contributor to the failures experienced this outage was the oxide buildup on the MSIV seating surfaces combined with the slow closures of the A, B and C MSL MSIV's. The oxide buildup creates additional closing friction which may prevent adequate seating. The nose guide poppet modifications being planned will overcome the problems associated with the oxide buildup. In the interim, the MSIV's will be stroked quarterly, which should help to clear the seating surfaces of any oxide buildup. To facilitate the planned MSIV modifications, the bores of the F028 B and C valves were machined this outage, in conjunction with the seat replacements, using the newly purchased Climax tool. The Climax was also used to clean the seats on F022 A and D. The accuracy with which this machine can perform seat cleanup and repair should, in itself, improve the leak tightness of the valves it was used on. Other plants have reported better success using this tool than the tools previously available. Finally, the dimensional checks of the valves taken this outage, combined with the comparison of dimensions taken during the first outage, will be useful in determining and quantifying wear on the MSIV's during future outages.

Primary containment integrity ensures that the release of radioactive materials from the containment atmosphere will be restricted to those leakage paths and associated leak rates at the peak pressure of 11.31 psi assumed in the accident analyses limiting the site boundary radiation dose to within the limits of 10 CFR Part 100. The design basis analysis of the leakage resulting from a loss of coolant accident as presented in Table 15.6-15 of the USAR was re-evaluated because of the increased leakage from the failed MSIV's. In performing this re-evaluation a more realistic estimate of total MSIV leakage was made by assigning 50% of the as-found leakage for main steam line penetrations A and D to each of the MSIV's in these lines and 100% of the as-left leakage in main steam line penetrations B and C to the valves which were not reworked in main steam lines B and C. This re-evaluation showed that the whole body and the inhalation doses at the site boundary are still well within the 10CFR100 limits of 25 rem and 300 rem, respectively. Control room doses are regulated by General Design Criteria, GDC-19, "Control Room" which limits exposure to 5 rem whole body. The control room whole body dose remains well within the actual GDC-19 limit of 5 rem. NUREG-0800 "Standard Review Plan," provides guidance for control room inhalation doses as well; the calculated control room inhalation dose increases to 31.18 rem, which is an incremental increase of only 6.8% over the design basis analysis value presented in USAR Table 15.6-15 and only 1.18 rem greater than the NRC staff guidance of 30 rem for inhalation dose. Since the design basis calculation of control room inhalation dose is very conservative, control room exposure would actually be lower, and established plant procedures for protection of control room personnel will continue to ensure exposures are minimized. Based upon this re-evaluation, this event is not considered to be safety significant.

LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-630), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20546, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)	DOCKET NUMBER (2)	REP NUMBER (8)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
Perry Nuclear Power Plant, Unit 1	0500044090	0	25	0	205	OF 07

TEXT (if more space is required, use additional NRC Form 358A's) (17)

Three previous similar events have been identified. On July 5, 1987 primary containment leakage rate exceeded Technical Specification limits through the inboard and outboard MSIVs for MSLs A and B, and through the inboard MSIV and the LCS Steam Tunnel Isolation Valve for MSL D (LER 87-051). The cause of the MSIV leakage was attributed to seat wear. The cause of the MSIV-LCS valves leaking was inadequate rating and sealing of the bonnet pressure seal ring which was aggravated by use of a ANSI Class 2500 valve in a Class 900 application. The seal ring design was modified to compensate for this. The second event occurred September 6, 1987 (LER 87-067). Primary containment leakage rate through the outboard MSIV on MSL B exceeded its Technical Specification limit. The excess leakage flow path was through the outboard MSIV. The cause was due to deformation in the lower part of the valve seating surface which had not been removed by lapping during the prior maintenance outage in July 1987. As the valve was stroked, the seat contact point moved down on the seating surface into the deformation allowing excessive leakage to occur. The third event occurred on February 24, 1989, (LER 89-006), when it was determined that leakage exceeded Technical Specification limits through all four MSL's. Many factors contributed to the degraded condition of the MSIV's and the other isolation valves. Of the MSIV's, only the inboard and outboard MSIV's in MSL's A and C and the outboard MSIV in MSL D required corrective maintenance. Following corrective maintenance, the resulting leakage rates were within Technical Specification limits.

As a result of the events described in this LER, corrective maintenance as described in Table 1 was performed to return the valves to an acceptable condition. Modifications to enhance proper seating of the MSIV's are being purchased. These modifications include a poppet anti-rotation device, an improved nose guide poppet and a cover modification for the top seat of the poppet to minimize vibration of the poppet when the MSIV is open. These valve improvements will be installed during the next refueling outage on any MSIV's requiring rework at that time. In the interim, the MSIV's will be cycled quarterly, which should help to minimize the buildup of the oxide layer on the valve seats. Evaluations are being performed to improve the leak tightness of the MSIV-LCS isolation valves and the outboard MSIV drain valves.

Energy Industry Identification System Codes are identified in the text as [XX].

LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-630), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20545, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1) Perry Nuclear Power Plant, Unit 1	DOCKET NUMBER (2) 05000440910	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
		02	5	02	06	07	

TEXT (If more space is required, use additional NRC Form 388A's) (17)

TABLE 1
MSIV-LLRT Results and Corrective Action

Penetrations	Leakage AF/AL *	Identified Problems	Corrective Actions
<u>MSL A</u>	288**/2.556		
F022A		- Minor valve seat depressions - Raised metal on pilot seat - Guide rib wear - Stem and spring retaining ring wear	- Lapped valve body seat - Lapped pilot poppet seat - Weld repaired lower guide rib - Replaced stem and spring retaining ring
F028 A		- Stem exceeded TIR	- Replaced stem
F067 A		- Inadequate seat contact	- Lapped seat and replaced disc
<u>MSL B</u>	1598**/0.417		
F028 B		- Crack in valve seat - Stellite layer not complete on poppet	- Removed and replaced valve seat - Replaced poppet
F067 B		- Inadequate seat contact	- Lapped seat and replaced disc
E32-F001 E		- Inadequate seat contact	- Lapped seat and replaced seal ring
<u>MSL C</u>	873**/1.748		
F028 C		- Indications on seat/bore - Scratched stem - Guide rib wear	- Removed and replaced valve seat - Replaced stem - Weld repaired lower guide rib
F067 C		- Inadequate seat contact	- Lapped seat and replaced disc

LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 500 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-630), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1) Perry Nuclear Power Plant, Unit 1	DOCKET NUMBER (2) 0 5 0 0 0 4 4 0 9 0	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
		0	2	5	0	2	0 7 OF 0 7

TEXT IF MORE SPACE IS REQUIRED, USE ADDITIONAL NRC FORM 306A (17)

Penetration	Leakage AF/AL*	Identified Problems	Corrective Actions
MSL D	45/2.778		
F022 D		<ul style="list-style-type: none"> - Valve seat angle incorrect - Raised metal on pilot seat - Guide rib wear - Stem and spring retaining ring worn and scratched - Stuck stud 	<ul style="list-style-type: none"> - Machined and lapped valve seat - Lapped pilot seat - Weld repaired lower and upper left guide ribs - Replaced stem and spring retaining ring - Drilled stud out and replaced
F028 D		<ul style="list-style-type: none"> - Pilot bore damage - Star plate stuck - Stem scratched 	<ul style="list-style-type: none"> - Lapped pilot seat - Removed and replaced star plate & stanchions - Replaced stem
F067 D		<ul style="list-style-type: none"> - Inadequate seat contact, scored seat and disc. 	<ul style="list-style-type: none"> - Lapped seat and replaced disc
E32-F001 N		<ul style="list-style-type: none"> - Inadequate seat contact 	<ul style="list-style-type: none"> - Lapped seat and replaced seal ring

* AF/AL - As found/As left - Leakage rates in SLM

** Estimated