

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 FLCRP3 2010-100000-00 3 41111 4 5
7 8 9 14 15 25 26 30 57 CAT 58

CONT
01 L 6050-0302 7101782 8 111682 9
7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10
02 | On October 17, 1982, at 1315, during an unrelated shutdown, con-
03 | tainment isolation valve DHV-4 could not be operated from the
04 | Control Room and was subsequently determined to be inoperable
05 | (T.S.3.6.1). Before continuing shutdown operations, DHV-3 and DHV-4
06 | were cycled to assure that the effected penetration could be secured.
07 | DHV-4 was returned to operability at 1430. There was no effect on
08 | public health or safety. This was the first time DHV-4 failed due to
09 | an inoperable switch.

09 SID E F VALVEX E D
7 8 9 10 11 12 13 14 15 16 17 18 19 20

17 1812 1 01615 1 03 1 0
21 22 23 24 25 26 27 28 29 30 31 32

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27
10 | This event was caused by a stuck mechanical interlock on DHV-4.
11 | The interlock was cleaned and lubricated. DHV-4 was tested satis-
12 | factorily and returned to service.
13 |
14 |

15 G 0000 N/A A operator observation
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

16 Z Z N/A N/A
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

17 000 Z N/A
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

18 000 N/A
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

19 Z N/A
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

20 N N/A
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

NAME OF PREPARER P. G. Hughes PHONE: (904) 795-3802

8211230449 821116
 PDR ADOCK 05000302
 S PDR

SUPPLEMENTARY INFORMATION

REPORT NO: 50-302/82-065/03L-0

FACILITY: Crystal River Unit #3

REPORT DATE: November 16, 1982

OCCURRENCE DATE: October 17, 1982

IDENTIFICATION OF OCCURRENCE:

Containment isolation valve DHV-4 was inoperable contrary to Technical Specification 3.6.3.1.

CONDITIONS PRIOR TO OCCURRENCE:

MODE 4 (HOT SHUTDOWN)

DESCRIPTION OF OCCURRENCE:

On October 17, 1982, at 1315, during an unrelated shutdown, containment isolation valve DHV-4 could not be operated from the control room and was subsequently determined to be inoperable. DHV-3 and DHV-41 were cycled to assure that the affected penetration could be isolated. DHV-4 was returned to operability by 1430.

DESIGNATION OF APPARENT CAUSE:

This event was caused by a stuck mechanical interlock on DHV-4.

ANALYSIS OF OCCURRENCE:

There was no effect on public health or safety because the penetration could be isolated using DHV-3 and DHV-41.

CORRECTIVE ACTION:

The interlock was cleaned and lubricated. DHV-4 was tested satisfactorily and returned to service.

FAILURE DATA:

This is the first time that DHV-4 failed due to an inoperable switch and is the forty-fourth report under Specification 3.6.3.1.