## U. S. NUCLEAR REGULATORY COMMISSION NRC FORM 366 (7.77) LICENSEE EVENT REPORT CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION) 10101010 CON'T 0 1 L 6 015 0 2 5 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) T-82B (B Safety Injection Tank) level reached 0 2 During normal power operation. This occurred 14 times between 9-29-82 and [0]3 [the T/S limit of 198 inches. In 8 of these cases, boron concentration in T-82B fell below the 110-22-82. IT/S limit of 1720 ppm. Tank level and boron concentration were promptly restored to the normal operating range; therefore, no threat to public heal or safety. Condition reportable per TS 3.3.1.b and 6.9.2.b(2). 0 8 SYSTEM COMP SUBCODE CAUSE SUBCODE CODE COMPONENT CODE SUBCODE Z | (16 B 13 Z 15 C C U M U 14 0 9 OCCURRENCE REVISION SEQUENTIAL REPORT NO. REPORT CODE EVENT YEAR NO 10 | 3 111 10 13 13 8 2 IX I REPORT 3 NPRD4 PRIME COMP. COMPONENT MANUFACTURES HOURS (22) ATTACHMENT SUBMITTED EFFECT N PLANT Y 23 101010 N 24 N 1 1 5 N 25 Z (20) Z (21) 01 CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) due to minor leakage past loop check valve and SIT check Level increase walve or fill and drain valve. Loss of SIT level indication is compounding Primary coolant leak rate is being closely monitored. Valves the problem. [will be inspected during next refueling outage. Level transmitter failure ito be investigated during next extended shutdown. METHOD OF FACILITY STATUS OTHER STATUS (30) DISCOVERY DESCRIPTION (32) & POWER 1 0 0 29 A (31 Alarm annunciation ACTIVITY CONTENT AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36) RELEASED OF RELEASE Z 3 , Z 3 NA NA 1 6 PERSONNEL EXPOSURES DESCRIPTION (39 0 0 0 0 0 3 Z 38 NUMBER TYPE NA PERSONNEL INJURIES DESCRIPTION (41) NUMBER 0 0 0 0 NA 9 11 12 LOSS OF OR DAMAGE TO FACILITY (43) DESCRIPTION Z 1(42) NA 1 9 PUBLICITY NRC USE ONLY DESCRIPTION (45) SSUED 44 NA

68

Attachment to LER 82-033 Consumers Power Company Palisades Plant Docket 50-255

As reported in LER 82-029, Palisades has been experiencing minor leakage (within Technical Specification limits) into T-82B (B Safety Injection Tank). The leakage is past loop check valve 3116 and either the tank check valve 3117 or the fill and drain valve CV-3043. While this leakage would not normally result in a significant problem or a reportable event, the problem has been compounded by a failure of the Safety Injection Tank (SIT) level indicating system. Consequently, the operators have had to rely on the high and low level switch alarms for level indication. Each time one of the alarms is received, a Limiting Condition for Operation (LCO) is entered. Specifically, the SIT must be declared inoperable until the level and boron concentration are reestablished within the limits of TS 3.3.1.b; therefore, the LCO of TS 3.3.2.a is entered.

The first event occurred before the failure of the T-82B level indicating system was recognized. To correct an apparent high level condition in T-82B, the SIT level was lowered, relying on the level indicating system. During the evolution, a low level alarm was received, even though the indicated level still showed the tank level to be within the operating band. Level was promptly restored to clear the alarm. The reportability of this event was determined on November 4.

The remaining events have all occurred in the following manner. A high level alarm is received in the control room. The tank level is lowered and the boron concentration is measured. The SIT boron concentration is diluted by the primary coolant, containing approximately 620 ppm, leaking into the SIT. Restoring the concentration is done with SIRW tank water, which is normally at 1900 ppm. Consequently, it takes several drain and fill cycles to restore the concentration. To minimize the number of drain and fill cycles, the SIT level is lowered as far as possible prior to refilling. Occasionally, the low level alarm is received while draining. The draining is then stopped and the tank is refilled. These events are summarized in Table 1.

Inspection and repair of check valve 3116 is currently scheduled for the next refueling outage. Additional monitoring will be performed to determine which other valves are leaking and necessary repairs will also be made during the next refueling outage.

We speculate that the problem with the T-82B level system appears to be related to temperature effects on the transmitter reference leg. Repair of this system during plant operation is precluded because of the high radiation field. Therefore, additional testing will be performed to isolate and correct the problem during the next extended shutdown.

Attachment to LER 82-033 Consumers Power Company Palisades Plant Docket 50-255

TABLE 1

Out	of	Specification	Condition
out		Of Christian Cross	001104 04011

	Date	Time	High Level	Low Level	Low Boron
	9/2	1420		х	
	9/29	0401	X	х	
	10/3	0208	Х		X
	10/3	2313	x		х
	10/4	2058	х		
	10/5	1305	x	х	
	10/6	1749	х		
3	10/7	1946	х		
	10/9	0055	x		х
	10/10	1332	x		х
	10/13	1525	x		х
	10/15	1418			х
	10/19	1005		x	
	10/19	1836	x		
	10/20	2000	x		
	10/21	1607	x		x
	10/22	2020	x		X