LICENSEE EVENT REPORT

	CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1	M A P P S 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5 5 CAT 58
CON'T 0 1 7 8	REPORT L 6 0 5 0 - 0 2 9 3 7 1 0 2 8 8 2 8 1 1 1 1 0 8 2 9 SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
0 2	On 10/28/82, at 2330, the HPCI system was declared inoperable. A ground in the "B"
0 3	125 VDC supply was traced to the limit switch circuitry for MOV 2301-3. On 11/1/82
0 4	a short was traced to the 250 VDC circuitry for the 2301-3 motor operator. On both
0 5	dates, T.S. required surveillances were initiated and terminated when HPCI was made
0 6	operable. These events caused no threat to the public health and safety. The NRC
0 7	was notified via ENS. The valve is a 10" venturi gate valve supplied by Velan Co.
0 8	80
09	SYSTEM CODE CAUSE CAUSE COMPONENT CODE SUBCODE
	TO REPORT NUMBER SEQUENTIAL REPORT NO. SEQUENTIAL REPORT NO. SEQUENTIAL REPORT NO. OCCURRENCE REF. JRT TYPE NO. NO. NO. 17 LER/RO SEQUENTIAL REPORT NO. 17 LER/RO SEQUENTIAL REPORT NO. 17 LER/RO SEQUENTIAL REVISION NO. NO. 32 SEQUENTIAL REVISION NO. 33 SEQUENTIAL REVISION NO. NO. 34 SEQUENTIAL REVISION NO. 36 SEQUENTIAL REVISION NO. 18 SEQUENTIAL REVISION NO. 19 SEQUENTIAL REVISION NO. 10 SEQUENTIAL REPORT NO. 10 SEQUENTIAL REVISION NO. 10 SEQUENTIAL REPORT NO. 10 SEQUENTIAL REVISION NO. 11 SEQUENTIAL REVISION NO. 12 SEQUENTIAL REVISION NO. 13 SEQUENTIAL REPORT NO. 14 SEQUENTIAL REVISION NO. 15 SEQUENTIAL REVISION NO. 16 SEQUENTIAL REVISION NO. 17 SEQUENTIAL REVISION NO. 17 SEQUENTIAL REVISION NO. 18
	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) ACTION FUTURE ON PLANT SHUTDOWN HOURS (22) ATTACHMENT FORM SUB. PRIME COMP. SUPPLIER MANUFACTURER LA 18 A 19 Z 20 Z 20 Z 20 O O O O O N 23 ATTACHMENT FORM SUB. SUPPLIER MANUFACTURER LA 18 A 19 Z 20 Z 20 Z 20 Z 20 A 11 Z 20 A 12 A 25 A 12 A 12 A 12 A 12 A 12 A 12
10	The root cause is valve stem packing leakage due to a scored stem. The packing was
1 1	replaced for the first event and tightened for the second. The stem is to be re-
1 2	placed during a scheduled preventive maintenance outage for the HPCI System. The
1 3	grounds in the circuits were corrected by drying out the affected components.
1 4	80
1 5	ACILITY SPOWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 E 28 1 0 0 0 29 NA C C 31 Trouble shooting investigation 30 9 10 12 13 44 45 46 46 80
	LEASED OF RELEASE AMOUNT OF ACTIVITY (35) NA N
1 7	PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39 O O O O 37 Z 38 NA PERSONNEL INJURIES NA 80
1 8	NUMBER DESCRIPTION NA NA 80
1 9	LOSS OF OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION NA NA 80
20	PUBLICITY SSUED DESCRIPTION (4 PDR ADDCK 05000293 PDR NA NA SO-5
	G. G. Whitney PHONE 617-746-7900