LICENSEE EVENT REPORT

| CONTROL BLOCK: 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 |
|--|
| 1 A L B R F 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 1 5 5 5 5 5 5 5 5 5 5 5 5 5 5 |
| THE REPORT L TO 0 5 0 0 0 2 5 0 7 1 0 2 4 8 2 0 1 1 1 1 9 8 2 0 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) |
| During normal operation, while performing a routine check, it was observed |
| that 480-V reactor MOV board 1DA motor-generator (MG) set voltage was swinging |
| about +5 to -5 volts from nominal. The MG set was removed from service and the |
| [voltage regulator was replaced (T.S. 3.9.B.13). There was no effect on public health |
| and safety. T.S. 3.9.B.13 allows operation for 7 days with one MG set inoperable. |
| All other unit 1480-V reactor MOV board MG sets were operable. |
| D (|
| SYSTEM CAUSE CODE CODE SUBCODE COMPONENT CODE SUBCODE |
| LERINO EVENT YEAR REPORT NO. OCCUPANT TYPE ACTION FUTURE TAKEN ACTION ON PLANT METHOD ACTION FUTURE TAKEN ACTION ON PLANT METHOD ACTION FUTURE SUPPLIES |
| regulator failed. The regulator was replaced. It was previously determined |
| that this type failure does not make the MG set inoperable. Since this is not |
| a significant generic problem and this is the only failure in the past 13 months, |
| no recurrence control is required. |
| FACILITY STATUS OF POWER OTHER STATUS OF METHOD OF DISCOVERY DESCRIPTION (32) Routine check ROUTINE CHECK ROUTINE CHECK |
| TOCATION OF HELEASE (9) NA LOCATION OF HELEASE (9) NA LOCATION OF HELEASE (9) |
| 1 10 10 10 10 Z C PESCALETION (1) |
| PERF NOVALE TO A TOP TO A TO |
| - 8211290323 821119 NA S ADDCK 05000259 PDR |
| NAC USE STRY NA |
| **** OF PHILEMPEN Walt T. Christopher (205) 729-0800 |

LER SUPPLEMENTAL INFORMATION

| BFRO-50- | 259/ | 82087 | Technical | Specification | Involved | 3.9.B.13 | |
|----------|-------|-------|-----------|---------------|----------|----------|--|
| Reported | Under | | | on 6.7.2.b.(2 | | | |

Event Narrative:

Unit 1 was operating normally at 98-percent power; unit 2 was in a refueling outage; unit 3 was operating normally at 99-percent power. Unit 1 was the only unit affected by this event. During a routine check, the 480-Vreactor MOV board 1DA motor-generator (MG) set voltage was observed to swing about +5 to -5 volts from nominal. The MG set was removed from service and Basler Electric Company Type KR4F, model P/N-9-1161-100 voltage regulator was replaced (T.S. 3.9.B.13). The voltage swing was due to the failure of capacitor C8 in the voltage regulator. There was no effect on public health and safety in that the MG set was returned to service within the time limits as specified by T.S. 3.9.B.13. All other unit 1480-V reactor MOV board MG sets were available and operable. As a result of LER No. BFRO-50-296/8152, a failure analysis by Louis Allis Company determined that the failure of capacitor C8 does not make the MG set inoperable. Therefore, this event is not reportable due to the capacitor failure. However, this event is reportable due to the MG set being removed from service for replacement of the voltage regulator. This is the only capacitor failure in the past 13 months in the eight regulators now in service. It is concluded that this is not a significant generic equipment problem. Therefore, no recurrence control is required.

* Previous Similar Events:

BFRO-50-296/81052

Retention: Period - Lifetime; Responsibility - Document Control Supervisor

*Revision: