	LICENSFE EVENT REPORT Attachment to AECM-82/566
**	Page 1 of 1 CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1	M S G G S 1 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5 57 CAT 58
CON'T	REPORT L 6 0 5 0 0 0 4 1 6 7 1 0 2 4 8 2 8 1 1 2 3 8 2 9 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10
0 2	On October 24, 1982, the smoke detectors in the East electrical switchgear room and a
0 3	piping penetration room of the Auxiliary Building, elevation 119 foot, alarmed and
0 4	would not reset. Investigation revealed no smoke or fumes present in the area. An
0 5	hourly fire watch was established in accordance with Technical Specification 3.3.7.9.
0 6	This event did not constitute a threat to plant safety, and there was no effect on
0 7	public health or safety.
7 8	SYSTEM CAUSE CAUSE COMP. VALVE
0 9	A B 11 X 12 Z 13 I N S T R U 14 E 15 Z 16
	17 LERIRO EVENT YEAR SEQUENTIAL REPORT NO. 1 1 3
	ACTION FUTURE EFFECT SHUTDOWN METHOD HOURS 22 ATTACHMENT SUBMITTED FORM SUB. SUPPLIER SUPPLIER MANUFACTURER X 18 Z 19 Z 20 Z 21 0 0 0 N 23 N 24 A 25 H 2 6 0 26 30 31 32 33 34 35 36 37 40 41 31 42 43 43 44 47 47 47 47 47
FITOI	The exact cause of the alarm is unknown. A surveillance test was performed on the
Link and	smoke detectors on October 24, 1982, and the results were satisfactory. The detectors
[1]3]	were returned to service, and the LCO was lifted on October 29, 1982. This is a final
13	report.
7 8	9
[1]5]	FACILITY STATUS SPOWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 B 28 0 0 0 0 29 NA 44 45 46 80
	ACTIVITY CONTENT ELEASED OF RELEASE AMOUNT OF ACTIVITY (35) Z (33) Z (34) NA NA NA
r s	9 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39) NA
7 8	9 11 12 13 80 PERSONNEL INJURIES 80
1 8	O O O O O NA
	USS OF OR DAMAGE TO FACILITY 43
1 9	NA 8211290512 821123 PDR ADDCK 05000416
2 0	PUBLICITY ISSUED DESCRIPTION (45) NA PDR HRC USE ONLY NA
7 8	Original signed by Matthew V. Rohrer NAME OF PREPARER.
	THE PRICE AND ADDRESS OF THE PRICE AND ADDRESS