	LICENSEE EVENT REPORT
	CONTROL BLOCK:
0 1 1	M D C C N 2 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5 5  LICENSE CODE 14 15
CON'T 0 1 7 8	REPORT L 6 0 5 0 0 0 3 1 8 7 1 0 2 5 8 2 8 1 1 0 9 8 2 9  SOURCE 60 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80  EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10
0 2	During Mode 6 Operation at about 0900, discovered that no audible source
03	range indication was operable (T.S. 3.9.2). All 4 channels of visual
0 4	indication were operable. Unit 2 had entered Mode 6 at 1000 on 10-21-82.
0 5	Audible indication was repaired at 1550 on 10-25-82. No core alterations
0 6	had been performed during this time period.
0 7	Similar events: none.
08	80
	SYSTEM CODE CODE SUBCODE COMPONENT CODE SUBCODE SUBCOD
10	The cause of this event was a failure of administrative controls. The
TIT	surveillance test procedure (STP) that checks the operability of the
1 2	source range flux monitors failed to address audible indication. This
13	STP has since been corrected. Additionally, a checklist is being devel-
14	oped for entry into Mode 6 to ensure all T.S. requirements are met.
7 8 F. S	H 28 0 0 0 29 N/A D 31 NRC Resident Inspector
1 6 RE	9 10 12 13 44 45 46  CIVITY CONTENT LEASED OF RELEASE AMOUNT OF ACTIVITY (35)  Z (33) Z (34) N/A  9 10 11  PERSONNEL EXPOSURES  80  N/A  44 45 46  N/A  80  80
1 7 8	NUMBER TYPE DESCRIPTION (39) N/A  9 11 12 13 13 80
1 8 7 8	NUMBER DESCRIPTION (41)  0 0 0 0 0 0 N/A  9 11 12  LOSS OF OR DAMAGE TO FACILITY (43) TYPE DESCRIPTION  Z (42) N/A  PDR ADDCK 05000318
2 0	9 10 80 PUBLICITY SSUED DESCRIPTION 45 NRC USE ONLY N/A 9 10 68 69 80 5
	NAME OF PREPARER R. L. Wenderlich PHONE: 301-269-4776