LICENSEE EVENT REPORT
CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 A L J M F 2 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5 5 15 LICENSE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58 5
CON'T O 1 SOURCE L 6 0 5 10 0 10 3 6 4 7 1 10 2 3 8 12 8 1 11 2 2 8 2 9 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10 O 2 At 1120, 1900, and 2030 on 10-23-82 during performance of FNP-2-STP-604.0 (Pressurizer)
Safety Police Valve Test) Pressurizer Safety Relief valves 02B13V031A, 02B13V031B and I
. 02813V031C were declared inonerable due to their relief setpoint being out of tolerance
o 4 Q2B13V031c were decrared moperable due to their review sespential points of the conservative direction)
[0]6] [Tech. Spec. 3.4.3 requires all pressurizer code safety valves to be operable with a
[0] 7 [lift setting of 2485 psig $\pm 1\%$. Tech. Spec. 3.4.3 action statement requirements were
omet. Health/safety of the public was not affected.
SYSTEM CAUSE CODE SUBCODE COMPONENT CODE SUBCODE SUBCO
E 18 Z 19 Z 20 Z 21 0 0 0 0 0 N 23 N 24 N 25 C 7 1 0 26 CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27
This event was attributed to setpoint drift. Following an adjustment of the safety
[1] [relief setpoint, Pressurizer Safety Relief Valves Q2B13V031A, Q2B13V031B and Q2B13V031C]
were declared operable at 1200, 1945 and 2120 on 10-23-82.
7 8 9 FACILITY STATUS NOWER OTHER STATUS 30 METHOD OF DISCOVERY DISCOVERY DESCRIPTION 32 1 5 D 28 0 0 0 29 N/A B 31 Surveillance Test
7 8 9 10 12 13 12 13 AMOUNT OF ACTIVITY (35) N/A LOCATION OF RELEASE (36) 1 6 Z (33) Z (34) N/A N/A
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39 N/A
7 8 9 PERSONNEL INJURIES DESCRIPTION 41) 1 8 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
7 8 9 10 PUBLICITY AS
SSUED DESCRIPTION (45) N/A 68 69 80 5
NAME OF PREPARER W. G. Hairston, III PHONE: (205) 899-5156