

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | 0 | H | D | B | S | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5
7 8 | 9 | | | | | 14 | 15 | | | | | | | | | 25 | 26 | | | | | | 57 | 58 | 80

CON'T
0 1 | REPORT SOURCE | L | 6 | 0 | 5 | 0 | 0 | 0 | 3 | 4 | 6 | 7 | 1 | 0 | 2 | 1 | 8 | 2 | 8 | 1 | 1 | 1 | 9 | 8 | 2 | 9
7 8 | 60 | 61 | | | | | | | | | 68 | 69 | | | | | | 74 | 75 | | | | | | 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
0 2 | (NP-33-82-66) At 1115 hours on 10/21/82, and again at 1914 hours on 10/24/82, Safety
0 3 | Features Actuation System (SFAS) Channel 4 Radiation Monitor RE-2007 failed low. On
0 4 | both occurrences, the high radiation output bistable was tripped in accordance with
0 5 | Technical Specification 3.3.2.1, Action Statement 9. There was no danger to the
0 6 | health and safety of the public or station personnel. The remaining three SFAS chan-
0 7 | nel radiation monitors were operable.

0 8 | _____ 80
0 9 | SYSTEM CODE | I | B | 11 | CAUSE CODE | X | 12 | CAUSE SUBCODE | Z | 13 | COMPONENT CODE | I | N | S | T | R | U | 14 | COMP. SUBCODE | E | 15 | VALVE SUBCODE | Z | 16
7 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 |

17 | LER/RO REPORT NUMBER | 8 | 2 | 21 | 22 | SEQUENTIAL REPORT NO. | 0 | 5 | 5 | 24 | 26 | OCCURRENCE CODE | 0 | 3 | 27 | 29 | REPORT TYPE | L | 30 | REVISION NO. | 0 | 32
ACTION TAKEN | C | 18 | FUTURE ACTION | X | 19 | EFFECT ON PLANT | Z | 20 | SHUTDOWN METHOD | Z | 21 | HOURS | 0 | 0 | 0 | 0 | 22 | ATTACHMENT SUBMITTED | Y | 23 | NPRD-4 FORM SUB. | Y | 24 | PRIME COMP. SUPPLIER | N | 25 | COMPONENT MANUFACTURER | V | 1 | 1 | 5 | 26
33 | 34 | 35 | 36 | 37 | 38 | 39 | 40 | 41 | 42 | 43 | 44 | 45 | 46 | 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
1 0 | The root cause is unknown. A module (readout) check was performed, all cabling was
1 1 | tested for continuity, grounds or shorts, and all connectors and terminal strip connec-
1 2 | tions were inspected, however, no faults were found. On both occurrences, the detec-
1 3 | tors were replaced, Surveillance Test ST 5031.01 run successfully, and RE-2007 de-
1 4 | clared operable, removing the unit from the action statement.

1 5 | FACILITY STATUS | E | 28 | % POWER | 0 | 8 | 6 | 29 | OTHER STATUS | NA | 30 | METHOD OF DISCOVERY | A | 31 | DISCOVERY DESCRIPTION | Operator Observation | 32
7 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | 25 | 26 | 27 | 28 | 29 | 30 | 31 | 32

1 6 | ACTIVITY CONTENT RELEASED OF RELEASE | Z | 33 | Z | 34 | AMOUNT OF ACTIVITY | NA | 35 | LOCATION OF RELEASE | NA | 36
7 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | 25 | 26 | 27 | 28 | 29 | 30 | 31 | 32

1 7 | PERSONNEL EXPOSURES NUMBER | 0 | 0 | 0 | 37 | TYPE | Z | 38 | DESCRIPTION | NA | 39
7 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | 25 | 26 | 27 | 28 | 29 | 30 | 31 | 32

1 8 | PERSONNEL INJURIES NUMBER | 0 | 0 | 0 | 40 | DESCRIPTION | NA | 41
7 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | 25 | 26 | 27 | 28 | 29 | 30 | 31 | 32

1 9 | LOSS OF OR DAMAGE TO FACILITY TYPE | Z | 42 | DESCRIPTION | NA | 43
7 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | 25 | 26 | 27 | 28 | 29 | 30 | 31 | 32

2 0 | PUBLICITY ISSUED | N | 44 | DESCRIPTION | NA | 45
7 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | 25 | 26 | 27 | 28 | 29 | 30 | 31 | 32

8211290543 821119
PDR ADOCK 05000346
S PDR

TOLEDO EDISON COMPANY
DAVIS-BESSE NUCLEAR POWER STATION UNIT ONE
SUPPLEMENTAL INFORMATION FOR LER NP-33-82-66

DATE OF EVENT: October 21 and 24, 1982

FACILITY: Davis-Besse Unit 1

IDENTIFICATION OF OCCURRENCE: Failure of Safety Features Actuation System (SFAS) Channel 4 Radiation Monitor RE-2007

Conditions Prior to Occurrence: The unit was in Mode 1 on both occurrences with Power (MWT) = 2373 and Load (Gross MWE) = 799 on October 21; and Power (MWT) = 2380 and Load (Gross MWE) = 800 on October 24.

Description of Occurrence: At 1115 hours on October 21, 1982 and again at 1914 hours on October 24, 1982, SFAS Channel 4 Radiation Monitor RE-2007 failed low. On both occurrences, the high radiation output bistable was tripped in accordance with Technical Specification 3.3.2.1, Action 9. This placed the unit in a 1 out-of-3 trip condition on SFAS radiation channel monitoring.

On both occurrences, an SFAS alarm on containment radiation fail was received, and the Control Room operator verified a low (off-scale) reading.

There was no power reduction required by either occurrence.

Designation of Apparent Cause of Occurrence: The root cause of these occurrences is unknown. On both occurrences, the failure appeared to be the detector. A module (readout) check was accomplished, and no faults could be found. All cabling was tested (continuity, grounds and shorts), and no faults could be found. All connectors and terminal strip connections were inspected, and no faults were found. The detectors were tested by Maintenance Work Order IC-590-82 and found to be good. The detectors were put on test for a period of three to four days and were subjected to heating, cooling, and vibration, but no fault would recur. The detectors were recalibrated and returned to the I&C storage area.

Analysis of Occurrence: There was no danger to the health and safety of the public or station personnel. The remaining three SFAS channel radiation monitors were operable as well as the containment air monitors, the containment high radiation area monitors, and the containment access area radiation monitors. There were no off-site consequences.

Corrective Action: For the first occurrence, corrective action was the replacement of the detector by Surveillance Test ST 5031.04. Operations personnel ran Surveillance Test ST 5031.01 Section 6.2 and declared SFAS Channel 4 operational on October 22, 1982 at 0530 hours. This removed the station from the action statement of Technical Specification 3.3.2.1.

TOLEDO EDISON COMPANY
DAVIS-BESSE NUCLEAR POWER STATION UNIT ONE
SUPPLEMENTAL INFORMATION FOR LER NP-33-82-66
PAGE 2

The corrective action for the second occurrence was again to replace the detector by Surveillance Test ST 5031.04. Operations personnel again ran Surveillance Test ST 5031.01 Section 6.2 and declared SFAS Channel 4 operational on October 27, 1982 at 1807 hours. Again, the station was removed from the action statement of Technical Specification 3.3.2.1.

Additional testing was performed as described above, but no definite cause of failure was determined.

Failure Data: There have been twelve previously reported component failures of the SFAS radiation monitors, with only two Licensee Event Reports, NP-33-82-06 (82-005) and NP-33-82-52 (82-047) being reported within the previous year.

LER #82-055