

Department of Energy

Albuquerque Operations Office P.O. Box 5400 Albuquerque, New Mexico 87115 RETURN ORIGINAL TO POR, HQ.

FEB 0 7 1991

AECEIVE

Mr. Ramon E. Hall
Director, Uranium Recovery
Field Office
Region IV
U.S. Nuclear Regulatory Commission
P.O. Box 25325
Denver, CO 80225

Dear Mr. Hall:

Enclosed for your information is a Class III Project Interface Document (PID) No. 03-S-41 for the Durango, Colorado, Uranium Nill Tailings Remedial Action site. The PID involves a change for the completion date in Specification 01010-1.8.A. In addition, a copy of the previously sent Class II PID 93-S-30 is enclosed per the request of Dawn Jacoby of your staff.

Should you have any questions, please contact Steve Ham of my staff at FTS 845-5640.

Sincerely,

Mark L. Matthews

Project Manager Uranium Mill Tailings Remedial Action Project Office

Enclosures

cc w/o enclosures: M. Abrams, UMTRA D. Gillen, NRC

DESIGNATED ORIGINAL

Certified By many C 21 rd

9102270249 910207 PDR WASTE


PDR

91-0254




UNTRA PROJECT OFFICE PROJECT INTERFACE DOCUMENT


		L. Line Line							
Site Durango, Col	orado	Date	12/31/96	PID No. 03-	-S-41 S18	e No. 03		Vic Pro No.	
Originator and Location Tom Jernings, APO		Phone (505)	766-1667	Organizacion MK-Fergus	n Ans	wer By:		References: Subcontract:	
Subject								Subcontract No: DUR-	86-02
Extension of Sul	contract Comp	pletion	Date						
of	delays delays to June 30, 19	mpletion to the 1 991, is	n date of work, the considere	Specificati Project can d to be in	not be co	-1.8.A is D omplated by interest o	that date.	1990, but because An extension of	
Disposition			oved [] Appr	oved as Noted		RAC Site Manag		3ebich 1/1	nate 1/9/
Criteria Change? (If Yes, DOE approval		-	NTROL ORK GO	LED M	C Engineeri	fon Engineer_ Quality //	Potent 6	Cooney 1/4	1/91 91 4/9/ Bate
distribution Name	ne Loc	ation			Kame	e	Location	Cost/Tim	e Est.
TAC Site Mgr. 7 TAC Site Mgr. 8 RAC Site Qual, Engr.	Thomson Hamp Edge I. Harr	c//		RAC Constr. E RAC Qual. Mgr Other		Proposition Whenex	D 3000	DATES	equired
AC HS&E Mgr. F	PotelKa				m	Skrin	VI.		





PRUTILE (LOOKING NORTIZERLY)

FIGURE 2.










AT DITCH NO. I DUTLET

go 690. RIPRAP TYPE B-1 DITCH NO. 2 BERM TYPICAL DN DWG NO. FIGURE 7: REVISIONS OF EDGE DETAILS ON WESTERN SLOPE AND SOUTHWESTERN DRAINAGE ALONG DITCH NO. 2.



MA	MORRISON
No	MORRISON KNUDSEN

UMTRA PROJECT OFFICE PROJECT INTERFACE DOCUMENT

PID0330.DUR Sheet 1 of 3

Site Durango	Date8/09/90	PID No. 03-S-3	Site No. 03	Vic Pro	No.
Originator and location M. L. Wesely, SF	Phone 415/442-751	Organization MKES	Answer By:	Referen	
Subject Redesign of the Di Along Ditch No. 2			inage Outlet		ract Ho:
Description of Problem and Recommend	ed Solution	3 Clarific	tion	Change Change	
PROBLEM 1: A drill locations in the region area are shown in Fig Ditch No. 1 is much de competent bedrock was observation wells (see embankment which contareservoir for water en SOLUTION 1: Revise thend of Ditch No. 1 on Drawing DUR-DS-10-0340	pure 1 and 2, reper than original implemented, the location of we ins the discharging the ditcher outlet struct Drawing DUR-DS	No. 1 outfall. respectively. nally anticip ne excavation lls in Figure ge water of the and affect ure on Drawing-10-0335 per	The plan vi The depth to ated. If the of the outlet 3) and undere the toe trench the groundwat g DUR-DS-10-0 Figure 5, and lowing note to	ew and profile to bedrock at to original design would cut into cut the existing . It would also cer regime in the 337 per Figure 1 revise Section to Drawing DUR-1	of the outlet the outlet of n to key into the adjacent holding pond form a large his area.
Disposition Approved	Disapproved Appr	roved as Noted	RAC Site Manag	or Armany of	~ MITT 8/21/90
Criteria Change? DYes	₩ Ho	RAC Prof	ect Controllilly		3/21/70
(If Yes, DOE approval required)	MISTORI I ER			Jaal A dal	2/13/90
Class II			truction Engineer	Pohel & Come	4 8/21/90
W. W.	ORK COPY		for Quality	Co Co Corre	() Oloshi
00	Sanar See .		frements Oh	BALLON.	NZ1/90
				Signature	Date
Distribution Name L	ocation		Name	Location	Cost/Time Est.
RAC Site Mgr. M. Thomas		RAC Constr. Engr.	Mgr. / Coon	0/	☐ Attached
DOE Proj Engr. F. Dom/cr		RAC Qual. Mgr.	P Cate	/	☐ Not Required
TAC Site Mgr. Lage		Other	gldton	D. Sactor	DOE Approval
RAC Site Qual. Engr. / Llorge	//		1. Nymas		
RAC HS&E Mgr. 1. 1-4-110			m' 1/h-	-1	

"2. Riprap for the apron from the edge of outfall to natural drainage channel shall be Type B-Type C approved designated waste riprap from Wheeler Pit screening operations with approximate size range of 6 - 16 inches."

COMMENT:

Design of the outlet structure was reevaluated to determine what volume and size of rock would be required to maintain erosion protection for water discharging from Ditch No. 1. The attached drawings (Figures 4, 5, and 6) and supporting calculations present the proposed revisions. Changes include:

o Removal of the words "key into bedrock",

o Slope from ditch into outlet box steepened to 2:1 and subsequent shift of outlet further away from the northern drainage channel.

Addition of a rock apron from the far edge of the outlet to the northern drainage

channel to prevent gully initiation from water exiting the outlet box,

Regrade slope of natural ground towards northern drainage channel to approximately 8:1, and

o Continue 1 foot of Type B riprap from ditch across top of outlet box.

PROBLEM 2: A similar situation of bedrock not encountered for a considerable distance occurs along the southern Ditch No. 2. Two small regions on the outside edge of the ditch were covered with riprap and edged with a key trench and spillway. During installation of temporary retention basins DS-3 and DS-4 rock was not encountered. Test pits in these regions indicate depths up to 23 feet. The site boundary, adjacent to the southeastern drainage, limits extension of the design if the trench must be excavated to key into competent bedrock.

SOLUTION 2: Revise Drawing DUR-DS-10-0337 per Figure 7 and revise Sections W on Drawing DUR-DS-10-0338 and Section S on Drawing DUR-DS-10-0339 per Figure 8. Revise Note 5 on Drawing DUR-DS-10-0335 to read "5. Existing channel shall be widened as noted in Section S on Drawing DUR-DS-10-0339."

COMMENT:

The southeastern and southwestern riprapped key trenches were also reevaluated. The drainage areas for both are quite small as shown in the attached supporting calculation. The proposed revisions are shown in Figure 7 and Figure 8 and include:

o Removal of the words "key into bedrock".

o Section W to be included in both areas and the top width set at approximately 24 feet,

PROBLEM 3: On the western edge of the disposal cell, the key trench is duplicated on an inner edge rather than only edging the outside rim. This extra detail is not necessary for maintaining a raw edge since it is in the middle of a 5:1 riprapped slope.

SOLUTION 3: Remove the inner key trench in the middle of the 5:1 slope on Drawing DUR-DS-10-0337 per Figure 7.