### LICENSEE EVENT REPORT

	CONTROL BLOCK:
	[FIL   S   L   S   1 @   0   0   0   0   0   0   0   0   0
, 3	3 LIGENSEE CODE 14 15 LICENSE TYPE 10 57 CAT 58
O I	ASPORT L 6 0 5 0 0 0 3 3 5 7 1 0 2 3 8 2 3 1 1 2 2 8 2 9
	EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10
0 2	During recovery from a reactor trip with all three charging pumps operating
0 3	to recover pressurizer level, all three charging pumps became gas bound.
0 4	This resulted in less than the required operable charging pumps per Tech
0 5	Spec 3.1.2.4. See Attachment A. Due to the plant transient, an Iodine
0 6	buildup (spike) also occurred. See Attachment B. The health and safety of
0 7	the public were not affected. This is the sixth report involving charging !
0 3	pumps; see 82-36. This is the twelfth Iodine report; see 82-41.
0 9	SYSTEM CAUSE CAUSE COMPONENT CODE 18CODE SUBCODE SUBCODE 19 10 11 12 12 13 13 13 15 19 15 16
	TO REPORT YEAR REPORT NO.  17 REPORT   18 2
	ACTION PLANT SHUTDOWN HOURS 27 ATTACHMENT NOON SUPPLIER WANDFACTURER LE (13) Z (19) Z (20) Z (21) LO O O O LY (23) N (24) Z (25) Z 9 9 9 9 (2)
	23 14 25 26 37 40 41 42 43 44 47
	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)  The charging pumps became gas bound when the volume control tank was pumped!
	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
hann become	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)  The charging pumps became gas bound when the volume control tank was pumped!
hann become	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (2)  The charging pumps became gas bound when the volume control tank was pumped    dry and hydrogen was admitted to the pump suctions. The VCT level indica-
	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (2)  The charging pumps became gas bound when the volume control tank was pumped   dry and hydrogen was admitted to the pump suctions. The VCT level indication was erroneous due to an empty reference leg. The reference leg was refilled and the VCT level instrument calibrated. Proper response of the instrument to level changes was verified.
	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (2)  The charging pumps became gas bound when the volume control tank was pumped   dry and hydrogen was admitted to the pump suctions. The VCT level indication was erroneous due to an empty reference leg. The reference leg was  refilled and the VCT level instrument calibrated. Proper response of
113 113 114,	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)  [The charging pumps became gas bound when the volume control tank was pumped]  dry and hydrogen was admitted to the pump suctions. The VCT level indication was erroneous due to an empty reference leg. The reference leg was  refilled and the VCT level instrument calibrated. Proper response of  the instrument to level changes was verified.    A   (31)   (32)   (33)   (34)   (35)   (34)   (35)   (34)   (35)
113 113 114,	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (2)  The charging pumps became gas bound when the volume control tank was pumped    dry and hydrogen was admitted to the pump suctions. The VCT level indication was erroneous due to an empty reference leg. The reference leg was refilled and the VCT level instrument calibrated. Proper response of  the instrument to level changes was verified.    A   (1)   (2)   (3)   (4)
1 2 1 2 2 3 1 5 7 8	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (2)  [The charging pumps became gas bound when the volume control tank was pumped]  dry and hydrogen was admitted to the pump suctions. The VCT level indication was erroneous due to an empty reference leg. The reference leg was  refilled and the VCT level instrument calibrated. Proper response of  the instrument to level changes was verified.    Continty   Contint   Contin
1 3	CAUSE GESCRIPTION AND CORRECTIVE ACTIONS (2)  [The charging pumps became gas bound when the volume control tank was pumped]  dry and hydrogen was admitted to the pump suctions. The VCT level indication was erroneous due to an empty reference leg. The reference leg was  refilled and the VCT level instrument calibrated. Proper response of  the instrument to level changes was verified.    Comparison of the instrument to level changes was verified.   Comparison of the instrument to level changes was verified.   Comparison of the instrument to level changes was verified.   Comparison of the instrument to level changes was verified.   Comparison of the instrument to level changes was verified.   Comparison of the instrument to level changes was verified.   Comparison of the instrument to level changes was verified.   Comparison of the instrument to level changes was verified.   Comparison of the instrument of the instrument calibrated. Proper response of the instrument to level changes was verified.   Comparison of the instrument calibrated. Proper response of the instrument to level changes was verified.   Comparison of the instrument calibrated. Proper response of the instrument calibrated. Proper respo
1 3	The charging pumps became gas bound when the volume control tank was pumped of the charging pumps became gas bound when the volume control tank was pumped of the charging pumps became gas bound when the volume control tank was pumped of the charging pumps became gas bound when the volume control tank was pumped of the charging pumps became gas bound when the volume control tank was pumped of the charging pumps became gas bound when the volume control tank was pumped of the charging pumps became gas bound when the volume control tank was pumped of tank pumped
1 1 2 1 3 1 4 3 7 3 8 1 1 6 3 7 3 8 1 1 7 3 8 1 1 7 3 8 1 1 7 3 8 1 1 7 3 8 1 1 7 3 8 1 1 7 3 8 1 1 7 3 8 1 1 7 3 8 1 1 7 3 8 1 1 7 3 8 1 1 7 3 8 1 1 7 3 8 1 1 7 3 8 1 1 7 3 8 1 1 7 3 8 1 1 7 3 8 1 1 7 3 8 1 7 3 8 1 1 7 3 8 1 7 3	The charging pumps became gas bound when the volume control tank was pumped of the charging pumps became gas bound when the volume control tank was pumped of the charging pumps became gas bound when the volume control tank was pumped of the charging pumps became gas bound when the volume control tank was pumped of the charging pumps became gas bound when the volume control tank was pumped of the charging pumps became gas bound when the volume control tank was pumped of the charging pumps became gas bound when the volume control tank was pumped of the volume gas pumped of the pump suctions. The VCT level indication was erroneous due to an empty reference leg. The reference leg was refilled and the VCT level instrument calibrated. Proper response of the instrument to level changes was verified.    30
1 1 2 1 3 1 4 3 7 3 8 1 1 6 3 7 3 8 1 1 7 3 8 1 1 7 3 8 1 1 7 3 8 1 1 7 3 8 1 1 7 3 8 1 1 7 3 8 1 1 7 3 8 1 1 7 3 8 1 1 7 3 8 1 1 7 3 8 1 1 7 3 8 1 1 7 3 8 1 1 7 3 8 1 1 7 3 8 1 1 7 3 8 1 1 7 3 8 1 1 7 3 8 1 7 3 8 1 1 7 3 8 1 7 3	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (2)  The charging pumps became gas bound when the volume control tank was pumped of the charging pumps became gas bound when the volume control tank was pumped of the charging pumps became gas bound when the volume control tank was pumped of the charging pumps became gas bound when the volume control tank was pumped of the charging pumps became gas bound when the volume control tank was pumped of the charging pumps became gas bound when the volume control tank was pumped of the charging pumps became gas bound when the volume control tank was pumped of the charging pumps became gas bound when the volume control tank was pumped of the charging pumps became gas bound when the volume control tank was pumped of the volume control tank was pumped
1 1 2 1 3 1 4 3 7 3 8 1 1 6 3 7 3 8 1 1 7 3 8 1 1 7 3 8 1 1 7 3 8 1 1 7 3 8 1 1 7 3 8 1 1 7 3 8 1 1 7 3 8 1 1 7 3 8 1 1 7 3 8 1 1 7 3 8 1 1 7 3 8 1 1 7 3 8 1 1 7 3 8 1 1 7 3 8 1 1 7 3 8 1 1 7 3 8 1 1 7 3 8 1 7 3 8 1 1 7 3 8 1 7 3	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (2)  The charging pumps became gas bound when the volume control tank was pumped of the charging pumps became gas bound when the volume control tank was pumped of the charging pumps became gas bound when the volume control tank was pumped of the charging pumps became gas bound when the volume control tank was pumped of the charging pumps became gas bound when the volume control tank was pumped of the charging pumps became gas bound when the volume control tank was pumped of the vo

ATTACHMENT A

LER 335-82-050

Page 2 of 5

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (Continued)

A reactor trip/turbine trip occurred on low steam generator water level following loss of feed when one of the condensate pump motors tripped on differential phase current and a feedwater pump tripped on low suction pressure. Pressurizer level had returned to above the heater cutoff and the primary plant had stabilized at no-load T average and 1960 psia when all three charging pumps became gas bound. The pumps were restored to operation one at a time by repeated venting after filling the Volume Control tank high in the operating band. During the period that the charging pumps were inoperable, pressurizer level fluctuated about the heater cutoff setpoint with variations in T average. When the first charging pump was restored, pressurizer level was returned to the no-load set point. Two charging pumps were operating at reduced flow within 15 minutes; all three were restored to operability well within the required time limits. Other LER's concerning charging pumps are numbers 77-11, 77-14, 81-35, 82-12 and 82-36; this is the first failure of this type.

ATTACHMENT B

LER 335-82-050

Page 3 of 5

As a result of the reactor trip, Dose Equivalent Iodine (DEQ) I-131 exceeded the Tech. Spec. 3.4.8.a limit of 1.0  $\mu$ Ci/gm. The DEQ I-131 was first measured above the limit at 1920 hours on 23 October, 1982, and remained above the limit for a total of 31 hours and 10 minutes. Other LER's involving Iodine spiking are numbers 78-13, 78-24, 78-33, 80-39, 81-41, 81-56, 82-17, 82-20, 82-38, 82-40, and 82-41. The following information is submitted in accordance with Tech. Spec. 3.4.8.d:

# 1. Reactor Power History Starting 48 Hours Prior to the First Sample in which the Limit was Exceeded

#### AVERAGE REACTOR POWER

Time	October 21, 1982	October 22, 1982	October 23, 1982
0000		99.44	99.30
0100		99.44	99.28
0200		99.36	99.23
0300		99.30	99.09
0400		99.34	99.15
0500		99.66	99.05
0600		99.57	99.23
0700		99 15	99_23
0800		99.70	99.20
0900		89.05	99.20
1000		82.44	99.20
1100		82.52	99.23
1200		82.75	99.23
1300		82.88	99.20
1400		82.83	99.28
1500		82.78	99.36
1600		82.78	99.23
1700		83.05	79.73
1800		86.91	0
1900	99.28	93.03	0
2000	99.23	94.57	
2100	99.23	95.26	
2200	99.34	98.35	
2300	99.28	99.26	

Page 4 of 5

### 2. Fuel Burnup By Core Region

Region	Enrichment (w/o)	Number of Assemblies	Exposure (MWD/MTU)
Е	3.03	40	31019.1
E*	2.73	25	26775.6
F	3.65	40	21863.0
F*	3.03	48	25448.4
G	3.65	32	8743.3
G*	3.20	24	11221.3
G/	3.65	4	9735.5
GX	3.03	4	11779.7

# 3. Cleanup Flow History Starting 48 Hours Prior to the First Sample in which the Limit was Exceeded

October 21,	1982	1900,	2000	83	gpm
		2100-	2300	84	gpm
October 22,	1982	0000		84	gpm
		0100			gpm
		0200,	0300		grm
		0400			gpm
		0500-	0700		gpm
		0800			gpm
		0900			gpm
		1000-	1300		gpm
		1400,	1500		gpm
		1600-	1800		gpm
		1900,	2000		gpm
		2100-			gpm
October 23,	1982	0000,	0100	84	gpm
		0200			gpm
		0300			gpm
		0400-	0900		gpm
		1000-	1300		gpm
		1400-	1600		gpm
		1700			gpm
		1800			gpm
		1900			gpm

Page 5 of 5

4. History of Degassing Operation, If Any, Starting 48 Hours Prior to the First Sample in Which the Limit Was Exceeded

There were no degassing operations during the 48 hour period prior to exceeding the DEQ I-131 limit.

5. The Time Duration When the Specific Activity of the Primary Coolant Exceeded 1.0 µCi/gm DEQ I-131:

The DEQ I-131 exceeded the limit for 31 hours and 10 minutes.

Date		Time	DEQ 1-131
October 23,	1982	0230	1.542 E-01 µCi/gm
October 23,	1982	1920	2.601 E00 µC1/gm
October 23,	1982	2320	2.284 E00 µCi/gm
October 24,	1982	0310	1.850 E00 µCi/gm
October 24,	1982	0710	1.531 E00 µC1/gm
October 24,	1982	1100	1.112 E00 µCi/gm
October 24,	1982	1500	9.192 E-01 µCi/gm
October 24,	1982	2230	1.030 E00 µC1/gm
October 25,	1982	0230	8.161 E-01 µCi/gm