

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | C | T | M | N | S | 1 | 2 | 0 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5

CON'T REPORT SOURCE 6 0 5 0 0 0 2 4 5 7 1 0 1 9 8 2 8 1 1 1 9 8 2 9

0 2 | On October 19, 1982, at 1340 hours, while performing Main Steam Line High Flow Function-  
0 3 | al Calibration Test, pressure switch 261-2D tripped at 95 psid. Technical Specificat-  
0 4 | ion, Table 3.2.1 requires a main steam line high flow trip level setting at less  
0 5 | than or equal to 120 percent of rated steam flow. This corresponds to a differential  
0 6 | pressure less than or equal to 94 psid. There were no consequences.

0 9 | SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE  
S D 11 E 12 E 13 I N S T R U 14 S 15 Z 16  
17 LER/RC REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.  
8 2 0 2 4 0 3 L 0  
18 19 20 21 22 23 24 25 26 27 28 29 30 31 32  
E Z Z Z 0 0 0 0 Y Y N B 0 8 0 0 26

1 0 | Cause Description and Corrective Actions (27)  
1 1 | Failure of the switch to trip at its desired setpoint is attributable to setpoint  
1 2 | drift. The pressure switch was reset to its required setpoint and tested satisfactor-  
1 3 | ily. Similar occurrence: 80-04/3L.

1 5 | FACILITY STATUS % POWER OTHER STATUS 30 METHOD OF DISCOVERY 31 DISCOVERY DESCRIPTION 32  
H 0 0 0 NA B Routine Surveillance

1 6 | ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36  
Z Z NA NA

1 7 | PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39  
0 0 0 Z NA

1 8 | PERSONNEL INJURIES NUMBER DESCRIPTION 41  
0 0 0 NA

1 9 | LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION 43  
Z NA

2 0 | ISSUED DESCRIPTION 45 PUBLICITY PDR ADOCK 05000245 S PDR NRC USE ONLY

NAME OF PREPARER Trudy Schweikert-Thull PHONE 447-1791 Ext. 4197