: LICENSEE EVENT REPORT
CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 M D C C N 1 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5 6 5 15 LICENSE CODE 14 57 CAT 58
CON'T 0 1 REPORT L 6 0 5 0 0 0 3 1 7 7 1 0 1 4 8 2 8 1 1 1 2 8 2 9
At 2300 during normal plant operation, it was discovered that the Spent
Fuel Pool charcoal filter bypass damper was open and would not go shut,
rendering the Spent Fuel Pool Ventilation system inoperable (T.S.
0 5 2 3.9.12). No fuel movement was being conducted at that time. The damper
was repaired, tested and returned to service at 1300 on October 15.
O 7 Similar events: none.
7 8 9
SYSTEM CODE SUBCODE COMPONENT CODE SUBCODE SUB
COMPONENT SEQUENTIAL REPORT NO. OCCURRENCE REPORT NO.
Troubleshooting found the damper (0-P0-5416-18) hanging up in the inter-
mediate position due to mechanical binding of the damper piston rod. All
8 bypass damper piston rods were cleaned and lubricated. To prevent
recurrence, periodic damper lubrication will be done and documented
under a preventive maintenance program. under a preventive maintenance program.
FACILITY STATUS % POWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 1 5 E 28 1 0 0 29 N/A A 31 Operator Observation
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY 35 1 6 Z 33 Z 34 N/A PERSONNEL EXPOSURES AMOUNT OF ACTIVITY 35 N/A 44 45 80
NUMBER DESCRIPTION (39) NUMBER DESCRIPTION (39) N/A PERSONNEL INJURIES NUMBER DESCRIPTION (41)
1 8 0 0 0 0 40 N/A 7 8 9 11 12 80 LOSS OF OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION N/A
PUBLICITY 10 10 10 10 10 10 10 1
NAME OF PREPARER M. A. Junge/L. F. Basso PHONE: 301-269-4969/4933