

LICENSEE EVENT REPORT

CONTROL BLOCK: \_\_\_\_\_ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | I | L | Z | I | S | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | \_\_\_\_\_ | 5  
7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE J0 57 CAT 58

CON'T  
0 1 | REPORT SOURCE | L | 6 | 0 | 5 | 0 | 0 | 0 | 2 | 9 | 5 | 7 | 1 | 0 | 2 | 5 | 8 | 2 | 3 | 1 | 1 | 1 | 9 | 8 | 2 | 9  
7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)  
0 2 | #1 Penetratic Pressurization (PP) air compressor failed to run during  
0 3 | an auto start upon sensing a low PP air supply header pressure. #1 PP  
0 4 | air compressor was declared inoperable and this placed the PP system  
0 5 | in a degraded mode (TS 3.9.2.D). There were no safety implications  
0 6 | since system remained pressurized from IA system and other PP compres-  
0 7 | sors were operable. This is the first event of this type.  
0 8 | \_\_\_\_\_  
7 8 9 80

0 9 | SYSTEM CODE | S | D | 11 | CAUSE CODE | E | 12 | CAUSE SUBCODE | F | 13 | COMPONENT CODE | B | L | O | W | E | R | 14 | COMP. SUBCODE | X | 15 | VALVE SUBCODE | Z | 16 |  
7 8 9 10 11 12 13 14 15 16 17 18 19 20  
17 | LER/RO REPORT NUMBER | 8 | 2 | 21 | 22 | SEQUENTIAL REPORT NO. | 0 | 3 | 7 | 24 | 26 | OCCURRENCE CODE | / | 27 | REPORT TYPE | L | 30 | REVISION NO. | 0 | 32 |  
A | 18 | A | 19 | EFFECT ON PLANT | Z | 20 | SHUTDOWN METHOD | Z | 21 | HOURS | 0 | 0 | 0 | 0 | 22 | ATTACHMENT SUBMITTED | Y | 23 | NPRD-4 FORM SUB. | Y | 24 | PRIME COMP. SUPPLIER | A | 25 | COMPONENT MANUFACTURER | P | 1 | 3 | 5 | 26  
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)  
1 0 | Failure was caused by damaged drive belts (2 of 4 found broken with  
1 1 | burnt marks). They became stretched with age and slipped from the  
1 2 | sheave as motor was turning. A new set of belts was installed and  
1 3 | compressor operates satisfactorily. Other PP compressors are being  
1 4 | investigated for similar problems. No further response is necessary.  
7 8 9 80

1 5 | FACILITY STATUS | E | 28 | % POWER | 1 | 0 | 0 | 29 | OTHER STATUS | NA | 30 | METHOD OF DISCOVERY | A | 31 | DISCOVERY DESCRIPTION | Operator Observation | 32  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50  
1 6 | ACTIVITY CONTENT | Z | 33 | Z | 34 | AMOUNT OF ACTIVITY | NA | 35 | LOCATION OF RELEASE | NA | 36  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50  
1 7 | PERSONNEL EXPOSURES | 0 | 0 | 0 | 37 | Z | 38 | DESCRIPTION | NA | 39  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50  
1 8 | PERSONNEL INJURIES | 0 | 0 | 0 | 40 | DESCRIPTION | NA | 41  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50  
1 9 | LOSS OF OR DAMAGE TO FACILITY | Z | 42 | DESCRIPTION | NA | 43  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

2 0 | PUBLICITY | N | 44 | DESCRIPTION | \_\_\_\_\_ | 45 | 6211290749 821119 PDR ADOCK 05000295 S PDR  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50  
NAME OF PREPARER Kyung Shim PHONE: 312-746-2084 ext. 331  
NRC USE ONLY

ATTACHMENT TO LER

NO. 82 - 037 / 03 L - 0

COMMONWEALTH EDISON CO.

ZION GENERATING STATION

50-295

Description of Event On 10/25/82, #1 Penetration Pressurization (PP) air compressor failed to run during an auto start upon sensing a low PP air supply header pressure. #1 PP air compressor was declared inoperable, and this placed the PP system in a degraded mode (TS3.9.2.D).

Consequences of Occurrence There were no safety implications since PP system remained pressurized from IA system, and other PP compressors were operable. This is the first event of this type.

Cause of Occurrence The compressor failure was caused by damaged drive belts (2 out of 4 found broken with burnt marks). They became stretched with age and slipped from the sheave as motor was turning. Excessive friction had generated between the two contacting surfaces, and belts finally gave away. During maintenance, another problem was discovered with the compressor - worn out piston rings due to age. Although this was not related to the belt failure problem, worn out rings would certainly have degraded the compressor performance. Other internal components such as packing rings and wiper rings were showing signs of wear due to natural cause, also. The compressors are load tested every refueling outage for proper performance as per Tech Spec Surveillance Requirement 4.9.2.D.

Corrective Actions A new set of belts as well as all worn out internal components have been replaced. The compressor has been load tested, and it operates satisfactorily. The other two compressors will also be load tested to verify operability. No further response is necessary.