

January 25, 1991

United States Nuclear Regulatory Commission Washington, DC 20555

Reply to a Notice of Violation Docket No. 030-30233 License No. 45-16546-03

Attention: Document Control Desk

Dear Sirs:

The following violations have been addressed, corrected, and the necessary procedures implemented to assure any recurrence of these and other violations.

- A. Sealed Source No. 8725 not leak tested. Acting RSO at that time failed to have the source leak tested prior to hi terminating his employment with the company. Leak test failed to be performed until October 1990. RSO chart was developed in December 1990 in order to post and track dates concerning sources, meters, surveys, etc.
- B. Oral exams were not conducted. Prior and current RSO's were not cognizant of this requirement in our license. This test will be developed by January 28, 1990 and will be implemented in our refresher safety exam to be given to each radiographer and radiographer's assistant annually.
- C. Unrestricted storage area dose rate was 15 mr/hr above "shooting cell". Current RSO and radiographers were not aware of the dose rate in the storage area. Sign has been posted on the shooting cell door to remind radiographers's to post radiation area sign at the top of the stairs to the storage area prior to any exposures. Sign posted on shooting cell door on December 5, 1990.

9102070011 910125 NMSS LIC30 45-16546-03 PDR

Consulting Envir - mental, Geotechnical and Materials Engineers

Please feel free to contact this office should you have any questions or concerns.

Sino ly,

ATEC ASSOCIATES, INC.

Peter A. Lipphardt, Assistant Vice President

Director of Technical Services

MGJ:tc cc: Regional Administrator Region II 101 Marietta Street, N.W. Atlanta, GA 30323