

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: \_\_\_\_\_ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | F L I C I R P I 3 | 00-000000-000 | 41111 | \_\_\_\_\_

REPORT SOURCE | L | 050-0302 | 1021982 | 112682 | \_\_\_\_\_

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES

02 | At 1005, October 29, 1982, it was discovered that remote and local  
03 | 175 foot wind direction channels were out of tolerance, contrary  
04 | to T.S.3.3.3.4. Maintenance was initiated, and operability restored  
05 | at 1108 on October 29, 1982. There was no effect upon public  
06 | health or safety. This is the seventh event for the 175 foot  
07 | wind direction, and this is the twenty-fourth report under this  
08 | specification.

09 | SYSTEM CODE: I E | CAUSE CODE: X | CAUSE SUBCODE: Z | COMPONENT CODE: INSTRU | COMP. SUBCODE: E | VALVE SUBCODE: Z  
17 | LER/RO REPORT NUMBER: 82 | EVENT YEAR: 82 | SEQUENTIAL REPORT NO.: 069 | OCCURRENCE CODE: 03 | REPORT TYPE: L | REVISION NO.: 0  
ACTION TAKEN: AX | FUTURE ACTION: | EFFECT ON PLANT: Z | SHUTDOWN METHOD: Z | HOURS: 00000 | ATTACHMENT SUBMITTED: Y | NPRD-4 FORM SUB.: N | PRIME COMP. SUPPLIER: A | COMPONENT MANUFACTURER: C4115

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS

10 | The cause of this event is attributed to a failed direction sensor.  
11 | The failed wind direction sensor was replaced, and the instrument  
12 | recalibrated. The meteorological monitoring system is under  
13 | engineering evaluation to resolve this systems problem.

15 | FACILITY STATUS: C | % POWER: 000 | OTHER STATUS: N/A | METHOD OF DISCOVERY: B | DISCOVERY DESCRIPTION: Operator observation

16 | ACTIVITY CONTENT: Z | AMOUNT OF ACTIVITY: N/A | LOCATION OF RELEASE: N/A

17 | PERSONNEL EXPOSURES: 0 | TYPE: Z | DESCRIPTION: N/A

18 | PERSONNEL INJURIES: 0 | DESCRIPTION: N/A

19 | LOSS OF OR DAMAGE TO FACILITY: Z | DESCRIPTION: N/A

20 | PUBLICITY ISSUED: N | DESCRIPTION: N/A

NAME OF PREPARER: C. G. Brown | PHONE: (904) 795-6486

**SUPPLEMENTARY INFORMATION**

REPORT NO: 50-302/82-069/03L-0

FACILITY: Crystal River Unit #3

REPORT DATE: November 24, 1982

OCCURRENCE DATE: October 29, 1982

**IDENTIFICATION OF OCCURRENCE:**

The 175' wind direction instrument required by Technical Specification 3.3.3.4 was inoperable.

**CONDITIONS PRIOR TO OCCURRENCE:**

MODE 3 (HOT STANDBY)

**DESCRIPTION OF OCCURRENCE:**

At 1005 on October 29, 1982, while performing routine surveillance, it was discovered that the 175' wind direction channel was out of tolerance. The wind direction sensor was replaced, and the instrument calibrated, returning the wind direction channel to operability by 1108.

**DESIGNATION OF APPARENT CAUSE:**

This event was caused by an inoperable wind direction sensor.

**ANALYSIS OF OCCURRENCE:**

There was no effect on public health or safety. Other area weather stations and the 33' wind direction channel were available to provide data for estimating meteorological conditions.

**CORRECTIVE ACTION:**

The wind direction sensor was replaced, and the instrument channel was recalibrated.

**FAILURE DATA:**

This is the seventh event for the 175' wind direction channel and the twenty-fourth report under Technical Specification 3.3.3.4.