LICENSEE EVENT REPORT

	CONTROL BLOCK:
	(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1	M I 5 C C 2 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5 CAT 58
O 1	SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE
0 2	DURING THE PERFORMANCE OF THE CONTAINMENT ISOLATION VALVE OPERABILITY TEST, IT WAS
0 3	FOUND THAT THE CONTAINMENT HYDROGEN SAMPLE ISOLATION VALVE (ECR-21) WOULD NOT CYCLE.
0 4	THIS CONDITION WAS NON-CONSERVATIVE WITH RESPECT TO TECHNICAL SPECIFICATION 3.6.3.1,
0 5	TABLE 3.6-1 ITEM 38. THE PUBLIC HEALTH AND SAFETY WERE-NOT AFFECTED.
0 6	
0 7	
0 8	
0 9	SYSTEM CAUSE CAUSE SUBCODE SUB
110	LERIRO EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE REPORT TYPE NO. ACTION FUTURE TAKEN ACTION ON PLANT METHOD NO. ACTION FUTURE TAKEN ACTION ON PLANT METHOD ACTION FUTURE SHUTDOWN METHOD ACTION FUTURE SHUTDOWN METHOD ACTION FORM SUB. ACTION FORM SUB. ACTION FORM SUB. SUPPLIER MANUFACTURER A 18 Z 19 Z 20 Z 21 Q 0 0 0 0 0 N 23 Y 24 N 25 A 14 9 9 26 CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27 LINVESTIGATION FOUND A DEFECTIVE COIL ON THE SOLENOID FOR THE CONTAINMENT HYDROGEN
11	SAMPLE ISOLATION VALVE (ECR-21). THE COIL, MANUFACTURED BY AT 'O, WAS REPLACED.
1 2	ECR-21 WAS VERIFIED TO BE OPERATING CORRECTLY WITHIN THE ALLOWAL E CLOSING TIME AND
1 3	RETURNED TO SERVICE.
1 4	
1 5	ACILITY STATUS STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 NA B 31 OPERATOR OBSERVATION 32
1 6	CTIVITY CONTENT ELEASED OF RELEASE AMOUNT OF ACTIVITY 35 NA NA LOCATION OF RELEASE 36
1 7 8	PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39 NA POLICIONAL STATEMENT STATE
1 3	PERSONNEL INJURIES 13 NUMBER DESCRIPTION (41) NA S PDR ADDCK 05000316 PDR PDR PDR
1 9	LOSS OF OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION NA NA
10	PUBLICITY SSUED DESCRIPTION (45) NRC USE ONLY NA NA
	NAME OF PREPARER R.A. PALMER PHONE 616-465-5901 80.5