



Commonwealth Edison  
LaSalle County Nuclear Station  
2601 N. 21st. Rd.  
Marseilles, Illinois 61341  
Telephone 815/357-6761

February 15, 1994

U.S. Nuclear Regulatory Commission  
Attention: Document Control Desk  
Washington, D.C. 20555

Licensee Event Report #94-002-00, Docket #050-373 is being submitted to your office in accordance with 10CFR50.73(a)(2)(iv).

D. J. Ray  
Station Manager  
LaSalle County Station

DJR/JR/mkl

Enclosure

xc: Nuclear Licensing Administrator  
NRC Resident Inspector  
NRC Region III Administrator  
INPO - Records Center  
IDNS Resident Inspector

220140  
9402240019 940215  
PDR ADOCK 05000373  
S PDR

1-1888  
11

LICENSEE EVENT REPORT (LER)

Form Rev 3.0

Facility Name (1) LaSalle County Station Unit 1	Docket Number (2) 0 5 0 0 0 3 7 3	Page (3) 1 of 0 3
--	--------------------------------------	----------------------

Title (4)  
Single Control Rod Scram Due To Bad Fuse Clip

Event Date (5)			LER Number (6)			Report Date (7)			Other Facilities Involved (8)																	
Month	Day	Year	Year	Sequential Number	Revision Number	Month	Day	Year	Facility Names	Docket Number(s)																
0	1	2	2	9	4	9	4	---	0	0	2	---	0	0	0	2	1	5	9	4						

OPERATING MODE (9) 1

THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10CFR (Check one or more of the following) (11)

POWER LEVEL (10) 0 7 4	<input type="checkbox"/> 20.402(b)	<input type="checkbox"/> 20.405(c)	<input checked="" type="checkbox"/> 50.73(a)(2)(iv)	<input type="checkbox"/> 73.71(b)
	<input type="checkbox"/> 20.405(a)(1)(i)	<input type="checkbox"/> 50.36(c)(1)	<input type="checkbox"/> 50.73(a)(2)(v)	<input type="checkbox"/> 73.71(c)
	<input type="checkbox"/> 20.405(a)(1)(ii)	<input type="checkbox"/> 50.36(c)(2)	<input type="checkbox"/> 50.73(a)(2)(vii)	<input type="checkbox"/> Other (Specify in Abstract below and in Text)
	<input type="checkbox"/> 20.405(a)(1)(iii)	<input type="checkbox"/> 50.73(a)(2)(i)	<input type="checkbox"/> 50.73(a)(2)(viii)(A)	
	<input type="checkbox"/> 20.405(a)(1)(iv)	<input type="checkbox"/> 50.73(a)(2)(ii)	<input type="checkbox"/> 50.73(a)(2)(viii)(B)	
	<input type="checkbox"/> 20.405(a)(1)(v)	<input type="checkbox"/> 50.73(a)(2)(iii)	<input type="checkbox"/> 50.73(a)(2)(x)	

LICENSEE CONTACT FOR THIS LER (12)

Name	TELEPHONE NUMBER
John Reimer, System Engineer, Extension 2249	AREA CODE 8 1 5 3 5 7 - 6 7 6 1

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFAC-TURER	REPORTABLE TO NPRDS	CAUSE	SYSTEM	COMPONENT	MANUFAC-TURER	REPORTABLE TO NPRDS
X	A	A	F U B G O B 2	N					

SUPPLEMENTAL REPORT EXPECTED (14)

YES (If yes, complete EXPECTED SUBMISSION DATE)  NO

Expected Submission Date (15)

ABSTRACT (Limit to 1400 spaces, i.e, approximately fifteen single-space typewritten lines) (16)

On January 22, 1994 during half scram testing (LOS-RP-M1) on Unit 1 with power at 74%, control rod 54-47 (5A-peripheral rod) scrambled to the full in position. The unit was dropped 75 MWE per LOA-RD-06, "Control Rod Drift/Individual Rod Scram". No thermal limits were exceeded with this rod being at the full in position. A Qualified Nuclear Engineer (QNE) was notified that the rod was at the full in position and the QNE stated no further action was required for the scrambled rod. The event was reported to the NRC per 10CFR50.72(b)(2)(ii) within the required four hours.

Investigation revealed the "B" RPS fuse was loose in its clip. This coupled with the half scram from "A" Reactor Protection System (RPS) from the performance of LOS-RP-M1 caused the rod to scram in.

A work Request L26894 was written and the control rod was removed from service. The fuse block was found cracked and subsequently satisfactorily replaced. Since this work does not affect the scram time of the control rod, no additional tests were required on the control rod prior to returning the rod to service.

A new parts evaluation (I-94-0014) was performed and concluded that the electrical box assembly supplied by General Electric (part # 922d234G001) which contains the fuse holder on a terminal board is not safety related. Any failure of the terminal board would result in a control rod scram. It is the first time that this particular part had to be replaced at the station. This is considered an isolated event and no further action is required.

This event is reportable pursuant to 10CFR50.73(a)(2)(iv) due to an actuation of an Engineered Safety Feature ESF.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION													Form Rev 3.0									
FACILITY NAME (1)	DOCKET NUMBER (2)							LER NUMBER (6)						Page (3)								
								Year	///	Sequential Number	///	Revision Number										
LaSalle County Station	0	5	0	0	0	3	7	3	9	4	-	0	0	2	-	0	0	0	2	OF	0	3
TEXT Energy Industry Identification System (EIIIS) codes are identified in the text as [XX]																						

PLANT AND SYSTEM IDENTIFICATION

General Electric - Boiling Water Reactor

Energy Industry Identification System (EIIIS) codes are identified in the text as (XX).

A. CONDITION PRIOR TO EVENT

Unit(s): 1 Event Date: 1/22/94 Event Time: 0430 Hours  
 Reactor Mode(s): 1 Modes(s) Name: RUN Power Level(s): 74%

B. DESCRIPTION OF EVENT

On January 22, 1994 Unit 1 was in Operational Condition 1 (Run) at 74% power. At 0430 hours during half scram testing (LOS-RP-M1) control rod 54-47 (5A-peripheral rod) scrammed to the full in position. Reactor power was reduced 75 MWE per Operating Procedure LOA-RD-06, "Control Rod Drift/Individual Rod Scram" (RD) [AA].

No thermal limits were exceeded with this rod being at the full in position. A Qualified Nuclear Engineer (QNE) was notified that the rod was at the full in position and it was determined that no further action was required for the scrammed rod.

The event is reportable per 10CFR50.73(a)(2)(iv) due to an automatic Engineered Safety Feature (ESF) actuation.

C. APPARENT CAUSE OF EVENT

Investigation revealed the "B" Reactor Protection System (RPS, RP) [JC] fuse was loose in its clip. This coupled with the half scram from "A" RPS from the performance of LOS-RP-M1 caused the rod to scram in.

D. SAFETY ANALYSIS OF EVENT

Appropriate actions were taken when the rod scrammed in and no additional actions were necessary. No thermal limits were exceeded with the peripheral rod at the full in position. Actions provided in LOA-RD-06 provide conservative actions for any single rod scram.

E. CORRECTIVE ACTIONS

1. Work Request L26894 was written and the control rod was removed from service. The fuse block was found cracked and subsequently satisfactorily replaced. Since this work does not affect the scram time of the control rod, no additional tests were required on the control rod prior to returning the rod to service.
2. A new parts evaluation (1-94-0014) was performed and concluded that the electrical box assembly supplied by General Electric (part # 922d234G001) which contains the fuse holder on a terminal board is not safety related. Any failure of the terminal board would result in a control rod scram. It is the first time that this particular part had to be replaced at the station.
3. A programmatic review of fuse/fuseholder issues is being performed to determine if further action is necessary to address this type of event.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

Form Rev 3.0

FACILITY NAME (1)  LaSalle County Station	DOCKET NUMBER (2)  0   5   0   0   0   3   7   3	LER NUMBER (6)						Page (3)		
		Year	///	Sequential	///	Revision				
			///	Number	///	Number				
		9   4	-	0   0   2	-	0   0	0   3	OF	0   3	
TEXT Energy Industry Identification System (EIIS) codes are identified in the text as [XX]										

F. PREVIOUS EVENTS

A review of all single rod SCRAMS that occurred during the past three years determined that none were caused by a problem with fuse clips.

G. COMPONENT FAILURE DATA

Manufacturer	Nomenclature	Model Number	MFG Part Number
General Electric	Electric Box Assembly		922d234G001

# EVENT SUMMARY AND CAUSE CODES

DVR Number  
-----

- |   |   |   |
|---|---|---|
| <input type="checkbox"/> Lost generation  | <input type="checkbox"/> Reactor trip   | <input type="checkbox"/> NRC violation, level__ |
| <input type="checkbox"/> Cost > \$25,000  | <input type="checkbox"/> ESF actuation  | <input type="checkbox"/> GSEP event, class__    |
| <input type="checkbox"/> Hazard or Spill  | <input type="checkbox"/> NRC reportable | <input type="checkbox"/> Tech Spec LCO          |
| <input type="checkbox"/> Personnel injury | <input checked="" type="checkbox"/> LER | <input type="checkbox"/> Potential or future to |
| <input type="checkbox"/> Component type   | <input type="checkbox"/> PSE            | <input type="checkbox"/> SALP functional area__ |
|   | Failure mode                            |   |

	Component type	Failure mode	Department	
X	CE	M2	EM	
X				
X				

	Licensed? L or blank	Level	Department	Type	Detail code
A					
A					
A					

	Type	Detail Code	Department	
B				
B				
B				

	Type	Detail code	
C			

	Type of deficiency	Detail code	Procedure type	
D				
D				
D				

	Type	Detail code	Department	
E				
E				
E				