

### LICENSEE EVENT REPORT

CONTROL BLOCK: \_\_\_\_\_ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | N | J | S | G | S | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5  
7 8 9 14 15 25 26 30 57 58  
LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT

CON'T  
01 | L | 0 | 5 | 0 | 0 | 0 | 3 | 1 | 1 | 1 | 7 | 1 | 0 | 3 | 1 | 8 | 2 | 8 | 1 | 1 | 1 | 7 | 8 | 2 | 9  
7 8 60 61 68 69 74 75 80  
REPORT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

#### EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

02 | On two separate occasions, on October 31 and November 5, 1982, the Control Room  
03 | Operator observed that service water flow to No. 23 Containment Fan Coil Unit (CFCU)  
04 | was slightly less than required by the Technical Specifications. In each case the  
05 | unit was declared inoperable and Action Statement 3.6.2.3a was entered. Both  
06 | containment spray systems were operable throughout the occurrence; the event  
07 | constituted operation in a degraded mode in accordance with Technical Specification  
08 | 6.9.1.9.b. (82-123, 82-117, 82-105, 82-099, 82-098)

09 | S | B | C | Z | H | T | E | X | C | H | C | Z | 11 | 12 | 13 | 14 | 15 | 16  
9 10 11 12 13 18 19 20  
SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE  
17 | 8 | 2 | 1 | 3 | 0 | 0 | 3 | L | 0 | 21 | 22 | 23 | 24 | 26 | 27 | 28 | 29 | 30 | 31 | 32  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32  
LER RO REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.  
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER  
10 | E | Z | Z | Z | 0 | 0 | 0 | 0 | Y | N | A | W | 1 | 2 | 0 | 33 | 34 | 35 | 36 | 37 | 40 | 41 | 42 | 43 | 44 | 47  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47  
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

10 | The low service water flow was assumed to involve silt clogging the back pressure  
11 | control valves. The first problem was corrected by cycling of the valves during  
12 | repair of a cooler leak. In the second instance, starting the unit for testing  
13 | eliminated the low flow.

14 | \_\_\_\_\_  
15 | E | 0 | 8 | 2 | NA | B | Surveillance Testing  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47  
FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION  
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE

16 | Z | Z | NA | NA  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47  
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION

17 | 0 | 0 | 0 | 2 | NA  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47  
PERSONNEL INJURIES NUMBER DESCRIPTION

18 | 0 | 0 | 0 | NA  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47  
LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION

19 | Z | NA  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47  
PUBLICITY ISSUED DESCRIPTION

20 | N | NA  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47  
NAME OF PREPARER R. Frahm  
8212060214 821117 PDR ADOCK 05000311 S PDR  
NRC USE ONLY  
68 69 80

817-926