

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | N | Y | J | A | F | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | - | 0 | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5
7 8 9 14 15 25 26 30 57 58

CON'T
0 1 | L | 6 | 0 | 5 | 0 | 0 | 0 | 3 | 3 | 3 | 7 | 1 | 1 | 1 | 0 | 8 | 2 | 8 | 1 | 1 | 2 | 4 | 8 | 2 | 9
7 8 60 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
0 2 | During normal operation, while conducting surveillance testing, the
0 3 | HPCI Turbine High Exhaust Diaphragm Pressure Switch 23-PS-86B setpoint
0 4 | was found less conservative than the TS Table 3.2-2 required setting
0 5 | of \leq 10 PSIG. The as found value was 10.14. Other trip channels
0 6 | monitoring the same parameter were available and had setpoints \leq 10
0 7 | PSIG. The event did not represent a significant hazard to the public
0 8 | health and safety.

0 9 | S | D | 11 | X | 12 | Z | 13 | I | N | S | T | R | U | 14 | S | 15 | Z | 16 |
7 8 9 10 11 12 13 18 19 20
17 | 8 | 2 | 21 | 22 | 0 | 5 | 2 | 24 | 26 | 0 | 3 | 28 | 29 | L | 30 | 0 | 32
18 | E | 18 | Z | 19 | Z | 20 | Z | 21 | 0 | 0 | 0 | 0 | 22 | N | 23 | Y | 24 | N | 25 | B | 0 | 6 | 9 | 26
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
1 0 | Instrument drift was the cause. Corrective action consisted of
1 1 | immediate adjustment of the switch setpoint within TS requirements and
1 2 | increasing the testing frequency for trend observation. No further
1 3 | corrective action is required.

1 4 | _____
7 8 9 80
1 5 | E | 28 | 1 | 0 | 0 | 29 | NA | 30 | B | 31 | Surveillance | 32
7 8 9 10 12 13 44 45 46 80

1 6 | Z | 33 | Z | 34 | NA | 35 | NA | 36
7 8 9 10 11 44 45 80

1 7 | 0 | 0 | 0 | 37 | Z | 38 | NA | 39
7 8 9 11 12 13 80

1 8 | 0 | 0 | 0 | 40 | NA | 41
7 8 9 11 12 80

1 9 | Z | 42 | NA | 43
7 8 9 10 80

2 0 | N | 44 | NA | 45
7 8 9 10 80
8212060231 821124
PDR ADOCK 05000333
S PDR
NRC USE ONLY
68 69 80