	LICENSEE EVENT REPORT
40	CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
7 8	N J S G S 1 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 6 5 5 CAT 58
CON'T 0 1 7 8	REPORT L 6 0 5 0 0 0 2 7 2 7 1 1 0 2 8 2 8 1 1 1 7 8 2 9 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10 On November 2, 1982, during routine shutdown operation, the Control Room Operator
0 2	
0 3	observed that the temperature recorder for the air temperature-delta T channels was
0 4	not printing. The channels were declared inoperable, and Action Statement 3.3.3.4a
0 5	was entered. The channels were restored to operation within the 7 day time period
0 6	specified in the action statement. The event involved operation in a degraded mode in
0 7	accordance with Technical Specification 6.9.1.9 b.
08	
7 8	SYSTEM CAUSE CAUSE SUBCODE SUB
	LER RO EVENT YEAR REPORT NO. 17 REPORT NUMBER 21 22 23 24 26 27 28 29 30 31 31 32 ACTION FUTURE EFFECT SHUTDOWN COMPONENT
	TAKEN ACTION ON PLANT METHOD HOURS (22) SUBMITTED FORM SUB. SUPPLIER MANUFACTURER A 18 Z 19 Z 20 Z 21 O O O O O Y Y 23 Y 24 A 25 L 1 3 O 26 CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
1 0	The inoperability of the chart recorder was due to the failure of the pinion gear on
11	the chart drive motor. No previous failure of this type were noted. The motor was
1 2	replaced, the channels were satisfactorily tested, and the action statement was
1 3	terminated.
1 4	
7 8	H 28 0 0 0 29 N/A A 31 Operator Observation
	9 10 10 10 10 10 10 10 10 10 10 10 10 10
1 7 8	9 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39 0 0 0 37 Z 38 N/A 9 PERSONNEL INJURIES 13 80
1 8	NUMBER DESCRIPTION 41 N/A
7 8	9 11 12 LOSS OF OR DAMAGE TO FACILITY (43) B212060298 B21117 TYPE DESCRIPTION B212060298 B21117
7 8	Z 42 N/A S PDR 80
2 0	PUBLICITY ISSUED DESCRIPTION 45 N/A N/A
7 8	9 10 68 69 80 5 R. Frahm 609/935-6000 Fyt 7079
	NAME OF PREPARER PHONE