

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

7 8 9 0 1 | N | J | S | G | S | 1 | (2) | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | (3) | 4 | 1 | 1 | 1 | 1 | (4) | | (5)

LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T

7 8 0 1 | REPORT SOURCE L (6) | 0 | 5 | 0 | 0 | 0 | 2 | 7 | 2 | (7) | 1 | 0 | 2 | 7 | 8 | 2 | (8) | 1 | 1 | 2 | 4 | 8 | 2 | (9)

DOCKET NUMBER 60 61 EVENT DATE 68 69 REPORT DATE 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | On October 27, 1982, during routine surveillance of the 122' Elevation of the

0 3 | Auxiliary Building, 5 fire barrier penetrations were found to be non-functional. One

0 4 | barrier was open due to construction, two barriers were inadequately sealed; sealing

0 5 | of the remaining two barriers had apparently been overlooked at installation. Action

0 6 | Statement 3.7.11 was already in effect, dating back to 0001 hours, October 29, 1981, due

0 7 | to other open penetrations; a fire watch was already assigned. The occurrence consti-

0 8 | tuted operation in a degraded mode in accordance with Technical Specification 6.9.1.9.b.

7 8 9 0 9 | SYSTEM CODE A | B | (11) | CAUSE CODE D | (12) | CAUSE SUBCODE Z | (13) | COMPONENT CODE X | X | X | X | X | X | (14) | COMP. SUBCODE Z | (15) | VALVE SUBCODE Z | (16)

17 LER NO. REPORT NUMBER | EVENT YEAR 8 | 2 | (21) | (22) | SEQUENTIAL REPORT NO. 0 | 8 | 6 | (24) | (25) | OCCURRENCE CODE 0 | 3 | (28) | (29) | REPORT TYPE L | (30) | REVISION NO. 0 | (32)

ACTION TAKEN G | (18) | FUTURE ACTION Z | (19) | EFFECT ON PLANT Z | (20) | SHUTDOWN METHOD Z | (21) | HOURS 0 | 0 | 0 | (22) | (23) | ATTACHMENT SUBMITTED Y | (23) | NPSR-4 FORM SUB. N | (24) | PRIME COMP. SUPPLIER A | (25) | COMPONENT MANUFACTURER U | 0 | 8 | 0 | (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | The fire barrier surveillance procedure did not identify or locate the penetrations.

1 1 | An improved procedure had been implemented; this was the first occasion on which the

1 2 | procedure was performed for this area. The penetrations were sealed on October 27,

1 3 | 1982. (82-046, 81-106, 81-082)

7 8 9 1 5 | FACILITY STATUS H | (28) | % POWER 0 | 0 | 0 | (29) | OTHER STATUS N/A | (30) | METHOD OF DISCOVERY B | (31) | DISCOVERY DESCRIPTION Surveillance Testing | (32)

7 8 9 1 6 | ACTIVITY RELEASED Z | (33) | CONTENT Z | (34) | AMOUNT OF ACTIVITY N/A | (35) | LOCATION OF RELEASE N/A | (36)

7 8 9 1 7 | PERSONNEL EXPOSURES NUMBER 0 | 0 | 0 | (37) | TYPE Z | (38) | DESCRIPTION N/A | (39)

7 8 9 1 8 | PERSONNEL INJURIES NUMBER 0 | 0 | 0 | (40) | DESCRIPTION N/A | (41)

7 8 9 1 9 | LOSS OF OR DAMAGE TO FACILITY TYPE Z | (42) | DESCRIPTION N/A | (43)

7 8 9 2 0 | PUBLICITY ISSUED N | (44) | DESCRIPTION N/A | (45)

8212060316 821124
PDR ADOCK 05000272
S PDR

NRC USE ONLY