s. 04008905840E

QUIVIRA MINING COMPANY

POST OFFICE BOX 218 + GRANTS, NEW MEXICO 67020

40-8905 X6/2/0

November 12, 1993

RETURN ORIGINAL TO PDR, HQ.

Certified Mail Return Receipt Requested P 762 964 197

Mr. Ramon Hall, Director Uranium Recovery Field Office U.S. Nuclear Regulatory Commission P.O. Box 25325 Denver, Colorado 80225

DOCKETED

Re: Annual Report, Groundwater Corrective Action Plan

Ambrosia Lake Facility License SUA-1473, Docket No. 40-8905

Dear Mr. Hall:

Please find attached a supplementa. Corrective Action Program (CAP) report for the original CAP annual report submitted on July 30, 1993 for the above referenced facility.

As stated within the July 30, 1993 CAP submittal, this supplemental report contains the revised areal plume plots for those hazardous constituents which contained data not representative of historical concentrations at two (2) Dakota sandstone monitoring wells.

If you have any questions concerning this submittal, please contact me at (505) 287-8851, extension 246.

18 177

Peter Luthiger

Sincerely,

Supervisor, Radiation Safety and Environmental Affairs

9402250248 931112

Attachments: As Stated

B. Ferdinand - RAMC (OKC) w\attachments XC:

A. Gebeau - RAMC (Ambrosia Lake) w\attachments

R. Ohrbom - NMED (Santa Fe) w\attachments

file

Certified By many C. Hard

94-0077

Dakota Sandstone Areal Plume Plots

The July 30, 1993 Corrective Action Program (CAP) submittal contained Dakota formation areal plume plots of those hazardous constituents required by license condition #34 of Source Material License SUA-1473. These plots include antimony, beryllium, cadmium, and nickel.

Due to the contract laboratory performing a 5:1 dilution on the groundwater samples obtained from monitoring wells 36-01KD and 36-04KD, the reported results for the four hazardous constituents listed above were not indicative of historical concentrations at the two wells.

As such, Quivira resampled the wells for confirmation of the questionable data. Results of the resampling along with the values reported in the July 30, 1993 CAP submittal are presented in Table 1.

TABLE 1
COMPARISON OF WELLS 36-01KD AND 36-04KD
All Values in milligrams per liter

| WELL | PARAMETER | REPORTED | RESAMPLE |
|---------|-----------|----------|----------|
| 36-01KD | Antimony | < 0.25 | < 0.003 |
| | Beryllium | < 0.05 | < 0.01 |
| | Cadmium | < 0.025 | < 0.005 |
| | Nickel | < 0.05 | < 0.01 |
| 36-04KD | Antimony | < 0.25 | < 0.003 |
| | Beryllium | < 0.05 | < 0.01 |
| | Cadmium | < 0.025 | < 0.005 |
| | Nickel | < 0.05 | < 0.01 |


Table 1 indicates that all results obtained from the resampling of 36-01KD and 36-04KD for those parameters which contained questionable data were below the laboratory's level of detection. The results of the resampling are representative of historical concentrations for these parameters at these two Dakota monitoring wells.

As a result of confirming that the results reported within the July 30, 1993 CAP submittal were indeed not representative, the revised areal plume plots for the Dakota formation for the hazardous constituents antimony, beryllium, cadmium, and nickel are attached.


QUIVIRA MINING COMPANY AMBROSIA LAKE FACILITY

CORRECTIVE ACTION PLAN 1992 ANNUAL REPORT (SUPPLEMENTAL)

Antimony 1993 Concentration Isopleth Groundwater Standard - 0.05 mg/l



Beryllium
1993 Concentration Isopleth Groundwater Standard - 0.01 mg/l



Cadmium
1993 Concentration Isopleth
Groundwater Standard - 0.01 mg/l

