



LER No.: 50-366/1980-103  
Licensee: Georgia Power Company  
Facility: Edwin I. Hatch  
Docket #: 50-366

Narrative Report  
for LER 50-366/1980-103, R.1

With the unit operating steady-state at 97% power, the performance of the "HIGH DRYWELL PRESSURE SWITCHES, ADS" procedure showed that High Drywell Pressure Switches N010A thru D actuated at pressures of 2.21 psig for A, 2.34 psig for B, 2.27 psig for C, and 2.47 psig for D. Item 4.a of Tech. Specs. Table 3.3.3-2 gives a trip setpoint of  $\leq 2$  psig. Plant operation was not affected by this event. The health and safety of the public were not affected by this event. This event is repetitive as last reported on LER 50-366/1980-100.

The cause of this event has been attributed to setpoint drift. The switch was recalibrated, successfully functionally tested, and returned to service. An engineering study to find a means of preventing or reducing the frequency of recurrence has recommended a Design Change. Recommended corrective measures are being evaluated.