

PDR



UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
WASHINGTON, D. C. 20555

MAY 03 1993

MEMORANDUM FOR: Those on Attached List

FROM: Leif J. Norrholm, Chief  
Vendor Inspection Branch  
Division of Reactor Inspection  
and Licensee Performance  
Office of Nuclear Reactor Regulation

SUBJECT: MONTHLY UPDATE OF VENDOR INSPECTION BRANCH PART 21 TRACKING  
SYSTEM - MONTH OF APRIL

Attached is the April update of the Part 21 database maintained by the Vendor Inspection Branch (VIB). It identified those new Part 21 issues appended to the database during the month of April. In addition to formal Part 21 submittals, it also contains LER, Part 50.55(e), and Part 50.72 issues as well as other communications that were determined to possibly address Part 21 type matters that require review. If you are aware of any Part 21 type matters that are not included in the database, or if you need additional information regarding the Part 21 issues assigned to your branch or the Part 21 review program itself, please contact Walter Haass at 504-3219.

Leif J. Norrholm, Chief  
Vendor Inspection Branch  
Division of Reactor Inspection  
and Licensee Performance  
Office of Nuclear Reactor Regulation

Enclosure:  
Part 21 Tracking System and Monthly Update

070018

Addresses - Memorandum dated 5/3/93

James G. Partlow, Associate Director, ADPR  
William T. Russell, Associate Director, ADT  
Charles E. Rossi, Director, DRIL  
Brian K. Grimes, Director, DORS  
James E. Richardson, Director DE  
Ashok C. Thadani, Director, DSSA  
Frank J. Congel, Director, DRSS  
Jack W. Roe, Director, DRPW  
Dennis M. Crutchfield, Associate Director, ADAR  
Jack R. Strosnider, Acting Branch Chief, EMCB  
James A. Norberg, Branch Chief, EMEB  
Jared S. Wermiel, Branch Chief, HICB  
Goutam Bagchi, Branch Chief, HICB  
Carl H. Berlinger, Branch Chief, EELB  
Conrad E. McCracken, Branch Chief, SPLB  
Robert C. Jones, Branch Chief, SRXB  
Alfred E. Chaffee, Branch Chief, OEAB  
Kathy Gray, OEAB/NRR  
Gail H. Marcus, Branch Chief, OGCB  
Gregory Cwalina, Section Chief, SIB  
Eugene Imbro, Branch Chief, SIB  
William D. Beckner, Branch Chief, SPSB  
Lemoine Cunningham, Branch Chief, PSRPB  
Edward J. Butcher, Deputy Director, DRSS  
Anthony T. Gody, Branch Chief, ILPB  
Donald R. Haverkamp, Chief, TSS, Region I  
Ellis W. Merschoff, Director, DRP, Region II  
Stephen J. Vias, Chief, TSS, Region II  
Robert A. Hasse, Chief, TSS, Region III  
Arthur Beach, Director, DRSS, Region IV  
Kenneth Perkins, Director, DRSP, Region V  
R. Lee Spessard, Director, DOA/AEOD  
Thomas M. Novak, Director, DSP/AEOD  
John A. Skoczlas, Jr. TB/IRM  
Scott Newberry, Branch Chief, PDLR  
Karen H. Vendermel, SECY/PDR, LL-6  
Richard J. Barrett, Branch Chief, SCSB

Enclosure

## PART 21 TRACKING SYSTEM AND MONTHLY UPDATE

Vendor Inspection Branch (VIB) Part 21 computerized database is used to track the screening, evaluation and resolution of Part 21 notifications submitted to the NRC. The database identifies the specific issue to be tracked, the submitter, the date of the input report, the NUDOCS accession number, the responsible individuals assigned to evaluate and resolve the issue, and the accepted resolution. The following specific information is included:

- The LDG number is the VIB assigned five digit identification consisting of the year of submittal and the sequence of receipt.
- The SUB and VEND column identifies the submitter and associated vendor codes as appropriate. The codes utilized are generally consistent with those given in "The 21/55 Data Base User's Manual", NUREG/CR-4011.
- The REPORT DATE indicates the date of issuance of the Part 21 notification.
- The ACCESSION NUMBER is the ten digit identification number of Part 21 notification in NUDOCS.
- The ASSIGNED column identifies the NRR branch and individual assigned responsibility to evaluate and resolve the issue.
- The CLOSEOUT column indicates the accepted closeout rationale (a listing of the commonly used closeout acronyms and their definitions is attached), and the date of closeout.
- The DESCRIPTION provides a brief synopsis of the Part 21 notification with references to other related Part 21 logs as appropriate.

COMMONLY USED ABBREVIATIONS  
TO SIGNIFY CLOSEOUT OF 10 CFR PART 21 ISSUES

VASU            VENDOR ACTIONS ARE CONSIDERED SUFFICIENT  
                 TO ADDRESS THE ISSUE

LISU            LICENSEE ACTIONS ARE CONSIDERED SUFFICIENT  
                 TO ADDRESS THE ISSUE

BUIS            AN NRC BULLETIN WAS ISSUED TO REQUEST THAT  
                 INDUSTRY TAKE SPECIFIC ACTIONS TO ADDRESS  
                 THE ISSUE

INIS            AN NRC INFORMATION NOTICE WAS ISSUED TO  
                 HIGHLIGHT THE ISSUE FOR INDUSTRY

NGTR            THE ISSUE IS NOT BELIEVED TO BE GENERIC

FRNW            FAILURE CONSIDERED RANDOM OR NORMAL WEAR

LPSP            ISSUE IS BELIEVED TO BE A LOW PRIORITY  
                 SAFETY PROBLEM

CTBI            THE TECHNICAL ISSUE ASSOCIATED WITH THIS  
                 NOTIFICATION HAS ALREADY BEEN RAISED IN A  
                 DIFFERENT 10 CFR PART 21 NOTIFICATION -  
                 TRACKING OF THIS ISSUE IS BEING CLOSED  
                 ADMINISTRATIVELY BY RVIB - RESOLUTION OF  
                 THE TECHNICAL ISSUE IS BEING TRACKED AS A  
                 DIFFERENT 10 CFR PART 21 NOTIFICATION

10 CFR PART 21 TRACKING SYSTEM

VENDOR INSPECTION BRANCH  
DIVISION OF REACTOR INSPECTION AND LICENSEE PERFORMANCE

LOG #	SUB REPORT AND DATE VEND CODE	ACCESSION NUMBER	ASSIGNED	CLOS DESCRIPTION OUT CODE
93154	B340 03/31/93		ECGB: G.BAGCHI	BOEING COMPUTER SERVICES REPORTS PROBLEM WITH STRUCTURAL ANALYSIS CODE GTSTRUDLE THAT RESULTS IN INCORRECT ANSWERS THAT MAY NOT BE APPARENT. SEVERAL NUCLEAR CUSTOMERS NOT NOTIFIED.  DUE BY: 6/1/93
93155	C028 04/01/93 CRSM		RVIB: D.BREWER	CAJON OF MACEDONIA, OHIO REPORTS SALE OF S/S PIPE FITTING, PART NO. SS-4-CP, THAT MAY CONTAIN AN INCLUSION WHICH COULD CAUSE ACCELERATED CORROSION & FAILURE. 60 FITTINGS DELIVERED TO DAVIS BESSE & 50 TO NMP. ALL FITTINGS BEING RECALLED.  DUE BY: 6/7/93
93156	B340 03/09/93		ECGB: G.BAGCHI	BOEING COMPUTER SERVICES REPORTS THAT ERROR NOTICES WERE RECEIVED FROM THEIR FORMER SOFTWARE SUPPLIERS INDICATING THAT INCORRECT ANSWERS MAY RESULT FROM GTSTRUDL THAT ARE NOT APPARENT. NOT ALL NUCLEAR CUSTOMERS NOTIFIED.  DUE BY: 6/7/93
93157	B340 03/23/93		ENEB: C.WU	BOEING COMPUTER SERVICES REPORTS THAT ERROR NOTICE WAS RECEIVED FROM THEIR FORMER SOFTWARE SUPPLIER REGARDING THE FAILURE OF NU PIPE-11 TO PRODUCE EXPECTED RESULTS OF MULTIPLE RESPONSE SPECTRA LOAD CASES.  DUE BY: 6/7/93
93158	W120 03/24/93	9304020066	EMEB: C.WU	CTBI WESTINGHOUSE PROVIDES UPDATE TO AN INTERIM REPORT ON THE UPPER PLENUM ANOMALY CHARACTERIZED BY INCR & DECR IN ADJACENT HOT LEG TEMP IN CYCLES LASTING SEVERAL MINUTES. SG FLOWS ALSO INCR/DECR. CONCERN IS ALTING THERM STRESS & EFFECT ON FATIGUE USAGE FAC.  DUE BY: 4/30/93
93159	REC 10/30/92 W030	9211040037	RVIB: D.BREWER	WGTR PEACH BOTTOM/2 REPORTS CRACKING OF YOKES ON TWO TORUS COOLING INJECTION MOTOR-OPERATED VALVES. VALVES ARE 18" CS BY WALWORTH. CAUSE OF CRACKING APPEARS TO BE AN OVERTHRUST CONDITION CAUSED BY THE VALVE ACTUATOR.  DUE BY: 6/7/93
93160	CWE 02/22/93 W120	9302250330	SRXB: CY.LIANG	ZION 1 REPORTS REQUESTING PERMISSION FROM WRC TO RESET LOW TEMP OVERPRESS PROTECTION (LTOP) SYSTEM BELOW 435 PSIG AT 402 & 407 PSIG DUE TO DIFF LOCATIONS OF PRESS SENSOR TAPS ON HOT LEG PIPING BASED ON WESTINGHOUSE INFO.  DUE BY: 5/24/93
93161	V085 04/08/93 WPS		RVIB:L.CAMPBELL	CTBI VELAN VALVE CORP REPORTS THAT SERVICE BULL.#SB-106 WILL BE ISSUED SHORTLY TO LICENSEES TO WARN OF NEEDED INSPECTIONS OF ANTI-ROTATION KEYS ON "L" SHAPED GLOBE VALVES FOR POSSIBLE WEAR WHICH COULD RESULT IN FAILURE. SEE LOG#93147 FOR CLOSURE.  DUE BY: 8/27/93
93162	APS 04/08/93 G080		RVIB: G.CWALINA	PALO VERDE 3 REPORTS FAILURE OF THE "B" LPS1 GE CIRCUIT BREAKER TO RECHARGE ITS CLOSING SPRINGS AT LAST CLOSURE RENDERING LPS1 PUMP INOPERABLE. APPARENT INTERFERENCE OF PARTS. VENDOR MANUAL DOES NOT ADDRESS.  DUE BY: 6/14/93

10 CFR PART 21 TRACKING SYSTEM

VENDOR INSPECTION BRANCH  
DIVISION OF REACTOR INSPECTION AND LICENSEE PERFORMANCE

LOG #	SUB	REPORT	ACCESSION	ASSIGNED	CLOS	DESCRIPTION
	AND	DATE	NUMBER		OUT	
	VEND				CODE	
	CODE					
93163	MOV	01/15/93		OGCB:R.KIESSEL		ITI MOVATS REPORTS ON SEVERAL EXAMPLES OF RECENT TESTING THAT DEMONSTRATE VARIATIONS IN THE OUTPUT THRUST OF A MOV DUE TO LUBRICATION CYCLE TIME AND TYPE OF LUBRICATION. RECOMMENDATIONS PROVIDED.
				DUE BY: 6/14/93		
93164	SFI	04/12/93		RVIB:U.POTAPOVS		SENIOR FLEXONICS, INC REPORTS THAT CLAM SHELL EXPANSION JOINTS PROVIDED BY PURCHASE ORDER TO QUAD CITIES WERE NOT HYDROSTATICALLY TESTED AS REQUIRED BY ASME. LICENSEE NOTIFIED.
	CWE			DUE BY: 6/14/93		
93165	WNE	03/31/93		EMEB: J.WORBERG		MILLSTONE 3 REPORTS FAILURE OF A MSSV TO RESEAT FOLLOWING A TRANSIENT. FAILURE IS ATTRIBUTABLE TO AN INACCURATE LOWER RING SETTING BY CROSBY DUE TO A PROCEDURAL ERROR. 7 OF 11 SV AFFECTED.
	C711			DUE BY: 6/14/93		
	D245					
93166	THCI	02/23/93		SPLB: McCracken		THERMAL CERAMICS PROVIDED RESULTS OF A FIRE TEST TO DETERMINE CAPABILITY OF KAOWOOL CERAMIC FIBER BULKY MATL FOR CABLE TRAYS, ELECT. CABLES, CONDUIT, & JUNCTION BOXES. TESTING DONE BY UL, INC REPORT DATED 3/22/85. APPENDED INFO ON 5/18/92. SEE LOG#93167/93168.
				DUE BY: 6/14/93		
93167	THCI	02/23/93		SPLB: McCracken		THERMAL CERAMICS PROVIDED TEST RESULTS FOR AN FP60 1-HR PROTECTION SYSTEM (KAOWOOL) FOR 1" CONDUIT, CABLE DROP & JUNCTION BOX. TESTING WAS CONDUCTED BY SW RESEARCH REPORT DATED FEB 1986. SEE LOG#93166/93168.
				DUE BY: 6/14/93		
93168	THCI	02/23/93		EELB: BERLINGER		THERMAL CERAMICS PROVIDED TEST REPORT OF AMPACITY DERATING OF CABLES IN CONDUIT/CABLE TRAYS USING KAOWOOL FIRE PROTECTION SYSTEM. TESTING DONE BY SW RESEARCH REPORT DATED JULY 8, 1986. DESCRIPTION OF CABLE TRAY WRAP SYSTEM INCL. SEE LOG#93166/93167.
				DUE BY: 6/14/93		
93169	B340	04/01/93		ECGB: G.BAGCHI		BOEING COMPUTER SERVICES REPORTS THAT THEIR FORMER SOFTWARE SUPPLIERS HAVE SUBMITTED ERROR NOTICES FOR GTSTRUDL 93.09 & 93.10. SEVERAL NUCLEAR CUSTOMERS HAVE NOT BEEN NOTIFIED.
				DUE BY: 6/14/93		
93170	B080	03/29/93	9304080013	RVIB: G.CWALINA		ITT BARTON REPORTS THAT QUALIFICATION TESTS PERFORMED ON THE DASH ONE MODEL 580 SERIES INSTRUMENTATION WERE INSUFFICIENT TO JUSTIFY ANY QUAL OTHER THAN "STRUCTURAL INTEGRITY". ALL CUSTOMERS ARE BEING IDENTIFIED.
				DUE BY: 6/14/93		
93171	CONP	04/02/93	9304120002	RVIB:L.CAMPBELL		CONSOLIDATED POWER SUPPLY REPORTS THEIR INABILITY TO CONFIRM THE TRACEABILITY OF BLIND FLANGE MATERIAL TO A HEAT NUMBER AS REQD BY ASME. FLANGES HAVE BEEN RECLASSIFIED TO COMMERCIAL & ALL AFFECTED CUSTOMERS HAVE BEEN NOTIFIED.
				DUE BY: 9/31/93		

10 CFR PART 21 TRACKING SYSTEM

VENDOR INSPECTION BRANCH  
DIVISION OF REACTOR INSPECTION AND LICENSEE PERFORMANCE

LOG #	SUB	REPORT	ACCESSION	ASSIGNED	CLOS	DESCRIPTION
	AND	DATE	NUMBER		OUT	
	VEND				CODE	
	CODE					
93172	C628	04/14/93	9304190045	RVIB: W.HAASS	VASU	COOPER BESSEMER REPORTS FAILURE OF 12 FUEL PUMPS SINCE 11/89 DUE TO BREAKDOWN OF QA REQMTS AT THE HAYNES CORP, MNFCTR OF THE PUMPS (INADEQUATE CLEANING OF SHOTBLAST GRIT MEDIA FROM PUMPS). CORRECTIVE ACTION TAKEN & AFFECTED LICENSEES INFORMED.
	HYNC					
				DUE BY: 6/14/93		
93173	WPP	02/12/93	9302220096	SPLB:McCRACKEN		WNP-2 REPORTS THAT A SINGLE FAILURE COULD RESULT IN THE CONTROL ROOM HEATING & VENTILATING SYSTEM TO OPERATE IN THE RECIRC MODE DURING EMERGENCY CONDITIONS. ORIGINAL DESIGN BY BURNS & ROE DID NOT PROTECT AGAINST ALL POSSIBLE SINGLE FAILURES.
	B570					
				DUE BY: 6/14/93		
93174	TVA	04/08/93	9304130370	RVIB: D.BREWER		TVA REPORTS FAILURE OF MOTOR SHAFT PINION GEAR KEY & MOTOR SHAFT OF A LIMITORQUE MODEL SB-3 VALVE ACTUATOR IN THE RHR SYSTEM. OTHER VALVE ACTUATORS WERE FOUND WITH DEFORMED KEYS SIMILAR TO FAILURES FOUND IN 1982.
	L200					
	W120					
				DUE BY: 8/16/93		
93175	WPS	04/09/93		RVIB:L.CAMPBELL		KEWAUNEE PROVIDES ADDITIONAL INFORMATION ON THE FAILURE OF ANTI-ROTATION KEYS OF VELAN VALVES LOCATED BETWEEN THE VALVE STEM & YOKE BUSHING. CAUSE ATTRIBUTED TO DEFICIENCIES IN MACHINING OF THE KEYS. REDESIGN HAS BEEN DONE. SEE LOG#93147.
	V085					
				DUE BY: 8/27/93		
93176	TWO	03/31/93	9304060401	PD1-2: R.CLARK		TWO PP&L CONTRACTOR EMPLOYEES SUMMARIZE THEIR VIEW OF THE RESULTS OF THE MTNG AT NRC WITH LICENSEE ON 3/18/93 REGARDING THEIR CONTENTION THAT THE SUSQUEHANNA DESIGN FOR LOSS OF NORMAL SPENT FUEL POOL COOLING DOES NOT MEET NRC REQMTS. SEE LOG#93003/93004.
	CONT					
	ENGS					
				DUE BY:10/15/93		
93177	CWE	03/03/93	9303090085	SRXB: CY.LIANG		BRAIDWOOD REPORTS NONCOMSV CALC USED TO GENERATE HEATUP/COOLDOWN CURVES & LTOP/COMS NOMINAL PORV SETPOINT CURVES. ERROR DUE LACK OF CONSIDERATION OF PRESS DROP FROM THE PV BELTLINE TO PRESS TRANSMITTER. MANY WEST PLANTS AFFECTED. SEE LOG#93160 ET AL.
	W120					
				DUE BY: 6/15/93		
93178	VYC	04/14/93		RVIB:		VERMONT YANKEE 1 REPORTS SLOW SCRAM INSERTION TIMES FOR SEVERAL CONTROL RODS. PROB ATTRIB. TO SLOW RESPONSE OF THE SCRAM SOLENOIDPILOT VALVES ON THE HCU. VALVES ARE ASCO HVA90-4050-2A SUPPLIED & DEDICATED BY GE.
	A499			PETROSINO INFO: H		
	G080			.ORNSTEIN		
				DUE BY:		
				6/16/93		
93179	APS	04/15/93		RVIB:U.POTAPOVS		PALO VERDE 2 EXPERIENCED HIGH FAILURE RATE OF HYDRAULIC PIPING SHUBBERS DURING REFUELING OUTAGE DUE TO "LOCKING UP". MOST FAILURES WERE SMALL SHUBBERS, SIZES PSA-1/4 & PSA-1/2. ROOT CAUSE BEING DETERMINED.
	P029					
				DUE BY: 6/16/93		
93180	C628	04/14/93	9304190063	RVIB: W.HAASS	VASU	COOPER-BESSEMER PROVIDES ITS LATEST FINDINGS & HAS REVISED ITS CORRECTIVE ACTIONS FOR AFFECTED LICENSEES REGARDING NEED FOR REPLACEMENT OF IDLER GEAR. SEE LOG#93114.
	T274					
	GERW					
				DUE BY: 6/19/93		

10 CFR PART 21 TRACKING SYSTEM

VENDOR INSPECTION BRANCH  
DIVISION OF REACTOR INSPECTION AND LICENSEE PERFORMANCE

LOG #	SUB	REPORT	ACCESSION	ASSIGNED	CLOS	DESCRIPTION
		AND	NUMBER		OUT	
		VEND			CODE	
		CODE				
93181	B340	04/12/93		ECGB: G.BAGCHI		BOEING COMPUTER SERVICES REPORTS ERROR NOTICES WERE RECEIVED FROM THEIR FORMER SOFTWARE SUPPLIERS REGARDING GTSTRUDL 93.11 USED FOR STRUCTURAL ANALYSIS. SEVERAL NUCLEAR CUSTOMERS HAVE NOT BEEN NOTIFIED.
				DUE BY: 6/21/93		
93182	HLP	02/22/93	9303020173	RVIB:U.POTAPOVS		SOUTH TEXAS PROJECT REPORTS OVERSPEED TRIP CONDITION ON THE TERRY TURBINE DRIVE FOR THE AFW PUMP #24 INDICATED WHEN CONDITION DID NOT EXIST. VENDOR MANUAL CONFLICT WITH HL&P PROCEDURE
	T129					ALSO USED LARGER SIZE PIN FOR MECH O/S LINKAGE.
				DUE BY: 6/21/93		
93183	GPL	03/26/93	9303290254	RVIB: G.CWALINA		CAROLINA POWER & LIGHT PROVIDES AN EVALUATION OF POSSIBLE MANUFACTURING DEFECTS IN WESTINGHOUSE TYPE HMCP & KFD C/Bs PURCHASED UNDER WEST APP B PROGRAM. FAILURE COULD CAUSE C/Bs NOT TO TRIP WHEN CONDITIONS WARRANT. SEE LOG#93079/93084.
	W120					
				DUE BY: 6/21/93		
93184	CPL	04/21/93		PRPB:S.KLEHEN-		ROBINSON 2 REPORTS FAILURE OF AN INTERNAL POWER SUPPLY FOR R-18 RADIATION MONITOR W/O INDICATION IN CONTROL ROOM VIA ANNUNCIATOR.
	N330			TOWICZ		ALL SUCH MONITORS DECLARED INOPERABLE. MANUFACTURER IS NUCLEAR RESEARCH CORP. SEE LOG#93193.
				DUE BY: 6/22/93		
93185	FPC	04/05/93		RVIB:U.POTAPOVS		CRYSTAL RIVER 3 REPORTS AN RCS O/COOLING EVENT IN WHICH A CONTROL VALVE OPENED FULLY ON ITS OWN WHEN AN OPERATOR ATTEMPTED TO TAKE MANUAL CONTROL. MISOPER WAS ATTRBD TO INCORRECT ORDER OF INSTRUCTION STEPS & DAMAGE TO VALVE KEY. MANUFR IS FISHER.
	F130			INFO: OEAB		
				DUE BY: 6/22/93		
93186	B080	04/15/93	9304260229	RVIB:G.CWALINA		ITT BARTON PROVIDES IDENTIFICATION OF ALL CUSTOMERS THAT MAY BE AFFECTED BY LACK OF QUAL OF THE DASH ONE MODEL 580 SERIES INSTRUMENTATION. ALL CUSTOMERS WILL BE INFORMED OF PROBLEM AND OFFER OF FIELD UPGRADE KITS. SEE LOG#93170
				DUE BY: 6/14/93		
93187	W336	04/14/93		RVIB: K.WAIDU		WYLE LABS PROVIDES RESPONSES TO NRC COMMENTS REGARDING TESTING OF THE EIGHT AVC MANIFOLD ASSEMBLIES FOR SEVERAL LICENSEES. SEE LOG#92143/92239.
	TVA					
				DUE BY: 6/22/93		
93188	U009	04/12/93		RVIB:U.POTAPOVS		NRC REGION V REPORTS THAT 4- & 8-INCH ANCHOR DARLING CHECK VALVES AT DIABLO CANYON HAVE BONNET HOLD-DOWN DOWELS THAT ARE TOO SHORT THEREBY NEGATING THEIR FUNCTION OF PREVENTING UPWARD MOVEMENT OF HINGE RING UNDER DYNAMIC CONDITIONS.
	PGE					
	A391					
				DUE BY: 6/22/93		
93189	SF1	04/12/93		RVIB:U.POTAPOVS		SENIOR FLEXONICS, INC PROVIDES FURTHER INFO REGARDING THEIR FAILURE TO PERFORM HYDROSTATIC TESTING OF CLAM SHELL EXPANSION JOINTS AS REQUIRED BY ASME
	CWE					WPT STAMP ERRONEOUSLY APPLIED. SEE LOG# 93164.
				DUE BY: 6/14/93		



10 CFR PART 21 TRACKING SYSTEM

VENDOR INSPECTION BRANCH  
DIVISION OF REACTOR INSPECTION AND LICENSEE PERFORMANCE

LOG #	SUB	REPORT	ACCESSION	ASSIGNED	CLOS	DESCRIPTION
		AND DATE	NUMBER		OUT	
		VEND			CODE	
		CODE				
93190	B455	04/07/93	9304160080	RVIB: K.NAIDU		ABB POWER DISTRIBUTION PROVIDES A RECORD OF EVALUATION OF THE FAILURE OF THE K-400 CIRCUIT BREAKER TO MEET CERTAIN REQUIREMENTS BASED UPON ANSI C37.16. SEE LOG# 92254/93027.
				DUE BY: 6/28/93		
93191	S382	04/01/93	9304210025	RVIB: G.CWALINA		STATIC-O-RING, INC HAS DISCOVERED A PROBLEM IN VACUUM SWITCHES IN WHICH THE O-RING SEAL LEAKS WHEN EXPOSED TO HYDRO PRESS >150 PSI AFTER EXPOSURE TO 33 MRAD GAMMA RADIATION & 230 F TEMPERATURE. SOR NOTICE ISSUED TO ALL NUCLEAR PLANT USERS.
				DUE BY: 6/28/93		
93192	OPL	10/27/92	9212210005	RVIB:U.POTAPOVS INFO: EMEB		CAROLINA POWER & LIGHT REPORTS DEFECTS IN 3",4",6,"& 10" ANCHOR/DARLING DOUBLE-DISC GATE VALVES THAT PERMIT VALVE SEAT LEAKAGE IN EXCESS OF ACCEPTABLE LIMITS. DEFECTS INCLUDE CASTING/MANUFACTURING DEFICIENCIES.
	A391			DUE BY: 6/28/93		
93193	W330	04/21/93		RVIB: G.CWALINA		NUCLEAR RESEARCH CORP REPORTS ON A MODIFICATION TO MODEL DRM-200SERIES RATEMETERS TO CORRECT THE LACK OF ANNUNCIATION OF A FAIL-ALARM WHEN THE +5 VDC POWER SUPPLY FAILS. ALL LICENSEES INFORMED OF THE MOD. SEE LOG#93184.
				DUE BY: 6/28/93		
93194	WPP	04/26/93		RVIB:U.POTAPOVS		WASHINGTON NUCLEAR 2 REPORTS FIRE DAMPERS BY RUSKIN LACK PROPER SEISMIC QUALIFICATION DUE TO WEAK COMPONENTS HOLDING THE DAMPERS OPEN. LICENSEE HAS TAKEN COMPENSATING MEASURES, BUT ISSUE APPEARS GENERIC. NPROS SEARCHED FOR OTHER SIMILAR EVENTS.
	R411			DUE BY: 6/28/93		
93195	DPC	04/01/93	9304060262	RVIB: G.CWALINA		DUKE POWER REPORTS THAT WIRING ERRORS WERE FOUND IN THE SOLID STATE PROTECTION SYSTEM AT CATAWBA 1 DUE TO A MANUFACTURER FABRICATION DEFICIENCY AT WESTINGHOUSE. OTHER LICENSEES AFFECTED & BEING INFORMED BY WESTINGHOUSE.
	W120			DUE BY: 6/28/93		
93196	CWE	03/19/93	9303220152	SRXB: R.JONES		COMMONWEALTH EDISON REPORTS THAT ECCS MAY NOT BE CAPABLE OF ATTAINING VESSEL LEVEL ABOVE TOP OF ACTIVE FUEL FOLLOWING A LOCA DUE TO DRAINAGE THRU JET PUMPS. GE WAS NOTIFIED. SEE LOG#93197.
	G080			DUE BY: 6/29/93		
93197	CWE	04/23/93	9304270147	SRXB: R.JONES		COMMONWEALTH EDISON REPORTS THAT ECCS MAY NOT BE CAPABLE OF ATTAINING VESSEL LEVEL ABOVE TOP OF ACTIVE FUEL FOLLOWING A LOCA DUE TO DRAINAGE THRU JET PUMPS. INTERIM REPORT SEE LOG#93196
	G080			DUE BY: 6/29/93		