

FEB 4 1991

Docket No. STN 50-482/90-39
License No. NPF-42
EA 91-003

Wolf Creek Nuclear Operating Corporation
ATTN: Bart D. Withers
President and Chief Executive Officer
P.O. Box 411
Burlington, Kansas 66839

Gentlemen:

This refers to the enforcement conference conducted at Region IV's request in the Region IV office on January 30, 1991. This meeting pertained to the frozen safety injection pump recirculation line that occurred December 23, 1990. The meeting was attended by those on the attached Attendance List.

The subjects discussed at this meeting are described in the enclosed Meeting Summary. At the meeting, you committed to provide to the NRC Staff the written guidance given to the dedicated operator, for the safety injection pumps.

It is our opinion that this meeting was beneficial and has provided the staff with a better understanding of the event and your corrective actions. In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter will be placed in the NRC's Public Document Room.

Should you have any questions concerning this matter, we will be pleased to discuss them with you.

Sincerely,

ORIGINAL SIGNED BY
SAMUEL J. COLLINS

Samuel J. Collins, Director
Division of Reactor Projects

Enclosure:
Meeting Summary w/attachments

cc w/enclosure:
Wolf Creek Nuclear Operating Corp.
ATTN: Gary Boyer, Plant Manager
P.O. Box 411
Burlington, Kansas 66839

*RIV:DRP/D
LLGundrum;df
1/ /91

*C:DRP/D
ATHowell
1/ /91

D. J. COLLINS
S. J. COLLINS
1/4/91

*previously concurred
9102130057 910204
PDR ADOCK 05000482
Q PDR

IE45
11

Wolf Creek Nuclear Operating
Corporation

-2-

Shaw, Pittman, Potts & Trowbridge
ATTN: Jay Silberg, Esq.
1800 M Street, NW
Washington, D.C. 20036

Public Service Commission
ATTN: Chris R. Rogers, P.E.
Manager, Electric Department
P.O. Box 360
Jefferson City, Missouri 65102

U.S. Nuclear Regulatory Commission
ATTN: Regional Administrator, Region III
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Wolf Creek Nuclear Operating Corp.
ATTN: Otto Maynard, Manager
Regulatory Services
P.O. Box 411
Burlington, Kansas 66839

Kansas Corporation Commission
ATTN: Robert Elliot, Chief Engineer
Utilities Division
4th Floor - State Office Building
Topeka, Kansas 66612-1571

Office of the Governor
State of Kansas
Topeka, Kansas 66612

Attorney General
1st Floor - The Statehouse
Topeka, Kansas 66612

Chairman, Coffey County Commission
Coffey County Courthouse
Burlington, Kansas 66839

Kansas Department of Health
and Environment
Bureau of Air Quality & Radiation
Control
ATTN: Gerald Allen, Public
Health Physicist
Division of Environment
Forbes Field Building 321
Topeka, Kansas 66620

Wolf Creek Nuclear Operating
Corporation

-3-

bcc to DMB (IE45)

bcc distrib. by RIV:

R. D. Martin

Section Chief (DRP/D)

DRSS-RPEPS

RIV File

Project Engineer (DRP/D)

DRS

Resident Inspector

DRP

Section Chief (RIII, DRP/3C)

SRI, Callaway, RIII

Lisa Shea, RM/ALF

MEETING SUMMARY

Licensee: Wolf Creek Nuclear Operating Corporation (WCNOC)
Facility: Wolf Creek Generating Station (WCGS)
License No.: NPF-42
Docket No.: STN 50-482
Subject: FROZEN SAFETY INJECTION PUMP RECIRCULATION LINE

On January 30, 1991, representatives of WCNOC presented to Region IV personnel in Arlington, Texas, their description of the freezing of the safety injection pumps' common recirculation line to the refueling water storage tank.

The licensee's presentation addressed the design bases for the safety injection system and freeze protection heat tracing; operations issues, including the applicable Technical Specification, the timeline of events, and immediate actions; long-term actions; safety significance of the event; and the lessons learned.

The attendance list is attached to this summary.

Attachments:

1. Attendance List
2. Licensee Presentation (NRC distribution only)

ATTENDANCE LIST

Attendance at the January 30, 1991, meeting between WCNOG and NRC in
Arlington, Texas:

WCNOG


B. Withers, President
J. Bailey, Vice President, Operations
G. Boyer, Director, Plant Operations
J. Pippin, Director, Nuclear Plant Engineering
J. Weeks, Manager, Operations
T. Garrett, Manager, Nuclear Safety Assessment
H. Chernoff, Supervisor, Licensing

NRC

S. Collins, Director, Division of Reactor Projects
J. Jaudon, Acting Director, Division of Reactor Safety
T. Stetka, Acting Deputy Director, Division of Reactor Safety
A. Howell, Chief, Project Section D, Division of Reactor Projects
G. Sanborn, Enforcement Officer
D. Pickett, Project Manager, Office of Nuclear Reactor Regulation
M. Skow, Senior Resident Inspector, Wolf Creek Generating Station
L. Gundrum, Resident Inspector, Wolf Creek Generating Station

WCNOC MANAGEMENT MEETING WITH
NRC REGION IV MANAGEMENT

FROZEN SAFETY INJECTION
PUMP RECIRCULATION LINE



January 30, 1991

WOLF CREEK
NUCLEAR OPERATING CORPORATION

FROZEN SAFETY INJECTION PUMP RECIRCULATION LINE

INTRODUCTION	-	JOHN BAILEY
DESIGN BASIS DISCUSSION	-	JACK PIPPIN
OPERATIONS ISSUES	-	JIM WEEKS
TECHNICAL SPECIFICATIONS		
TIMELINE OF EVENTS		
IMMEDIATE ACTIONS		
LONG-TERM ACTIONS	-	GARY BOYER
SAFETY SIGNIFICANCE	-	TERRY GARRETT
LESSONS LEARNED	-	GARY BOYER
SUMMARY	-	JOHN BAILEY
CLOSING REMARKS	-	BART WITHERS


DESIGN BASIS DISCUSSION OF SAFETY INJECTION AND ITS FREEZE PROTECTION

- SI IS ONE OF THE
ECCS SYSTEMS

- ECCS PROVIDES TWO SAFETY
RELATED FUNCTIONS

- ECCS IS DESIGNED TO COOL
THE REACTOR CORE AND
PROVIDE SHUTDOWN CAPABILITY

SIMPLIFIED ECCS



SI SYSTEM OVERVIEW

- SI SYSTEM SUPPLEMENTS
NORMAL RCS MAKEUP

- SI SYSTEM SPECIFICS

TWO CENTRIFUGAL HORIZONTAL
11 STAGE PUMPS

DESIGN PUMP RATE 450 GPM @ TOTAL
DEVELOPED HEAD 2780 FT OR 1201 PSI

SHUT-OFF HEAD 1520 PSIG


MOTOR SIZE NOMINAL
450 HP/ 4kv/ 3 PHASE/ 60HZ

- MINIMUM RECIRCULATION LINE
DESIGN FUNCTION

PROVIDES PATH TO RWST THAT ALLOWS
MINIMUM FLOW TO PROTECT PUMP AT OR
NEAR SHUT-OFF CONDITIONS

SI Recirculation Line


Safety Injection Pumps



CREDIBLE PUMP FAILURE MECHANISMS


- PREDICTED FAILURE DUE TO
FLASHING WATER (VAPOR LOCK)

SAFETY INJECTION PUMP (INTERNAL ASSEMBLY SIMPLIFIED)




NOTES: 1. NOT TO SCALE

2. PORTIONS SIMPLIFIED FOR
DISCUSSION PURPOSES



AREA OF PREDICTED FAILURE DUE TO VAPORIZATION OF FLUID (LOSS-OF-SUCTION) AND/OR WELDING OF AN IMPELLER O.D. TO DIFFUSER/SPACER DUE TO THERMAL EXPANSION

13.8 KV BUS PA02 (NON-Q)



DISTRIBUTION
PWR PNL.
PG18LBF3-19

MAIN CONTROL ROOM



ANN. WINDOW
IN RK020

FRZ
PROT
TROUBLE


RK045
ANN. CABINET

RWST VALVE HOUSE ROOF

BN181 HEAT
TRACE CONTROL
CABINET



AMBIENT T-STAT
OPENS AT 40°F



LO-ALARM
T-STAT
CLOSES AT 35°F

CREDIBLE FREEZE PROTECTION FAILURE MECHANISMS

(ELECTRICAL & MECHANICAL)

- KEY ELECTRICAL COMPONENTS
- INSULATION SYSTEM INTEGRITY
- LACK OF SUFFICIENT ADMINISTRATIVE CONTROLS

TECHNICAL SPECIFICATION 3.5.2

REQUIRES OPERABILITY OF TWO INDEPENDENT
ECCS SUBSYSTEMS. EACH SUBSYSTEM
COMPRISED OF:

- ONE CENTRIFUGAL CHARGING PUMP
- ONE SAFETY INJECTION PUMP
- ONE RESIDUAL HEAT REMOVAL PUMP
AND HEAT EXCHANGER
- A SUCTION FLOW PATH FROM THE
RWST CAPABLE OF TRANSFERRING
SUCTION TO THE CONTAINMENT SUMP

SEQUENCE OF EVENTS

RWST FREEZE
PROTECTION TROUBLE
ALARM ON 12/21/90 AT
2045 HRS

ATTEMPT TO FILL RWST
UNSUCCESSFUL ON
12/23/90 AT 0007 HRS

SECOND ATTEMPT
TO FILL RWST
INITIATED ON
12/23/90 AT 1139 HRS

MALFUNCTION OF RWST
HEAT TRACE DISCOVERED
ON 12/23/90 AT 1145 HRS

SECOND ATTEMPT TO
FILL RWST NOT
SUCCESSFUL;
RECIRCULATION LINE
DETERMINED FROZEN
AND SI PUMPS WERE
DECLARED
INOPERABLE ON
12/23/90 AT 1230 HRS

SEQUENCE OF EVENTS

- On December 20 and 21, 1990, the Control Room received freeze protection trouble alarms for several outside water storage tanks.
 - On December 20, 1990, at 2203 CST, a Freeze Protection Trouble Alarm was received. Alarm was on the Demineralized Water Storage Tank.
 - On December 21, 1990, at 0357 CST, alarm was received on the Condensate Storage Tank. At 1454 CST, alarm was received on the Reactor Makeup Water Storage Tank.
- The Freeze Protection Panel breakers were verified to be closed by Operations per procedure and the current flow in the heat trace was verified for the affected circuits by Electrical Maintenance at the request of Operations.
- On December 21, 1990, at 2045 CST, the Control Room received a freeze protection trouble alarm for the Refueling Water Storage Tank (RWST).
- The evening shift for Electrical Maintenance on December 21, 1990 was different than the previous two days. It appears that the Control Room personnel did not emphasize the need to check the current on the RWST heat tracing because they knew Electrical Maintenance personnel had been doing it the previous two days and assumed some turnover would have occurred. The major discussion with Electrical Maintenance personnel on that evening was focused on how the alarm circuit worked and whether there was a reflash on that alarm.
- Electrical Maintenance concluded that if an alarm on the heat trace circuit was in and a breaker feeding the heat trace were to trip, a "reflash" would not occur on the locked in alarm.

SEQUENCE OF EVENTS

- The Control Room then began to check the circuit breakers approximately every four hours to ensure that the breakers were closed.
- On December 22, 1990 at 1206 CST, a RWST low level alarm was received. The Auxilliary Building Watch was dispatched to check for leaks and also to check the heat tracing.
- On December 23, 1990 at 0007 CST, an unsuccessful attempt was made to add water to the RWST following a low level alarm.
- In the process of determining why no flow was indicated, Operations personnel discovered a Work Request Tag on Valve BGV0195 stating that the valve stem was believed to be separated from the valve diaphragm. Based on past experience of having problems with getting flow through BGV0195 when it had similar problems, this was believed to be the reason for no flow at this time.
- Because the RWST level was still substantially above the minimum required level, it was decided to wait until dayshift to have the problem with the valve further evaluated.
- The dayshift crew decided to try to fill the RWST using an alternate flow path and to have Electrical Maintenance verify the operations of the heat trace circuits.
- At 1139 CST, the dayshift crew started the lineup to fill the RWST through an alternate flow path, which did not require flow through Isolation Valve BGV0195.
- At 1145 CST, Electrical Maintenance determined that the heat tracing on the RWST return line had a faulty Ambient Temperature Switch and that no current existed in the heat tracing.

SEQUENCE OF EVENTS

- At 1230 CST, after the attempt to fill the RWST failed, the RWST return line was determined to be frozen and therefore unable to fulfill its function as a recirculation line for both SI pumps. Both SI pumps were declared inoperable and Technical Specification 3.0.3 was entered.

IMMEDIATE ACTIONS

- BOTH SI PUMPS WERE PLACED IN "PULL-TO-LOCK" AT 1250 CST AND AN OPERATOR WAS ASSIGNED TO OPERATE THE SI PUMPS IN THE EVENT THAT FLOW FROM THE SI PUMPS WAS NEEDED
- A JUMPER WAS INSTALLED ACROSS THE INOPERABLE AMBIENT TEMPERATURE SWITCH TO PROVIDE POWER TO THE HEAT TRACE
- A TEMPORARY EXTERNAL HEAT SOURCE WAS USED ON THE FROZEN SECTION OF THE PIPE
- THE FUEL POOL COOLING PUMPS WERE USED TO PROVIDE INTERNAL PRESSURE TO THE BLOCKAGE. FUEL POOL CLEANUP PUMPS CYCLED ON/OFF TO GIVE AN ADDITIONAL PRESSURE SURGE

IMMEDIATE ACTIONS

(CON'T)

- AT 1600 CST, THE PLANT DECLARED A NOTIFICATION OF UNUSUAL EVENT AND BEGAN TO REDUCE POWER
- AT 1702 CST, FLOW WAS ESTABLISHED TO THE RWST FROM THE FUEL POOL COOLING PUMPS AND REACTOR POWER WAS STABILIZED AT 65 PERCENT WHILE VERIFYING SI PUMP RECIRCULATION FLOW
- AT 1705 POWER REDUCTION STOPPED PENDING S₁ PUMP FLOW VERIFICATION
- RECIRCULATION FLOW FOR SI PUMP PEM01A WAS VERIFIED AT 1735 CST PER SURVEILLANCE PROCEDURE STS EM-100A AND TECHNICAL SPECIFICATION 3.0.3 WAS EXITED

IMMEDIATE ACTIONS

(CON'T)

- TECHNICAL SPECIFICATION 3.5.2 WAS THEN ENTERED FOR HAVING ONE EMERGENCY CORE COOLING SYSTEM SUBSYSTEM INOPERABLE AND THE NOTIFICATION OF UNUSUAL EVENT WAS TERMINATED
- RECIRCULATION FLOW FOR SI PUMP PEM01B WAS VERIFIED AT 1757 GPM PER SURVEILLANCE PROCEDURE STS EM-100B AND TECHNICAL SPECIFICATION 3.5.2 WAS THEN EXITED
- AT 2235 GST, REACTOR POWER WAS RESTORED TO 100 PERCENT

SUBSEQUENT ACTIONS

- ELECTRICAL MAINTENANCE WAS INSTRUCTED TO VERIFY THE CURRENT FLOW IN ALL HEAT TRACE CIRCUITS EVERY FOUR HOURS TO CONFIRM PROPER OPERATION WHILE ANY ALARM EXISTED
- A REVIEW WAS CONDUCTED TO DETERMINE IF THERE WERE OTHER SIMILAR PUMP ARRANGEMENTS IN WHICH A HEAT TRACED LINE COULD FREEZE AND PREVENT RECIRCULATION CAPABILITIES OF PUMPS AND NONE WERE FOUND
- A NEW AMBIENT TEMPERATURE SWITCH WAS SUBSEQUENTLY INSTALLED TO REPLACE THE TEMPORARY JUMPER AT 1340 CST ON DECEMBER 24, 1990

SUBSEQUENT ACTIONS (CON'T)

- THE RWST WAS PLACED IN RECIRCULATION

- ENGINEERING WAS REQUESTED TO EVALUATE THE EFFECTS OF FREEZING ON PIPE STRUCTURE AND TO REVIEW DESIGN ASPECTS OF LINE

ROOT CAUSE AND LONG TERM CORRECTIVE ACTIONS

- AMBIENT TEMPERATURE SWITCH
- ADMINISTRATIVE CONTROLS
- COMMUNICATIONS
- PREVENTATIVE MAINTENANCE
- DESIGN ENHANCEMENTS

EVALUATION APPROACH

- REVIEW FUNCTIONAL REQUIREMENTS OF
RHSI PUMPS TO MITIGATE CONSEQUENCES
OF DESIGN BASIS ACCIDENTS
- IDENTIFY USAR LICENSING BASIS
ANALYSES IMPACTED BY THE RETURN
LINE FREEZE CONDITION
- EVALUATE AFFECTED DESIGN BASIS
ACCIDENTS TO ASSESS THE
CONSEQUENCES
- CONCLUSIONS

FUNCTIONAL REQUIREMENTS

- ECCS PRIMARY FUNCTIONS:

1. PROVIDE EMERGENCY CORE COOLING FOR A DECREASE IN REACTOR COOLANT RESULTING FROM A LOCA
2. PROVIDE EMERGENCY BORATION FOR AN EXCESSIVE COOLDOWN EVENT

- ECCS IS DESIGNED TO COOL THE REACTOR CORE AND PROVIDE SHUTDOWN CAPABILITY FOR:

1. LOCA
2. ROD EJECTION ACCIDENT
3. SECONDARY SYSTEM PIPE RUPTURE ACCIDENT
4. STEAM GENERATOR TUBE RUPTURE ACCIDENT

AFFECTED DESIGN BASIS ACCIDENTS

THE AFFECTED SAFETY ANALYSES ARE THOSE WHICH CREDIT THE ACTUATION OF SAFETY INJECTION FLOW:

- LOCA SPECTRUM
- FEEDWATER LINE BREAK ACCIDENT
- STEAM LINE BREAK ACCIDENT -
CORE RESPONSE
- STEAMLINER BREAK ACCIDENT -
M & E RELEASE IN CONTAINMENT
- STEAMLINER BREAK ACCIDENT -
M & E RELEASE OUTSIDE CONTAINMENT
- STEAM GENERATOR TUBE RUPTURE
ACCIDENT
- INADVERTENT OPENING OF STEAM
GENERATOR RELIEF OR SAFETY VALVE

CONSEQUENCE EVALUATION

- FEEDWATER LINE BREAK ACCIDENT:

POTENTIAL IHSI PUMP DAMAGE

NO IMPACT TO THE CONSEQUENCES
SINCE THE IHSI PUMP WAS NOT CREDITED

- STEAMLINER BREAK ACCIDENT -
CORE RESPONSE:

NO IHSI PUMP DAMAGE

NO IMPACT TO THE CONSEQUENCES
SINCE THE IHSI PUMP WAS NOT CREDITED

- STEAMLINER BREAK ACCIDENT -
M & E RELEASE IN CONTAINMENT:

POTENTIAL IHSI PUMP DAMAGE

NO IMPACT TO THE CONSEQUENCES
SINCE THE IHSI PUMP WAS NOT CREDITED

CONSEQUENCE EVALUATION

- STEAMLINE BREAK ACCIDENT -
M & E OUTSIDE CONTAINMENT:

POTENTIAL IHSI PUMP DAMAGE

NO IMPACT TO THE CONSEQUENCES
SINCE THE IHSI PUMP WAS NOT CREDITED

- STEAM GENERATOR TUBE RUPTURE
ACCIDENT:

POTENTIAL IHSI PUMP DAMAGE

MAXIMIZING SAFETY INJECTION FLOW
MAXIMIZES THE CONSEQUENCES

THUS LOSS OF IHSI PUMP FLOW WOULD
RESULT IN LESS SEVERE CONSEQUENCES

- INADVERTENT OPENING OF A STEAM
GENERATOR RELIEF OR SAFETY VALVE:

NO IHSI PUMP DAMAGE

NO IMPACT TO THE CONSEQUENCES
SINCE THE IHSI PUMP WAS NOT CREDITED

CONSEQUENCE EVALUATION

- LARGE BREAK LOCA:

(BREAK SIZES GREATER THAN 1 FT.²)

THESE EVENTS ARE CHARACTERIZED
BY A RAPID DEPRESSURIZATION

NO IHSI PUMP DAMAGE

THE IHSI PUMPS PROVIDE AN
INSIGNIFICANT PROPORTION OF THE
TOTAL SI FLOW

THEREFORE CONSEQUENCES ARE NOT
AFFECTED

CONSEQUENCE EVALUATION


- SMALL BREAK LOCA - BREAKS LESS THAN 1":

EQUILIBRIUM PRESSURE GREATER THAN
IHSI PUMP CUT-IN PRESSURE

POTENTIAL IHSI PUMP DAMAGE

CONSEQUENCES ARE NOT ADVERSELY
AFFECTED

MASS BALANCE EQUIL. PRESSURE



CONSEQUENCE EVALUATION

- SMALL BREAK LOCA -
BREAKS GREATER THAN 1.75":


EQUILIBRIUM PRESSURE BELOW
IHSI PUMP CUT-IN PRESSURE

RCS WILL DEPRESSURIZE BELOW
IHSI PUMP CUT-IN PRESSURE
WITHIN 2 MINUTES

NO IHSI PUMP DAMAGE

THEREFORE CONSEQUENCES ARE
UNAFFECTED

DELTA TIME TO REACH IHSIP CUT-IN PRESSURE



CONSEQUENCE EVALUATION

- SMALL BREAK LOCA - BREAKS BETWEEN 1" AND 1.75":

EQUILIBRIUM PRESSURE BELOW IHSI
PUMP CUT-IN PRESSURE

RCS DEPRESSURIZATION TO IHSI
PUMP CUT-IN PRESSURE GREATER
THAN 2 MINUTES

POTENTIAL IHSI PUMP DAMAGE

CONSEQUENCES ADVERSELY AFFECTED

CONSEQUENCE EVALUATION


- CONSEQUENCES OF LOCAS BETWEEN 1" AND 1.75":

EVALUATION BASED ON A 2" LOCA AND WILL BOUND ALL BREAK SIZES BETWEEN 1" AND 1.75"

ONLY 1 CCP ASSUMED AVAILABLE

NOTRUMP ANALYSIS OF A 2" LOCA RESULTS IN LESS THAN 2200 DEGREES F PCT

PEAK CLAD TEMPERATURE



CONCLUSIONS

- EVALUATION AND ANALYSIS HAVE DEMONSTRATED THAT FOR ALL AFFECTED ACCIDENTS THE CONCLUSIONS IN THE USAR REMAIN VALID

- ECCS CONTINUES TO COOL THE REACTOR CORE

- ECCS WILL PROVIDE SHUTDOWN CAPABILITY FOR:
 1. LOCA
 2. RCD EJECTION ACCIDENT
 3. SECONDARY SYSTEM PIPE RUPTURE ACCIDENT
 4. STEAM GENERATOR TUBE RUPTURE ACCIDENT