

Arizona Public Service Company

P.O. BOX 21666 • PHOENIX, ARIZONA 85036

RECEIVED
MPC

1982 DEC -2 11:11:08

November 23, 1982

ANPP-22374-GHD/BSK

U. S. Nuclear Regulatory Commission
Region V
Creskide Oaks Office Park
1450 Maria Lane - Suite 210
Walnut Creek, California 94596-5368

Attention: Mr. D. M. Sternberg, Chief
Reactor Projects Branch 1


Subject: Final Report - DER 82-41
A 50.55(e) Reportable Condition Relating to
G. E. Switchgear in Unit 3 Control Building Has
Improperly Crimped AMP Termination Lugs.
File: 32-019-026
D.4.33.2

Reference: (A) Telephone Conversation between J. Eckhardt and
G. Duckworth on August 2, 1982
(B) ANPP-21756 dated September 1, 1982 (Interim Report)

Dear Sir:

Attached is our final written report of the Reportable Deficiency, under
10CFR50.55(e) referenced above.

Very truly yours,



E. E. Van Brunt, Jr.
APS Vice President
Nuclear Projects Management
ANPP Project Director

EEVBJr/GHD:db

Enclosure

cc: See Attached Page 2

1827

U. S. Nuclear Regulatory Commission
Attention: Mr. D. M. Sternberg, Chief
Page 2

November 23, 1982
ANPP-22374-GHD/BSK

cc: Richard DeYoung, Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

T. G. Woods, Jr.
J. A. Roedel
D. B. Fasnacht
G. C. Andognini
A. C. Rogers
B. S. Kaplan
W. E. Ide
J. Vorees
J. A. Brand
A. C. Gehr
W. J. Stubblefield
W. G. Bingham
R. L. Patterson
R. W. Welcher
R. M. Grant
D. R. Hawkinson
L. E. Vorderbrueggen
G. A. Fiorelli
J. R. Bynum

Lynne Bernabei, Esq.
Harmon & Weiss
1725 "I" Street, NW
Washington, D. C. 20006

R. L. Greenfield
Assistant Attorney General
Bataan Memorial Building
Santa Fe, New Mexico 87503

General Electric Company
General Manager
Switchgear Business Division
6901 Elmwood Avenue
Philadelphia, Pennsylvania 19142

FINAL REPORT - DER 82-41
DEFICIENCY EVALUATION 50.55(e)
ARIZONA PUBLIC SERVICE COMPANY (APS)
PVNGS UNITS 1, 2 and 3

I. DESCRIPTION OF DEFICIENCY

During testing of class IE 4.16kv switchgear IE-PBA-S03 and IE-PBB-S04, two (2) conductors were found pulled from the crimped area of the termination lug barrel(s), and some of the crimped lugs within the equipment did not exhibit marks which identify correct use of crimping tools and dies.

The attached General Electric (GE) letter provides the criteria and corrective action for providing acceptable termination crimps in switchgear furnished by GE under Bechtel specification 13-EM-009. A followup random inspection performed by Bechtel Construction using GE criteria in Unit 3 switchgear (7 cubicles noted below) revealed that not all lug terminations were in compliance; however, no open circuits were apparent. In some cases, conductors were less than flush with the crimp connector barrel, and the ends of the wires were not visible under high intensity light and magnification.

<u>SWGR CUBICLE</u>	<u>TERM. BLOCK</u>	<u>TERM. POINT</u>
3E-PBS-S03S	RRF	H1
3E-PBS-S03N	RRF	H1
3E-PBB-S04L	SC	11
3E-PBB-S04L	RRF	X1
3E-PBB-S04M	SA	1
3E-PBB-S04M	RRF	X1
3E-PBB-S04P	SE	4
3E-PBB-S04F	RRF	X1
3E-PBB-S04R	SC	5
3E-PBB-S04R	SH	3
3E-PBB-S04R	DD	11

II. ANALYSIS OF SAFETY IMPLICATION

This condition is evaluated as Reportable. Connections with reduced contact area in termination lug barrels do not adequately assure the degree of electrical continuity required for reliable operations. If inadequately crimped lugs were left uncorrected, potential open circuits could jeopardize safety related functions of this switchgear.

III. CORRECTIVE ACTION

All vendor terminations utilizing crimp-type lugs in switchgear supplied by GE under specification 13-EM-009 shall be inspected for compliance to GE's visual criteria:

"The conductor shall be flush or protrude through the connector barrel up to approximately 1/16 inch."

Any connectors which do not meet this requirement shall be removed and have a new AMP connector installed in accordance with Bechtel's termination practices established in construction specification 13-EM-306 (including proper usage and traceability of crimping tools.).

This condition will be corrected via the following Design Change Packages:

10E-PG-015
20E-PG-015
30E-PG-015

In addition to reportability under 10CFR50.55(e), PVNGS Project considers this deficiency to be Reportable by the supplier under the requirements of 10CFR Part 21. Deficiency Evaluation Report 82-41 addresses the reporting requirements specified under 10CFR 21.21(b) (3) with the exception of sub-part (vi) which requires the number and location (customers and/or facilities) of other possible defective equipment. A copy of this report has been sent to GE requesting their review for reporting under 10CFR Part 21, including number and location of all components supplied.

GENERAL ELECTRIC



GENERAL ELECTRIC COMPANY, 9350 E. FLAIR DR., EL MONTE, CALIFORNIA 91734
 Phone: (213) 572-5200
 MAILING ADDRESS: P.O. BOX 2830, TERMINAL ANNEX, LOS ANGELES, CALIF. 90051

May 14, 1982

MT
MA 5/16/82

Bechtel Power Corporation
 P.O. Box 60850
 Terminal Annex
 Los Angeles, CA 90060

Attn: W. G. Bingham

Subj: ANPP
 4.16 kV Switchgear
 P.O. EM-009
 Your Feb. 25, 1982 Letter

Gentlemen:

The first item in your letter was answered in my 3-24-82 letters. The second item in your 2-25-82 letter concerned AMP connectors.

The conductor should be flush or protrude through the connector barrel up to approximately 1/16 inch. Any connectors which do not meet this requirement should have new AMP connectors installed.

Very truly yours,

L. R. Fickel
 Sales Engineer

/b1

cc: Bob Welsher - Bechtel
 M. Torikian - Bechtel

Enclosure (2)

TK

ELECTRIC UTILITY

SALES DIVISION

166885
 JOB 10607
 FILE EM-009
 MAY 14 '82

B	FILE NAME	A
	RESUME	
	APL BIRTH	
	APL MARRIAGE	
	APL APT	
	PE BIRTH	
	COOP 1	
	COOP 2	
	PL	
	PL EMP 500	
	PA	DA
	MECH	
	LS	
	CON TALK	
	BIRTH	
	RED	
	RECLIM	
	PAN DESIGN	
	STR & SUP	
	CLERK	
	PC FILE	

NCE E-J-2197
2201
5/18/82
3/8/83