LICENSEE EVENT REPORT

• • •	CONTROL BLOCK: [] [] (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1	G A E I H 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5 67 CAT 58 5
CON'T 0 1 3	REPORT LL 6 0 5 0 0 0 3 2 1 7 1 1 0 7 8 2 8 12 0 2 8 2 9 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10 With the plant in cold shutdown for refueling, the liquid radwaste dis-
0 2	
0 3	charge monitor auto control to the discharge isolation valve was found
0 4	to have been inoperable during a liquid radwaste discharge. This event
0 5	is contrary to ETS Table 2.1-3. However, the Radwaste Discharge Monitor
0 6	Alarm function remained operable, and thus the capability to monitor
0 7	discharges was maintained. Plant operation was not affected. The health
0 8	and safety of the public were not affected by this non-repetitive event.
0 9	SYSTEM CAUSE CODE SUBCODE COMPONENT CODE SUBCODE SUBCO
	THE Cause of this event was attributed to a jumper not being removed
	after completion of corrective maintenance. The jumper was removed and
1 2	the isolation valve returned to normal operable status. Responsible
1 3	personnel have been counseled as to the importance of returning the
1 4	system to the normal mode of operation.
1 5	FACILITY SPOWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 H 28 0 0 0 0 29 NA B 31 Surveillance Test 9 10 12 13 NA 44 45 46 80
	ELEASED OF RELEASE AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36
1 7	PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39) O O O O (37) A (38) NA PERSONNEL INJURIES NA 80
1 8	NUMBER DESCRIPTION (41) O O O O O O O O O O O O O O O O O O O
1 9	Z 42 NA
7 8	9 10 8212210088 821202 PDR ADOCK 05000321 S PDR 9 10 68 69 80 80 5
	NAME OF PREPARER S. B. Tipps PHONE (912) 367-7851 a