# LICENSEE EVENT REPORT

	CONTROL BLOCK:
اداه	VIAISIPISINO 0101-1010101010101010101010101010101010
1	S LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT SE
OIO	SOURCE L 60 01 5 0 0 0 0 2 8 0 7 1 1 1 2 1 8 2 8 1 2 1 3 8 2 6 9 EVENT DATE 80
	On November 21, 1982, radiation menitor recorder (RR-175) was found to be
0121	
1	inoperable. This is contrary to T.S.3.11.B.4 and 4.9C and is reportable per
014	T.S.6.6.2.b(4). All releases in progress were terminated immediately. The
0 5	associated radiation monitors, including the alarms and automatic actuating
0 16	functions, were operable. Therefore, the health and safety of the public would
017	not have been affected.
1 8	9 CAUSE CAUSE COMPONENT CODE SUBCODE SUBCODE
0 9	CODE SUBCODE COMPONENT CODE SUBCODE SU
7 6	SEQUENTIAL OCCURRENCE REPORT REVISION NO.
	1 ASPORT   8   2
	ACTION FUTURE EFFECT SHUTDOWN HOURS (22) ATTACHMENT NPRD4 PRIME COMP. COMPONENT MANUFACTURER
	TAKEN ACTION OF LANT METHOD IN 19 19 19 19 19 19 19 19 19 19 19 19 19
	B 18 Z 19 Z 20 Z 21 10 10 10 Q Y 23 N 24 A 25 H 2 6 0 26 CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27
10	B 15 Z 19 Z 20 Z 21 10 10 10 1 Y 23 N 24 A 25 H 2 6 10 26
10	B 18 Z 19 Z 20 Z 21 10 10 10 Q Y 23 N 24 A 25 H 2 6 0 26 CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27
110	LB 18 Z 19 Z 20 Z 35 D 10 D D Y 23 N 24 A 25 H 2 6 D 26 CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27  The inoperability was caused by a slipped drive cable. The drive cable was
	LB 18 Z 19 Z 20 Z 35 D 10 D D Y 23 N 24 A 25 H 2 6 D 26 CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27  The inoperability was caused by a slipped drive cable. The drive cable was
112	B 18 Z 19 Z 20 Z 35 10 0 0 0 0 Y 20 N 24 A 25 H 2 6 0 26 A 25 CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27  The inoperability was caused by a slipped drive cable. The drive cable was  re-installed and the recorder returned to service.
1 1 2	B (5) Z (9) Z (20) Z (30) D (0) D (1) Z (40) A (20)
1 1 2	B (B) (Z (9) (Z (20) (3) (10) (0) (40) (1) (20) (41) (20) (41) (42) (42) (42) (43) (42) (43) (42) (43) (42) (43) (42) (43) (43) (44) (43) (44) (43) (44) (43) (44) (43) (44) (43) (44) (43) (44) (43) (44) (45) (44) (45) (46) (47) (47) (47) (47) (47) (47) (47) (47
1 1 2 1 3 1 4 7 8 7 8	B 18 Z 19 Z 20 Z 20 J 10 0 0 0 Y 20 N 24 A 25 H 2 6 0 25 A 25 CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27  The inoperability was caused by a slipped drive cable. The drive cable was  re-installed and the recorder returned to service.    The inoperability was caused by a slipped drive cable. The drive cable was   10 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
1 1 2 1 3 1 4 7 8	B 15 Z 3 Z 30 Z 35 35 37 40 41 2 6 0 25 35 CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27 The inoperability was caused by a slipped drive cable. The drive cable was re-installed and the recorder returned to service.    The inoperability was caused by a slipped drive cable. The drive cable was re-installed and the recorder returned to service.    The inoperability was caused by a slipped drive cable. The drive cable was   10 0 0 30 N/A   10 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
1 1 2 1 3 1 4 7 8 7 8	B 18  Z 19  Z 20  Z 20   35  Z 20  Z
1 1 2 1 3 1 4 7 8 7 8	B (B) Z (9) Z (20) (10 0 0 0 1 1 20) M (20)
1 1 2 1 3 1 4 7 8 7 8	B (S) Z (9) Z (20) Z (20) 30 0 0 0 0 41 (20) M (20)
1 1 2 1 3 1 4 7 8 7 8	B (B) Z (B) 2 (B) 2 (B) 32 (B)
1 1 2 1 3 1 4 7 8 7 8	B (S) Z (9) Z (20) Z (20) D (0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
1 2 1 3 1 4 7 8 1 5 7 6	B (3) Z (3) 32 33 32 33 33 33 33 33 33 33 33 33 33
1   2   1   3   1   4   7   8   1   6   7   8   1   9	B (S) Z (S)

ATTACHMENT 1

SURRY POWER STATION, UNIT NO. 1

DOCKET NO: 50-280

REPORT NO: 82-113/03L-0 EVENT DATE: 11-21-82

TITLE OF THE EVENT: RR-175-MALFUNCTION

#### 1. Description of the Event

With Unit 1 and 2 operating steady state at 100% power, radiation monitor recorder (RR-175) was found to be inoperable. This is contrary to T.S.3.11.B.4 and T.S.4.9.C and is reportable as per T.S.6.6.2.b(4).

# 2. Probable Consequences and Status of Redundant Equipment

The radiation monitor recorder (RR-175) serves to record, for permanent record, the gross activity of liquids and gases being released. The recorder, in itself, does not mitigate the consequences of any system malfunction. The associated radiation monitors, including the alarm and automatic actuating functions, remained operable. The discharge tunnel radiation monitor and its recorder remained operable, therefore, the health and safety of the public were not affected.

#### 3. Cause

The recorder became inoperable due to a slipped drive cable.

### 4. Immediate Corrective Action

The immediate corrective action was to terminate all releases that were in progress.

# 5. Subsequent Corrective Action

The drive cable was replaced and the recorder was returned to service.

# 6. Actions Taken to Prevent Recurrence

Preventative maintenance is performed on these recorders at least once per month, therefore, no additional actions are deemed necessary.

### 7. Generic Implications

This is a random event and is not considered to be generic.