

LICENSEE EVENT REPORT

CONTROL BLOCK: \_\_\_\_\_ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | M | S | G | G | S | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33  
LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 58

CON'T  
0 1 | REPORT SOURCE | L | 6 | 0 | 5 | 0 | 0 | 0 | 4 | 1 | 6 | 7 | 1 | 1 | 2 | 4 | 8 | 2 | 8 | 1 | 2 | 2 | 8 | 8 | 2 | 9  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33  
DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)  
0 2 | On November 24, 1982, fire doors OC408 and OC706 (RPS Motor-Generator Set rooms A  
0 3 | and B) were blocked open to aid in room ventilation. A continuous fire watch was  
0 4 | established in accordance with T.S.3.7.7.a. The event had no effect on the health  
0 5 | and safety of the public and did not constitute a threat to plant safety. This is  
0 6 | submitted as a Special Report pursuant to T.S.3.7.7.a.  
0 7 |  
0 8 |

0 9 | SYSTEM CODE: A B (11) CAUSE CODE: X (12) CAUSE SUBCODE: Z (13) COMPONENT CODE: X X X X X X X (14) COMP. SUBCODE: Z (15) VALVE SUBCODE: Z (16)  
7 8 9 10 11 12 13 14 15 16 17 18 19 20  
17 | LER/RO REPORT NUMBER: 8 2 (21) SEQUENTIAL REPORT NO.: 1 4 7 (24) OCCURRENCE CODE: 9 9 (28) REPORT TYPE: X (30) REVISION NO.: 0 (32)  
21 22 23 24 25 26 27 28 29 30 31 32  
ACTION TAKEN: X (33) FUTURE ACTION: Z (34) EFFECT ON PLANT: Z (35) SHUTDOWN METHOD: Z (36) HOURS: 0 0 0 0 (37) ATTACHMENT SUBMITTED: N (40) NPRD-4 FORM SUB.: N (42) PRIME COMP. SUPPLIER: Z (43) COMPONENT MANUFACTURER: Z 9 9 9 (44)  
33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)  
1 0 | The fire doors were opened due to rising temperatures caused by inoperability of the  
1 1 | Plant Chilled Water (PCW) system which is the cooling supply to the Motor-Generator  
1 2 | Set room HVAC equipment. PCW was not operable due to shutdown of Plant Service Water  
1 3 | for support of the Standby Service Water System hydro test. The doors were restored  
1 4 | to operability on December 9, 1982. This is a final report.

1 5 | FACILITY STATUS: B (28) % POWER: 0 0 0 (29) OTHER STATUS: NA (30) METHOD OF DISCOVERY: A (31) DISCOVERY DESCRIPTION: Planned Activity (32)  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

1 6 | ACTIVITY CONTENT: Z (33) Z (34) AMOUNT OF ACTIVITY: NA (35) LOCATION OF RELEASE: NA (36)  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

1 7 | PERSONNEL EXPOSURES: 0 0 0 (37) TYPE: Z (38) DESCRIPTION: NA (39)  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

1 8 | PERSONNEL INJURIES: 0 0 0 (40) DESCRIPTION: NA (41)  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

1 9 | LOSS OF OR DAMAGE TO FACILITY: Z (42) DESCRIPTION: 8301040084 821228 PDR ADOCK 05000416 S PDR (43)  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

2 0 | PUBLICITY ISSUED: N (44) DESCRIPTION: NA (45) NRC USE ONLY  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

GPO 91 7-926