LICENSEE EVENT REPORT UPDATE REPORT - PREVIOUS

| • | REPORT DATE 9/23/80 |
|-------|--|
| 1-7 | ODNTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION) |
| 0 1 | G A E I H 1 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5 6 57 CAT 58 |
| O 1 8 | REPORT LL 6 0 5 0 0 0 3 2 1 7 0 9 0 2 8 0 8 1 2 2 3 8 2 9 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) |
| 0 2 | [With the unit operating steady-state at 2389 MWt, all points of Drywell] |
| 0 3 | Temperature Recorder R612 were found to be reading high. The recorder |
| 0 4 | was declared inoperable. Tech. Specs Section 4.2.1. requires two |
| 0 5 | operable instrument channels. Plant operation was placed in a 30-day LCO |
| 0 6 | Redundant recorder R611 was operable. The health and safety of the |
| 0 7 | public were not affected by this repetitive event (as last reported on) |
| 0 8 | LER 50-321/1980-089). |
| 0 9 8 | SYSTEM CAUSE CODE SUBCODE COMPONENT CODE SUBCODE SUBCO |
| | ACTION FUTURE EFFECT SHUTDOWN HOURS 22 ATTACHMENT SUBMITTED FORM SUB. SUPPLIER MANUFACTURER C 18 Z 19 Z 20 Z 21 D 0 0 0 0 N 23 N 24 EA 25 T 0 3 PRIME COMP. CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27 |
| 1 0 | The cause of this event has been attributed to instrument drift. The |
| 11 | instrument was recalibrated, functionally tested satisfactorily, and |
| [][2] | returned to service. Because of the poor reliability of this recorder, |
| 1 3 | a design change was implemented replacing the old recorder with a Model |
| 1 4 | L&N-250 on 05/22/81. |
| | E 28 0 9 8 29 NA B OPERATOR OF DISCOVERY DESCRIPTION 32 |
| 1 6 A | 9 10 12 13 44 45 46 80 CTIVITY CONTENT AMOUNT OF ACTIVITY (35) AMOUNT OF ACTIV |
| 1 7 | NUMBER OF STATE OF ST |
| 1 B | NUMBER DESCRIPTION (41) NA 9 11 12 LOSS OF OR DAMAGE TO FACILITY (43) |
| 1 9 | Z @ NA |
| 4 | PUBLICITY PDR ADOCK 05000321 SSUED DESCRIPTION 45 S NA PDR |
| 7 19 | 9 10 68 69 80 5 S B Tipps (912) 367-7851 9 |