BOSTON EDISON Pligrim Nuclear Power Station Rocky Hill Road Plymouth, Massachusetts 02360

R. A. Anderson Vice President & Station Director Nuclear Operations

February 13, 1991 BECo Ltr. #91-014

U.S. Nuclear Regulatory Commission Attention: Document Control Desk Washington, DC 20555

> License No. DPR-35 Docket No. 50-293

Subject: January 1991 Monthly Report

Dear Sir:

· . · · · .

In accordance with PNPS Technical Specification 6.9.A.2, a copy of the Operational Status Summary for Pilgrim Nuclear Power Station is attached for your information and planning. Should you have any questions concerning this report please contact me directly.

R.A. Anderson

TEZ

WJM/bal

Attachment

cc: Regional Administrator, Region 1 U.S. Nuclear Regulatory Commission 475 Allendale RC. King of Prussia, PA 19406

Senior Resident Inspector

9102140188 910131 PDR ADOCK 05000293 R PDR

AVERAGE DAILY UNIT POWER LEVEL

DOCKET NO.	50-	293	
UNIT	Pil	grim 1	
DATE	Febru	ary 13,	1991
COMPLETED	BY W.	Munro	
TELEPHONE	(508) 747-84	74

MONTH	Jan	uary	1991
			and the second sec

1.4.4

DAY	AVERAGE DAILY POWER LEVEL (MWe-Net)	DAY	AVERAGE DAILY POWER LEVEL (MWe-Net)
1	355	17	664
2	475	18	664
3	505	19	663
4	630	20	665
5	664	21	665
6	662	22	664
7	663	23	665
8	663	24	665
9	664	25	663
10	654	26	663
11	628	27	665
12	620	28	664
13	664	29	664
14	665	30	664
15	664	31	663
16	664		

This format lists the average daily unit power level in MWe-Net for each day in the reporting month, computed to the nearest whole megawatt.

OPERATING DATA REPORT

DOCKET NO.	50-293
DATE	February 13, 1991
COMPLETED	BY W. Munro
TELEPHONE	(508) 747-8474

OPERATING STATUS

298 578 555 596 570 570 5 Number 3	Through 7) S	ince Last
A 101-5		
et Mwe)	None	
This Month	<u>Yr-to-Date</u>	Cumulative
744.0	744.0	159072.0
744.0	744.0	93344.7
744.0	744.0	89660.1
0.0	0.0	0.0
433016.0	1433016.0	16767165.0
493840.0	493840.0	52141354.0
100.0	4/5427.0	56.4
100.0	100.0	56.4
95.4	95.4	47.0
97.6		48.1
0.0	0.0	12.7
elv 70 davs	no buration	or Each):
	his Month 744.0 744.0 744.0 0.0 744.0 0.0 433016.0 493840.0 493840.0 475427.0 100.0 100.0 95.4 97.6 0.0 0 0,0 0 100.0 95.4 97.6 0.0 0 0 0,0 100.0 95.4 97.6 0.0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	it MWe) None None Yr-to-Date None Ythe None None None None None None None None None None None

25. If Shut Down At End Of Report Period, Estimated Date of Startup _____ N/A

BOSTON EDISON COMPANY PILGRIM NUCLEAR POWER STATION DOCKET NO. 50-293

Operational Summary for January 1991

The unit started the reporting period at approximately 76 percent power with the "C" Reactor Feedwater Pump (RFP) secured for repairs. On January 1, 1991 at 1000 hours a power reduction to approximately 50 percent was made to conduct a backwash of the main condenser, and to replace the brushes on the "A" Recirculation Motor Generator Set. At 2043 hours the "A" Recirculation Motor Generator Set was restarted, and by 0303 hours on January 2, 1993 reactor power was increased to 76 percent. On January 3, 1991 power was reduced to approximately 52 percent to perform a control rod pattern change. Power was again increased to 100 percent on January 4, 1991 and remained there until January 11, 1991 when at 2009 hours, maintenance personnel, welding on the turbine building exhaust fan above the "A" RFP, reported smoldering on the roof. Power was reduced to 70 percent and the "A" RFP was secured. An Unusual Event was declared at 2031 hours and terminated at 2201 hours. On January 12, 1991 the "A" RFP was returned to service, power was increased to 100 percent and remained there for the remainder of the reporting period. Power reductions to 90 percent were performed on January 6, 11, 19 and 26 for control rod exercising.

> Safety Relief Valve Challenges Month of January 1991

Requirement: NUREG-0737 T.A.P. II.K.3.3

There were no safety relief valve challenges during this reporting period.

An SRV challenge is defined as anytime an SRV has received a signal to operate via reactor pressure, auto signal (ADS) or control switch (manual). Ref. BECo Itr. #81-01 dated 01/05/81.

REFUELING INFORMATION

The following refueling information is included in the Monthly Report as requested in an NRC letter to BECo, dated January 18, 1978:

For your convenience, the information supplied has been enumerated so that, each number corresponds to equivalent notation utilized in the request.

- The name of this facility is Pilgrim Nuclear Power Station, Docket Number 50-293.
- 2. Scheduled date for next Refueling Shutdown: Second Quarter 1991
- 3. Scheduled date for restart following refueling: Third Quarter 1991
- Due to their similarity, requests 4, 5, & 6 are responded to collectively under #6.
- 5. See #6.
- The new fuel loaded during the 1986/87 refueling outage was of the same design as loaded in the previous outage, and consisted of 192 assemblies.
- 7. (a) There are 580 fuel assemblies in the core.
 - (b) There are 1320 fuel assemblies in the spent fuel pool.
- 8. (a) The station is presently licensed to store 2320 spent fuel assemblies. The actual usable spent fuel storage capacity is 2320 fuel assemblies.
 - (b) The planned spent fuel storage capacity is 2320 fuel assemblies.
- With present spent fuel in storage, the spent fuel pool now has the capacity to accommodate an additional 1000 fuel assemblies.

Month January 1991

PILGRIM NUCLEAR POWER STATION

MAJOR SAFETY RELATED MAINTENANCE

SYSTEM	COMPONENT	MALFUNCTION	CAUSE	MAINTENANCE	CORRECTIVE ACTION TO PREVENT RECURRENCE	ASSOCIATED
Feed- water System	"C" Reactor Feed- water Pump (RFP) suction relief valve standpipe.	Pipe cracked and leaking. (F&MR 90-426)	Physical contact of the two (2) inch outlet pipe with the wall caused a twist- ing moment on the inlet stand- pipe.	Installed Temporary Modification TM 91-01 consisting of a C ⁻¹ - lar welded together axially, and then welded around the "C" RFP suction relief valve (PSV-3444) inlet pipe. The two (2) inch outlet pipe was shortened to remove interference with the wall.	Replacement of inlet pipe during RFO-8.	N/A
Reactor Core Isola- tion Cooling System	Control cable bet- ween the Electronic Speed Controller (EGM) and the Electro-Hydraulic Valve Actuator (EGR)	Turbine tripped on high steam flow. (F&MR 91-33).	Faulty control cable due to environmental conditions res- ulting from seat leakage on MO 1301-61 valve.	Replaced control cable and signal con- verter card. Perform- ed Proc. 8.E.13.1 successfully to prove operability.	Refurbish MO1301-61 valve. (MR 19013040)	LER 91-001-00 (To be issued
Reactor Core Isola- tion Cooling System	Turbine Exhaust line.	Failed rupture disc PSD-9 (F&MR 90-128).	Extreme environ- mental condit- ions resulting from seat leak- age on MO1301- 61 valve.	Installed new rupture disc.	Refurbish MO1301-61 valve. (MR 19013040)	N/A

	UNIT	SHU	TDOWNS	AND	POWER	REDUCTI	ONS
--	------	-----	--------	-----	-------	---------	-----

DOCKET	NO. 50-293
NAME	Pilgrim 1
DATE F	ebruary 13, 1991
COMPLET	TED BY W. Munro
TELEPH	DNE (508) 747-8474

REPORT MONTH January 1991

NO.	DATE	TYPE1	DURATION (HOURS)	REASON ²	METHOD OF SHUTTING DOWN REACTOR ³	LICENSE EVENT REPORT #	SYSTEM CODE ⁴	COMPONENT CODE5	CAUSE & CORRECTIVE ACTION TO PREVENT RECURRENCE
18	01/01/91	F	0.0	N/A	5	N/A	N/A	N/A	Power reduction to backwash main condenser and replace brushes on "A" Recirc. MG set.

1	2	2	3	4&5	
F-Forced	A-Equip Failure	ıdmin	1-Manual	Exhibit F & H	
S-Sched	B-Maint or lest C-Refueling	G-Oper Error H-Other	2-Manual Scram 3-Auto Scram	Preparation of	
	D-Regulatory Restric	tion	4-Continued	Nata Entry Sheet	
	& License Examinat	ion	9-Other	(LER) File (NUREG-1022)	