Commonwealth Edison
Dresden Nuclear Power Station
R.R. #1
Morris, Illinois 60450
Telephone 815/942-2920

February 1, 1991

EDE LTR: #91-088

Director, Nuclear Reactor Regulation United States Nuclear Regulatory Commission Washington, DC 20555

Attention: Document Control Desk

Subject: Monthly Operating Data Report

Dresden Nuclear Power Station Commonwealth Edison Company

Docket Nos. 50-010, 50-237, and 50-249

Gentlemen:

Enclosed is the Dresden Nuclear Power Station Monthly Operating Summary Report for January, 1991. This information is supplied to your office in accordance with the instructions set forth in Regulatory Guide 1.16. Please note that the report contains information which had been previously submitted to your attention on an annual basis in accordance with 10CFR50.59.

Sincerely,

L. D. Eenigenburg for
Station Manager
Dresden Nuclear Power Station

EDE: DM: jws

Enclosure

cc: U.S. NRC Region III Office
Illinois Dept f Nuclear Safety, State of Illinois
U.S. NRC, Dorurent Management Branch
Nuclear Lineasing Administrator
Vice Prer. - BWR Operations
General Manager - Nuclear Services
T. S. ENGR. (2)
NRC Senior Resident Inspector
Nuclear Quality Programs - Dresden
Nuclear Engineering Manager
Comptroller's Office
D. Eggett - Reliability Programs
INPO Records Center
File/NRC Op. Data
File/Numerical

ZEDE/445 9102150269 910131 PDR ADDCK 05000010 RDR PDR (25)0369511 1524 MONTHLY NRC
SUMMARY OF OPERATING EXPERIENCE.
CHANGES, TESTS, AND EXPERIMENTS
PER REGULATORY GUIDE 1.16 AND 10 CFR 50.59
FOR

DRESDEN NUCLEAR POWER STATION COMMONWEALTH EDISON COMPANY FOR JANUARY, 1991

UNIT	DOCKET	LICENSE
1	050-010	DPR-2
2	050-237	DPR-19
3	050-249	DPR-25

TABLE OF CONTENTS

- 1.0 Introduction
- 2.0 Summary of Operating Experience
 - 2.1 Unit 2 Monthly Operating Experience Summary for January, 1991 2.2 Unit 3 Monthly Operating Experience Summary for January, 1991
- 3.0 Operating Data Statistics
 - 3.1 Monthly Operating Data Report Unit 2
 - 3.2 Monthly Operating Data Report Unit 3
 - 3.3 Average Daily Power Level Data Unit 2
 - 3.4 Average Daily Power Level "ata Unit 3
 - 3.5 Unit Shutdown and Power Reduction Data Unit 2
 - 3.6 Unit Shutdown and Power Reduction Data Unit 3
 - 3.7 Station Maximum Daily Load Data
- 4.0 Unique Reporting Requirements
 - 4.1 Main Steam Relief and/or Safety Valve Operations Unit 2 and Unit 3
 - 4.2 Off-Site Dose Calculation Manual Changes
 - 4.3 Major changes to the Radioactive W. . Treatment
 - 4.4 Failed Fuel Element Indications
 - 4.4.1 Unit 2
 - 4.4.2 Unit 3
- 5.0 Plant or Procedure Changes, Tests, Experiments, and Safety Related Maintenance
 - 5.1 Amendments to Facility License or Technical Specifications 5.1.1 Unit 2
 - 5.1.2 Unit 3
 - 5.2 Changes to Procedures Which are Described in the Final Safety Analysis Report (FSAR) (Units 2 and 3)
 - 5.3 Significant Tests and Experiments Not Described in the FSAR (Units 2 and 3)
 - 5.4 Safety Related Maintenance (Units 2 and 3)
 - 5.5 Completed Safety Related Modifications
 - 5.6 Temporary System Alterations
 - 5.6.1 Unit 2
 - 5.6.2 Unit 3

1.0 Introduction

Dresden Nuclear Power Station is a three reactor generating facility owned and operated by the Commonwealth Edison Company of Chicago, Illinois. Dresden Station is located at the confluence of the Kankakee and Des Plaines Rivers, in Grundy County, near Morris, Illinois.

Dresden Unit 1 is a General Electric Boiling Water Reactor with a design net electrical output rating of 200 megawatts electrical (MWe). The unit is retired in place with all nuclear fuel removed from the reactor vessel. Therefore, no Unit 1 operating data is provided in this report.

Dresden Units 2 and 3 are General Electric Boiling Water Reactors with design net electrical output ratings of 794 MWe each.

Waste heat is rejected to a man-made cooling lake using the Kankakee River for make-up and the Illinois River for blowdown.

The Architect-Engineer for Dresden Units 2 and 3 was Sargent and Lundy of Chicago, Illinois.

This report for January, 1991 was compiled by Donald C. Maxwell of the Dresden Technical Staff, telephone number (815)942-2920 extension 2489.

2.0 SUMMARY OF OFERATING EXPERIENCE OR JANUARY, 1991

2.1 UNIT 2 MONTHLY OPERATING EXPERIENCE SUMMARY

01-01-91 to 01-31-91

Unit 2 remained off-line during the month of January for its 12th Refueling Outage. Major work during the month included:

- In-Service Inspection (ISI) of various Primary System Piping.
- Normal Refueling Outage related work.
- Local Leak Rate Testing of various Primary Containment Valves and Components

The Unit 2 reactor was made critical on January 4, 1991, and reactor heatup and pressurization followed. In the course of turbine roll, a bearing problem resulted in the turbine being manually tripped. The reactor was subsequently shutdown. Turbine bearing repairs were begun, and the month ended with repairs in progress. Further, with the unit shutdown, a decision was made to replace the Recirculation Pump 2A shaft. This replacement activity was also in progress at the end of January.

SUMMARY OF OPERATING EXPERIENCE FOR JANUARY, 1991

2.2 UNIT 3 MONTHLY OPERATING EXPERIENCE SUMMARY

01-01-91 to 1-31-91

Unit 3 entered the month on-line and operating in Single Loop Operation at 330 MWe. The 3B Recirculation Pump motor had experienced high vibration and was idle. On 1-13-91 at 1105 hours the Unit was taken off-line to repair the 3B Recirculation Pump motor and the Reactor was made sub-critical at 1525 hours of the same day.

The unit remained off-line the remainder of the month while repairs to the 3B Recirculation Pump motor were being done. Capacity factor of the unit was 15.8% and the availability factor was 40.2%.

3.0 OPERATING DATA REPORT

3.1 OPERATING DATA REPORT - UNIT TWO

DOCKET KO. 050-237

DATE February 1, 1991

COMPLETED BY D. C. Maxwell

TELEPHONE (815) 942-2920

OPERATING STATUS

- 1. REPORTING PERIOD: January, 1991
- 2. CURRENTLY AUTHORIZED FOWER LEVEL (MWth): 2,527 MAX DEPEND CAPACITY (Mwe-Net) 772
 DESIGN ELECTRICAL RATING (Mwe-Net) 794
- 3. POWER LEVEL TO WHICH RESTRICTED (IF ANY) (MWe-Pat), 4/4
- 4. REASONS FOR RESTRICTIONS (IF ANY): N/A

		F	EPORTING PERIO	DD DATA
		This Month	Yr-to-Date	Cumulative
5.	HOURS IN FERIOD	744	744	181,632
6.	TIME REACTOR CRITICAL (HOUKS)	48.1	48.1	136,787.0
7.	TIME REACTOR RESERVE SHUTDOWN (HOURS)	0.0	0.0	0.0
8.	TIME GENERATOR ON-LINE (HOURS)	0.0	0.0	130,972.8
9.	TIME GENERATOR RESERVE SHUTDOWN (HOURS)	0.0	0.0	0.0
0.	THERMAL ENERGY GENERATED (MWHt-GROSS)	0	0	271,604,143
1.	ELECTRICAL ENERGY GENERATED WHE GROSS)	0.0	Ć.	86,805,777
2.	ELECTRICAL ENERGY GENERATED (MWHe-NET)	-7,611	-7,611	82,059,950
3.	REACTOR SERVICE FACTOR (%)	6.5	6.5	75.3
4.	REACTOR AVAILABILITY FACTOR (%)	6.5	6.5	75.3
5.	SERVICE FACTOR (%)	0.0	0.0	72.1
6.	AVAILABILITY FACTOR (%)	0.0	0.0	72.1
7.	CAPACITY FACTOR (USING MDC) (%)	0.0	0.0	58.5
8.	CAPACITY FACTOR (USING DESIGN MWe) (%)	0.0	0.0	56.9
9.	FORCED OUTAGE FACTOR (%)	0.0	0.0	10.7

20. SHUTDOWNS SCHEDULED OVER THE NEXT 6 MONTHS (TYPE, DATE AND DURATION OF EACH)

NONE

21. IF SHUTDOWN AT END OF REPORT PERIOD, ESTIMATED DATE OF STARTUP 02-06-91

3.0 OPERATING DATA PEPORT

3.2 OPERATING DATA REPORT - UNIT THREE

DOCKET NO. 050-249
DATE February 1, 1991
COMPLETED BY D.C. Maxwell
TELEPHONE (815) 942-2920

OPERATING STATUS

- 1. REPORTING PERIOD: January, 1991
- 2. CURRENTLY AUTHORIZED POWER LEVEL (MWth): 2,527 MAX DEPEND CAPACITY (MWe-Net) 773
 DESIGN ELECTRICAL RATING (MWe-Net) 794
- 3. FOWER LEVEL TO WHICH RESTRICTED (IF ANY) (MWe-Net): N/A
- 4. REASONS FOR RESTRICTIONS (IF ANY): N/A

REPORTING PERIOD DATA

		AND AND THE PART AND AND AND AND AND AND AND AND AND	we have not seen any security over the seen and that the	THE R. S. SEC. SEC. SEC. SEC. SEC. SEC. SEC.
		This Month	Yr-to-Date	Cumulative
5.	HOURS IN PERIOD	744.0	744	171,217
6.	TIME REACTOR CRITICAL (HOURS)	305.7	305.0	127,992.8
7.	TIME REACTOR RESERVE SHUTDOWN (HOURS)	0.0	0.0	0.0
8.	TIME GENERATOR ON-LINE (HOURS)	299.1	299.1	119,934.6
9.	TIME GENERATOR RESERVE SHUTDOWN (HOURS)	0.0	0.0	0.0
10.	THERMAL ENERGY GENERATED (MWHt-GROSS)	335,978	335,978	248,685,265
11.	ELECTRICAL ENERGY GENERATED (MWHe GROSS)	97,935	97,935	80,202,891
12.	ELECTRICAL ENERGY GENERATED (MWHe-NET)	86,370	86,370	76,080,779
13.	REACTOR SERVICE FACTOR (%)	41.0	41.0	74.8
14.	REACTOR AVAILABILITY FACTOR (%)	41.0	41.0	74.8
15.	SERVICE FACTOR (%)	40.2	40.2	70.1
16.	AVAILABILITY FACTOR (%)	40.2	40.2	70.1
17.	CAPACITY FACTOR (USING MDC) (%)	15.0	15.0	57.5
18.	CAPACITY FACTOR (USING DESIGN MWe) (%)	14.6	14.6	56.0
19.	FORCED OUTAGE FACTOR (%)	0.0	0.0	11.6

- 20. SHUTDOWNS SCHEDULED OVER THE NEXT 6 MONTHS (TYPE, DATE AND DURATION OF EACH)
 - 1. Refuel Outage (D3R12) scheduled to begin March 31, 1991.
- 21. IF SHUTDOWN AT END OF REPORT PERIOD, ESTIMATED DATE OF STARTUP 2/10/91

3.3 AVERAGE DAILY UNIT POWER LEVEL

DOCKET NO. 050-237

			UNIT_II
			DATE February 1, 1991
		COL	MPLETED BY D. C. Maxwell
MONTH	JANUARY, 1991		TELEPHONE 815/942-2920
DAY	AVERAGE DAILY POWER LEVEL (MWe-Net)	DAY	AVERAGE DAILY POWER LEVEL (MWe-Net)
1	0	17	0
2	0	18	0
3	0	19	0
4	00	20	0
5	QQ	21	0
6	0	22	0
7	0	23	0
8	0	24	0
9	0	25	0
10	0	26	0
11	0	2.7	0
12	0	28	0
13	0	29	0
14	0	30	0
15	0	31	0
16	0		
15		31	0

3.4 AVERAGE DAILY UNIT POWER LEVEL

DOCKET NO. 050-249

UNIT III

DATE February 1, 1991

COMPLETED BY D. C. Maxwell

TELEPHONE 815/942-2920

MONTH			
DAY	AVERAGE DAILY POWER LEVEL (MWe-Net)	DAY	AVERAGE DAILY POWER LEVEL (MWe-Net)
1	313	17	0
2	311	18	0
3	310	19	0
4 _	310	20	0
5	303	21	0
6 _	297	22	0
7 _	299	23	0
8	298	24	0
9	307	25	0
10 _	310	26	0
11	310	27	0
12	309	28	0
13	117	29	0
14	0	30	0
15 _	0	31	0
16 _	0		

3.5 UNIT SHUTDOWNS AND POWER REDUCTIONS

DOCKET NO. 050-237
UNIT MAME DRESDEN UNIT II
DATE February 1, 1991
COMPLETED BY D. C. Maxwell
TELEPHONE (815)942-2920

REPORT MONTH JANUARY, 1991

NO.	DATE	TYPE ¹	DURATION (HOURS)	REASON ²	METHOD OF SHUTTING DOWN REACTOR ³	LICENSEE EVENT REPORT #	SYSTEM CODE	COMPONENT	CAUSE & CORRECTIVE ACTION TO PREVENT RECURRENCE
4	09-23-90	S	744.0	C	1	N/A	N/A	N/A	Off-line for 12th Refueling Outage.

F: Forced

ZR18/630/10

2 Reason:

S: Scheduled A-Equipment Failure (Explain)

B-Maintenance or Test

C-Refueling

D-Regulatory Pestriction

E-Operator Training & Licensee Examination

F-Administrative

G-Operational Error

H-Other (Explain)

Method:

1-Manual

2-Manual Scram

3-Automatic Scram

4-Other (Explain)

5-Load Reduction

Exhibit G-Instructions for Preparation of Data

Preparation of Data Entry Sheets for Licensee Event Report (LER) File

(NUREG-0161)

5 Exhibit I - Same Source

3.6 UNIT SHUTDOWNS AND POWER REDUCTIONS

DOCKET NO. 050-249

UNIT NAME DRESDEN UNIT III

DATE February 1, 1991

COMPLETED BY D. C. Maxwell

TELEPHONE (815)942-2920

REPORT MONTH JANUARY, 1991

NO.	DATE	TYPE	DURATION (HOURS)	REASON ²	METHOD OF SHUTTING DOWN REACTOR ³	LICENSEE EVENT REPORT #	SYSTEM CODE	CODE	CAUSE & CORRECTIVE ACTION TO PREVENT RECURRENCE
0	01-13-91	S	444.9 (444:55)		1	N/A	AD	MO	3B Recirc Pp Motor High V gration repair.

2 Reason:

F: Forced S: Scheduled

ZR18/643/11

ceason:

A-Equipment Failure (Explain)

B-Maintenance or Test

C-Refueling

D-Regulatory Restriction

E-Operator Training & Licensee Examination

F-Administrative

G-Operational Error

H-Other (Explain)

3

Method:

1-Manual

2-Manual Scram

3-Automatic Scram

4-Other (Explain)

5-Load Reduction

- 20

Exhibit G-Instructions for Preparation of Data Entry Sheets for Licensee Event Report (LER) File

(NUREG-0161)

5 Exhibit I - Same Source

3.7 COMMONWEALTH EDISON COMPANY - DRESDEN NUCLEAR POWER STATION MAXIMUM DAILY ELECTRICAL LOAD FORM FOR THE MONTH OF JANUARY, 1991

Day	Hour Ending	kWe
1	1400	337,700
2	0100	336,300
3	0200	334,500
4	0400	334,600
5	0900	334,400
6 7	0300	334,000
	0400	323,300
8	2200	323,400
9	1300	335,500
10	0100	334,200
11	1700	333,300
12	1500	333,000
13	0700	332,600
14	N/A	0
15	N/A	0
16	N/A	0
17	N/A	0
18	N/A	0
19	N/A	0
20	N/A	0
21	N/A	0
22	N/A	- 0
23	N/A	0
24	N/A	0
25	N/A	0
26	N/A	0
27	N/A	0
28	N/A	0
29	N/A	0
30	N/A	0
31	N/A	0

4.0 UNIQUE REPORTING REQUIREMENTS

4.1 MAIN STEAM RELIEF VALVE OPERATIONS

Relief valve operations during the reporting period, January, 1991, are summarized in the following table. The table includes information as to which relief valve was actuated, how it was actuated, and the circumstances resulting in its actuation.

Unit	Date	Values Actuated	No. and Type of Actuations	Plant Conditions	Description of Events
2	1-5-91	2-203-3A 2-203-3B 2-203-3C 2-203-3D 2-203-3E	2, Manual 2, Manual 2, Manual 2, Manual 2, Manual	Start-up Start-up Start-up Start-up Start-up	Relief valves were lifted during performance of Dresden Operating Surveillance Surveillance (DOS) 250-5, Automatic Blowdown System Test at Low Pressure and Rated Pressure.

3 No Unit 3 Main Steam Relief and/or Safety Valve actuations occurred during this reporting period.

4.2 OFF-SITE DOSE CALCULATION MANUAL (ODCM) CHANGES

No ODCM changes were reported for the month of January, 1991. However, On-Site Review No. 90-21 was conducted, which proposed revision of the ODCM to contain the Radiological Effluent Technical Specifications (RETS) in accordance with NRC Generic Letter 89-01. Off-Site Review, Nuclear Licensing, and Corporate Emergency Preparedness are reviewing this change as of the date of this report. Further, minor changes to the ODCM are required for approval. None of the changes will reduce the accuracy or reliability of dose calculations or setpoint determinations.

4.3 MAJOR CHANGES TO THE RADIOACTIVE WASTE TREATMENT SYSTEMS during January 1991

In 1991 the Radwaste Upgrade will continue with installation of 10" and 12" Equipment Drain and Floor Drain Tank Inlet Headers.

DRESDEN UNIT 2 SAFETY RELATED MAINTENANCE

EQUIPMENT	NA1.E OF MAINTENANCE	LER DR OUTAGE NUMBER	MALFUNC EAUSE	TION RESULT	EGREECTIVE ACTION
2-1501-2A 2A CCSW DISCH VALVE	CORRECTIVE WK D70156	H/A			REPLACED DISC MELDED AND GROUND GUIDES, REASSEMELED VALVE STROKE AND SET NEW PACKING
0-2 220-629	PREVENTIVE WR ERRIPSR	N/A			REMOVED BONNET. INSTALLED NEW OIL RING. NEW DISC RING ASSEMBLY. LOCK MIRED POLTS
2-022-2	CORRECTIVE MR D82143	R/A			REPLACED PUSH BUTTON STATION, LUGS, RUBBER GASKET AND BULBS
2-2301-28 U-2 HPC1 DRN POY	DY - MEETIVE MR D82665	N/A			REPLACED VALVE
24 DRYMELL COOLER SLOWER	PREVENTIVE WR D04057	N/A			CLEANED. CHECKED. LUBRICATED BREAKER
2TB-A-17, 19, B18, 20 U-2 JUNCTION BOXES	CORRECTIVE WK D04999	N/A			INSTALLED NEW TERMINAL BLOCKS INTO THE 4 JB'S 27B-A17, 27B 818, 27B A19, 27B B20 PER STATION TRAVELER
2F DRYWELL COOLER BLOWER 4800 CB	PREVENTIVE WR D05070	N/A			DID INSPECTION 8 MAINTENANCE ON BREE., CLEANED, CHANGED OUT BREAKER CONTACTS DUE TO POOR WIPE, CHANGED OUT ARE DASH
2-1501-35 TORUS X-FER ISOLATION VALUE	CORRECTIVE WR D05311	N/A			POTS DUE TO LEAKAGE REMOVED OLD HARD PACKING AND INSTALLED NEW
2-5746-A 2A 2PCI FOOM COOLER	PREVENTIVE WR D86112	N/A			REMOVED BUARD AND BELTS, REMOVED AND REPLACED BEARINGS, REMOVED FILTERS AND CLEANED FILTERS AND COILS, REPLACED FILTERS & HOOKED UP BELTS AND GUARD
2-2301-36 MOV	PREVENTIVE MR 086756	N/A	-		REPLACED SPRING PACK AGM

SAFETY RELATED MAINTENANCE

2-203-18 D-2 IB WSIV	2-203-1E 0-2 18 MSIV 10	2-203-38 0-2 8 ELECTROMATIC	2-203-3C 2C ELECTROMATIC	2-203-30 20 FLECTROMATIC	2-203-3E 2E ELECTROMATIC	2-220-1	2-220-2	2-2301-46 0-2 03L0 POV-2301-46	2-2301 U-2 HPCI AUX DIL STAFF	EQUIPMENT
82	83	¥2	E 2	52		F.2	52	82	57	
PREVENTIVE WK 590330	PREVENTIVE #R 1990829	WE DESCRIPTION	PREVENTIVE BP0826	PREVENTIVE MR DROBUS	PREVENTIVE NR DROS24	PREVENTIVE MI DP6823	HE CHOSE?	PREVENTIVE WR D90710	PRECENTAR MR D90332	MATURE OF
N/A	26/16	87/8	H/A	NVA	W/W	N/A	MIA	N/A	8//8	LER OR OUTAGE
										MALFUNCTION CAUSE RESULT
CLEANID GHISE POSTS AND STEM: ALSO FILED OUT WICKS AND BUNGS FILE SMOOTH	CLEANED BURDE FOSTS AND STEM, FILED OUT WICKS AND BURES TILL SMUGTH	REMOVED AND REPLACED PILST ON LIEUTROMATIC FOLLOWING ALL PERTINANT STES IN DWF 0200-35. ADDRESSED ALL HOLD	REMOUSD DED VALUE: CLEANED GASKET SURFACE: REPLACED WITH REBUILT VALUE	REMOUTD AND REPLACED PILOT FOLLOWING ALL PERTIDANT STEES IN DMP 0200-35	REMOVED MAIN WALVE SM SK 7802* REPLACED WITH REBUILT SK 2079	AELUSTED PROKING AND LUBED STEM	ADJUSTED PACKING AND DERIFIED NO LEAKAGE, LUEED STEM	REPLACED AIR BIAPHRAGM, PACKING, SPRING ADJUSTER AND INSTALLED NEW GASKET	REPLACED 2ND STAGE IMPELLER WITH MEN	CORRECTIVE ACTION

SAFETY RELATED HAINTENLACE NATURE OF LEE OF OUTAGE HAINTENLACE MAINTENANCE HUMBER CAUSE OF

2-1501-21A	PREVENTIVE	N/A	CAUSE	EE508.T	PERFORMED THE LIMITORDER OPERATOR
302	WE 007019				MAINTENANCE DEP 0040-09, ALSO FERFORMED THE ED MAINTENANCE
2-2301-31 UALVE	PREVENTIVE MR D88002	8/8			CEMPONENTS
T-5506-08 W-3506-08	CORRECTIVE WK DOS410	9/8			REMOVED AND INSTALLED 2 NEW ANCHORS
2-2306 HFCI FLOW MBU SIEWAL CONVERTER	CORRECTIVE MR DROSSING	W/W			REPLACED CAPACITORS 3C AND 4C MITH LIKE FOR LIKE, VERIFIED ACCEPTAGE BE VOLTAGE AND 4C RIPPLE TESTED CORCUIT
2-33178-12**-L	PREVENTIVE MR 589142	N/A			INSTALLED NEW BASE PLATES AND ANCHOR BOLTS PER MUTECH DRAWING M-3204-10 SHEETS 1-3
2-M0-2301-8 D-2 2301-8	FREVENTIVE MR D09227	W/K			REMOVED» CHECKED» AND REASSEMELED PARIS
62P(5# #1	CORRECTIVE WE 109954	N/A			REPLACED THE METER FUNCTION SWITCH
2-2322-1"-8 H9CI STEAM LINE (DRAIN FOT TO COMMENSER) UNIT 2	PREVENTIVE MR 090140	8/4			CUT OUT AFFECTED FIFTING REQUIREST TO ELIMINATE BOTH FERMINITE ENCLOSURES, FABRICATED NEW PIPING ASSEMBLY & INSTALL LINE WAS KEINSDEATED
2-1501-114	CDRSECTIVE SE 090205	N/A			REPACKED VALUE WITH NEW PACKING
2-2301-3	PREVENTIVE MR 090202	8/6			ADDED I HIMS OF PACKING TO STUFFING SOX LUBRIKATED STEM, GLAND AND FLANGE STUDS, EVENLY TIGHTENED FLANGE MUTS TIL RINGS WERE COMPRESSED

0 0

DRESDEN UNIT 2 SAFETY RELATED MAINTENANCE

EQUIPMENT	NATURE OF MAINTENANCE	LER OR OUTAGE NUMBER	MALFUNCTION CAUSE RESULT	CORRECTIVE ACTION
2-2303-DOF D-2 HPCI DIL FILTER	PREVENTIVE WR 090832	H/A		REMOVED. CLEANED. INSPECTED AND REINSTALLED EAST AND MEST HPCI CIL FILTERS
D-2 HPCI	PREVENTIVE MR D90833	N/A		DRAINED OIL FROM TANK. PERFORMED VISUAL INSPECTION
2-202-4A	PREVENTIVE MR 090867	N/A		INSPECTED GREASE, FOUND BREASE AND BREASE LEVEL TO BE ACCEPTABLE
2-2301-4	PREVENTIVE MR D90870	N/A		INSPECTED GREASE: FOUND GREASE AND GREASE LEVEL TO BE ACCEPTABLE
2-1301-1	PREVENTIVE MR D90095	N/A		FOUND DREASE UNACCEPTABLE, REBUILT PER MR90895, REFLACED: 2 HANDWHEEL BEARINGS, 1 MORNSHAFT BEARING, AND 1 MORKSHAFT BEARING REAR
2-1001-1A D-2 MD-1001-1A	PREVENTIVE WE 090099	N/A		INSPECTED GREASE, FOUND GREASE AND GREASE LEVE. TO BE ACCEPTABLE
2-A1-220-47	PREVENTIVE MR D91200	N/A		REMOVED OLD REGULATOR AND INSTALLED WITH NEW, REPLACED KINKED SUPPLY AIR LINE AND REINSTALLED WITH NEW FITTINGS
2-202-5A MOV	PREVENTIVE MR D91331	N/A		USING LIBERTY TEST EQUIPMENT: DIAGNOSTICALLY TESTED MOV 2-202-5A
2-202-58: MOV	PREVENTIVE WR 091332	H/A		USING LIBERTY TEST EQUIPMENT, DIAGNOSTICALLY TEST MOV 2-202-5B
2-1001-1A W)	PREVENTIVE WR E91340	N/A		USING LIBERTY TEST EQUIPMENT: DIAGNOSTICALLY TESTED MOV 2-1001-1A

SAFETY RELATED MAINTENANCE

2-203-IE D-2 IB MS, V ATS OPERATOR IC	2-203-18 0-2 IB MSIV AIR OFERATOR	LERW CABLES	2-1298-2 HDV	1-220-2 HUU	2-1501-32A MDD	2-1201-2 NOV	2-1201-1 NOV	MDV 2-1001-28	2-1001-IB MQU	EQUIPMENT
PREVENTIVE WR B91792	PREVENTIVE NR D91791	CORRECTIVE ME D91752	PREVENTIVE PREVENTIVE	285.169 MH 585.169 MH	PREVENTIVE WR D91372	PREVENTIVE MR D91347	PREVENTIVE MR D91345	PREVENTIVE WR 591343	PREVENTIVE MR D91345	NATURE OF MAINTENANCE
81/6	M/A	678	97.8	N/A	N/A	W/#	N/A	N/A	M/A	LER DR DUTAGE HUMBER
										SAHAFUN
										RESULT.
DISASSEMBLED PILOT VALUE ASSEMBLY. REPLACED O RINGS AND SPRIMSS. REBUILT & RESTED AS REGULTED DISASSUMBLED WELV AIR RESTED AS REPLACED E KING SPALS & D RING	REPLACED & SEALS+ ADJUSTED PACKING AND LUBRICATED STEM	INSTALLED MEW COMM ON LPRM CAL6-336, 24-526 DHE TO FAILED COMM INSTALLED NEW COMM ON 32-57D AT IRON LEVEL, ALSO INST. 6' PIECE OF LPRM CA TO 32-57D	INSTALLED VOTES SENSOR ON MOU 2-1201-2	INSTALLED VOTES SENSOR ON MOV 2-220-2	USING LIBERTY TEST EQUIPMENT. DIAGNOSTICALLY TESTED MOV2-1501-32A	USING LIBERTY TEST EQUIPMENT. DIADMOSTICALLY TESTED MOV 2-1701-2	USING LIBERTY TEST EQUIPMENT. DIAGNOSTICALLY FESTED MOUZ-1201-1	VOTES TESTED VALVE	USING LIBERTY TEST EQUIPMENT. DIAGNOSTICALLY TESTED MOV2-101-1B	CORRECTIVE ACTION

SAFETY KELATED MAINTENANCE LES OR BUTAGE MALFUNCTION

2-2301-51 HFCI AUX CROKING WATER FUMP BISCH CHECK WALVE	2-3999-252 SERVICE WATER TO EMERG AIR CORLERS CHECK VALUE	2-1502-8 28-LPCI FOME	2-2301-64 52 MFCI 2301-64 VALVE	2-11028 0-28 SBLC PUMP	2-1102-A D-2A SELC PUMP	52 DRYMELL VENT VALVE	2-1601-22 D-2 DRYMELL WENT DALUE	2-1601-63 I/2 DRYWELL VENT VALUE	EQUIPMENT 2-220-578 D-2 VALUE
WE DESCRIPTION	PREVENTIVE MR D92529	CGSRECTIVE	PREVENTIVE MR Q91946	PREVENTIVE WK D91933	PREVENTIVE WE D91932	NE SOISOI NE SOI	ME D91890 PREVENTIVE	PREJENTIVE	MAINTENANCE PREVENTIVE NE 091839
NZA	W/A	N/A	N/A	B./N	M/A	N/A	W/W	8//6	HUMBER N/A
					Manual Confession		1		CAUSE
									LYRS 39
REMOVED BLD CHECK VALVE, ELEANED, REPLACED WITH HEM BASKETS AND CHECK VALVE INSTALLED	REMOVED BOWNET AND ASSISTED TS IN TEST FAILED, REPLACED PER ABOVE WORK INSTRUCTIONS	REPLACED BOLT IN FLANGE WOTOR COOLING	REPACKED WALVE, SET VALUE STROKE, REPLACED AIR DIAPHRASM, VERTEIFED NO LEAKS	DISASSEMBLED PUMP, CRANK CASE AND GEARBOX, INSPECTED PARTS, REPLACED SEATS, PACKING AND MACHINED VALUES, NEW GUIDE BUSHES, REASSEMBLED	DISASSEMELED. PUMP BEAR POW AND CRAMK CASE. REPLACED SEATS, WACHINED WALUES AND NAE PLUMBER GUIDES.	DISASSEMBLED AIR OPERATOR ON UENT WALVE REASSEMBLED AIR OPERATOR ON UENT WALVE 1601-208	DISASSEMBLED. INSFECTED. REASSEMBLED VALUE	DISASSEMBLED, INSPECTED, REASSEMBLED VALUE	ADJUSTED PACKING TO STOP LEAKAGE. CLEANED AND LUBED STEM

SMEET STATE STATES ALTERS ALTERS STATES SALES STATES SALES S

2-2499-1A SOLEMOID VALUE	SOLENOID WALVE	2-2499-2A SOLENOTO VALVE	2-2499-28 SOLEMOID VALUE	2-2499-3A SOLENOIS VALVE	2-2499-38 SOLENOID VALUE	2-2499-44 SOLENOID WALVE	2-2499-4B SOLENDID WALVE	2-1503-1A CESW + DMF & BISCHARGE CHECK VALUE	2-1301-11 ISD COMBENSER MU CHECK VALVE	EQUIPMENT
PREVENTIVE MR D92654	FREVENTIVE MR 092663	FREVENTIVE WR 592562	PREUENTIUE WR D92661	PREVENTIVE WK D92560	PREVENTIVE MR 092659	PREVENTIVE MR D92658	PREVENTIVE MR 092457	PREVENTIVE WR 892552	PREVENTIVE WR D92546	MATURE DE
81/4	N/A	8/8	N/A	N/A	N/W	N/A	M/A	N/A	N/A	LES DE DUTAGE MUMBER
										CAUSE RESULT
ABJUSTED THE OPEN & CLOSED REED SWITCH. CONNN. TED THE FLUKE TO THE CLOSE SW. AFFLY A FEED TO THE SULEMOTO WHILE MOVING THE REED SW.TIL IT MAKES & DREAKS	PERFORMED EQ MAINTENANCE AND SURVEILLANCE ON 2499-18	PERFORMED EQ MATNIEMANCE AMB SURVEILLANCE DN 2499-2A	REPLACED SOME O RINGS AND WASHER INSULATORS	REPLACED ALL D KINGS, GASKET AND INSULAIGES	REPLACED ALL D RINGS+ BASKETS+ INSULATORS	DISASSEMBLED, INSPECTED, REPLACED ALL 6 RINGS, GASKETS, INSULATORS, REINSTALLED	DISASSEMBLED, REPLACED ALL D RINGS, DISC ASSEMBLY, TESTED, REASSEMBLED VALVE	RESTACED BASKY CORROBED CHECK VALUE	REMOVED INSULATION AND BINNET'S REMOVED FLAFFR INSPECTED BY TECH STAFF, ALL DK * REINSTALLED WITH NEW BASKET AND TIGHTEN BOWN BOWN.	CORRECTIVE ACTION

SAFETY RELAYED MAINTEHANCE

161A 181A	NSTA NSTA	45.00-28 45.00-28	2-203-2E #51V	2-203-20 MS10	2-220-44 ABU	2-203-3E ELECTROMATIC	2-203-XE ELECTROMATIC	2-203-30 SLECIROMATIC 2-203-30	SQUIPMENT 2-203-38 ELSC BROWATEC
PREVENTIVE MX DR2676	PREVENTIVE WK 592675	PREVENTIVE WK D92674	PREVENTIVE MR D92473	PAEUEMITUE MK 092672	PREUENTIVE WK D92670	PREVENTIVE NO 592668	PREVENTIVE WR [192667	PREVENTIVE #8 092566	NATURE OF MAJOR PREVENTIVE ARE D92645
N/A	8/8	8/8	N/4	N/A	1/18	87.8	N/A	W/K	LER DR DUTAGE NUMBER N/A
					Annual management				MALFUNETIUM CAUSE RESULT
NESW NB3834	PERFORMED	FOUND MARKE AND R	FOUND LANDE AND R TESTI	GANNER R	ADSOLA ADSOLA EINE EINES	WE WEN BASEND STATES	SEMOU OFEKA	REMON AND I USING IN PL	
NWED EQ SUNDVETLEANCE ON 1 'D'	MOMED ED SURVEILLANCE ON 2"A"	FOUND MSIV IN GOOD CONDITION, WIRES MARKED AND LANDED FER PRINT, UNLANGED AND PER HORK INSTRUCTIONS	FOUND MSTY IN SOOD CONDITION, ALL LEARS LAMBED AND MARKED FEW PRINT, UNLAMBED AND RELAMBED LEADS AND RAW UNLUE FOR FSTING	B AND LANGED, TESTED ON	INSTALLED NEW O RINGS ON THE CABLE ASSEMBLY, NEW ARRY, NEW LIMIT SWITCH. NEW SAY CHEM SPLICE FOR SOLENDID COIL WINE 3	REMOVED, TESTED, INSPECTED AND DUERHAULED GFERATORS, REINSTALLED USING APPLICABLE PROCEDURES	SEMBUED, IMSPECIED, TESTED, LUBED OPERAFOR, REINSPALLED	REMOVED OPERATOR. INSPECTED, OVERHADLED, AND TESTED OK. REINSTALLED OF ENATOR USING APPLICABLE PROCEDURES, TESTED IN PLACE ON	CORRECTIVE ACTION REMOVED OPERATORS, INSPECTED, GVERHAULED AND TESTED, REINSTALLED
							1	Y)

SAFETY RELATED MAINTENUNCE

2-2499-48 SOLEHOID VALUE	2-2499-4A SOLEWOID VALUE	2-2499-38 SOLENGID VALUE	2-2499-3A SDLENDID VALU	2-28-1 480V MCE 88*	2-29-4 4800 MCE PRH	2-203-1A MSIV	2-203-18 MSIQ	2-203-1E MSIV
		,		-501-3A	- 1501 - 36			ERUJOAENT
CONNECTIVE NR D92498	CORRECTIVE MR 392692	CDPRECTIVE MR B92696	COMMECTIVE MR D92495	FREVENTIVE WR D92697	PREDENTIVE WR D92480	PREVENTIVE WR 092679	FREVENTIVE MR B92678	NATURE OF MAINTENANCE PREVENTIVE AR 092677
N/A	8/4	N/A	20 20	N/A	8/4	8/8	N/A	LES OR DUTAGE NUMBER N/&
					1		1	CAUSE RESUL
								RESULT 110%
REWELDED TACKS PER WELD WAP	REMELDED YACKS PER WELD MAP	RENELDED TACKS PER WELD MAP	REWELLES TACKS PER WELD MAP	REMOUPE DREAKER FROM CUBICLE: BURNISHED CONTACTOR CONTACTS: MESSERED DREAKER WIRTING: REPLACED AUX CONTACTS	PERFORMED EQ INSPECTION OF 4800 MCC BREAKER FOR 1501-36	DISCOMMECTED MSTV. TESTED, RELANDED WIRING AND FERFORMED TESTING FER MORK	REPLACED MANIFOLD ASI	CORRECTIV CTION FERFORMED ED SURVEILLANCE ON 1 'C'
	H/A REMELDED TACKS	CORRECTIVE N/A REWELDED TACKS PER CORRECTIVE N/A REWELDED TACKS PER UR 092898 N/A REWELDED TACKS PER	MALUE CORRECTIVE N/A CORRECTIVE N/A CORRECTIVE N/A NALUE CORRECTIVE N/A N/A NALUE CORRECTIVE N/A	CORRECTIVE N/A CORRECTIVE N/A CORRECTIVE N/A CORRECTIVE N/A CORRECTIVE N/A CORRECTIVE N/A	PREVENTIVE N/A CORRECTIVE WR D92695 N/A ALUE CORRECTIVE WR D92696 N/A CORRECTIVE WR D92697 N/A CORRECTIVE WR D92697 N/A CORRECTIVE WR D92697	PREVENTIVE N/A FREVENTIVE HR D92690 N/A CONSECTIVE HR D92695 N/A CONSECTIVE HR B92696 N/A CONSECTIVE HR B92696 N/A CONSECTIVE HR B92698 N/A CONSECTIVE HR B92698 N/A CONSECTIVE HR B92698 N/A CONSECTIVE HR B92698 N/A	PREVENTIVE N/A PREVENTIVE NALVE PREVENTIVE NALVE PREVENTIVE NA PREVEN	PREVENTIVE N/A WK D92678 PREVENTIVE N/A PRE

SAFETY RELATED MAINTEMANCE

0 0 0 0 0

2-261-15A COR UNIT 2 X-AREA GRI TEMP WR	2-2370A UNIT 2 HPCI ROOM TEMP SWITCHES WE	VARIOUS EXT. STM. REACTOR FEED. DOND. FAI EDGSTER. FEEDWATER HEATERS AND DEALN, SOC PIPING	7-2301-48 opp	2-257-2844 PR BUS 19 FEED TO MIC 28-1 MR	TIP SHEAR WALVE PRINCES PR	HPCI ROOM CBOLER PR	2-2202-75 INSD COND REACTOR INLET ULU VALANS PAL	2-320A-01 SMUHBER	2-3202-24 SAURRER W	SNEWAINDE
CORRECTIVE WR D93364	PREVENTIVE MR 093363	WE DESTRO	AN DESTREE	#F 893070	PREVENTIVE MR (192910	PREVERTIVE WE D92905	PREVENTIVE MR D92883	PREVENTIVE WE D92767	FREUENTIVE MR E92706	MAINTENANCE
N/A	11/4	N/A	W/W	N/A	N/A	N/A	N/A	N/A	N/A	ER OR OUTAGE NUMBER
										CAUSE RESUL
										MESULT TON
PERFORMED STATION TRAVELER FOR	REPLACED ALL HPCI AFTER TEMPERATURE SWITCHES PER PACKAGE, PERFORMED 015 2 30-6	COMPLETED MORE PER FEIT MORE PACKAGES G93350-01* 02* 03: 04* 05: 06* 07		CLEAMED. LUKED SWEAKER, MADE UP JUMFER CABLE TO SWAP DUT EREAKER, CLEAMED CUBICLE AND CONTACTS, LUBED LINKAGE,	REPLACED TIP SHEAR VALUE PRIMERS PER BMP-700-3 REU. 4	MADE UY MOTOR LEADS REZUSTALLED FAN BUARD AND REPLACED FAN BELTS	CHECKED PAMEL FOX DIRT, TIGHTENED TERMINALS	COMPLETED WORK PER FCII WORK PACKAGE 090707-01	COMPLETED WORK PER FCII WORK PACKAGE 892706-01	CONSECTIVE ACTION

ORESDEN UNIT 2 FETY RELATED MAINTENANCE

		The state of the s	make an activities of the contract of the cont		
EQUIPMENT	NATURE OF 1.	IR OUTAGE	HALFUNCTION CAUSE RES	ULT	CORRECTIVE ACTION
2-900 902-5 PANEL TERM FF FUSE 1130-702A	CORRECTIVE WR 094172	N/A		REPLACE TESTED	ED ERGKEN FUSE BLOCK AND MAP
2-833 REFUEL GRAPPLE	PREUEL. VE WR D94187	N/A			DJUSTMENTS ON GRAPPLE AS TED BY FUEL HANDLERS
2-1301-1 MOV	PREVENTIVE WR 094195	N/A		INSTALL	NECTEU MOTOR, DISASSEMBLEO, LED NEW MOTOR AND MOTOR GASKET MPARTMENT COVER GASKET, INSTALLED ROUE
U-2 DRYMELL EQUIP HATCH	PREVENTIVE WE D94338	N/A			AND INSTALLED THE U-2 EQUIPMENT HATCH
3-702-IRM-11 IRM NOISE PROBLEMS FOR IRMS 11, 12, 13, 14, 15, 16, 17, 18	PREVENTIVE WR 094528	N/A		AND TUE	CURVES ON ALL IRM DETECTORS RNED DATA OVER TO GE 094477 WAS TO COMPLETE FURTHER TESTS RDED BY 6.E.
2-1:30-MISC FLANGE AND PIPING BETWEEN 1501-276, 28A (ILRT)	PREVENTIVE WR D94574	N/A		FLANGE SETWEEN	BLING FLANGE FROM 4" LINE: 10" AND FIPING: INSTALLED SPOOL PIECE 1 72" 10" AND 4" FOR ILRT & TESTNG LLED FLANDE
2-0388-1"A CRD LINE 2-0388-1"A	CORRECTIVE MR 094661	H/A		PREFABE	ICATED AND INSTALLED NEW PIPE
EAST AND WEST TORUS HATCHES	PREVENTIVE SR D94713	N/A		REMOVED REPLACE REINSTA	EAST MAICH PER TECH STAFF D HATCH WITH NEW GASKETS LLED
2-1601-MISC PRIMARY CONTAINMENT DRYMELL VENT AND PURGE VALVES	PREVENTIVE MR E94732	N/A		F HLLOWI ACCUMUL	ED 7 FITTING AND ALVE ON THE NA U" T AND PURGE "ALVES EMERG. A 1601 "0A 208, 21, 22,23, 6 16' 3
2-202-68 MOV	PREVENTIVE NR D94U58	N/e			AND MARKED WIRING. ED PER INSTRUCTIONS

DRESDEN UNIT 2 SAFETY RELATED MAINTENANCE

EQUIPMENT	NATURE OF NAINTENANCE	LER OR OHTAGE HUMBER	MALFUN	CTION RESULT	CORRECTIVE ACTION
2-202-6A MOV	PREVENTIVE WR 094859	N/A			REMOVED AND MARKED WIRING. VERIFIED PER INSTRUCTIONS
2-700-AFRM6 AFRM CHANNEL 6	CORRECTIVE WR D94941	N/A			REPLACED K4 AND K16 RELAYS, KEPLACED HI HI LAMP ALSO. COMPLITED DIS 700-06 PER PACKAGE.
2-29-9 MCC	CORRECTIVE WE 094954	N/A			REPLACED PREAKERS IN COMPARTMENTS 20, 20, 30, 40 & 40 AND REMOVED REMAINING PREAKERS IN MCC 29-9
2-1600 D-2 REACTOR ASSEMBLY	PREVENTIVE WR D94958	N/A			INSTALLED DRYWELL COVER AND REACTOR SHIELF BLEDKS PER DMF 1600-05 5800-3 AND DAP 3-14
713-48 PREAMPLIFIER PAFETY VALVES	CORRECTIVE WR 095001	N/A			REPLACED PREAMP AND CHECKED OPERABILITY
2-2301	PREVENTIVE WE 095008	N/A			PERFORMED MPCI OVERSPEED TEST PER MMF/TRAVELER
2-2301-36 VALUE	PREVENTIVE WR D95023	N/A			REMOVED DLD SPRING CARTRIDGE CAP, INSTALLED ALL REQUIRED O RINGS, AND NEW COVER, INSTALLED NEW GREASE RELIEF KIT
2-263-578 REACTOR VESSEL LEVEL TRANSMITTER	CORRECTIVE WR D95113	N/A			INSTALLED REBUILT ROSEMOUNT TRANSMITTER, TESTED AND RECALIBRATED LOOP
2-2001-102A ILRI	PREVENTIVE MR D95116	N/A			REMOVED. CHECKED. REINSTALLED CHECK VALUE
2· >=35 Mbv	PREVENTIVE NA D95179	H/A			USING LIBERTY TEST EQUIPMENT, DIAGNOSTICALLY TESTED MOV 2-2301-35, AND ADJUSTED TORQUE SWITCH AS REQUIRED

AFETY RELATED MAINTENANCE LER OR DUTAGE MALFUNCTION

2-220-62A MARD FW CHECK	ISI INSPECTIONS AND REPAIRS	2-203-3E 25 ELECTROMATIC	2-203-30 2D ELECTROMATIC	2-203-3C 2-C ELECTOMATIC	2-203-38 0-2 8 ELECTROMATIC	2-2301-10 MOU	2-2351A LS 2-2351A TORUS HI LEVEL SWITCH	2-2301-8 MDV	2-2301-16 MDU	EQUIPMENT
PREVENTIVE WR 895295	PREVENTIVE MR 095222	PREVENTIVE WR D95209	PREVENTIVE MR D95208	PRECTUTIVE WR DYSZOZ	PREVENTIVE WR D95206	PREVENTIVE	BELGENTIVE PREVENTIVE	PREVENTIVE MR 095181	PREVENTIVE MR 095120	MAINTENANCE
N/A	N/A	AVA	N/A	N/A	W/8	14/24	11/4	N/A	N/A	SEM ON USER
										CAUSE
									1	ESULT KLITHERS
INSTALLED NEW SEAT DISC ASSEMBLY	REPLACED COTTER PINS, ABJUSTED TO MAINTAIN FULL NUT ENDAGEMENT, REMOVAL OF RUST	INSTALLED AND REMOVED BAG	INSTALLED AND REMOVED GAG	INSTALLED GAG	INSTALLED AND REMOVED DAG AS REQUESTED	DISCONNECTED MOTOR LEADS, LIMITS, TORQUE SWITCH, MMD OVERHAULED, REINSTALLED	REMDUED HEAVY RUST FROM INTERIOR OF CHAMBER, CLEANED ENTIRE ACTUATING MECHANISM, REPLACED FLANGE GASKET AND SEASSEMBLED	USING LIBERTY TEST EQUIPMENT, DIAGNOSTICALLY TEST MOUZ-2301-8 ADJUSTED TORQUE SWITCH AS REQUIRED	USING LIBERTY TEST EGUIPHENT. DIANOSTICALLY TEST MOUZ-2301-10 AND ADJUSTED TORQUE SMITCH	CORRECTIVE ACTION
				er is	n		7	2		,

GRESDEN UNIT 2

2-1601-63 VERSA VALVE ON 2-1601-63	2-2301-65 AD 2-2301-65 HPCI TURBINE SU AEDUE SEAT DRAIN	CIS 2-1140-38	2-9208A SRYWELL AIR SAMPLE VALUE 9208A	3-1600 02 X-AREA CONTAINMENT	2-203-ID MAIN STEAM ISOLATION VALUE	2-203-1A HAIN STEAM ISOLATION VALUE	2-203-20 MAIN STEAM ISOLATION VALVE	2-2301-8 MOU	2-1502-A 2A-LPCI FUMP METER	EQUIPMENT	
PREVENTIVE WE D95496	PREUENTIVE WE 095476	CORRECTIVE WR 095462	CORRECTIVE WR D95413	PREVENTIVE WR 095378	NE D95361	PREVENTIVE MR D95360	PREVENTIVE WR D95359	PREVENTIVE NR 595351	PREUENTIVE WR D95320	MAINTENANCE	
N/A	H/A	N/A	N/A	N/A	N/4	H/A	4/4	N/A	N/A	LER OR OUTAGE HUMBER	ATTENDED ATTACH
										MALFUNCTION CAUSE RE	The state of the state of the
										LTINS 3N	STATE .
REPLACED VERSA VALVE	REPACKED, SET STROKE ON 2-2301-65 PER	REMOVED OLD METER RELAY SETPOINT UNIT	DISASSEMBLED, CHECKED, REASSEMBLED	INSTALLED PLATE AND TIGHTENED BOLTS, PACKED ALL HOLES, SEALED, INSTALLED THE	DISASSEMBLED PILOT VALUE ASSEMBLY. REPLACED COMPONENTS AND O RINGS. REPLACED FILOT ASSEMBLY ON MSTV AIR OPERATOR, REACSEMBLED	DISASSEMBLED, INSPECTED, CLEANED, REASSEMBLED	DISASSEMBLED VALVE, INSPECTED, REPAIRED REASSEMBLED	REMOVED LIMITS AND TORQUE CHITCH TESTED. REINSTALLED, AREASED LIMIT SEARS	REFLACED UPPER BEARINGS	CORRECTIVE ACTION	

DRESDEN UNIT 2 SAFETY RELATED MAINTENANCE

EQUIPMENT	NATURE OF MAINTENANCE	LER OR OUTAGE	MALFUNCTION CAUSE RESULT	CORRECTIVE ACTION
2-4799-281A TARGET RECK AIR SUPPLY CHECK VALUE	PREVENTIVE WR D96031	N/A		REMOVED CHECK VALVE: CLEANED THREADED SURFACES USING PST ON THREADS: REPLACED MITH HEW CHECK VALVE
LINE 2-0207-2" EOTTOM HEAD DRAIN LINE	CORRECTIVE WR D96039	N/A		OPENED UNION, INSTALLED TEMP FITTINGS, FLUSHED OUT LINE, VERIFIED FLOW, REMOVED TEMP FITTINGS, AND RESTORED UNION
D2-517-39K-89 ELOCKHALL	PREVENTIVE WR D96040	N/A		REMOVED 5 LAYERS OF CINDER BLOCK OFF BLOCK WALL
M-3212-06 HPCI SUPPORT	PREVENTIVE WR D96067	'A	May for the spirit and we would be a set appearing or any special spirit and	REMOVED RUST WITH AIR MOTOR AND WIRE BRUSH FROM BASE PLATE OF SUPPORT
2-2419A B2 DRYWELL HIGH RAD MONITOR POWER SUPPLY	CORRECTIVE WR D96069	N/A		REPLACED RESYSTOR AND COMPLETED CALIBRATION PER DIS 1600-16 REV. 6
2-2301 U-2 HPCI	PREVENTIVE WR D96071	N/A		INSTALLED JUMPERS AND PERFORMED DIL FLUSH ON HPCI DIL SYSTEM
2-2301 U-2 HPCI	PREVENTIVE WR 096072	H/A		INSPECTED HFCI OIL SYSTEM AND HFCI MAIN OIL FOMP MATER BEARINGS, FRUND BEARINGS GOOD
SRh 21 MGNITOR	PREVENTIVE WR D96073	N/A		CLEARED TEMP ALT II-48-90 AS PER SPC 90-005
2-1501-3A	PREVENTIVE WR D96125	N/A		INSTALLED NEW ANTI ROTATION PIN IN VALUE STEM
M-11509-54 CORE SPRAY SUPPORT	PREVENTIVE WR 096158	N/A		REMOVED STRUT AND CLAMP, DRILLED HOLE IN STRUT, REMOVED CLAMP AND TRIMMED AS REQUIRED, REPLACED ALL COMPONENTS AND VERIFIED ACCEPTABLE

ORESDEN 19417 2 AFETY RELATED MAINTENANCE

EQUIPMENT	NATURE OF MAINTENANCE	LER OR OUTAGE NUMBER	MALFUN	ETION RESULT	CORRECTIVE ACTION
CRD TRANSFER PIT HATCH	PREVENTIVE WR 095569	N/A			OPENED HATCH AND INSTALLED BRIDGE PLATE, REMOVED BRIDGE PLATE AND REPLACED HATCHWAY, REPLACED GASKETS, REINSTALLED HATCH
2-2301-35 MOV	PREVENTIVE MR 695674	N/A			DISCONNECTED, DISASSEMBLED, OVERHAULED, INSTALLED NEW O RINGS, ROLL FINS, LUGS, GASKETS, AND GREASE, RECONNECTED AND REASSEMBLED, BRIDGED, MEGGARED AND SIGN
APRM #2 PS5	CORRECTIVE WR D95600	H/A			REPLACED FOWER SUPPLY AND COMPLETED APPLICABLE SECTIONS OF DIS 700-9 REV.1
APRM #2 HIGH VOLTAGE PS1	CORRECTIVE MR 095605	N/A			REPLACED HUPS AND TESTED
1001-1A U-2 1001-1A VALVE	PREVENTIVE WR D95607	N/A			DISCONNECTED OLD THERMOCOUPLE AND REMOUNTED THE NEW
2-1301-3 Xiiy	PREVENTIVE WR D95804	N/A			DIAGNOSTICALLY TEST MOV2-1301-3 USING THE VOTES TEST EQUIPMENT AND ADJUSTED TORQUE SWITCH AS REQUIRED
2-1301-1 MOV	PREVENTIVE WR D95852	N/A			DIAGNUSTICALLY TESTED MOV2-1301-1 USING THE VOTES TEST EQUIPMENT
2305-M-235 MPCI SUFFORT	PREVENTIVE WR 195948	H/A			LOOSENED LOCKNUT ON STRUT AND TURNED CLOCKMISE AND RETIGHTEN AFTER A DIMENSION OF 5/16" MAS ATTAINED
2-3204-24 SMUBBER 2-3204-24	PREVENTIVE NR D95969	N/A			DRILLED A 1/4" HOLE IN SNUBBER AS PER DRAWING. REMOVED CHIPS AND BURRS FROM HOLE AND CLEANED AREA
2-320A-01 SNUBBER 2-320A-01	PREVENTIVE WR 195970	N/A			DRILLED 1/4" SIGHT HOLE: REPLACED LOCK NUTS ON SMUBBER PIPE: MOUNT SUPPORT: ADJUSTED SMUBBER PER STATION TRAVELER

SAFETY RELATED MAINTENANCE

RE-2-2418A ELEMENT DRYWELL HIGH RANGE MONITOR RABIATION	HM-Z-2252-818 HZ/82 ANALYSER PANEL	M-569 SHT 16 HANGER MARK M-569 SHT 16+ HANGER MARK NO 82-3012	2-2301-69 UZ HPCI RUPTURE DIAPHRAM	150 MELD 8-145 D-2 RMCU LN 1201	U2 1501-3B	SD-2-226-45 SDLENDID RECIRC LOOP SAMPLE VALUE OUTBOARD	AD-2-1601-50 PRIMARY CONTAINMENT VENT AND PURBE VALUES	2-3019A-60 SNUSEER 2-3019A-60 DWG M-564E SH 11* SERIAL NO. 7700	2-2001-5 ORYWELL EQUIPMENT DRAIN ISO VALVE	EQUIPMENT
PREVENTIVE WR D96406	PREVENTIVE WR 096405	PREDENTIVE WR 196366	CORRECTIVE WR D96362	PREVENTIVE WR 596297	PREVENTIVE WR D96288	PREVENTIVE WR 096293	PREVENTIVE MR 096261	PREVENTIVE WR D96249	PREVENTIVE WR D96191	MAINTENANCE
N/A		M/A	N/A	W/W	N/A	N/A	NZA	B/A	W/W	LER OR DUTAGE
		1								MALFUNCTION CAUSE RE
	the first and to the same and the									RESULT
INSTALLED CONNECTORS AT SPLICE PER WORK INSTRUCTIONS	REPLACED THE UNQUALIFIED SPLICE IN THE COMPUTY FITTING	REMOVED NOT FROM SPRING CAN AND SET GAGE PER INSTRUCTIONS	REMOVED NIFPED ASSEMBLY AND FOUND IHREADS ACCEPTABLE, REINSTALLED USING APPROVED THREAD SEALANT, TIGHTENED ALL FITTINGS	COMPLETED WORK PER FOIL WORK PACKAGE 096297-01	INSTALLED NEW BOLTING	REPLACED TAPED SPLICES, WITH RAD CHEM SPLICES	INSTALLED NEW CHECK VALVES WITH OC VERIFICATION ON CLEANLINESS	REMOVED SMUBBER. CLEANED, INSPECTED SMUBBER SPHERICAL SEARINGS, CHECKED REINSTALLED SMUBBER	REPACKED VALVE USING 8 RINGS OF PACKING	CORRECTIVE ACTION

SAFETY RELATED MAINTENANCE

2-2301 4 MOV	2-1100 STANDEY LIQUID CONTROL	AD 2-2500-4A	AO 2-2599-48	2×252-286D 26 08YMELL OLR BRKR	2-252-286C 2F DRYMELL CLR BRKR	2-2305-#-228 SMAY BRACE 2305-#-228	SRM/IRM ELECTRONIC WOISE	2-220-59-8 FEEDWATER CHECK VALUE	2-0203-20 20 MSIU
PREVENTIVE WR 596632	CORRECTIVE WR 096525	CORRECTIVE WR D96507	PREVENTIVE WS D96506	CORRECTIVE MR L94505	CORRECTIVE WR D96504	CORRECTIVE WR 196496	CORRECTIVE MR 096477	PREVENTIVE NR D96424	NATURE OF MAINTENANCE PREVENTIVE MR D96414
N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	11/4	LER OR OUTAGE NUMBER N/A
									CAUSE
									MALFUNCTION CAUSE RESULT
PERFORMED A BIAGNOSTIC TEST USING LIBERTY TEST EQUIPMENT ON MOV2-2301-4	INSTALLED 2 SUPPORTS AS DIRECTED IN MINOR DESIGN CHANGE PACKAGE: FOR SELC LINE NO. 2-1102-1 1/2"-A	REMOVED OLD SOLENOID AND REPLACED WITH NEW	REPLACED SOLENOID AS PER STATION TRAVELER, BENCH TESTED PRIGR TO INSTALLATION AND PERFORMED PNO AFTER	CENTERED FIN AND WIPED CLEAN SLIDES	CENTERED PIN AND WIFED CLEAN SLIDES	REPLACED OLD BROKEN ROUND STOCK WITH KEW. ADJUSTED COUPLING	COMPLETED ELECTRONIC NOISE ELEVATION WITH GE SERVICE REP	DISASSEMBLED, INSPECTED, CLEANED, REASSEMBLED	CORRECTIVE ACTION VERIFIED HSIV AIR SUPPLY WAS GOS. DISCONNECT, CLEAN, INSPECT, REASSEMBLE

SAFETY SELATED MAINTENANCE

AD 2-1601-63 DRVMELL VENT AND PURGE VALVE	#02-0203-1E #SIU	2-0305-127 127 VALUE ON HEU F-1	MO-2-0202-68 RECIRC RING HEADER VALUE	2-9207-A FCU	UM-2-2252-818 H2/02 AMALYSER (HEAT TRACE)	HM-2-2452A H2/02 AWALYSER (HEAT TRACS)	3-700-APRM2	M-11510-132 DOUBLE VARIABLE SPRING PIPE SUPPORT	EQUIFMENT 24/48 BATTERY CHARGER
CORRECTIVE WR D96813	CORRECTIVE WR D96804	CORRECTIVE	CORRECTIVE WE 094802	CORNECTIVE WR 096796	PREJENTIVE WE 096791	PREVENTIVE WR 896790	DEFRECTIVE WE D96764	PREVENTIVE WR 996739	MATURE OF MAINTENANCE CORRECTIVE NR 196734
N/A	N/A	M/H	M/A	NVA	W/A	N/A	ACH	N/A	LEK OR OUTABE NUMBER N/A
									MALFUNITION CAUSE RESULT
DISASSEMBLED, INSTALLED NEW END SEAL WITH WAVE SPRING AND DOW 55 GREASE INSPECTED, VERIFIED, ASSEMBLED	TORQUED FACKING NUTS TO 45 FT. LBS.+ THEN CYCLES VALUE FERFORMED THIS SEQUENCE THREE TIMES	ADJUSTED VALUE PACKING THAT WAS	ADJUSTED PACKING PER CRITERIA IN DMP 040-07 PER APPLICATION SECTION	INSTALLED NEW REGULATOR AND ASSURED ALL FITTINGS WEPE TIGHT	REMOVED THE FOUR UNGUALIFIED SPLICERS AND INSTALLED FOUR EQ SPLICES PER MMF TRAVELER	REMOVED BLD UNGUALIFIED SPLICES AND INSTALLED QUALIFIED ED SPLICES FER ATTACHED MMP	REPLACED RELAY K2 AND K5, PERFORMED APPLICABLE SECTION OF DIS700-6	ADJUSTED SPRING CAN TO PROPER COLD SETTING	CORRECTIVE ACTION CHECKED UDLIAGE ACROSS BATTERY BANK, MADE NECESSARY ADJUSTMENTS, PUT CHARGER IN FLOAT MODE.

SAFETY RELATED MAINTENANCE

2-1601-206	2-1601-23	MD2-1001-1A BREAKER	2-23890 HPCI TURBINE PER MISSING KEACTOR PRESSURE	24 FUEL ZONE LEVEL	2-202-58	UZ 125V ALT. BATTERY CHARGER	#-3212-05 HPCI SUPPORT	2-263-2-31-0 FLOW CHECK VALUE	EQUIPMENT 2-263-2-310 INSTRUMENT LINE CHECK UALVE
PREVENTIVE WR D97067	CORRECTIVE WR D97062	CORRECTIVE WR D97053	PREVENTIVE MR D97050	CORRECTIVE WR 897031	CORRECTIVE MR 097022	CORRECTIVE WR 597001	PREVENTIVE WR 096882	PREVENTIVE WR D96856	NATURE OF MAINTENANCE FREVENTIVE WR 096817
81/A	N/A	N/A	N/A	N/A	W/W	H/A	N/A	н/а	LER OF OUTAGE NUMBER N/A
									CAUSE
									MALFUNCTION EAUSE RESULT
USING SLUGGER DREW UP ON VALVE EDLIING IN A DIAMETRICALLY OPPOSING PATTERN-MENT AROUND FLANGE ABOUT 8 TIMES, USED SNOOP ON FLANGE TO STOP LEAKING VALVE	ADJUSTED LIMIT SMITCH AND HAD OPERATIONS CYCLE 3 TIMES	REPLACED THE SPLICE OF THE BLACK WIRE OF CABLE 22485	CHECKED CALIBRATION OF TRANS PER DIS 2300-11	REPLACED METER MITH NEW	TORGUED LIMITORQUE MOUNTING BOLTS	REPLACED TIMER, SET FLOAT AND EQUALIZE WITH FLUXE	REPAIRED CORRODED SUPPPORT W-3212-05 DN HPCT TURBINE EXHAUST LINE 2-2306-24"	REMOVED THE FLOW CHECK: CHECKED, REINSTALLED	CORRECTIVE ACTION REMOVED FLOW CHECK: CHECKED. REINSTALLED

GRESDEN UNIT 2

EQUIPMENT	MAINTENANCE	LER OR OUTAGE	CAUSE CAN	MAKTURKTION NUSE RESULT	CORRECTIVE ACTION
TS2-23718 HPCI AREA TEMP SWITCH	PREVENTIVE MR 897086	N/A			NWE PLATES FABRICATED AND SWITCH MOUNTED, TORQUED AS PER WORK INSTRUCTION SWITCH TESTED
1500 FLANGE BETWEEN 2-1501-278; 288	PASOLAN BALLINE	H/H			REMOUSED TEST FLANGE, CLEANED GASKET. INSPECTED AND LUBRICATED SOLITING. INSTALLED FLANGE WITH NEW FLEXITALIC GASKET
2-4699-315 U2 D/6 ATR REBULATOR	CORRECTIVE WR D97108	N/A			REMOVED DLD REGULATOR, APPLIED SEALANT AND NEW REGULATOR WITH DC PRESENT TO WITNESS CLEANLINESS, REINSTALLED REGULATOR AT UNIONS
203-3C ERV PRESSURE CONTROLLER	CORRECTIVE WR D97110	45			REPLACED EQUIDON TUBE, CALIBRATED SETPOINTS
2-0220-46	EGRRECTIVE MR 097112	N/A			ADJUSTED LIMIT SWITCH FOR PROPER WORKED PROPERLY
2-5641-66 02 TURBINE CONTROL VALUE PRESS SWITCHES	PREVENTIVE MP 097114	N/A			CHECKED CALIBRATION FO SWITCHES. ALL SWITCHES TRIPPED BELOW SETPOINT. CALIBRATED TO WITHIN TOLERANCE
A#-2-2301-64	CORRECTIVE	N/A			REMOVED THE BAD ADU SOLENOID 2-2301-64 INSTALLED A NEW ONE
3-2301-28	CORRECTIVE WR D97192	N/A			ADJUSTED THE LIMIT SMITCH AND TIBHTENED UP THE LIMIT BROCKET
2-305-130-10-11 CRD 10-11	CORRECTIVE MR B97196	H/A			REPLACED PRESSURE SWITCH WITH NEW AND CALIBRATED PER DIS 300-2 REV. 3
ACCUM 50-35 N9	CORRECTIVE MR D97197	NZA			REPACKED VALUE PER DWP 305-1 REV. 0 VERIFTED NO LEARAGE

SAFETY RELATED MAINTENANCE

		THE PARTY NAMED IN	ATERS MARTINES	LIVANCE	
EQUIPMENT M02-2301-35	NATURE OF MAINTENANCE	LER OR OUTAGE NUMBER	MALFU CAUSE	NCTION RESULT	CORRECTIVE ACTION
HPCI	CORRECTIVE WR D97199	N/A			MOTOR LEAG HAD FALLEN INTO TORQUE SMITCH NOT ALLOWING CLOSE CONTACTS TO CLOSE, RE TRAINED WIRES PROPERLY
2-2300-MISC U-2 HPCI OIL DRAIN	CORRECTIVE WR D97203	N/A			FOUND SMALL LEAKAGE ON #2 BEARING AREA, PEPLACED GASKET
2-250-1A SRMS/IRMS SPIKING	PREVENTIVE MR D97206	N/A			CONNECTED RECORDER TO MONITOR IRM AND GOSERVED SPIKES ON BOTH CHANNELS
HPCI FLOW SIGNAL CONVERTER	CORRECTIVE WR 897209	N/A			REPLACED HPCT ISOLATION PSI TRANSFORMER
2-24188 DRYWELL HI RAD DETECTOR	CORRECTIVE WR D97279	N/A			REPLACED DETECTOR WITH NEW DEVIATION REPORT WRITTEN
A02-203-2A MSIV	CORRECTIVE WR D97283	H/A			REPLACED THE AUX RELAY 203-2AR2 IN PANEL 902-62 IN THE DZ BATTERY KOOM
2-2301-35	PREVENTIVE WR 097315	N/A -			REMOVED SPRING PACK. INSPECTED, REPLACED WITH NEW SPRING PACK, INSTALLED GREASE
A02-203B 2B M5IV	CORRECTIVE MR 097334	N/A			REPLACED 3 WAY VALUE WITH 4 WAY VALUE
2-2301-35 HPCI 2301-35 VALVE	CORRECTIVE WR 097370	N/A			DISASSEMBLED, LAPPED NEDGE PER MMP AND TRAVELER, REASSEMBLED VALVE
2-305-111-06-27 ACCUM 06-27-8-7	CORRECTIVE WR D97390	H/A			OTSASSEMBLED VALUE, FOUND DISNAET GASKET TO BE WORN DUT, REPLACED ALL O RINGS, PACKING AND BONNET GASKET

OFFETY RELATED MAINTENANCE

2-3999-253 DIESEL SEN COOLING WATER TO WR 597541 EMERGENCY A/C CHECK VALUE	RM 1705-168 CDRRECTIVE 8 REFUEL POOL RAD MONITOR WR D97524	2-203-20 EDRRECTIVE #R D97489	2-203 CORRECTIVE UR D97472	EQUIPMENT MAINTENANCE OF
N/A	N/A	N/A	N/A	E HAMBER
			-	CAUSE RESULT
DISASSEMBLED, INSPECTED, REPLACED CHECK VALVES FOLLOWING ALL STEPS IN NMP	INSTALL & NEW SENSOR CONVERTER ST 503406 AND CALIBRATED PER DIS 1700-15 SOLUED PROBLEM	LOUSENED WOLWING BOLTS AND "CTION BOX MOUNTING PLACE, SLID WOLK 'S PLATE OUER SO ROLLER ON LIMIT SWITCH 'S FULL ROLLEF CONTACT WITH ACTIVATING .	REFLACED LIGHT SOCKET	SULT CORRECTIVE ACTION

2 2 3

ORESDEN UNIT 3 SAFETY RELATED MAINTENANCE NATURE OF LE OR OUTAGE MALFUNCTION

3-202-48 38 RECIRC PUMP SUCTION VALVE	ADJUST AFRM/RDM SETTINGS FER DGP 3-3	3-24528 38 HC B2 REAGENT SOLENDID VALVE	RBM CH 7	CRD WITHERAWAL TIMER	SD-3-2599-2A	3-1155 903-5 G-6 SBLC TANK TEMP HI/LD ALARM	3-1401-A 3A CORE SPRAY MOTOR	15-700 IRM 15	EGUIPMENT 3-263-2-178 EPN
CORRECTIVE WE D97052	PREVENTIVE MR E97047	CORRECTIVE WR D94524	CORRECTIVE WR 596404	CORRECTIVE HR D96157	CORRECTIVE WR B95730	PREVENTIVE WR 195631	PREUENTIUE WR 193996	PREVENTIVE WR D93868	MAINTENANCE CORRECTIVE WR D90249
N/A	N/A	8/4	N/A	N/A	N/A	N/A	N/A	H/A	NUMBER CAL
			-						CAUSE RESULT
INSTALLED HEW TORQUE SWITCH PER DEP 0040-29	READJUSTED APRW & RBW SETTINGS FOR SINGLE LOOP OPERATION TIL FURTHER MOTICI READJUSTED APRW & RBW SETTINGS FOR DOUBLE LOOP OPER NORMAL AS OF 1/15/91	REMOVED DLD SOLENDID, INSTALLED NEW SOLENDID AND HEW LUSS PER DEP 2100-04	REPLACED OLD RELAY WITH NEW, ENSURED SLIP ON CONNECTORS WERE IN PLACE	ADJUSTED 35 CONTACT TIMES FOR A LONGER MAKEUP TIME, ADJUSTED I FOLL TURN, NSO CYCLED AND FOUND ADJUSTMENT GORD NO FURTHER ACTION KERMIRED	INSTALLED NEW SOLENOID. INSTALLED LUGS	REPLACED THERMOSTAT AND EMECKED AMP	REMOUTE WORN BEARINGS AND INSTALLED HEN	REPAIRED AND REPLACED CONNECTOR FOR IRM 15	CORRECTIVE ACTION REMOVED FLOW CHECK VALUE, CLEAMED. INSPECTED. REINSTALLED VALUE

DRESDEN HAIT 3

EGUIFMENT	MAINTENANCE	LER OR DUTAGE	HALFUNCTION RESULT	CONSECTIVE ACTION)
3-5641-66 03 TURBINE CONTROL VALVE PRESSURE SWITCHES	PREVENTIVE WR 097115	W/A		TESTED FER SP-91-1-4 AND CALIBRATING PEN DATA CARDS	, ,
RV 3-1402-29A CORE SPRAY 'A' PUMP DISCHARGE RELIEF VALUE RV 3-1402-28A	PREVENTIVE WR D97129	H/A		INSTALLED NEW GAG CAP WITH SCREW TYPE HANDLE. INSTALLED STANDARD CAP AND VERIFIED TIGHTNESS	7
RU 3-1402-238 CORE SPRAY '8' PUMP DISCHARGE RELIEF VALVE RV 3-1402-238	PREVENTIVE MR D97130	W/A		INSTALLED NEW GAS CAP WITH SCREW TYPE HANDLE, INSTALLED STANDARD CAP AND VERIFIED TIGHTNESS	1
D/W INTERLOCK	PREVENTIVE MR 897172	W/W		INSTALLED NEW GASKETS, TORQUED TO 130 FT LES., TECH STAFF PERFORMED LLRY - PASSEB	1
3-250-15*16*17*18 MSL HIGH FLOW SWITCH	PREVENTIVE WE D97291	N/A		PERFORMED DIS 250-1, PERFORMED ON 8 CHANNEL ONLY, NO PROBLEMS FOUND AND NO NOTEY RELAYS FOUND	1 1
3-3999-252 SERVICE WATER TO A/C CHECK VALUE	PREVENTIVE WE D97540	N/A		REPLACED VALUE FOLLOWING APPLICABLE STEP IN MMP AND TRAVELER	•
REM CHANNEL 7	CORRECTIVE MR D97542	N/P		REM #7 WAS FOUND OUT OF CALTERATION MONITOR WAS RECALIBRATED PER DIS 700-8 CORRECTED PROBLEM	£
3-755-CH22 5RM 22	CORRECTIVE WE 597709	8/8		CLEANED CONNECTORS AT SRM 22 CHASIS AND FOUND FREAMP, VERIFIED CONNECTIONS NERE TIGHT	£
3-702-14 16M 14	PREVENTIVE WR D977730	H/A		CLEANED ALL CONNECTORS, REPLACED CONNECTOR ON DETECTOR, TESTED	1
302-82W WEST SCRAM INST. UALUE NOT BRAINED	PREVENTIVE MR 597763	N/A		CHECKED CALIERATION OF 302-82% LEVEL SWITCH AND FOUND NO PROBLEMS	

SAFETY RELATED MAINTEN-NCE

3-700-22 SRM 22	REACTOR PROTECTION SYSTEM	3-702-IRM-14 03 IRM 14	EGUIPMENT 3A RECIRC MG-FIELD BREAKER 3
CORRECTIVE WR D98045	PREVENTIVE MR 097992	CORRECTIVE WAR D97824	MAINTENANCE CORRECTIVE WR D97775
N/A	N/A	N/A	LEY OR OUTAGE AUMBER
			0
			MALFUNCTION AUSE RESULT
CLEANED CONNECTORS THE PREAMP AND THE SRM UNIT: INDICATION IS NOW READING CORRECTLY.	COMPLETED DISSOO-9 REV. 11 PER WORK INSTRUCTIONS	REPLACED IRM	COKRECTIVE ACTION REPLACED RELAY AND SECONDARY DISCONNECT 'A-2'

EQUIPMENT 2/3-9400-101 UNIT 2/3 AIR FILTRATION UNITS	NATURE OF MAINTENANCE PREVENTIVE MR D96247	SAFETY BRESDEN UNIT 2/ RELATED MAINTEN LER OR OUTAGE MALFUNC NUMBER CAUSE	FION RESULT
2/3-4641-21 2/3 A D/G STARTING AIR COMPRESSOR	CORRECTIVE MR D96359	N/A	OPENED/CLOSED BOORS FOR INSPECTION BY TECH STAFF DEPT., REINSTALLED LOCKWIRE
2/3-4199-198A 2/3 CRIB HGUSE UPPER LEVEL	CORRECTIVE MR D97223	N/A	PERFORMED DIS 6600-1 AND CALIBRATED
2/3-8350-2/3 2/3 250 VDC BATT CHARGER	CORRECTIVE MR D97490	N/A	REFAIRED VARIOUS FIRE LINES DAMAGED
CRI-120 2/3 D.G. AUX CONTACT PANEL	CORRECTIVE WE D97888	N/A	REPLACED CURRENT SENSING AND AMPLIFIER BOARDS, READJUSTED FLOAT AND EGBALIZE VOLTAGES, CHARGER NOW OPERATES PROPERLY REPLACED RELAYED
			REPLACED RELAYS AND MATCHED UP WITH EXISTING. INSPECTED PANEL AND CLEANED.

4.4 FAILED FUEL ELEMENT INDICATIONS

4.4.1 Unit 2

Dresden Unit 2 fuel performance during January, 1991 continued to show no indications of leaking fuel. This is based on the sum of the activities of the six noble gases as measured at the recombiner. Based on the reported data, Unit 2 had excellent fuel performance.

4.4.2 Unit 3

Dresden Unit 3 fuel performance during January, 1991 continued to show no indications of leaking fuel. This is based on the sum of the activities of the six noble gases as measured at the recombiner. Based on the reported data, Unit 3 had excellent fuel performance.

5.0 PLANT OR PROCEDURE CHANGES, TESTS, EXPERIMENTS, AND SAFETY RELATED MAINTENANCE

- 5.1 Amendments to Facility License or Technical Specifications.

 No new amendments to facility license or Technical Specifications were approved for use during January, 1991.
- 5.2 Changes to Procedures Which are Described in the FSAR (Units 2 and 3).

Table 5.2.1, attached, summarizes the revisions to procedures described in the FSAR which were approved during the January, 1991 reporting period.

TABLE 5.2.1

CHANGES TO PROCEDURES WHICH ARE DESCRIBED IN THE FSAR (UNITS 2 AND 3) FOR JANUARY, 1991

PROCEDURE TYPE	PROCEDURE NO.	PROCEDURE TITLE/DESCRIPTION	SUMMARY OF CHANGES
Dresden General Procedures	DGP 01-03	Unit 2(3) Hot Standby to Power Operation	1
	DGP 03-04	Control Rod Movements - Control Rod Sequences	3
Dresden Technical Surveillance Procedures	DTS 300-02	Control Rod Drive Scram Timing and Scram Valve Timing Test	1
	DTS 1600-04	Local Leak Rate Teting for Electrical Penetrations	3

NOTES: 1. Administrative change; intent of procedure unchanged.

2. Changed for clarification, intent of procedure unchanged.

3. Changed to incorporate requirements for new equipment; intent of procedure unchanged

4. Changed to implement improved testing/calibration methodology; intent of procedure unchanged.

5.3 Significant tests and experiments not described in the FSAR (Units 2 & 3)

Significant special procedures involving tests not described in the FSAR which were approved during the month of January, 1991 are listed below:

SP 90-12-170 Determination of Feedwater Insoluable Iron Concentration

The purpose of this procedure is for the determination of insoluable iron concentrations in the feedwater during the startup flushing using the Babcock and Wilcox color comparison method.

SP 90-12-171 Unit 2 Turbine Rotor Modification Test

The purpose of this procedure is to outline and document the ASEA BROWN BOVERI testing performed on the new low pressure "A" turbine rotor.

SP 91-01-01 Recirculation Pump Operation for Heating Reactor water

The purpose of this precedure is to specify the operation of the Reactor Recirculation Pumps to control reactor vessel temperature. The pumps will be run at greater than 28% pump speed with less than 20% feedwater flow.

SP 91-01-02 Control Rod Drive Stall Flow Verification Test

The purpose of this procedure is to determine if high stall flows are caused by improper closure of a CRD directional control valve.

SP 91-01-04 Generator Load Reject Instrument Response Time

The purpose of this procedure is to measure the instrument response time of the Main Generator Load Reject scram circuitry as a function of pressure switch setpoint. The time measured is from the initiation of Control Valve (CV) closure as indicted by CV position LVDT, to the trip of the Barksdale pressure switches which input the Reactor Protection System [PS 2(3)-5641-66. 67, 68, & 69]. This information will be used to ensure that the Fast Acting Solenoid modification M12-2(3)-81-25 has not significantly affected the transient analysis and that the response time is not a function of pressure switch setting.

SP 91-01-05 Vibration Analysis of the 2A Reactor Recirculation Pump at Elevated Recirculation Pump Speeds

The purpose of this procedure is to operate the 2A and 2B Recirculation Pumps at speeds greater than 28% rated speed with less than 20% feedwater flow to allow for acquisition and analysis of vibration data from the 2A Recirc. pump.

5.3 Continued

SP 91-01-06 125 Volt DC Stationary Battery Service Test

The purpose of this test is to verify that the battery is capable of meeting the design requirements. The battery is discharged at various rates in accordance with the load profile.

SP 91-01-07 Uncoupled Run of Reactor Recirculation Pump Motor 2A

The purpose of this procedure is to define the steps required to run the Unit 2 "A" Reactor Recirculation Pump Motor uncoupled from the pump so that vibration data can be obtained both before and after Recirculation Pump shaft replacement.

SP 91-01-08 Uncoupled Run of Reactor Recirculation Pump Motor 3B

The purpose of this procedure is to define the steps required to run the Unit 3 "B" Reactor Recirculation Pump Motor uncoupled from the pump so that vibration data can be obtained.

SP 91-01-09 Vibration Analysis of the 3B Reactor Recirculation Pump at Elevated Recirculation Pump Speeds

The purpose of this procedure is to operate the 3A and 3B Recirculation Pumps at speeds greater than 28% rated speed with less than 20% feedwater flow to allow for acquisition and analysis of vibration data from the 3B Recirc. pump.

SP 91-01-10 Modification Test for M12-2-88-063

This procedure provides instructions to test a Motor Operated Valve (MOV) in Modification Number M12-2-88-063, 2 to 4 Rotor MOV Limit Switch Replacement.

SP 91-01-11 D2 Drywell Penetration X-113 Helium Leak Test

The purpose of this procedure is to determine which ply of bellows penetration X113 is leaking. The information gathered from this procedure will be used in the calculation of the LLRT test results.

5.3 Continued

SP 91-01-12 Standby Gas Treatment Train B Logic Modifi ation Test

The purpose of this special procedure is to verify the proper function of the Standby Gas Treatment System and its interlocks with the Reactor Building Ventilation system upon the completion of Modification 12-0-90-025.

SP 91-01-14 Chemical Hygiene Plan

The purpose of this procedure is to provide a comprehensive approach for the protection of Commonwealth Edison Nuclear Generating Station laboratory personnel. The policies of Commonwealth Edison Company for personnel assigned to Dresden Nuclear Power Station chemistry laboratories are delineated by this procedure. The procedure provides guidelines for chemical procurement, maintenance, medical surveillance, accident response, and other vital health and safety issues. This procedure implements applicable regulatory requirements, in particular 29 CFR 1910.1450. This rocedure is applicable to personnel assigned to Dresden nuclear Power Station chemistry laboratories (i.e. chemistry technicians and chemistry management personnel).

SP 91-01-15 Modification Test for M12-2-91-001 2A Reactor Recirculation Pump Shaft Replacement

The purpose of this procedure is to provide instructions to operate the 2A and 2B Recirculation pumps at speeds greater than 28% rated speed and with less than 20% feedwater to allow for the acquisition and analysis of baseline data for Drive Flow, Pump Speed, and A & B Total Jet Pump Loop Flow following M12-2-91-001, 2A Reactor Recirculation Pump Shaft Replacement.

SP 91-01-17 Drywell Personnel Interlock Functional Mod Test for Minor Design Change D96368

The purpose of this test is to verify the proper function of the Drywell Personnel Interlock after the inscallation of new pressure equalizing valves for Minor Design Change D96368.

5.4 Safety Related Maintenance (Unit 2 and 3)

Safety related maintenance activities for January, 1991 are summarized in the attached tables.

5.5 Completed Safety Related Modifications (Units 2 and 3)

Only modifications which have been completely closed during January, 1991 are listed; modifications which are authorized for use but not completely closed will be reported based on the date of their final closure. For ease of reference, the changes have been identified by their design change control modification number.

Modification No.

Description

M12-1-77-35

This modification was performed to install safety related interfaces with existing primary system piping to perform the chemical cleaning on Urit 1. All piping, valves, and fittings conform to the applicable requirements of ANSI B31.1-1973 with addenda through Summer, 1976. The safety evaluation concluded that the margin of safety is not reduced.

M12-1-83-1

This modification was approved for completion of construction items and to assist in reactivation of the chemical cleaning facility and waste precessing equipment for Unit 1. All work associated with this modification has been completed although Unit 1 will NOT be restarted. The Chemical Cleaning building has been converted to an interim radwaste storage facility for Units 2 and 3. The safety evaluation concluded that the margin of safety is not reduced.

M12-1-84-5

This modification replaced the Unit 1 Radwaste Tank Heater Cables and installed a new Motor Control Center and ambient temperature switch. This was accomplished to reduce the hazard of exposed cables in the radwaste tank area and increase the reliability of monitoring the tank level. The safety evaluation concluded that the margin of safety is not reduced.

M12-2/3-88-98

This modification provided a new Unit 2 Trackway survey area for exiting the Radiological Controlled Area. This included new exit portal monitors and a low noise level room for surveying potentially contaminated equipment. The safety evaluation concluded that the margin of safety is not reduced.

5.6 *Temporary System Alterations (Unit 2 and Unit 3)

A "Temporary System Alteration" refers to electrical jumpers, lifted leads, removed fuses, fuses turned to non-conducting position, fuses moved from normal to eserve holder, temporary power supplies, test switches in alternate positions, temporary blank flanges, and spool pieces. Alterations controlled and documented as part of a routine out-of-service or other procedure, alterations which are a normal feature of system design, and hoses installed as part of a venting or draining process are not included.

5.6.1 Unit 2

Temporary System Alteration No.	Description	Installation Date	Removal Date
11-02-91	While the Unit 2 Turbine is out of service oil strainer plugs will be used to facilitate the turbine overhaul. These temporary plugs have been made physically different for positive identification purposes to ensure their removal. These plugs block flow of oil to bearings during all modes of operation and must be removed prior to rolling the turbine on the turning gear.	1-12-91	
11-04-91	This alteration installed a combination of three electro-chemical potential (ECP) measurement probes in a decon fitting of the 2A Recirculation water loop. This was done to determine ECP values for the Recirculation System Hydrogen Water Chemistry Verification System.	1-31-91	D2R13
5.6.2 Unit 3			
111-01-91	This temporary alteration provides a sample station for the condensate pump discharge to assist in sampling the conductivity and dissolved oxygen during relocation of the permanent sampling station being done by Modification M12-3-87-05C.	1-12-91	3 months
111-02-91	This temporary alteration adds instrumentation to the 3B Recirculation Pump which will monitor pump vibration. This additional equipment will enhance the temporary vibration monitoring equipment installed under Temp. Alt. III-12-90.	1-30-91	3 months