

Public Service Electric and Gas Company P.O. Box 236 Hancocks Bridge, New Jersey 08038 Hope Creek Generating Station

DATE May 18, 1994

U. S. Nuclear Regulatory Commission Document Control Desk Washington, DC 20555

Dear Sir:

HOPE CREEK GENERATING STATION DOCKET NO. 50-354 UNIT NO. 1 LICENSEE EVENT REPORT 94-005-00

This Licensee Event Report is being submitted pursuant to the requirements of 10CFR 50.73(a)(2)(iv).

Sincerely,

R.J. Hovey

General Manager -Hope Creek Operations

LLA/

Attachment SORC Mtg. 94-036 C Distribution

250029

1877 11

													LIC	ENS	EE E	VEN	T RE	PORT																			
FACIL	ITY N	AME	(1)		HOPI	E CRE	EK	GENE	RATIN	G ST	ATI	ON					DOCKET NUMBER (2) 0   5   0   0						0	ī	3	5	1	PAGE (3) 4 1 OF					1	4			
TITLE	(4):	Eng	ineer	ed Sa	afet	y Fee	tur	e Ac	tuati	on -	Re	sidu	ie (	Неа	t Re	HTIOV	al S	yste	em i	sola	tio	n di	e t	o d	esi	gn di	efi	cie	ncy				-				
EVENT	DATE	(5)			LER	NUME	ER	(6)						R	EPOR	T D	ATE	(7)			от	HER	FAC	ILI	TIE	SIN	VOL	VED	(8	)							
MONTH DAY			DAY YEAR			AY YEAR			YEAR		NU	UMBER		* 8		REV MO		MONT	MONTH		DAY YEAR		AR	R FAI		FACILITY NAME(S)					DO	DOCKET NUMBER(S)					
0	4 2	0	9	4	9	4		0	0	5	*	0	0		0	ž	1.	8	9	4																	
DPERAT		(9)			THI	S REF	ORT	15	SUBMI	TTED	PU	RSUA	NT	TO	THE	REQ	UIRE	MENT	5 0	F 10	CFR	: (0	HEC	K O	NE I	OR MO	ORE	BEI	LOW	) (	11)						
POWER LEVEL	X	0		0		20.40 20.40 20.40 20.40 20.40 20.40	)5(a )5(a )5(a )5(a	)(1) )(1) )(1) )(1)	(ii) (iii) (iv)		5 5 5	0.40 0.36 0.36 0.73 0.73	(c) (c) (a) (a)	(1) (2) (2) (2)	(i) (ii)		××	50. 50. 50.	.73(d .73(d .73(d	a)(2 a)(2 a)(2 a)(2	)(v )(v )(v	(vii) OTHER (S) (viii)(A) b						) Spe									
											LIC	ENSE	E C	ONT	ACT	FOR	THI	S LE	ER (	12)									_								
NAME		L	ouis A	Avers	50,	Seni	or !	Staf	f Eng	inee	r e	Tec	hni	cal									6	0	T	-	ELE	3	NE 9			3	8	6			
						(	OMP	LETE	ONE	LINE	FO	R EA	СН	COM	PONE	NT	FA1L	URE	NOTE	ED I	N T	HIS	REP	DRT	(1	5)		(All Property		- Acc				deem			
CAUSE	SYS	TEM	COMPO	ONENT	M/	ANUFA	CTU	RER	REP	ORTA	BLE	TO	NPR	DS?	100000		AUSE	USE SYSTEM C		4 C	COMPONEN		T	MAN	UFA	CTURI	ER	RI	EPO	RTA	BLE	то	DS?				
В	EC		XF	FMR		Mercelous									111														-								
SUPPLE	EMENT	AL RE	EPORT	EXPE	CTE	07 (1	4)	YES	1	N	0	х	D	ATE	EXP	ECT	ED (	D (15)   MONT						MONTH DAY YEAR													
11111	(111)	1111	HH	(111)	111	1111	111	1111	11111	1111	111	1111	111	111	1111	111	1111	111	1111		T			Г	T	T		100				1111					

# ABSTRACT (16)

On 4/20/94, control room personnel were performing an 18 month reactor pressure vessel hydrostatic surveillance test as the fifth refuel outage was nearing completion. Concurrent activities included scheduled repair, testing and system restorations in preparation for plant startup. One of the activities involved removal of the reactor protection system (RPS) motor-generator (MG) set for bearing replacement which required the "B" RPS bus to be powered via its alternate power supply. At 0005 hours the nuclear control operator (NCO - RO licensed) initiated a start of the "C" station service water pump. When the pump started the alternate RPS power supply electric protection assembly (EPA) breaker tripped resulting in a loss of RPS power, actuation of the Nuclear Steam Supply Shutoff System (NS4) logic and closure of the outboard main steam line drain valves. The NCO verified all appropriate automatic actions were complete and verified reactor pressure was within the allowable limits of the vessel pressure/temperature curves. The RPS EPA was reset, the NS4 logic was reset and the steam line drains were reopened. Initial investigation determined the breaker had tripped on undervoltage when the service water pump was started. Operation continued on the alternate power supply, until the M-G set was returned to service, with no further incidents. The root cause of this event is design deficiency. Less than timely implementation of corrective actions was a contributing factor for this event.

	LICENSEE EVENT RE	PORT (L	ER)	TEXT	CON	TINU	ATIO	N										
FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)									PAGE (3)							
HOPE CREEK GENERATING STATION	05000354	Y	YEAR		NUMBER			*	REV									
HUPE LREEK GENERALING STATION	02000334	9	4	-	0	0	5		0	0	0	2	1	of	1 0	1	4	

## PLANT AND SYSTEM IDENTIFICATION

General Electric - Boiling Water Reactor (BWR/4) Reactor Protection System Alternate power supply

### IDENTIFICATION OF OCCURRENCE

TITLE: Engineered Safety Feature Actuation - Main Steam Drain Line isolation due to Reactor Protection System power supply trip

Event Date: April 20, 1994

Event Time: 0005

This LER was initiated by Incident Report No. 94-088

# CONDITIONS PRIOR TO OCCURRENCE

Plant in OPERATIONAL CONDITION 4 (Cold Shutdown)
Reactor Power 0% of rated, 0 MWe
All Control Rods fully Inserted
Reactor vessel hydrostatic test in progress

#### DESCRIPTION OF OCCURRENCE

On 4/20/94, control room personnel were performing an 18 month reactor pressure vessel hydrostatic surveillance test as the fifth refuel outage was nearing completion. Concurrent activities included scheduled repair, testing and system restorations in preparation for plant startup. One of the activities involved removal of the reactor protection system (RPS) motor-generator (MG) set for bearing replacement which required the "B" RPS bus to be powered via its alternate power supply. At 0005 hours the nuclear control operator (NCO - RO licensed) initiated a start of the "C" station service water pump. When the pump started the alternate RPS power supply electric protection assembly (EPA) breaker tripped resulting in a loss of RPS power, actuation of the Nuclear Steam Supply Shutoff System (NS4) logic and closure of the outboard main steam line drain valves. The NCO verified all appropriate automatic actions were complete and verified reactor pressure was within the allowable limits of the vessel pressure/temperature curves. The RPS EPA was reset, the NS4 logic was reset and the steam line drains were reopened. Initial investigation determined the breaker had tripped on undervoltage when the service water pump was started. Operation continued on the alternate power supply, until the M-G set was returned to service, with no further incidents.

	LICENSEE EVENT R	EPORT (LE	R)	EXT	CON	TINU	ATIO	N									
FACILITY NAME (1)	DOCKET NUMBER (2)			PAGE (3)													
HOOS COREY CENEDATING STATION	DECOMPT.		YEAR		NUMBER			*	REV								
HOPE CREEK GENERATING STATION	05000354	9	4		0	0	5		0	0	0	F	3	of		0	4

### ANALYSIS OF OCCURRENCE

The normal power for the Nuclear Steam Supply Shutoff System logic is supplied via the Reactor Protection System (RPS) motor - generator (MG) set. An alternate power supply is also available via a 480/120VAC power supply transformer. Both the normal and alternate power is routed through an Electrical Protection Assembly (EPA) breaker which monitors the frequency and voltage level of the power being supplied to the NS4 and RPS logic. When the frequency or voltage exceeds predetermined limits the EPA will isolate the power source to ensure the logic devices are not subject to conditions outside their design ratings. The RPS MG set is designed with a flywheel to provide stable generator output during interruptions and/or minor fluctuations in the MG set motor power supply. The alternate power supply transformers incorporated in the original system design do not have the capability of maintaining a fixed output voltage during transient conditions, that is, as the input voltage varies so will the output voltage.

The alternate power supplies have been known to be susceptible to voltage swings when large motors are started. When the service water pump was started the voltage drop on the AC distribution system was of sufficient magnitude and duration to cause a drop in the output of the alternate power supply transformer of sufficient magnitude to trip the EPA breaker.

This problem has been previously identified and a corrective action to replace the alternate power supply transformer with a regulating power transformer was implemented. Regulated output transformers were installed during the third refuel outage to replace the in use 480 to 120 VAC transformers; however, the output waveform of the new transformers was tripping the EPA in the unloaded condition and was subsequently disconnected. Engineering continued to evaluate clanges that would eliminate the problem when a similar event occurred during the fourth refuel outage. Following this event, engineering proposed three options to rectify the problem. The selected option was a DCP which was targeted for installation during the fifth refuel outage. A review of the DCP installation instructions prior to the outage indicated the DCP could be installed at power and was not included in the outage. The DCP was scheduled to be performed during power operation following the outage.

Operations department procedures, used for the operation of the reactor protection system, had been revised previous to this event to caution operators that a loss of the alternate RPS power supply was possible when swapping infeed breakers to the electrical substations which supply the alternate power. Operator simulator training also included a scenario where the alternate power supply trips when a large motor is started and follow-up discussion of the alternate power supplies sensitivity to voltage swings induced during motor starts. Due to previous events, RPS MG-Set outages were minimized to avoid operation on the alternate power supply.

	LICENSEE EVENT REPOR	T (L	ER)	EXT	CON	TINU	OITA	N							
FACILITY NAME (1)	DOCKET NUMBER (2)			LI	ER NI	JMBE	R (6	PAGE (3)							
	AFAAA7F1	YEAR		*	NUMBER			*	REV						
HOPE CREEK GENERATING STATION	05000354		4	*	0	0	5		0	0	0	4	of	0	4

# APPARENT CAUSE OF OCCURRENCE

The root cause of this event is design deficiency. The installed RPS/NS4 alternate power supply transformers are susceptible to voltage transients which are expected to occur during normal plant operation. Contributing factors for this event are, less than timely implementation of corrective actions for the installation and testing of the new power supply transformers. Additionally, Control room operators did not anticipate the consequences of starting a large electrical load while operating on the RPS alternate power supply.

## PREVIOUS OCCURRENCES

There have been three previous events where the alternate power supply EPA breaker tripped resulting in an ESF actuation as reported in LER's 92-014-00, 91-015-00 and 90-033-00.

### SAFETY SIGNIFICANCE

The Reactor Protection System and Nuclear Steam Supply Shutoff System are designed to perform their safety function in the event of a loss of logic power. All systems functioned as required therefore the health and safety of the general public was not compromised during this event.

#### CORRECTIVE ACTIONS

The station has committed to install and test the new alternate power supply transformers by year end.

Operations department will review this event with Supervisors and Control Operators emphasizing the sensitivity of the alternate RPS power supply until the DCP is completed.

sincerely, Uponaco for By Hovey

R.J. Hovey

General Manager -

Hope Creek Operations

LLA/ SORC Mtg. 92-036 Recommended approval - Yes