

Entergy Operations, Inc.

HU, BOX 6 Killona, LA: 70066 Tel 504-464-3120

D. F. Packer General Manager Plant Operations Waterford 3

W3F1-94-0064 A4.05 PR

May 24, 1994

U.S. Nuclear Regulatory Commission Attn: Document Control Desk Washington, D.C. 20555

Subject:

Waterford 3 SES Docket No. 50-382 License No. NPF-38 Reporting of Licensee Event Report

Gentlemen:

Attached is Licensee Event Report Number LER-94-007-00 for Waterford Steam Electric Station Unit 3. This Licensee Event Report is submitted in accordance with 10CFR50.73 (a)(2)(iv).

Very truly yours,

py Star You

D.F. Packer General Manager Plant Operations

DFP/WHP/tjs Attachment

CC:

L.J. Callan, NRC Region IV G.L. Florreich J.T. Wheelock - INPO Records Center R.B. McGehee N.S. Reynolds NRC Resident Inspectors Office Administrator - LRPD

2600

9405260114 940524 ADOCK 05000382 PDR PDR

(NRC FC (5-92)	RM 366		U.S. NUCLEAR REGULATORY COMMISSION					APPROVED BY OMB NO. 3150-0104 EXPIRES 5/31/95								
LICENSEE EVENT REPORT (LER)							ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH INFORMATION COLLECTION REQUEST 50.0 HRS FORM COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMA AND RECORDS MANAGEMENT BRANCH (MNBB 7714), U.S. NUC REGULATORY COMMISSION, WASHINGTON, DC 20565-00031, AN THE PARERWORK REDUCTION PROJECT (9150-0104), DEFICE MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.									
FACILITY	AME (1)					ija matoki prote			DOCKET	NUMBER (2)			PAGE (3)			
Water	rford	Stear	n Elec	tric Statio	n Unit 3				1	0500	00 382		1 OF 7			
Rela	y Fai	lure	Causes	Reactor Po	wer Cutba	ick & S	ubseq	quent	React	or Trip						
EVE	T DATE	(5)		LER NUMBER	(6)	REPORT	T NUME	BER (7)	T	OTHER F	ACILITIES	INVOLVE	D (8)			
MONTH	(MAY		YEAR	SEQUENTIAL NUMBER	REVISION	MONTH	DAY	YEAR	FACILITY	n/a			oket Number 05000			
04	26	94	94	007	00	05	26	94	PAGILITY	NAME 1/a		100 (	DKET NUMBER			
OPERA	TING		THIS RE	PORT IS SUBMI	TTED PURSU	ANT TO TH	IE REQ	UIREMI	ENTS OF	10 CFR 5:	(Check one	or more	(11)			
MODI	E (9)	1	20.4	02(b)		20.405(c)			X	50.73(a)(2)	(IV)	T	73.71(b)			
POWER 20.405(a)(1)(i) LEVEL (10) 70 20.405(a)(1)(ii)			50.36(c)(1) 50.36(c)(2)				50.73(a)(2)	(v)		73.71(c)						
		20.405(a)(1)(ii)					50.73(a)(2)	(vii)		OTHER						
			20.4	05(a)(1)(iii)		50.73(a)(2)(i)				50.73(a)(2)(viii)(A)			(Specify in Abitract below and in Text, MIIC			
			20.405(a)(1)(iv)			50.73(a)(2)(ii)				50.73(a)(2)	(viii)(8)	For	6.366A)			
			20 405(a)(1)(V)			50.73(a)(2)(iii)				50.73(a)(2)						
N. A. B. A.					LICENSEE C	ONTACT F	OR THI	S LEA	(12)	1						
D.W.	Vinc	i, Su	perint	endent, Ope	erations					504/46	4-3178	de Ania Go				
			COMPLE	TE ONE LINE FO	OR EACH CON	PONENT	FAILUR	E DESC	CRIBED I	N THIS REP	ORT (13)					
GAU96	879.76M	COMP	ONENT	MANUFACTURER	REPORTABLE TO NPROS		0	SALISE	SYSTEM	VISTEM COMPONENT		ACTURER	REPORTABLE TO NPROS			
			SU	IPPLEMENTAL R	EPORT EXPER	CTED (14)			Party to an entry	diama la constante de la constante	EXPECTE	D MO	TH DAY YEAR			
YES (P yes	comp/wie		SUBMISSIO	N DATE)	X	NO				-	DATE (15	N				

At 0808 on April 26, 1994, a Reactor Power Cutback and Turbine Setback to 50% governor valve position occurred while placing the Reactor Power Cutback system in service at 70% reactor power. An automatic reactor trip occurred approximately 2 minutes later due to a low Pressurizer Pressure Core Protection Calculator Auxiliary trip set at 1860 psia. The Reactor Power Cutback actuation was caused by the presence of an erroneous Feedwater pump 'B' trip input signal to the Reactor Power Cutback circuitry. The subsequent low Pressurizer pressure and reactor trip resulted from the cooldown induced by a mismatch between turbine power and reactor power following the Reactor Power Cutback. The root cause of the erroneous Feedwater pump 'B' trip input signal was found to be a failure of a Westinghouse model BFD44S nonsafety relay which provides 'B' Feedwater pump trip status input to the Reactor Power Cutback circuitry. Immediate corrective actions included replacing the faulty relay and removing the Reactor Power Cutback system from service. Subsequent corrective actions will include, in part, evaluations and enhancements along with event review by operations personnel. This event did not compromise the public health and safety.

# REQUIRED NUMBER OF DIGITS/CHARACTERS FOR EACH BLOCK

BLOCK NUMBER	NUMBER OF DIGITS/CHARACTERS	TITLE
1	UP TO 46	FACILITY NAME
2	8 TOTAL 3 IN ADDITION TO 05000	DOCKET NUMBER
3	VARIES	PAGE NUMBER
4	UP TO 76	TITLE
5	5 TOTAL 2 PER BLOCK	EVENT DATE
6	7 TOTAL 2 FOR YEAR 3 FOR SEQUENTIAL NUMBER 2 FOR REVISION NUMBER	LER NUMBER
7	6 TOTAL 2 PER BLOCK	REPORT DATE
8	UP TO 18 - FAC LITY NAME 8 TOTAL - DOCKET NUMBER 3 IN ADDITION TO 05000	OTHER FACILITIES INVOLVED
9	1	OPERATING MODE
10	3	POWER LEVEL
11	1 CHECK BOX THAT APPLIES	REQUIREMENTS OF 10 CFR
12	UP TO 50 FOR NAME 14 FOR TELEPHONE	LICENSEE CONTACT
13	CAUSE VARIES 2 FOR SYSTEM 4 FOR COMPONENT 4 FOR MANUFACTURER NPRDS VARIES	EACH COMPONENT FAILURE
14	1 CHECK BOX THAT APPLIES	SUPPLEMENTAL REPORT EXPECTED
15	6 TOTAL 2 PER BLOCK	EXPECTED SUBMISSION DATE

	ESTIMATE INFORMAT COMMENT AND RECU REGULATI THE PAPI MANAGEN	ED BURDEN I TION COLLEC TS REGARDING ORDS MANAGE ORD COMMISS ERWORK RED	PER RES TION RE BURDE MENT BI ION, WAI UCTION	SPONSE TO C EQUEST: 50.0 N ESTIMATE TI RANCH (MNBB SHINGTON, DC PROJECT (315 SHINGTON, DC	COMPLY HRS 0 THE IN 7714), U 20555-0 10-0104),	WITH FORMAT S. NUCL 001, AND OFFICE	THIS ARD TION EAR D TO OF							
LICENSEE EVENT REPORT (LER) TEXT CONTINUATION					20003.		ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORMARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MNBB 7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.							
R (2)			PAGE (3)											
	YEAR	SEQUEN	TIAL ER	REVISION NUMBER		anner, di sali bi digita								
32	94	- 007		00	2	OF	/							
	2 2	2 94	2 94 007	2 2 4 (2) LER NUMBER (8) YEAR SEQUENTIAL NUMBER 94 007	2 94 - 007 - 00	2 94 007 00	LER NUMBER (6)     PAGE (3)       YEAR     SEQUENTIAL NUMBER     REVISION NUMBER     2       94     007     00							

## REPORTABLE OCCURRENCE

At 0808 on April 26, 1994, a Reactor Power Cutback and Turbine Setback to 50% governor valve position occurred while placing the Reactor Power Cutback system in service at 70% reactor power. An automatic reactor trip occurred approximately 2 minutes later due to a low Pressurizer Pressure Core Protection Calculator Auxiliary trip set at 1860 psia. The Reactor Power Cutback actuation was caused by the presence of an erroneous Feedwater pump 'B' trip input signal to the Reactor Power Cutback circuitry. The subsequent low Pressurizer pressure and reactor trip resulted from the cooldown induced by a mismatch between turbine power and reactor power following the Reactor Power Cutback. This event is thus being reported as an automatic Reactor Protection System (EIIS Identifier JC) actuation under 1^CFR50.73 (a)(2)(iv).

# INITIAL CONDITIONS

Plant Power	70 %
Plant Operating Mode	Mode 1; Power Operation
Procedures Being Performed Specific to this Event	OP-010-001, General Plant Operations OP-004-015, Reactor Power Cutback System OP-901-001, Reactor Power Cutback OP-902-000, Emergency Entry
Technical Specification LCO's in Effect	Procedure OP-902-001, Uncomplicated Reactor Trip Recovery Procedure.
Technical Specification LCO's in Effect Specific to this Event	None
Major Equipment Out of Service Specific to this Event	None

NRC FORM 366A

### U.S. NUCLEAR REGULATORY COMMISSION

## LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

#### APPROVED BY OMB NO. 3150-0104 EXPIRES 5/31/95

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS, FORMARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MNBB 7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)	DOCKET NUMBER (2)	And and a second	LER NUMBER (6)		PAGE (3)
and the second sec		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
Waterford Steam Electric Station Unit 3	ctric Station Unit 3 05000 382 94 007 0	00	3 OF 7		

TEXT (If more spece is required, use additional copies of NRC Form 366A). (17)

### EVENT SEQUENCE

(Times are approximate)

The Reactor Power Cutback System (RPCS)(No EIIS Identifier) is a control system designed to accommodate certain types of imbalances by providing step reduction in reactor power. The step reduction in reactor power is accomplished by the simultaneous dropping of one or more preselected sub groups of full length regulating Control Element Assemblies (CEAs)(EIIS Identifier AA-ROD) into the core. The RPCS also provides control signals to the Main Turbine (EIIS Identifier TA) to balance turbine and reactor power following the initial reduction in reactor power as well as to restore Steam Generator (EIIS Identifier AB-SB) water level and pressure to their normal controlled values. The system is designed to accommodate a loss of one Feedwater pump (EIIS Identifier SJ-P) or a large load rejection event.

At the time of an initiating event, the following control actions are generated by the Reactor Power Cutback System and transmitted to the Control Element Drive Mechanism Control System (CEDMCS) (EIIS Identifier AA) or the Main Turbine control system (EIIS Identifier TA): 1) Turbine setback to governor valve position equivalent to 50% turbine power; 2) Turbine ranback to match turbine power and reactor power; 3) Turbine power increase inhibit, and 4) Selected CEA subgroup drop command.

At 0720 on April 26, 1994 Operations personnel began power ascension from 68% to 93% reactor power for post refueling reactor physics testing. At 70% reactor power procedure OP-010-001, General Plant Operations, instructs operations personnel to place the RPCS into service in accordance with OP-004-015, Reactor Power Cutback System. At 0808 while the Primary Nuclear Plant Operator was attempting to place the RPCS into service in accordance with section 6.1 of OP-004-015 a Reactor Power Cutback and Turbine setback occurred. There were no prior indications to alert the operator that a Cutback signal was present. The selected CEA subgroups 11 and 5,

-

a

8

NRC FORM 366A	U.S. NUCLEAR REGU	APPROVED BY OMB NO. 3150-0104 EXPIRES 5/31/95						
LICENSEE EVENT REPORT (LER) TEXT CONTINUATION				D BURDEN PER RE TICN COLLECTION R TS REGARDING BURDI OROS MANAGEMENT B ORY COMMISSION, WA ERWORK REDUCTION MENT AND BUDGET, WI	SPONSE TO CI EQUEST: 50,0 IN ESTIMATE TO RANCH (MNBB 7 SHINGTON, DC 1 PROJECT (3150 ASHINGTON, DC 1	DMPLY WITH THI HRS. FORWARD THE INFORMATION 714), U.S. NUCLEAR 20855-0001, AND 72 20503.		
FACILITY NA	ME (1)	DOCKET NUMBER (2)	Contract Contracts Contract	LER NUMBER (8)		PAGE (3)		
	<ol> <li>Description of the second second second second seco</li></ol>		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
Waterford Steam Elect	Steam Electric Station Unit 3		94	- 007 -	00	4 OF /		

which are regulating groups 5 and 6, dropped into the core and the Main Turbine setback to a turbine load corresponding to 50% governor valve (EIIS Identifier TA-XCV) position (approx. 258 MWe) at a rate of 450%/min. The operating shift crew entered the Off-Normal operating procedure OP-901-101, Reactor Power Cutback. A turbine runback (at 200%/min.) should have acted to further reduce turbine load, thus balancing turbine and reactor power.

It appears that the turbine runback associated with this transient was not adequate in reducing turbine load sufficiently to terminate the Reactor Coolant System (RCS) (EIIS Identifier AB) cooldown. At approximately 0810, while the plant was in a transient condition, an attempt was made to further reduce turbine load to offset the observed dropping Pressurizer (EIIS Identifier AB-PZR) pressure and level. At approximately 0811 low Steam Generator pressure pre-trips were received on all 4 channels of the Reactor Protection System (RPS) (EIIS Identifier JC). The Shift Supervisor ordered a reactor trip but an automatic trip occurred before the reactor trip pushbuttons could be actuated. The reactor tripped on low Pressurizer Pressure Core Protection Calculator (CPC) (EIIS Identifier JC-CPU) auxiliary trip of 1860 psia. The lowest Pressurizer pressure observed during this event was 1840 psia.

The operating shift crew immediately entered the Emergency Operating procedure OP-902-000, Emergency Entry Procedure. At approximately 0817 the operating shift crew entered OP-902-001, Uncomplicated Reactor Trip procedure. The plant was stabilized and recovery actions were completed. The operating shift crew exited the Emergency Operating procedures and entered the General Plant Operations procedure, OP-010-001 at approximately 0900.

NRC FORM 366A U (5-92)	U.S. NUCLEAR REGULATORY COMMISSION					0-0104		
LICENSEE EVENT TEXT CONT	ESTIMATE INFORMA COMMENT AND RECI REGULATI THE PAPE MANAGEN	D BURDEN PER RES TION COLLECTION RE IARDING BURDE ORDS MANAGEMENT BF ORY COMMISSION, WAI ERWORK REDUCTION MENT AND BUDGET, WA	PONSE TO CA EQUEST: 50.0 N ESTIMATE TO RANCH (MNBB 7 SHINGTON, DC 3 PROJECT (3150 SHINGTON, DC 1	DMPLY WITH THIS HRS. FORWARD THE INFORMATION 714), U.S. NUCLEAF R0555-0001, AND TO -0104), OFFICE OF R0503.				
FACILITY NAME (1) DOCKET NUMBER (				LER NUMBER (6)				
Mar Production Plantate Cha	1. Fr. 11. 11. 11. 2	202	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	E		
waterford Steam Electric Sta	Steam Electric Station Unit 3		94	- 007 -	00	D OF J		

# CAUSAL FACTORS

Based on maintenance investigation it was discovered that the cause of the Reactor Power Cutback actuation was failure of a Westinghouse model BFD44S non-safety relay which provides 'B' Feedwater pump trip status input to the Reactor Power Cutback system circuitry. Although the relay was not energized, it was mechanically bound in the actuated state, thus sending a signal to the Reactor Power Cutback system circuitry which was representative of the Feedwater pump control oil low pressure switch actuations needed to cause a Reactor Power Cutback actuation. This actuation signal, due to the design of the RPCS, is not indicated in the main control room prior to placing the RPCS into service.

Based on preliminary failure analysis, the root cause of the relay failure is most likely attributed to mechanical binding caused by either wedged epoxy chips between the operating coil and plunger or by external pressure exerted on the coil by an adjacent coil (possibly due to thermal expansion) present in the ganged mounting configuration of the relays in the Feedwater pump control cabinet.

The cause of the reactor trip was low Pressurizer Pressure CPC auxiliary trip. Coincident with the Reactor Power Cutback actuation, the turbine setback to approximately 258 MWe (approx. 24% turbine power based on post trip data) and reactor power had dropped to approximately 19% (from plant computer data) just prior to the reactor trip. The resulting mismatch between reactor and turbine power induced a RCS cooldown which lowered Pressurizer pressure to the CPC auxiliary trip setpoint of 1860 psia. The turbine power/reactor power mismatch resulted from an anomaly in the turbine runback function to sufficiently lower turbine power to terminate the cooldown. The specific turbine control system anomaly is presently under investigation.

The Westinghouse model BFD44S relays are commonly used in non-safety applications

NRC FORM 366A (5-92)	APPROVED BY OMB NO. 3150-0104 EXPIRES 5/31/95							
LICENSEE E TEXT	ESTIMATE INFORMA COMMEN AND REC REGULAT THE PAP MANAGEN	D BURDEN PER RES TION COLLECTION RE TIS REGARDING BURDE ORDS MANAGEMENT BE ORY COMMISSION, WAS ERWORK REDUCTION MENT AND BUDGET, WA	PONSE TO C QUEST 50.0 N ESTIMATE TO SANCH (MNBB SHINGTON, DC PROJECT (315 SHINGTON, DC	OMPLY WITH TH HRS. FORWAR D THE INFORMATIO 7714), U.S. NUGLEA 20555-0001, AND T 0-0104), OFFICE C 20503.				
FACILITY NAME	(1)	DOCKET NUMBER (2)	printer and the second	LEA NUMBER (6)		PAGE (3)		
	- Chating Unit 2	202	YEAR	SEQUENTIAL NUMBER	AEVISION NUMBER	6		
Waterford Steam Electri	Steam Electric Station Unit 5		94	- 007	00	OF V		

The Westinghouse model BFD44S relays are commonly used in non-safety applications throughout the plant. These relays are 'energize to trip' elays and remain energized for the entire duration of plant shutdowns. Extender periods with the relays in the energized state may accelerate the failure mechanism and may have contributed to the failure in this event.

The reliability feature of the 2 out of 2 input logic employed by the Reactor Power Cutback system for Feedwater pump lube oil pressure switches is defeated by utilizing a single actuating relay to provide an actuation input signal to the Reactor Power Cutback Module. This type of arrangement facilitates a single failure scenario in that a single relay failure can cause a Reactor Power Cutback signal to be generated. In addition, the Reactor Power Cutback system provides no advance status information prior to placing the system in service, in effect resulting in a 'set-up' situation for the operator.

# IMMEDIATE CORRECTIVE MEASURES

Immediate corrective measures included a maintenance investigation of the erroneous Reactor Power Cutback, which resulted in the discovery and replacement of the faulty relay in the Feedwater pump control cabinet. Additionally, the Reactor Power Cutback System will remain out of service until adequate measures can be established to allow the control room staff to detect the presence of a Reactor Power Cutback signal or circuit malfunction prior to placing the Reactor Power Cutback System in service.

# ACTIONS TO PREVENT RECURRENCE

Actions to prevent recurrence include the following: (1) Identification of other similar relays and if any exist, evaluate their potential for affecting plant /system reliability; (2) Assessment of the overall response of the Reactor Power Cutback System as it responded in this event; (3) A review of this event by the Operations

IRC FORM 366A U.S. NUCLEAR REGULATORY COMMISSION				APPROVED BY OMB NO. 3150-0104 EXPIRES 5/31/95								
LICENSEE EVENT REPORT (LER) TEXT CONTINUATION					ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH TH INFORMATION COLLECTION REQUEST 50.0 HRS. FORWA COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATI AND RECORDS MANAGEMENT BRANCH (MNBB 77.14), U.S. NUCLE REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.						WARD MATION ICLEAP IND TO CE OF	
ang ngang ngang sa	FACILITY NAME (1)	1	DOCKET NUM	ABER (2)		L.	ER NUMB	(B) (R)	art. Lord Contract Contracts	1	PAGE	(3)
Waterford Sto	am Electric Station Unit	3	30.2		YEAR		SEQUENTIA NUMBER	-	REVISION NUMBER	7		7
wateriord ste	Steam Electric Station unit S		05000	302	94	-	007		00		OF	

Superintendent with Operations personnel during licensed operator requalification training, reemphasizing the importance of taking conservative action to manually initiate Plant Protection functions prior to reaching automatic Plant Protection setpoints; and (4) Discussion or simulation of expected plant responses during Reactor Power Cutback at reduced power levels in Operator requalification training.

In addition to the preceding actions to prevent recurrence Waterford 3 has placed information related to this event on the Nuclear Network for dissemination to other utilities.

# SAFETY SIGNIFICANCE

Although this event was initiated by an erroneous Reactor Power Cutback input signal, the Reactor Protection System functioned as designed to provide an automatic reactor trip on low Pressurizer pressure CPC auxiliary trip of 1860 psia. This provided plant protection as required therefore the health and safety of the general public was not compromised.

# SIMILAR EVENTS

A similar event occurred on April 15, 1987 and was reported on Licensee Event Report 87-012. In this event the Reactor Power Cutback System was placed in service at approximately 50% reactor power with only one Feedwater pump in operation. The Reactor Power Cutback System requires that both Feedwater pumps be in service before placing the Reactor Power Cutback System in service. The control room staff took immediate action to reduce turbine load to minimum and withdraw CEAs in response to rapidly dropping Reactor Coolant System temperature and pressure. The ensuing transient led to an automatic reactor trip due to complications with steam generator levels. The root cause identified for this event was inadequate procedures.