

LICENSEE EVENT REPORT

CONTROL BLOCK: \_\_\_\_\_ (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | NJ | OC | P | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 0 | 4 | 1 | 1 | 1 | 1 | 4 | \_\_\_\_\_ | 5

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

CON'T

01 | L | 6 | 0 | 5 | 1 | 0 | 0 | 0 | 2 | 1 | 9 | 7 | 0 | 1 | 1 | 2 | 6 | 8 | 3 | 8 | 0 | 3 | 0 | 4 | 8 | 3 | 9

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 | 7 | While performing the Containment Spray System Automatic Actuation Test,

03 | high drywell pressure switches IP15A, B, C tripped at a value

04 | greater than that specified in Technical Specifications,

05 | Table 3.1.1, E.1. The as found trip points were 2.15, 2.24, and 2.10 psig.,

06 | respectively. The desired setpoint is 2.0 psig. This event is reportable

07 | under Technical Specifications 6.9.2.b(2). Safety significance is mini-

08 | mal since switches would have actuated but at slightly high pressures.

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

09 | S | B | 11 | X | 12 | Z | 13 | I | N | S | T | R | U | 14 | S | 15 | Z | 16

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

17 | 8 | 3 | 21 | 22 | - | 23 | 0 | 0 | 5 | 24 | 25 | / | 26 | 0 | 3 | 27 | L | 28 | - | 29 | 0 | 30

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

18 | E | 18 | G | 19 | Z | 20 | Z | 21 | 0 | 0 | 0 | 0 | 27 | Y | 23 | N | 24 | N | 25 | I | 2 | 0 | 4 | 47

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 | The cause of the event has not yet been determined. Pressure switches

11 | IP15A, B, and C were readjusted to trip within Technical Specification

12 | limits. Investigation is continuing to determine the cause of the

13 | unusually high setpoint drift. Procedural acceptance criteria will be

14 | reviewed to possibly accommodate instrument repeatability problems.

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

15 | E | 28 | 0 | 4 | 7 | 29 | NA | 30 | B | 31 | Surveillance test | 32

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

16 | Z | 33 | Z | 34 | NA | 35 | NA | 36 | LOCATION OF RELEASE | 36

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

17 | 0 | 0 | 0 | 37 | Z | 38 | NA | 39

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

18 | 0 | 0 | 0 | 40 | NA | 41

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

19 | Z | 42 | NA | 43

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

20 | N | 44 | NA | 45

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

NAME OF PREPARER C.P. Sobel PHONE (609) 971-4891