

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 V A S P S 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 1 5

01 L 6 0 5 0 0 0 2 8 0 7 0 2 1 1 8 3 8 0 3 0 4 8 3 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

02 With the unit at cold shutdown during an investigation of a PCV-1455C malfunction,
03 it was found that the instrument air check valve to the PORV was installed backwards.
04 This event is contrary to T.S.-3.1.G.1.b.(3) and is reportable per T.S.-6.6.2.b(2).
05 The emergency air bottles for the PORV remained operable to supply the motive force
06 for the valve, therefore the health and safety of the public remained unaffected.

09 SYSTEM CODE PA 11 CAUSE CODE B 12 CAUSE SUBCODE C 13 COMPONENT CODE VALVE X 14 COMP. SUBCODE C 15 VALVE SUBCODE A 16
17 LER/RO REPORT NUMBER 83 EVENT YEAR 83 SHUTDOWN METHOD Z 21 HOURS 0000 ATTACHMENT SUBMITTED Y 23 NFRD-4 FORM SUB. N 24 PRIME COMP. SUPPLIER L 25 COMPONENT MANUFACTURER C685 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

10 The check valve was backwards in the line due to an installation error during
11 implementation of Design Change 79-53. The valve was removed and reinstalled in the
12 correct orientation.

15 FACILITY STATUS G 28 % POWER 0000 29 OTHER STATUS N/A 30 METHOD OF DISCOVERY A 31 DISCOVERY DESCRIPTION PCV-1455C Investigation 32

16 ACTIVITY CONTENT Z 33 Z 34 AMOUNT OF ACTIVITY N/A 35 LOCATION OF RELEASE N/A 36

17 PERSONNEL EXPOSURES NUMBER 0 10 0 37 TYPE Z 38 DESCRIPTION N/A 39

18 PERSONNEL INJURIES NUMBER 0 10 0 40 DESCRIPTION N/A 41

19 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION N/A 43

20 ISSUED DESCRIPTION N 44 PUBLICITY DESCRIPTION 8303160211 830304 PDR ADOCK 05000280 PDR S N/A 45

ATTACHMENT 1
SURRY POWER STATION, UNIT NO. 1
DOCKET NO: 50-280
REPORT NO: 83-011/03L-0
EVENT DATE: 02-11-83

TITLE OF THE EVENT: PCV-1455C INOPERABLE

1. Description of the Event

With the unit at cold shutdown during an investigation of the inoperability of PCV-1455C (Pressurizer PORV) it was found that the check valve in the instrument air line to the PORV was in backwards. This event is contrary to T.S.-3.1.G.1.b.3 and is reportable per T.S.-6.6.2.b.(2).

2. Probable Consequences and Status of Redundant Equipment

Air supplied through the instrument air line for PCV-1455C provides the normal motive force to open the PORV. The emergency air bottles for the PORV remained available to open the PORV, therefore the health and safety of the public were not jeopardized.

3. Cause

The check valve was installed backwards during implementation of design change 79-53 due to personnel error. Failure to find the error during final design testing was due to loss of administrative control in that the final design testing procedure for unit 1 was not sufficient to find the problem.

4. Immediate Corrective Action

The check valve was removed from the line and reinstalled in the correct orientation.

5. Subsequent Corrective Action

None scheduled.

6. Action Taken to Prevent Recurrence

No further action is required. Design Change Program Modifications over the past three years have strengthened controls over plant design modifications.

7. Generic Implications

The unit 2 check valve was verified to be properly installed, there are therefore, no generic implications of this event.