

LICENSEE EVENT REPORT

CONTROL BLOCK: \_\_\_\_\_ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | N | J | O | C | P | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | \_\_\_\_\_ | 5  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

CON'T  
01 | L | 6 | 0 | 5 | 0 | 0 | 0 | 2 | 1 | 9 | 7 | 0 | 1 | 2 | 3 | 8 | 3 | 8 | 0 | 3 | 0 | 4 | 8 | 3 | 9  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)  
02 | Operation in a degraded mode permitted by a limiting condition for oper-  
03 | ation as specified in Tech Spec 3.7.B. when startup Bank 5 was removed  
04 | from service to check for damage as a result of dilution plant main  
05 | breaker cable termination failure. Safety significance is minimal as a  
06 | standby power source was available if needed, no damage to the startup  
07 | bank was found and the startup bank was returned to service within 12  
08 | hours. Event is reportable per Tech Specs, paragraph 6.9.2.b.2.

09 | SYSTEM CODE: E A 11 | CAUSE CODE: E 12 | CAUSE SUBCODE: A 13 | COMPONENT CODE: E L E C T R O N 14 | COMP SUBCODE: Z 15 | VALVE SUBCODE: Z 16  
17 | LER/RO REPORT NUMBER: 83 | EVENT YEAR: 83 | SEQUENTIAL REPORT NO.: 002 | OCCURRENCE CODE: 03 | REPORT TYPE: L | REVISION NO.: 0  
18 | ACTION TAKEN: A | FUTURE ACTION: Z | EFFECT ON PLANT: Z | SHUTDOWN METHOD: Z | HOURS: 0000 | ATTACHMENT SUBMITTED: Y | NRC-4 FORM 504: N | PRIME COMP. SUPPLIER: L | COMPONENT MANUFACTURER: R 0 9 8

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)  
10 | Startup Bank 5 was removed from service to inspect for damage. The  
11 | startup bank and its associated cables were meggered satisfactorily and  
12 | returned to service. The dilution pump power feed terminations were  
13 | replaced. The cause of termination failure is being investigated.

14 | FACILITY STATUS: E 28 | % POWER: 047 29 | OTHER STATUS: NA 30 | METHOD OF DISCOVERY: A 31 | DISCOVERY DESCRIPTION: Operator observation 32  
15 | ACTIVITY CONTENT RELEASED OF RELEASE: Z 33 | AMOUNT OF ACTIVITY: NA 34 | LOCATION OF RELEASE: NA 35

16 | PERSONNEL EXPOSURES NUMBER: 0000 | TYPE: Z 37 | DESCRIPTION: NA 38  
17 | PERSONNEL INJURIES NUMBER: 0000 | DESCRIPTION: NA 40

18 | LOSS OF OR DAMAGE TO FACILITY TYPE: D 47 | DESCRIPTION: Dilution Pump power cables terminations damaged 48

19 | PUBLICITY ISSUED DESCRIPTION: N 44 | NRC USE ONLY

NAME OF PREPARER: Arthur C. Dickinson | PHONE: (609) 971-4626