

Final Remedial Investigation/Feasibility
Study—Environmental Assessment
for the Monticello, Utah,
Uranium Mill Tailings Site

Volume I
Remedial Investigation

January 1990

Prepared by
UNC Geotech
Grand Junction, Colorado 81502

for
U.S. Department of Energy
Surplus Facilities Management Program
Under Contract No. DE-AC07-86ID12584

This report was prepared as an account of work sponsored by an agency of the United States Government. Neither the United States Government nor any agency thereof, nor any of their employees, makes any warranty, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness, or usefulness of any information, apparatus, product, or process disclosed in this report, or represents that its use would not infringe privately owned rights. Reference herein to any specific commercial product, process, or service by trade name, trademark, manufacturer, or otherwise, does not necessarily constitute or imply its endorsement, recommendation, or favoring by the United States Government or any agency thereof. The views and opinions of authors expressed herein do not necessarily state or reflect those of the United States Government or any agency thereof.

TABLE OF CONTENTS

	<u>Page</u>
FOREWORD	xv
EXECUTIVE SUMMARY	xvi
1.0 INTRODUCTION	1-1
1.1 Program Overview	1-1
1.2 Site Background Information	1-2
1.2.1 Site Location and Description	1-2
1.2.2 History of the Monticello Mill Operations	1-9
1.2.2.1 Mill Ownership	1-9
1.2.2.2 Milling Processes	1-10
1.2.2.3 Environmental Problems Associated with Mill Operations	1-14
1.3 Nature and Extent of Problems	1-24
1.3.1 Quantities of Tailings and Contaminated Materials	1-24
1.3.1.1 Tailings and Contaminated Material: On Site	1-24
1.3.1.2 Contaminated Materials: Off Site	1-24
1.3.2 Hazards Associated with the Site	1-25
1.4 Report Organization	1-25
1.5 References	1-26
2.0 SITE FEATURES INVESTIGATION	2-1
2.1 Demography	2-1
2.1.1 Population	2-1
2.1.2 Housing	2-4
2.1.3 Employment and Economic Structure	2-4
2.1.4 Transportation	2-5
2.1.5 Community Services	2-8
2.2 Land Use	2-10
2.2.1 Land Use and Management in San Juan County	2-10
2.2.2 Zoning and Land Use	2-11
2.2.3 Land Values and Ownership	2-11
2.3 Natural Resources	2-12
2.3.1 Water	2-12
2.3.2 Minerals	2-13
2.3.3 Scenic, Historic, and Cultural Resources	2-13
2.3.3.1 Scenic Resources	2-13
2.3.3.2 Historic Resources	2-13
2.3.3.3 Cultural Resources	2-15
2.4 Climatology	2-15
2.5 References	2-23
3.0 HAZARDOUS SUBSTANCES INVESTIGATION	3-1
3.1 Introduction	3-1
3.1.1 Objectives and Scope of Waste Characterization	3-1

TABLE OF CONTENTS (continued)

	<u>Page</u>
3.1.2 Approach to Waste Characterization	3-2
3.1.2.1 Sample Selection	3-2
3.1.2.2 Statistical Methods of Data Analysis	3-2
3.2 Waste Types	3-3
3.2.1 Waste Quantity and Containment	3-3
3.2.2 Ore	3-4
3.2.2.1 Vanadiferous Ores	3-4
3.2.2.2 Nonvanadiferous Ores	3-6
3.2.2.3 Summary of Ores	3-6
3.2.3 Description of the Monticello Tailings	3-6
3.2.3.1 Antimony	3-6
3.2.3.2 Arsenic	3-7
3.2.3.3 Beryllium	3-8
3.2.3.4 Cadmium	3-11
3.2.3.5 Chromium	3-11
3.2.3.6 Copper	3-14
3.2.3.7 Lead	3-14
3.2.3.8 Mercury	3-14
3.2.3.9 Molybdenum	3-18
3.2.3.10 Nickel	3-18
3.2.3.11 Selenium	3-18
3.2.3.12 Silver	3-21
3.2.3.13 Thallium	3-21
3.2.3.14 Radium-226	3-21
3.2.3.15 Uranium	3-24
3.2.3.16 Vanadium	3-24
3.2.3.17 Zinc	3-27
3.2.3.18 Principal Components Analysis	3-27
3.2.3.19 Quantities of Hazardous Substances	3-31
3.2.4 Summary of Tailings Characterization	3-31
3.3 Waste Mobility	3-32
3.3.1 Introduction	3-32
3.3.2 Basic Concepts of Release, Mobility, and Retardation of Trace Constituents	3-32
3.3.3 Effect of Eh and pH	3-34
3.3.4 Equilibrium Versus Kinetic Mechanisms	3-34
3.3.5 Monticello Mill Site - Water Types	3-34
3.3.6 Mobility of Inorganic Contaminants	3-35
3.3.6.1 Uranium	3-35
3.3.6.2 Radium	3-39
3.3.6.3 Selenium	3-40
3.3.6.4 Vanadium	3-40
3.3.6.5 Arsenic	3-41
3.3.6.6 Molybdenum	3-42
3.3.6.7 Cr, Cu, Pb, Ni, and Zn	3-42
3.3.6.8 Other EPA hazardous substances: Sb, Be, Cd, Hg, Ag, and Tl	3-42
3.3.7 Concluding Statement on Contaminant Mobility	3-42
3.4 References	3-43

TABLE OF CONTENTS (continued)

	<u>Page</u>
4.0 HYDROGEOLOGIC INVESTIGATION	4-1
4.1 Soils	4-1
4.1.1 Soil Stratigraphy	4-1
4.1.2 Description of Tailings	4-2
4.1.2.1 Acid Tailings Pile	4-2
4.1.2.2 East Tailings Pile	4-2
4.1.2.3 Vanadium Tailings Pile	4-2
4.1.2.4 Carbonate Tailings Pile	4-5
4.1.3 Extent of Contamination	4-5
4.1.3.1 Introduction	4-5
4.1.3.2 Methods	4-6
4.1.3.3 Results	4-9
4.2 Geology	4-12
4.2.1 Regional Setting	4-12
4.2.2 Site Geology	4-14
4.2.2.1 Brushy Basin Member	4-21
4.2.2.2 Burro Canyon Formation	4-21
4.2.2.3 Dakota Sandstone	4-23
4.2.2.4 Mancos Shale	4-25
4.2.2.5 Unconsolidated Surficial Deposits	4-25
4.3 Ground-Water Investigation	4-26
4.3.1 Introduction	4-26
4.3.2 Alluvial Aquifer	4-26
4.3.2.1 Description	4-26
4.3.2.2 Hydraulic Characteristics	4-26
4.3.2.3 Water-Table Contour Map	4-28
4.3.3 Mancos Shale and Dakota Sandstone	4-31
4.3.4 Burro Canyon Aquifer	4-31
4.3.4.1 Description	4-31
4.3.4.2 Lithology and Hydrology	4-32
4.3.4.3 Hydraulic Characteristics	4-32
4.3.4.4 Burro Canyon Equipotential Surface and Aquifer Discharge	4-37
4.3.5 Vertical Conductivity of the Dakota Aquitard	4-38
4.3.6 Determination of Ground Water Age by Tritium Analysis	4-38
4.4 Ground-Water Chemistry	4-41
4.4.1 Introduction	4-41
4.4.2 Alluvial Aquifer	4-41
4.4.3 Burro Canyon Aquifer	4-46
4.4.4 Dakota Sandstone	4-58
4.5 References	4-59
5.0 SURFACE WATER INVESTIGATION	5-1
5.1 Surface Water	5-1
5.1.1 Montezuma Creek Watershed	5-1
5.1.1.1 Description of Monticello Reservoir	5-3
5.1.1.2 Highway 191 Embankment Description	5-4

TABLE OF CONTENTS (continued)

	<u>Page</u>
5.2 Flood Potential/Probable Maximum Flood	5-4
5.3 Drainage	5-7
5.4 Sediments	5-7
5.4.1 Physical Characteristics	5-7
5.4.2 Radiologic Surveys	5-8
5.4.3 Floodplain Soil and Stream Sediments	5-8
5.5 Surface-Water Chemistry	5-13
5.5.1 Characterization of Background	5-13
5.5.2 On-Site Surface Water	5-13
5.5.3 Off-Site Surface Water	5-14
5.5.3.1 Farm Pond	5-14
5.5.3.2 Montezuma Creek	5-18
5.5.3.3 Montezuma Canyon	5-19
5.6 References	5-22
 6.0 AIR INVESTIGATION	6-1
6.1 Atmospheric Radon	6-1
6.1.1 Sampling Method	6-1
6.1.2 Analytical Control	6-3
6.1.3 Measurement Results and Comparison With Federal Standards	6-4
6.1.4 Ongoing Atmospheric Radon Monitoring	6-7
6.2 Radon Flux	6-10
6.2.1 Measurement Method	6-10
6.2.2 Results of On-Site Measurements	6-14
6.2.3 Results of Off-Site Measurements	6-14
6.3 Atmospheric Transport	6-19
6.3.1 Model Description	6-19
6.3.2 Model Evaluation	6-20
6.3.3 Summary	6-24
6.4 Air Particulate Monitoring	6-25
6.4.1 Sampling Method	6-25
6.4.2 Analytical Results and Comparison with State and Federal Standards	6-25
6.4.2.1 Radiologic Air Particulates	6-25
6.4.2.2 Nonradiologic Air Particulates	6-27
6.5 References	6-29
 7.0 BIOTA INVESTIGATION	7-1
7.1 Vegetation	7-1
7.1.1 Description	7-1
7.1.2 Plant Species Present	7-2
7.1.3 Cover Data	7-3
7.1.4 Production	7-3
7.1.5 Shrub Density and Height	7-3
7.2 Wildlife	7-4
7.3 Aquatic Biology	7-5
7.3.1 Introduction	7-5

TABLE OF CONTENTS (continued)

	<u>Page</u>
7.3.2 Physical Habitat	7-5
7.3.3 Periphyton/Plankton	7-7
7.3.4 Aquatic Invertebrates	7-7
7.3.5 Fisheries	7-7
7.3.6 Rare and Endangered Fish.	7-7
7.4 References	7-7
 8.0 PUBLIC HEALTH EVALUATION	 8-1
8.1 Public Health Evaluation for Radioelements	8-1
8.1.1 Natural-Background Radiologic Environment	8-1
8.1.1.1 Gamma Exposure Rate	8-1
8.1.1.2 Soils	8-1
8.1.1.3 Air Particulates	8-2
8.1.1.4 Radon	8-2
8.1.2 Radiologic Conditions Due to the Millsite and Contaminated Peripheral Properties	8-2
8.1.2.1 Gamma Exposure Rate	8-2
8.1.2.2 Air Particulates	8-3
8.1.2.3 Radon	8-3
8.1.3 Radiation Source Terms	8-7
8.1.3.1 Exposure Pathways	8-7
8.1.3.2 Source Terms for Gamma-Radiation Exposure	8-8
8.1.3.3 Source Terms for Air-Particulate Concentrations	8-8
8.1.3.4 Source Terms for Radon Emissions	8-9
8.1.4 Population Dose Commitments from Natural Background and from Present Enhanced Conditions	8-9
8.1.5 Health Effects from Existing Conditions	8-10
8.2 Public Health Evaluation for Nonradioactive Substances	8-12
8.2.1 Selection of Indicator Elements	8-14
8.2.2 Exposure Assessment	8-18
8.2.2.1 Environmental Fate and Transport of Indicator Elements	8-18
8.2.2.2 Identification of Potential Exposure Pathways and Populations at Risk	8-20
8.2.2.3 Exposure Pathway Models and Assumptions	8-22
8.2.2.4 Exposure Estimates	8-22
8.2.3 Toxicity Assessment	8-22
8.2.4 Risk Characterization and Comparison to Standards	8-33
8.2.4.1 Comparison of Exposure Doses to Acceptable Intakes for Chronic Exposure	8-33
8.2.4.2 Comparison of Surface-Water Concentrations to Surface Water-Quality Standards	8-33
8.2.4.3 Arsenic	8-36
8.2.5 Conclusions	8-37
8.3 References	8-38

TABLE OF CONTENTS (continued)

	<u>Page</u>
APPENDIX A. GEOLOGIC DATA ACQUISITION	A-1
APPENDIX B. ANALYTICAL DATA FOR WATER	B-1
APPENDIX C. U.S. Army Corps of Engineers Wetlands Assessment	C-1

LIST OF FIGURES

Figure 1-1. Monticello, Utah, Regional Location Map	1-3
1-2. Monticello Millsite Land Survey	1-4
1-3. Contaminated Areas Under Investigation.	1-5
1-4. Topography of the Millsite and Adjacent Areas	1-7
1-5. Monticello Millsite Plan	1-8
1-6. Aerial View of the Millsite and Tailings Piles at Monticello, Utah	1-13
1-7. View of the Acid Pond Shortly after Start-up of the Acid Leach RIP Plant	1-15
1-8. View of the Monticello Mill, Summer 1960	1-18
1-9. Surface of the East Pile	1-18
1-10. View of the Carbonate Pile and the Toe of the Vanadium Pile	1-19
1-11. View of the Carbonate Pile, Acid Pile, Vanadium, and East Piles	1-19
1-12. Cloud of Windblown Tailings from Carbonate Pile	1-20
1-13. Eroded Slopes of the Vanadium Pile	1-20
1-14. View West up Montezuma Creek	1-21
1-15. Tailings Sand Dune at East End of the East Pile	1-21
1-16. Contaminated-Scrap Burial Trench on West Flank of the Carbonate Pile	1-22
1-17. View of the Contaminated-Scrap Burial Trench	1-24
1-18. "Ore Residue" Dumped on Foundation of Carbonate Plant at Monticello	1-23
1-19. "Ore Residue" Covering Foundation of the Resin-in-Pulp Building at Monticello	1-23
2-1. Monticello, Utah, Located at the Intersection of U.S. Highways 191 and 666	2-6
2-2. Annual Average Daily Traffic Counts for Highways in the Monticello Area	2-7
2-3. Aerial Photograph Showing Relation of Project Area to the Town of Monticello	2-9
2-4. San Juan County Political Boundaries and Major Scenic Areas	2-14
2-5. Rose Diagram of Prevailing Annual wind Trends for the Monticello Site, 1982 through 1986	2-18
2-6. Rose Diagram of Annual Average Wind Magnitudes for the Monticello Site, 1982 through 1986	2-19
2-7. Rose Diagram of Prevailing Night-Wind Trends for the Monticello site, 1982 through 1986	2-20

LIST OF FIGURES (continued)

	<u>Page</u>
Figure 2-8. Rose Diagram of Prevailing Day-Wind Trends for the Monticello Site, 1982 through 1986	2-21
3-1. Arsenic: Graphical Data Summary	3-9
3-2. Beryllium: Graphical Data Summary	3-10
3-3. Cadmium: Graphical Data Summary	3-12
3-4. Chromium: Graphical Data Summary	3-13
3-5. Copper: Graphical Data Summary	3-15
3-6. Lead: Graphical Data Summary	3-16
3-7. Mercury: Graphical Data Summary	3-17
3-8. Molybdenum: Graphical Data Summary	3-19
3-9. Nickel: Graphical Data Summary	3-20
3-10. Radium-226: Graphical Data Summary	3-22
3-11. Uranium: Graphical Data Summary	3-25
3-12. Vanadium: Graphical Data Summary	3-26
3-13. Zinc: Graphical Data Summary	3-28
3-14. Principal Components Analysis Plot Showing Overall Structure of the Data from the Four Tailings Piles	3-30
3-15. Results of July 1984 Water Analyses	3-37
4-1. Locations of Geologic and Tailings Pile Cross Sections at the Monticello Millsite	4-3
4-2. Contour Map Showing Radium-226 Activity (pCi/g) in Soil	4-7
4-3. Histogram of Analytical Results for Ra-226 in Soils on Peripheral Properties	4-11
4-4. Terrain Diagram of the Montezuma Canyon Area, San Juan County, Utah	4-13
4-5. Tectonic Setting of the Monticello Project Area	4-15
4-6. Generalized Bedrock Stratigraphy of the Monticello Area	4-16
4-7. Geologic Map of the Project Area	4-17
4-8. Locations of Bore Holes, Seismic-Refraction Lines, and Cross Section B-B'	4-19
4-9. Generalized West-East Cross Section Through the Project Area	4-22
4-10. Map Showing Inferred Subcrop of Bedrock Formations	4-24
4-11. Locations of Monitoring Wells Referred to in Sections 4.3 and 4.4	4-27
4-12. Water-Table Contour Map for the Monticello Project Area	4-29
4-13. Lithologic and Hydrologic Description of Well 70 in the Burro Canyon Formation	4-33
4-14. Time-Drawdown Curve for Observation Well 71	4-34
4-15. Time-Drawdown Curve for Observation Well 72	4-35
4-16. Time-Drawdown Curve for Observation Well 74	4-36
4-17. Equipotential Surface Map of the Burro Canyon Aquifer	4-39
4-18. Piper Diagram for Upgradient Wells for the Period 1984 through 1986	4-42
4-19. Piper Diagram for On-Site Wells for the Period 1984 through 1986	4-43

LIST OF FIGURES (continued)

	<u>Page</u>
Figure 4-20. Piper Diagram for Downgradient Wells for the Period 1984 through 1986	4-45
4-21. Maximum Concentrations of Arsenic (mg/L) Observed in the Alluvial Aquifer for the Period 1984-1986	4-49
4-22. Maximum Concentrations of Uranium (mg/L) Observed in the Alluvial Aquifer for the Period 1984-1986	4-51
4-23. Maximum Concentrations of Radium-226 (pCi/L) Observed in the Alluvial Aquifer for the Period 1984-1986	4-53
4-24. Maximum Concentrations of Chloride (mg/L) Observed in the Alluvial Aquifer for the Period 1984-1986	4-55
4-25. Piper Diagram for Burro Canyon Wells for the Period 1984 through 1986	4-57
5-1. Montezuma Creek Drainage Basin Above the Millsite Area	5-2
5-2. Flood Hydrograph for Probable Maximum Flood with Dam Break	5-6
5-3. Contoured Exposure-Rate Data from Aerial Radiologic Survey	5-9
5-4. Locations of Stream-Sediment Samples	5-11
5-5. Surface-Water Sampling Locations at the Monticello Millsite	5-15
5-6. Sampling Locations and Associated Uranium Concentrations in Montezuma Creek	5-20
6-1. Sampling Locations for Radon Monitoring in the Monticello Study Area	6-2
6-2. Calibration Curve for Track Etch® Detectors	6-4
6-3. Cross-Sectional View of Reduction in Radon Concentration as a Function of Distance from the Tailings Site	6-8
6-4. Sampling Locations for Radon Flux on the Monticello Tailings Piles	6-11
6-5. Results of Radon-Flux Measurements Made at the Control Location During 1984	6-13
6-6. Contour Map of Radon Flux for the Monticello Tailings Piles	6-17
6-7. Kriged Contour Map of Predicted Radon Concentrations for the Monticello Tailings Piles	6-21
6-8. Comparison of Observed Versus Predicted Radon Concentrations for the Monticello Tailings Site	6-23
6-9. Distribution of P/O Ratios for the Monticello Tailings Site	6-23
7-1. Aquatic Sampling Stations	7-6
8-1. Histogram of Exposure-Rate Measurement Results for the Monticello Peripheral Properties	8-4
8-2. Locations of Exposure-Rate Measurements Greater than 19 Microroentgens Per Hour at the Surface on the Monticello Peripheral Properties	8-5
8-3. Population Distribution Near the Tailings Site	8-11
8-4. Schematic of the Risk Assessment Process	8-13
8-5. Exposure Pathways	8-21

LIST OF FIGURES (continued)

	<u>Page</u>
Figure A-1. Location of Drill Holes, Seismic-Refraction Lines, and Cross Section B-B1	A-5
A-2. Drill Hole 50	A-8
A-3. Drill Holes 60, 66, and 21	A-10
A-4. Drill Hole 34A	A-12
A-5. Drill Holes 67 and 61	A-13
A-6. Drill Holes 63 and 28	A-14
A-7. Drill Hole 36B	A-16
A-8. Drill Hole 70	A-17
A-9. Drill Holes 7A and 62	A-18
A-10. Drill Hole 56	A-20

LIST OF PLATES

Plate 2-1. Land Ownership in Vicinity of Monticello Millsite	Map pocket
2-2. Potable Water Wells Within 0.5 Mile of Montezuma Creek	Map pocket
4-1. Engineering Characterization Sampling Locations at the Monticello Millsite and Adjacent Peripheral Properties	Map pocket
4-2. Geologic Cross Section of S-S' at the Monticello Millsite	Map pocket
4-3. Geologic Cross Section of S-SS at the Monticello Millsite	Map pocket
4-4. Cross Sections Showing Composition of the Tailings Piles at the Monticello Millsite	Map pocket
4-5a. Monticello Millsite and Peripheral Areas Showing Ra-226 Concentrations from Soil Sample Analyses at Depth	Map pocket
4-5b. Montezuma Creek Area East of Monticello Millsite Showing Ra-226 Concentrations from Soil Sample Analyses at Depth	Map pocket
4-6. Physiography and Core-Hole Fence Diagram of a Portion of the Monticello Mill Tailings Site	Map pocket
8-1. Contoured Exposure Rate Data, Monticello Millsite	Map pocket

LIST OF TABLES

Table 2-1. Distribution of 1980 Population by Direction and Distance from the Monticello Site	2-2
2-2. Summary of Population Distribution Data	2-2
2-3. Racial Composition of 1980 Population in Monticello and San Juan County	2-3
2-4. Historic Population and Projections for San Juan County and Monticello, 1970-2000	2-3
2-5. San Juan County Employment by Occupation in 1981	2-5
2-6. Average Monthly and Annual Meteorologic Data for the Monticello Site, 1982 through 1986	2-17

LIST OF TABLES (continued)

	<u>Page</u>
Table 2-7. Night Wind Frequency Distribution for Six Wind Speeds, 1982 through 1986	2-22
2-8. Day-Wind Frequency Distribution for Six Wind Speeds, 1982 through 1985	2-22
3-1. Elemental Composition of Vanadiferous Uranium Ore from the Salt Wash Member of the Morrison Formation (Jurassic)	3-5
3-2. Elemental Composition of Nonvanadiferous Ore from the Chinle Formation (Triassic)	3-7
3-3. Summary of Means for the Tailings Data	3-8
3-4. Disequilibrium in Colorado Plateau Uranium Ore	3-23
3-5. Results of Principal Components Analysis on the Correlation Matrix of Monticello Tailings Data	3-29
3-6. Amounts of Metals Contained in Monticello Tailings	3-32
3-7. Dominant Dissolved Uranium Species and Mineral Saturation Indices for Monticello Millsite Water Samples Collected in May 1984	3-36
4-1. Hydraulic Conductivity Values for the Alluvial Gravel Aquifer as Determined by Bail Testing	4-28
4-2. Average Concentrations of Selected Constituents Found in the Alluvial Aquifer	4-47
4-3. Maximum Concentrations Measured for Constituents Reported in Table 4-2	4-44
4-4. Average Concentrations of Selected Constituents in the Burro Canyon Aquifer	4-46
4-5. Comparison of Water-Quality Parameters between Dakota and Burro Canyon Wells	4-58
5-1. Reservoir Area - Capacity Table	5-3
5-2. Highway 191 Embankment Impoundment Area Data	5-4
5-3. Radium-226 Concentration in Stream Sediments of Montezuma Creek for the Period 1960 to 1964	5-10
5-4. Average and Maximum Concentrations of Radium-226 and Uranium in Sediments of Montezuma Creek, August 1982	5-10
5-5. Sample Analysis Results from On-Site Seeps and Ponds	5-14
5-6. Results of September 1981 Intensive Surface-Water Sampling in Montezuma Creek	5-17
5-7. Average Concentrations of Selected Constituents in Montezuma Creek	5-18
5-8. Uranium Concentrations at the Sorenson and Montezuma Canyon Sites, November 1981 to October 1986	5-21
6-1. Terradex Track Etch® Calibration Results	6-3
6-2. Radon Concentrations Reported by Terradex for the Period 2 November 1983 to 9 February 1984	6-5
6-3. Radon Concentrations Reported by Terradex for the Period 9 February 1984 to 9 May 1984	6-5
6-4. Radon Concentrations Reported by Terradex for the Period 9 May 1984 to 16 August 1984	6-6

LIST OF TABLES (continued)

	<u>Page</u>
Table 6-5. Radon Concentrations Reported by Terradex for the Period 16 August 1984 to 19 November 1984	6-6
6-6. Annual Average Radon Concentrations Reported by Terradex for the Monticello Area	6-7
6-7. Ongoing Radon Measurement Results	6-9
6-8. Terradex Track Etch® Calibration Results for Ongoing Radon Monitoring	6-9
6-9. Radon-Flux Measurements Made at the Control Location During 1984	6-10
6-10. Results of the Radon-Flux Survey	6-15
6-11. Radon Source Strength, Area, and Weighted-Average Radon Flux for the Monticello Tailings Piles	6-14
6-12. Results of Radon-Flux Measurements at Off-Site Locations Along the Montezuma Creek Drainage	6-19
6-13. Comparison of Observed Versus Predicted Radon Concentrations for the Monticello Tailings Site	6-20
6-14. Results of Air Particulate Study Conducted from 1984 through 1986	6-26
6-15. Comparison of Air Particulate Data Collected at the Monticello Site with Background Measurements at Other Western Sites	6-28
7-1. Plant Species List	7-9
7-2. Vegetative Cover Data	7-13
7-3. Herbaceous Production Data	7-13
7-4. Wildlife Observed or Likely to Occur in the Monticello Area	7-14
8-1. Concentrations of Naturally Occurring Radioactive Elements in Airborne Particulates, 1984-1986	8-3
8-2. Annual Average Radon Concentrations for the Monticello Area	8-6
8-3. Radon Emissions for the Monticello Tailings Site and Certain Peripheral Properties	8-6
8-4. Exposure-Rate Source Terms for Present Enhanced Conditions	8-8
8-5. Air-Particulate Source Terms for Present Enhanced Conditions	8-9
8-6. Radon Source Terms for Present Enhanced Conditions	8-9
8-7. Population Dose Commitments to Monticello Residents from Natural Background and the Present Enhanced Conditions	8-10
8-8. Estimated Incidence of Cancer in Monticello Area Residents Resulting from Natural Background and Existing Enhanced Conditions	8-12
8-9. Summary of Ground Water and Surface Water Sample Concentrations at the Monticello Site	8-15
8-10. Summary of Soil and Air Particulate Sample Concentrations at the Monticello Site	8-16
8-11. Summary of Organics and Other Constituents from Ground Water and Surface Water Samples at the Monticello Site	8-17

LIST OF TABLES (continued)

	<u>Page</u>
Table 8-12. Indicator Elements	8-18
8-13. Model for the Exposure to Tailings-Related Elements by the Inhalation of Resuspended Dust	8-23
8-14. Model for the Exposure to Tailings-Related Elements by the Ingestion of Soil	8-24
8-15. Model for the Exposure to Tailings-Related Elements by the Ingestion of Vegetables	8-25
8-16. Model for the Exposure to Tailings-Related Elements by the Ingestion of Beef	8-26
8-17. Total Dose (mg/kg/day) for a Child Including the Vegetable Pathway	8-27
8-18. Total Dose (mg/kg/day) for an Adult Including the Vegetable Pathway	8-28
8-19. Total Dose (mg/kg/day) for a Child Not Including the Vegetable Pathway	8-29
8-20. Total Dose (mg/kg/day) for an Adult Not Including the Vegetable Pathway	8-29
8-21. Comparison of AICs with Total Inhalation and Oral Doses Based on Average Soil Concentrations	8-30
8-22. Comparison of AICs with Total Inhalation and Oral Doses Based on Maximum Soil Concentrations	8-30
8-23. Comparison of Surface Water Concentrations with Federal Water Quality Standards	8-31
8-24. Comparison of Surface Water Concentrations with State Water Quality Standards	8-31
8-25. Recommended Limits for the Prevention of Toxicity to Life Forms	8-35
8-26. Estimated Lifetime Cancer Risks Associated with Arsenic Exposure	8-37
A-1. Drill-Hole Summary	A-2
B-1. Analytical Data for 1984, Monticello Millsite	B-2
B-2. Analytical Data for 1985, Monticello Millsite	B-19
B-3. Analytical Data for 1986, Monticello Millsite	B-36

FOREWORD

The Remedial Investigation/Feasibility Study (RI/FS) has been supplemented to include analyses sufficient to enable the U.S. Department of Energy to assess the impacts of the remedial action alternatives considered in terms of the requirements of the National Environmental Policy Act (NEPA). As such, this RI/FS also serves as an Environmental Assessment (EA) for purposes of NEPA. On the basis of this RI/FS-EA, the Department of Energy would issue a Finding of No Significant Impact (FONSI) for the preferred remedial action alternative identified therein, if appropriate.

EXECUTIVE SUMMARY

The Monticello Millsite is a 78-acre tract located along Montezuma Creek south of the City of Monticello, San Juan County, Utah. The mill was constructed by the Vanadium Corporation of America (VCA) in 1942 with funds from the Defense Plant Corporation. Initially, vanadium was produced, but from 1943 to 1944 a uranium-vanadium sludge was produced by VCA for the Manhattan Engineer District (MED). After milling operations ceased in 1944, VCA leased the mill from 1945 to 1946 to produce the uranium-vanadium sludge for MED. The Atomic Energy Commission (AEC) bought the site in 1948. Uranium milling commenced 15 September 1949 and continued to 1 January 1960, when the mill was permanently closed. Part of the land was transferred to the Bureau of Land Management, but otherwise the site has remained under the control of the AEC and its successor agencies, the U.S. Energy Research and Development Administration and the U.S. Department of Energy.

Approximately 1 million tons of uranium ore were processed at the mill; the resultant tailings are stored in four piles. The total volume of tailings and tailings-contaminated soil is estimated to be 1,570,000 cubic yards. In addition, some properties adjacent to the site (referred to as peripheral properties) are contaminated by residues from ore stockpiles and dispersed tailings. A number of business and residence properties in the City of Monticello are contaminated from the use of radioactive mill tailings as construction and fill material. The tailings piles were stabilized and covered with soil in 1961 to eliminate the possibility of further dispersal or use.

The chemical composition of the tailings is described in terms of the average concentrations of 17 elements. With one exception, these elements are listed as CERCLA hazardous substances at 40 CFR 302.4. The average concentrations of these elements indicate that most are enriched in the tailings and ore relative to typical or "average" sandstones.

Dispersal of ore and tailings during and after milling operations resulted in the contamination of surface soil on the millsite. Vanadium and uranium were the only substances extracted in the milling process; other radioactive and nonradioactive constituents of the ore remained in the tailings and were not separated prior to disposal. Consequently, dispersal of the tailings results in the dispersal of all of these substances. Measurement of a single constituent will adequately portray the areal distribution of the others. Radium-226, a product of the decay of uranium, was selected to portray the distribution of these elements because of the ease of measurement and because a standard for soil has been established at 40 CFR 192.12.

The background concentration of radium-226 in soil in the Monticello area is about 1 picocurie per gram (pCi/g), or about 0.037 disintegrations per second per gram. The regulations at 40 CFR 192 require remediation of open land if the radium-226 concentration in the upper 15 centimeters of soil exceeds 5 pCi/g above background. Thus, the remedial action standard for radium at the millsite is 6 pCi/g. Areas of elevated radium concentration are expected to have elevated concentrations of CERCLA hazardous substances that were enriched in the ore. Areas where radium is at or near background concentration will have correspondingly low concentrations of CERCLA hazardous substances.

Montezuma Creek, an intermittent stream which flows across the site, has cut through Mancos Shale, Dakota Sandstone, and the Burro Canyon Formation, all of Cretaceous age. The mill tailings were deposited on alluvium of Montezuma Creek and on Mancos Shale. The alluvium and Burro Canyon Formation are aquifers. Concentrations of uranium, vanadium, molybdenum, and selenium are elevated in the alluvial aquifer downgradient from the site. The alluvial aquifer is not used for domestic drinking-water supply, but two concerns arise over the observed concentrations of these elements. One is the possibility of this water migrating into the Burro Canyon aquifer, which is used by the City of Monticello for alternate water supply. The Mancos Shale, which locally underlies the alluvium, is impermeable and the Dakota Sandstone underlying the Mancos has been shown by on-site pumping tests to have very low vertical hydraulic conductivity. If there is uniform conductivity throughout the site, the estimated time for water to migrate through 87 feet of Dakota at well 34A on the Vanadium Pile is 745 years. Thus, the potential for contamination of the Burro Canyon aquifer appears to be low. Other concerns arise from the fact that the alluvial aquifer discharges to Montezuma Creek and can therefore affect surface-water quality downstream. Surface water in the creek is used for irrigation.

The drainage area of Montezuma Creek is approximately 26 square miles and is composed of two major sub-basins, North Creek and South Creek. Monticello Reservoir, which was recently constructed along South Creek, has a significant impact on the flood hydrology of Montezuma Creek. It is estimated that the probable maximum flood at the site, which would include a dam failure at Monticello Reservoir, would have a peak discharge of approximately 140,000 cubic feet per second. If left unprotected, the tailings piles would be subject to severe erosion from such a flood event.

Air monitoring for radon emissions and air particulates has been conducted for a number of years at the millsite. Standards listed at 40 CFR 192 for radon emissions on the piles and atmospheric radon concentrations at the edge of piles are exceeded. Radiologic air particulates are below the standards established in DOE Order 5480.1. Nonradiologic air particulate concentrations are consistent with background concentrations.

Natural background radiation is the major contributor to the overall radiation risk at Monticello. However, a smaller, but still significant addition results from the millsite in its present condition.

Several tailings-related elements are found in Montezuma Creek at concentrations that exceed State or Federal regulations. The potential for exposure to these concentrations suggests the need for remedial action to improve water quality. While the surface water should not be (and currently is not) used for drinking water, it appears to be acceptable for use in irrigating alfalfa for cattle.

1.0 INTRODUCTION

1.1 PROGRAM OVERVIEW

The U. S. Department of Energy (DOE), under the authority of the Atomic Energy Act, initiated the Surplus Facilities Management Program (SFMP) in 1978 to assure safe caretaking and decommissioning of government facilities that had been retired from service but which still had radioactive contamination. In 1980, the millsite operated by the Atomic Energy Commission from 1948 to 1960 at Monticello, Utah, was accepted into the SFMP, and the Monticello Remedial Action Project (MRAP) was established to restore the government-owned millsite to safe levels of radioactivity, to dispose of or contain the tailings in an environmentally safe manner, and to perform remedial actions on off-site (vicinity) properties that had been contaminated by radioactive material from the mill operations. In 1983, remedial activities for vicinity properties were separated from MRAP with the establishment of the Monticello Vicinity Properties (MVP) Project. Both MRAP and MVP are currently administered by the Grand Junction Projects Office (GJPO) of the DOE.

From its inception, the SFMP has mandated that decommissioning activities follow the procedural provisions of the National Environmental Policy Act (NEPA). Guidance and requirements for compliance included, but were not limited to, the following:

1. Regulations for Implementing the Procedural Provisions of the National Environmental Policy Act, issued by the Council on Environmental Quality at 40 CFR 1500 - 1508.
2. Final Guidelines for Compliance with the National Environmental Policy Act, issued by the U. S. Department of Energy at 45 FR 20694 - 20701 on 28 March 1980, and amended at 52 FR 47662 - 47670 on 15 December 1987.
3. The Environmental Compliance Guide, volumes 1 and 2, issued by the U.S. Department of Energy, Assistant Secretary for Environmental Protection, Safety, and Emergency Preparedness, Office of Environmental Compliance and Overview, National Environmental Policy Act Affairs Division, on 21 February 1981.
4. Implementation of the National Environmental Policy Act, U.S. Department of Energy Order 5440.1C, issued 9 April 1985.

In accordance with SFMP policy, MRAP initiated surveillance activities at the millsite in 1980. These activities at first consisted of water quality analysis but were later expanded to include atmospheric radon monitoring and air particulate sampling. Results are described in annual environmental monitoring reports issued at the GJPO (Korte and Thul, 1981, 1982, 1983, 1984; Korte and Wagner, 1985, 1986; Sewell and Spencer, 1987; U.S. Department of Energy, 1988, 1989). These activities continue.

Site characterization activities at the Monticello Millsite commenced in 1981. The resulting *Monticello Remedial Action Project Site Analysis Report* was issued in draft form in 1983 and was finalized in 1984 (Abramiuk and others,

issued in draft form in 1983 and was finalized in 1984 (Abramiuk and others, 1984). The Site Analysis Report describes the site's history, geology and hydrology, the extent of surface and subsurface contamination of soil and water, and engineering alternatives for remediation of the site. On the basis of the findings in the draft Site Analysis Report, the DOE issued an Action Description Memorandum in November 1983 recommending stabilization in place as the preferred remedial action alternative and preparation of an Environmental Assessment. The *Draft Environmental Assessment of Remedial Action at the Monticello Uranium Mill Tailings Site, Monticello, Utah* was completed in July 1985 (Bendix Field Engineering Corporation, 1985); it includes descriptions of remedial action alternatives and supporting information from the Site Analysis Report and on-going studies. While this draft Environmental Assessment was neither published nor used as a NEPA compliance document, it has been used extensively as a source for the present Remedial Investigation.

The Superfund Amendments and Reauthorization Act of 1986 (SARA) placed the SFMP activities at Monticello under the regulatory framework of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA) and has resulted in a number of new developments. The DOE submitted its Hazard Ranking System Score for the millsite to the Environmental Protection Agency (EPA) on 31 October 1987. During 1987, existing environmental site characterization and engineering documents were revised into the format of the CERCLA Remedial Investigation/Feasibility Study (RI/FS) and were issued for DOE internal review in January 1988. The DOE, EPA, and the State of Utah entered into a Federal Facility Agreement (FFA) pursuant to CERCLA Section 120 in December 1988. This agreement stipulates the procedural framework for developing and implementing response actions under CERCLA/SARA.

1.2 SITE BACKGROUND INFORMATION

1.2.1 Site Location and Description

The Monticello mill tailings site is a 78-acre tract located in San Juan County, Utah (Figure 1-1). The site lies in Section 36, T. 33 S., R. 23 E., and Section 31, T. 33 S., R. 24 E. (Salt Lake Meridian). It is bordered on the south and southeast by land held by the Bureau of Land Management (BLM). Elsewhere, the site is bordered by the City of Monticello and private property. Land survey (Figure 1-2) indicates encroachments on all boundaries of the site, the largest being on the east and southeast sides. The encroachment onto the property directly east of the millsite has been remedied. The millsite and areas under investigation are shown in relation to the city of Monticello in Figure 1-3.

The Monticello site lies in the valley of Montezuma Creek which has incised a broad erosional surface that slopes eastward from the Abajo Mountains. Elevations of the property range from 6990 feet (ft) at the northwest corner to 6820 ft at the southeast corner. The topography of the millsite and adjacent areas is detailed in Figure 1-4.

A plan of the site is shown in Figure 1-5. The mill area covers approximately 10 acres and the tailings impoundment area covers the remaining 68 acres. During the period of mill operation, the site also included private land to




Figure 1-1. Monticello, Utah, Regional Location Map




Figure 1-2. Monticello Millsite Land Survey

MR&P - 710002307 GEOTECHNICAL DATA BASE FOR MONTICELLO MILLSITE CHARACTERIZATION - P.N.MORRIS CREATED 09/30/91 LAST UPDATED 11/22/91

MRAP - 710002307 - GEOTECHNICAL DATA BASE FOR MONTICELLO MILLSITE CHARACTERIZATION - R.N. MORRIS, CREATED 09/00/91, LAST UPDATED 11/22/91

AREA	DATA SOURCE	BORING OR TEST PIT NUMBER	SAMPLE & TYPE	TOP OF SAMPLE (FEET)	BASE OF SAMPLE (FEET)	SAMPLE MIDPOINT (FEET)	USCS SYMBOL	MATERIAL TYPE	IN-PLACE DRY MOISTURE CONTENT (%)			FRACTION #4 SIEVE (PERCENT)	FRACTION #200 SIEVE (PERCENT)	ASTM D-658 MAXIMUM DRY DENSITY (PCF)		ASTM D-698 OPTIMUM MOISTURE CONTENT (PERCENT)		OTHER TESTS
									DENSITY (PCF)	SPECIFIC GRAVITY	(PERCENT)	PASSING	PASSING	LIMIT	PLASTICITY INDEX	DENSITY	MOISTURE CONTENT	
CARBONATE PILE	D&M	TP-6	4/ST	10.5	11.0	10.75	CL	Tails-sim	70.5	48.3	NA	NA	NA	NA	NA	NA	NA	
CARBONATE PILE	D&M	TP-6	6/ST	17.0	17.5	17.25	SM	Tails-and	73.3	19.6	NA	NA	NA	NA	NA	NA	NA	
CARBONATE PILE	D&M	TP-6	-BULK	18.0	18.0	18.00	SM	Tails-and[?]	NA	15.5	NA	100.0	48.4	NA	NA	95.1	18.9	
CARBONATE PILE	D&M	TP-11	-BULK	6.0	6.0	6.00	SM	Tails-and[?]	NA	15.7	2.78	100.0	47.6	NA	NA	103.7	16.9 Dir Shear, Perm, Mod Proct	
CARBONATE PILE	D&M	TP-11	-BULK	15.0	15.0	15.00	CL	Tails-sim	NA	53.1	NA	100.0	91.3	NA	NA	96.8	24.0	
VANADIUM PILE	BENDIX	MRAP-85-04	MKB-682/ST	4.0	6.0	5.00	SC	Tails-and&sim	80.7	39.8	2.62	100.0	44.0	27.0	10.0	NA	NA	
VANADIUM PILE	BENDIX	MRAP-85-04*	MKB-783/BULK	1.0	1.0	1.00	ML	Cover	NA	NA	NA	NA	71.0	NA	NA	NA	NA	
VANADIUM PILE	BENDIX	MRAP-85-04	MKB-784/BULK	2.0	2.0	2.00	SP	Tails-and	NA	NA	2.87	NA	NA	NA	NA	NA	174.3	
VANADIUM PILE	BENDIX	MRAP-85-04	MKB-786/BULK	7.0	7.0	7.00	ML	Tails-sim	NA	NA	2.60	NA	NA	NA	NA	NA	107.6	
VANADIUM PILE	BENDIX	MRAP-85-05	MKB-676/ST	8.0	8.0	8.00	CL-ML	Tails-sim	76.1	41.7	2.63	100.0	94.0	21.0	5.0	NA	NA	
VANADIUM PILE	D&M	31SW91-031	3/ST	5.5	7.5	6.50	SM	Tails-and	NA	9.4	2.69	100.0	21.4	39.1	17.1	NA	NA	
VANADIUM PILE	D&M	31SW91-032	1/SST	2.0	3.5	2.75	SM/SC	Cover	NA	16.8	NA	NA	NA	NA	NA	NA	NA	
VANADIUM PILE	D&M	31SW91-032	2/SS	3.3	5.0	4.25	SM/CL	Tails-and&sim	NA	16.9	NA	NA	NA	NA	NA	NA	NA	
VANADIUM PILE	D&M	31SW91-032	3A-1	5.0	6.5	5.75	SM	Tails-and[?]	NA	15.0	NA	NA	NA	NA	NA	NA	NA	
VANADIUM PILE	D&M	31SW91-032	5/SS	8.5	10.0	9.25	ML	Tails-sim	NA	34.1	NA	NA	NA	NA	NA	NA	NA	
VANADIUM PILE	D&M	31SW91-032	6/SS	10.0	11.5	10.75	SM	Tails-and&sim	NA	11.5	2.68	100.0	21.8	NA	NA	NA	NA	
VANADIUM PILE	D&M	31SW91-032	7/SS	11.5	13.0	12.25	ML	Tails-sim	NA	25.0	NA	NA	NA	NA	NA	NA	NA	
VANADIUM PILE	D&M	31SW91-032	9/SS	15.0	16.5	15.75	SM/CL	Tails-and&sim	NA	28.0	NA	NA	NA	NA	NA	NA	NA	
VANADIUM PILE	D&M	31SW91-032	10/SS	16.5	18.0	17.25	SM/CL	Tails-and&sim	NA	16.3	NA	NA	NA	NA	NA	NA	NA	
VANADIUM PILE	D&M	31SW91-032	11/SS	19.0	19.5	19.25	CL	Alluvium	NA	25.9	NA	NA	NA	NA	NA	NA	NA	
VANADIUM PILE	D&M	31SW91-032	12/SS	19.5	21.5	20.50	CL	Alluvium	NA	18.7	NA	NA	NA	NA	NA	NA	NA	
VANADIUM PILE	D&M	31SW91-032	13/SS	21.5	23.5	22.50	CL	Alluvium	NA	20.1	NA	NA	NA	44.3	24.0	NA	NA	
VANADIUM PILE	D&M	31SW91-032	14/SS	24.0	25.0	24.50	CL	Alluvium	NA	18.0	NA	NA	NA	NA	NA	NA	NA	
VANADIUM PILE	D&M	31SW91-032	15/SS	25.5	27.5	26.50	CL	Alluvium	NA	23.9	NA	NA	NA	NA	NA	NA	NA	
VANADIUM PILE	D&M	31SW91-032	16/SS	27.5	29.5	28.50	CL	Alluvium	NA	17.8	NA	NA	NA	NA	NA	NA	NA	
VANADIUM PILE	D&M	31SW91-032	17/SS	29.5	31.5	30.50	CL	Alluvium	NA	17.9	NA	NA	NA	NA	NA	NA	NA	
VANADIUM PILE	D&M	31SW91-032	18/SS	31.5	33.5	32.50	CL	Alluvium	NA	19.5	NA	NA	NA	NA	NA	NA	NA	
VANADIUM PILE	D&M	31SW91-032	19/SS	33.5	34.8	34.15	CL	Alluvium	NA	17.6	NA	NA	NA	37.9	19.1	NA	NA	
VANADIUM PILE	D&M	31SW91-032	20/SS	35.5	37.5	36.50	CL	Alluvium	NA	23.7	NA	NA	NA	NA	NA	NA	NA	
VANADIUM PILE	D&M	31SW91-032	21/SS	37.5	39.5	38.50	CL	Alluvium	NA	22.2	NA	NA	NA	NA	NA	NA	NA	
VANADIUM PILE	D&M	31SW91-032	22/SS	39.5	41.0	40.25	CL	Alluvium	NA	23.1	NA	NA	NA	NA	NA	NA	NA	
VANADIUM PILE	D&M	31SW91-032	23/SS	41.5	42.8	42.15	SC/CL	Alluvium	NA	23.2	NA	NA	NA	NA	NA	NA	NA	
VANADIUM PILE	D&M	31SW91-032	24/SS	43.5	44.9	44.20	GC	Alluvium	NA	16.9	NA	NA	NA	NA	NA	NA	NA	
VANADIUM PILE	D&M	31SW91-032	28/SS	48.5	48.9	48.70	Km	Shale	NA	15.5	NA	NA	NA	NA	NA	NA	NA	
VANADIUM PILE	D&M	31SW91-40b	5/ST	6.0	7.5	6.75	CL	Tails-sim	95.1	25.3	NA	NA	NA	45.7	24.9	NA	NA	
VANADIUM PILE	D&M	31SW91-40b	8/SS	13.5	14.8	14.15	CL	Tails-sim	NA	20.3	2.80	NA	NA	45.7	22.5	NA	NA	
VANADIUM PILE	D&M	31SW91-40b	9/SS	18.5	20.5	19.50	CL	Tails-sim	NA	19.4	NA	NA	NA	NA	NA	NA	NA	
VANADIUM PILE	D&M	31SW91-40b	11/SS	23.5	25.3	24.40	CL	Tails-sim	NA	23.4	NA	NA	NA	NA	NA	NA	NA	
VANADIUM PILE	D&M	31SW91-041	1/SS	5.0	6.0	5.50	CL	Tails[?]-sim[?]	NA	23.8	NA	NA	NA	51.7	14.0	NA	NA	
VANADIUM PILE	D&M	31SW91-041	2/SS	10.0	11.0	10.50	CL	Alluvium	NA	21.3	NA	NA	NA	NA	NA	NA	NA	
VANADIUM PILE	D&M	31SW91-041	3/SS	14.0	16.0	15.00	CL	Alluvium	NA	18.8	NA	NA	NA	NA	NA	NA	NA	
VANADIUM PILE	D&M	31SW91-041	8/SS	24.0	26.0	25.00	CL	Alluvium	NA	14.9	NA	NA	NA	NA	NA	NA	NA	
VANADIUM PILE	D&M	31SW91-041	7/SS	29.0	31.0	30.00	CL	Alluvium	NA	19.3	NA	NA	NA	NA	NA	NA	NA	
VANADIUM PILE	D&M	31SW91-041	8/SS	34.5	36.0	35.25	CL	Alluvium	NA	27.7	NA	NA	NA	NA	NA	NA	NA	
VANADIUM PILE	D&M	31SW91-041	9/SS	39.0	40.0	39.50	SC	Alluvium	NA	13.2	NA	100.0	40.1	NA	NA	NA	NA	
VANADIUM PILE	D&M	31SW91-041	10/SS	44.0	44.5	44.25	Kd	Sandstone	NA	9.3	NA	NA	NA	NA	NA	NA	NA	
VANADIUM PILE	D&M	TP-5	1/ST	4.5	5.0	4.75	SM	Tails-and	90.1	7.4	NA	NA	NP	NP	NA	NA	NA	
VANADIUM PILE	D&M	TP-5	2/ST	5.5	6.0	5.75	CL	Tails-sim	76.7	51.8	NA	NA	NA	NA	NA	NA	NA	
VANADIUM PILE	D&M	TP-5	4/ST	9.0	9.5	9.25	CL	Tails-sim	71.0	45.7	NA	NA	NA	NA	NA	NA	NA	
VANADIUM PILE	D&M	TP-5	5/ST	11.0	11.5	11.25	CL	Tails-sim	NA	84.8	16.5	NA	NA	NA	NA	NA	NA	
VANADIUM PILE	D&M	TP-5	7/ST	14.0	14.5	14.25	CL	Tails[?]-sim[?]	NA	69.8	51.8	NA	NA	NA	NA	NA	NA	
VANADIUM PILE	D&M	TP-12	-BULK	6.0	8.0	6.50	CL	Tails-sim	NA	24.3	2.75	NA	NA	29.2	12.3	115.0	14.0 Perm, Mod Proct	
EAST PILE	BENDIX	MRAP-85-06	MKD-682/ST	2.0	4.0	3.00	SM	Tails-sim	NA	53.9	2.84	NA	NA	44.7	20.5	100.7	21.2 Triax-CUPP, Perm, Mod Proct, CMR	
EAST PILE	BENDIX	MRAP-85-06*	MKB-779/BULK	1.0	1.0	1.00	ML	Cover	NA	NA	NA	100.0	52.0	NA	NA	111.2	NA Consol w/perm, CMR @15 bar	
EAST PILE	BENDIX	MRAP-85-06*	MKB-780/BULK	3.0	3.0	3.00	SM/ML	Tails-sim	NA	NA	NA	NA	NA	NA	NA	107.1	NA	
EAST PILE	BENDIX	MRAP-85-06*	MKB-782/BULK	15.0	15.0	15.00	SP?	Tails-and[?]	NA	NA	2.70	NA	NA	NA	NA	103.6	15.5	
EAST PILE	BENDIX	MRAP-85-07	MKB-687/ST	2.0	4.0	3.00	SM	Tails-and	NA	94.0	9.5	2.61	100.0	13.0	NP	NA	NA Consol w/perm, CMR @15 bar	
EAST PILE	BENDIX	MRAP-85-08	MKB-714/ST	12.0	14.0	13.00	CL	Tails-sim	NA	108.6	34.4	2.70	100.0	81.0	41.0	22.0	NA Consol w/perm, CMR @15 bar	
EAST PILE	BENDIX	MRAP-85-09	MKB-754/ST	4.0	6.0	5.00	ML	Tails-sim	NA	109.7	21.4	2.63	100.0	88.0	42.0	13.0	NA Consol w/perm, CMR @15 bar	
EAST PILE	D&M	31SW91-002	1/SS	3.5	5.5	4.50	SP	Tails-and	NA	12.8	NA	NA	NA	NA	NA	NA	NA	
EAST PILE	D&M	31SW91-002	2/SS	8.5	10.5	9.50	SM/ML	Tails-and&sim	NA	15.8	NA	NA	NA	NA	NA	NA	NA	
EAST PILE	D&M	31SW91-002	3/SS	15.5	15.5	14.50	SM/ML	Tails-and&sim	NA	15.3	NA	NA	NA	NA	NA	NA	NA	
EAST PILE	D&M	31SW91-002	NA	24.0	25.0	24.50	CL	Alluvium	NA	16.5	NA	NA	NA	NA	NA	NA	NA	
EAST PILE	D&M	31SW91-002	10/SS	28.0	30.0	29.00	CL	Alluvium	NA	16.5	NA	NA	NA	NA	NA	NA	NA	
EAST PILE	D&M	31SW91-003	3/SS	7.0	8.3	7.55	ML	MVP soil	NA	7.2	NA	NA	NA	NA	NA	NA	NA	

MRAP - 710002307 - GEOTECHNICAL DATA BASE FOR MONTICELLO MILL SITE CHARACTERIZATION - R.N. MORRIS, CREATED 09/30/91, LAST UPDATED 11/22/91

AREA	DATA SOURCE	BORING OR TEST PIT NUMBER	SAMPLE NUMBER & TYPE	TOP OF SAMPLE (FEET)	BASE OF SAMPLE (FEET)	SAMPLE MIDPOINT (FEET)	USCS SYMBOL	MATERIAL TYPE	IN-PLACE DRY DENSITY (PCF)	NATURAL MOISTURE CONTENT (%)	SPECIFIC GRAVITY	FRACTION PASSING #4 SIEVE (PERCENT)	FRACTION PASSING #200 SIEVE (PERCENT)	LIQUID LIMIT	PLASTICITY INDEX	ASTM D-698		ASTM D-598		OTHER TESTS
																MAXIMUM DRY DENSITY (PCF)	OPTIMUM MOISTURE CONTENT (%)	DRY MOISTURE CONTENT (%)	OPTIMUM MOISTURE CONTENT (%)	
EAST PILE	D&M	TP-1	1/ST	6.5	7.0	6.75	CL	MVP spoil	103.3	11.1	NA	NA	NA	NA	NA	NA	NA	NA	NA	
EAST PILE	D&M	TP-1	-BULK	7.0	7.0	7.00	CL	MVP spoil	NA	18.2	NA	NA	NA	NA	NA	NA	103.1	18.1	Perm. Mod Proct	
EAST PILE	D&M	TP-1	2/ST	9.0	9.5	9.25	CL	MVP spoil	86.8	20.4	NA	NA	NA	NA	NA	NA	NA	NA	NA	
EAST PILE	D&M	TP-1	3/ST	14.0	14.5	14.25	SM	Tails-snd	101.9	7.4	NA	NA	NA	NA	NA	NA	NA	NA	NA	
EAST PILE	D&M	TP-1	-BULK	15.0	15.0	15.00	SM	Tails-snd	NA	10.8	NA	99.0	31.0	NA	NA	NA	109.4	14.3		
EAST PILE	D&M	TP-2	1/ST	9.0	9.5	9.25	SM	Tails-snd	91.8	27.9	NA	NA	NA	NA	NA	NA	NA	NA	NA	
EAST PILE	D&M	TP-2	-BULK	10.0	10.0	10.00	ML	Tails-snd	NA	35.0	NA	NA	NA	NA	NA	NA	103.0	20.0	Consol. CMR	
EAST PILE	D&M	TP-2	2/ST	10.5	11.0	10.75	SM	Tails-snd	87.3	1.7	NA	NA	NA	NA	NA	NA	NA	NA	NA	
EAST PILE	D&M	TP-2	3/ST	13.5	14.0	13.75	ML	Tails-and&sim[?]	65.8	53.8	NA	NA	NA	NA	NA	NA	NA	NA	NA	
EAST PILE	D&M	TP-2	-BULK	14.0	14.0	14.00	ML	Tails-and&sim[?]	NA	7.8	NA	100.0	54.4	NA	NA	NA	103.5	17.1	CMR	
EAST PILE	D&M	TP-2	4/ST	14.5	15.0	14.75	ML	Tails-and&sim[?]	74.0	25.4	NA	NA	NA	NA	NA	NA	NA	NA	NA	
EAST PILE	D&M	TP-4	-BULK	9.0	9.0	9.00	ML	Tails-and&sim	NA	32.4	NA	100.0	91.0	NA	NA	NA	98.8	21.5	Dir Shear, Perm, CMR	
EAST PILE	D&M	TP-4	3/ST	9.5	10.0	9.75	ML	Tails-and&sim	89.6	7.9	NA	NA	NA	NA	NA	NA	NA	NA	NA	
EAST PILE	D&M	TP-4	-BULK	14.0	14.0	14.00	ML	Tails-and&sim	NA	14.7	2.71	100.0	56.6	NA	NA	NA	101.8	17.3	Perm, CMR	
EAST PILE	D&M	TP-4	5/ST	14.5	15.0	14.75	ML	Tails-and&sim	61.8	57.1	NA	100.0	98.1	NA	NA	NA	NA	NA	NA	
ACID PILE	BENDIX	MRAP-85-10	MKB-723/ST	4.0	6.0	5.00	CL	Tails-sim	66.1	43.5	2.63	100.0	72.0	44.0	20.0	NR	NA	NA	NA	
ACID PILE	BENDIX	MRAP-85-10	MKB-791/BULK	1.0	1.0	1.00	SM	Cover	NA	NA	NA	100.0	49.0	NA	NA	NA	111.8	16.9		
ACID PILE	BENDIX	MRAP-85-10	MKB-792/BULK	3.0	3.0	3.00	SP	Tails-snd	NA	NA	NA	NA	NA	NA	NA	NA	110.4	12.4		
ACID PILE	BENDIX	MRAP-85-10	MKB-793/BULK	8.0	8.0	8.00	CL	Tails-sim	NA	NA	2.76	NA	NA	NA	NA	NA	NA	NA	NA	
ACID PILE	BENDIX	MRAP-85-11	MKB-741/ST	4.0	6.0	5.00	CL	Tails-sim	74.8	39.8	2.63	100.0	72.0	44.0	20.0	NR	NA	NA	NA	
ACID PILE	BENDIX	MRAP-85-12	MKB-732/ST	4.0	6.0	5.00	ML	Tails-sim	76.4	40.5	2.68	100.0	87.0	47.0	10.0	NA	NA	NA	NA	
ACID PILE	D&M	31SW91-026	1/ST	4.5	5.0	4.75	CL	Tails-and&sim	NA	30.0	NA	NA	NA	33.8	13.1	NA	NA	NA	NA	
ACID PILE	D&M	31SW91-025	2/SS	8.5	9.0	8.75	CL	Alluvium	NA	12.8	NA	NA	NA	NA	NA	NA	NA	NA	NA	
ACID PILE	D&M	31SW91-026	5/SS	13.5	14.5	14.00	CL	Alluvium	NA	17.1	NA	NA	NA	NA	NA	NA	NA	NA	NA	
ACID PILE	D&M	31SW91-027	3/ST	6.0	8.0	7.00	CH	Alluvium	71.5	48.0	NA	NA	NA	58.9	28.7	NA	NA	NA	NA	
ACID PILE	D&M	31SW91-027	4/ST	9.0	11.5	10.25	CH	Alluvium	56.0	75.2	NA	NA	NA	68.5	31.4	NA	NA	NA	NA	
ACID PILE	D&M	31SW91-027	6/ST	19.0	20.5	19.75	CL/SC	Alluvium	109.3	18.3	NA	NA	NA	37.4	21.0	NA	NA	NA	NA	
ACID PILE	D&M	31SW91-025	2/SS	4.0	6.0	5.00	SM	Tails-and&sim[?]	NA	17.2	NA	NA	NA	NA	NA	NA	NA	NA	NA	
ACID PILE	D&M	31SW91-026	3/SS	6.0	6.9	6.45	SM	Tails-and	NA	17.2	NA	NA	NA	NA	NA	NA	NA	NA	NA	
ACID PILE	D&M	31SW91-028	4/SS	9.0	10.0	9.50	CL/ML	Tails-sim	NA	37.6	2.70	NA	NA	NA	NA	NA	NA	NA	NA	
ACID PILE	D&M	31SW91-028	5/SS	10.5	12.0	11.25	ML	Tails-sim	NA	38.5	NA	NA	NA	NA	34.8	9.6	NA	NA	NA	
ACID PILE	D&M	31SW91-028	6/SS	13.5	15.0	14.25	ML	Tails-and&sim	NA	27.9	NA	100.0	51.7	NA	NA	NA	NA	NA	NA	
ACID PILE	D&M	31SW91-028	7/SS	15.0	17.0	16.00	SM	Tails-and&sim	NA	18.5	NA	100.0	34.7	NA	NA	NA	NA	NA	NA	
ACID PILE	D&M	31SW91-028	8/SS	18.0	19.0	18.50	ML	Tails-sim	NA	43.3	NA	NA	NA	NA	NA	NA	NA	NA	NA	
ACID PILE	D&M	31SW91-028	9/SS	19.0	21.0	20.00	ML	Tails-sim	NA	39.0	NA	100.0	65.9	NA	NA	NA	NA	NA	NA	
ACID PILE	D&M	31SW91-028	10/SS	22.5	23.0	22.75	SM	Tails-snd	NA	60.0	NA	NA	NA	NA	NA	NA	NA	NA	NA	
ACID PILE	D&M	31SW91-028	11/SS	24.0	25.0	24.50	MUCL	Tails-and&sim	NA	53.1	NA	NA	NA	NA	NA	NA	NA	NA	NA	
ACID PILE	D&M	31SW91-028	12/SS	25.0	27.0	26.00	MUCL	Tails-and&sim	NA	56.3	NA	NA	NA	NA	NA	NA	NA	NA	NA	
ACID PILE	D&M	31SW91-028	13/SS	27.0	29.0	28.00	CL	Tails-and&sim	NA	56.9	NA	100.0	92.0	NA	NA	NA	NA	NA	NA	
ACID PILE	D&M	31SW91-028	14/SS	29.0	30.5	29.75	MUCL	Tails-and&sim	NA	51.4	NA	NA	NA	NA	NA	NA	NA	NA	NA	
ACID PILE	D&M	31SW91-028	15/SS	31.0	33.0	32.00	CL	Tails-and&sim	NA	64.7	NA	NA	NA	NA	NA	NA	NA	NA	NA	
ACID PILE	D&M	31SW91-028	16/SS	33.5	34.0	33.75	ML	Tails-and&sim	NA	41.3	NA	NA	NA	NA	NA	NA	NA	NA	NA	
ACID PILE	D&M	31SW91-028	17/SS	36.0	37.0	36.50	MUSIC	Alluvium[?]	NA	19.1	NA	NA	NA	NA	NA	NA	NA	NA	NA	
ACID PILE	D&M	31SW91-028	18/SS	37.5	39.0	38.25	SC/CL	Alluvium	NA	20.9	NA	NA	NA	NA	NA	NA	NA	NA	NA	
ACID PILE	D&M	31SW91-028	19/SS	39.0	41.0	40.00	CL	Alluvium	NA	24.5	NA	NA	NA	NA	NA	NA	NA	NA	NA	
ACID PILE	D&M	31SW91-034	1/SS	5.0	6.0	5.50	MUCL	Tails-sim	NA	57.3	NA	NA	NA	NA	NA	NA	NA	NA	NA	
ACID PILE	D&M	31SW91-034	3/SS	14.0	16.0	15.00	CL/ML	Tails-sim	NA	87.3	2.86	NA	NA	47.4	17.8	NA	NA	NA	NA	
ACID PILE	D&M	31SW91-034	7/SS	29.0	29.5	29.25	Km	Shale	NA	10.1	NA	NA	NA	NA	NA	NA	NA	NA	NA	
ACID PILE	D&M	31SW91-035	3/SS	5.0	5.5	5.25	SM	Tails-and	NA	4.6	NA	100.0	25.7	NA	NA	NA	NA	NA	NA	
ACID PILE	D&M	31SW91-035	4/SS	10.0	10.5	10.25	SM	Tails-and	NA	5.1	NA	NA	NA	NA	NA	NA	NA	NA	NA	
ACID PILE	D&M	31SW91-035	8/SS	15.0	15.5	15.25	SM	Tails-and	NA	15.3	NA	100.0	28.0	NA	NA	NA	NA	NA	NA	
ACID PILE	D&M	31SW91-035	9/ST	18.0	20.0	19.00	SM	Tails-and	100.8	13.4	NA	100.0	17.2	NA	NA	NA	NA	NA	NA	
ACID PILE	D&M	31SW91-035	12/SS	24.5	25.0	24.75	CL/ML	Tails-sim	NA	59.4	NA	NA	46.0	16.3	NA	NA	NA	NA	NA	
ACID PILE	D&M	TP-7	-BULK	2.0	2.0	2.00	SM	Tails-snd	NA	9.4	2.71	100.0	42.3	NP	NP	109.0	14.5	Trax-CUPP, Consol, Perm, Mod Proct, CMR		
ACID PILE	D&M	TP-7	2/ST	5.0	5.5	5.25	CL	Tails-sim	82.5	82.6	NA	NA	NA	NA	NA	NA	NA	NA	NA	
ACID PILE	D&M	TP-7	3/ST	6.5	7.0	6.75	CL	Tails-sim	86.1	54.4	NA	NA	NA	NA	NA	NA	NA	NA	NA	
ACID PILE	D&M	TP-7	4/ST	9.5	10.0	9.75	CL	Tails-sim	51.3	65.0	NA	NA	NA	NA	NA	NA	NA	NA	NA	
ACID PILE	D&M	TP-7	5/ST	12.5	13.0	12.75	CL	Tails-sim	53.1	74.1	NA	NA	NA	NA	NA	NA	NA	NA	NA	
ACID PILE	D&M	TP-7	6/ST	16.5	17.0	16.75	CL	Tails-sim	51.4	85.1	NA	NA	NA	NA	NA	NA	NA	NA	NA	
ACID PILE	D&M	TP-8	1/ST	2.5	3.0	2.75	SM/ML	Tails-and/sim	78.5	11.8	NA	NA	NA	NA	NA	NA	NA	NA	NA	
ACID PILE	D&M	TP-8	2/ST	4.5	5.0	4.75	SM	Tails-and	90.0	9.5	2.82	NA	NA	NA	NA	NA	NA	NA	NA	
ACID PILE	D&M	TP-8	4/ST	4.5	4.5	4.50	SM	Tails-and	NA	7.8	NA	100.0	28.9	NA	NA	NA	103.8	15.9	Dir Shear, Perm, Mod Proct, CMR	
ACID PILE	D&M	TP-8	-BULK	4.5	5.0	5.25	CL	Tails-and[?]	8											

MRAP - 710002307 - GEOTECHNICAL DATA BASE FOR MONTICELLO MILLSITE CHARACTERIZATION - R.N. MORRIS CREATED 09/30/01 LAST UPDATED 11/22/09

AREA	DATA SOURCE	BORING OR TEST PIT NUMBER	SAMPLE NUMBER & TYPE	TOP OF SAMPLE (FEET)	BASE OF SAMPLE (FEET)	SAMPLE MIDPOINT (FEET)	USCS SYMBOL	MATERIAL TYPE	IN-PLACE DRY DENSITY (PCF)	NATURAL MOISTURE CONTENT (%)	SPECIFIC GRAVITY (PERC.L.)	FRACTION #4 SIEVE PASSING (PERCENT)	FRACTION #200 SIEVE PASSING (PERCENT)	LIQUID LIMIT	PLASTICITY INDEX	ASTM D 598 MAXIMUM DRY DENSITY (PCF)	ASTM D 598 OPTIMUM MOISTURE CONTENT (PERCENT)	OTHER TESTS
BLM PROPERTY-NORT D&M	TP-10	-BULK	5.0	5.0	5.00	CL	Loess[?]		NA	10.9	NA	100.0	86.6	29.5	11.1	107.7	14.2 Mod Proct	
BLM PROPERTY-NORT D&M	TP-10	2/ST	6.0	6.5	6.25	CL	Loess[?]		91.7	8.2	NA	NA	NA	27.9	9.6	NA	NA Unconf Comp	
BLM PROPERTY-NORT D&M	TP-10	4/ST	11.0	11.5	11.25	CL	Loess[?]		109.3	16.7	NA	NA	NA	43.8	21.6	NA	NA Peim	

KEY: USCS = Unified Soil Classification System group symbol, ASTM D 2487 or D2488 (For rocks, symbol indicates geologic unit)

ASTM = Test designation of the American Society for Testing and Materials

BENDIX "Data Collection for Engineering for the Uranium Mill Tailings Site and Adjacent Peripheral Properties, Monticello, Utah," Bendix Field Engineering Corporation, September 1986

D&M = "Final Report, Monticello Remedial Action Project, 1991 Milsite Characterization Study," Dames & Moore, September 17, 1991

* Sample taken from a test pit excavated next to the designated borehole.

[?] = Questionable value or identification

MATERIAL TYPE:	Tails-snd	Tailings sand	OTHER TESTS:	Mod Proct	Modified Proctor compaction
	Tails-slm	Tailings silt		Unconf Comp	Unconfined compressive strength
	Tails-andslm	Tailings sand and slimes, interbedded		Dir Shear	Direct shear, consolidated-drained
	Tails-snd&slm	Tailings sand and slimes, mixed		Triax-CUPP	Triaxial shear, consolidated-undrained with pore pressure measurements
	Cover	Cover material in place on tailings piles		Consol	One-dimensional consolidation
	MVP spoils	Material removed from Monticello Vicinity Properties		Perm	Permeability, falling-head or flexible-membrane
	Alluvium	Miscellaneous surficial deposits, mostly stream-laid		CMR	Capillary moisture rise
	Loess	Windblown fine-grained deposits	SAMPLE TYPES:	BULR	Disturbed bag sample of loose cuttings or material from test pit
	Shale	Mancos Shale, usually weathered		SS	Disturbed sample from 3.0' O.D. standard split-spoon drive sampler
	Sandstone	Dakota Sandstone		ST	Relatively undisturbed sample from 3.0' O.D. thin-walled (Shelby) tube sampler
	Fill	Miscellaneous man-made fill		U	Relatively undisturbed sample from Dames & Moore Type "U" ring-lined drive sampler

All data in this table compiled or interpreted from consultant's reports by R.N. Morris, Chem-Nuclear Geotech, Inc., October 1991. Checked by L.H. Golden & corrected by R.N. Morris, November 1991.







Figure 1-3. Contaminated Areas Under Investigation

ORIGINAL












ORIGINAL



SEARCHED	Searched _____	INDEXED	Indexed _____
SERIALIZED	Ser. No. _____	FILED	File No. _____
SEARCHED & SERIALIZED IN ACCORDANCE WITH THE REQUIREMENTS OF THE ATTACHED STANDARD FORM CONTRACT.		APR - 1962	
		U. S. DEPARTMENT OF JUSTICE FEDERAL BUREAU OF INVESTIGATION	
LABORATORY		6261-L4	






40' "STARTER" PORTABLE CONVEYOR w/CV-B


卷之三

NOTE: COMMERCIAL C-4 IS SHARPLY CONTRAST CYCLED TO 200°



FIELD CONVEYORS are C-C, CV-G, & CV-F


SCA, E = 100



To BE FIELD
VERIFIED.

THE SOUTHERN STATES

卷之三



EPIGRAPHY FIELD COR