

UNITED STATES NUCLEAR REGULATORY COMMISSION WASHINGTON, D. C. 20555

Ower's

OCT 3 0 1381

Turbine Bldg Anchor Bolt Calculations

ing s

MEMORANDUM FOR:

Gus C. Lainas, Assistant Director

for Safety Assessment Division of Licensing

FROM:

James P. Knight, Assistant Director

for Components and Structures Engineering

Division of Engineering

SUBJECT:

SAN ONOFRE 1 SEISMIC EVALUATION, STRENGTH OF COLUMN-TO-FOOTING CONNECTIONS IN NORTH

TURBINE BUILDING EXTENSION

During the week of October 12, 1981, the Structural Engineering Branch (SEB) was asked to provide input to the Systematic Evaluation Program Branch (SEPB) concerning the ongoing seismic safety evaluation of the San Onofre Nuclear Generating Station Unit 1 (SONGS 1). SEPB was concerned that the seismic resistance of portions of the plant is such that it cannot be allowed to continue operation until structural modifications to the North Turbine Building Extension are made. Southern California Edison (SCE) had previously made a commitment to make such modifications by June 1, 1982, or shut the plant. However, SEPB indicated that certain structural components might be completely inadequate to resist the postulated earthquake and thus the plant would have to cease operation immediately in order to make the required modifications.

SEB was asked to review the available material and make a quick assessment of the adequacy of the structural components in question. The structural members considered weakest are several columns in the North Turbine Building Extension. Specifically, the resistance of column-to-footing connections against rotation was considered to be the most vital concern. More specifically, the capacity of the anchor bolts which connect the columns to the foundation was considered inadequate.

At a meeting on October 15, 1981, SCE presented an evaluation which indicated that the anchor bolts in question would survive the postulated seismic event if credit were allowed for the 8" thick reinforced concrete slab-on-ground, and the poured concrete surrounding the columns. SEB was asked to provide an evaluation of this analysis.



SEB has performed a somewhat rough calculation (copy enclosed) to evaluate the column base connections. This indicates that the slab-on-ground can be considered to provide sufficient restraint for the column base connections based on the maximum loads postulated. Therefore, the adequacy of these connections should not be used as a basis for requiring immediate modifications to the Turbine Building structure.

Since SEB was not involved in this evaluation previously, our investigation was confined to the immediate area of interest, namely the adequacy of column base/slab-on-ground connections in the North Turbine Building Extension of SONGS 1.

> James P. Knight, Assistant Director for Components and Structures Engineering Division of Engineering

Enclosure: As Stated

(w/enclosure)

F. Schauer

P. Kuo

D. Jeng

W. Russell

R. Hermann


On Rothberg

R. Lipinski

J. Semecky

K. Herring

CONTACT: O. Rothberg, SEB, x29566



Max Load Carried By Glab. Let mate strain = 0.650"/" Ed 57000 /4000 = 3.61 × 106 #/9" SO PMAX - AE = 0.002 (8×14) (3.61×103) - ENTIMATED CENSHING PMX= 808 -LOAD OF GLAS ESHINE COLL FIG. - MINIMUM M=16320 V=10'9K MAX Bolt Load ! 105× 00 = 102 × / BOLT = 204 9 2 BOLTS. P. 226 73 F 03 7 + R=31" Load into Glas - EMX=0 6= (09×24 + 16520 - 226×155- 264×31)/= 3304 380 2 536. P.K. (2Fx=0) Therefore of Required = 330-100 = 271x [EFy.0] = Rx= 226 + 204 - 317k; Friction Force available = 5017 card = 317x0,5= 159k. 50 about 271-159= 112 Must be taken in the Concrete below - lab. arrange 10 7' available Concrete Forallel to plane of templete So shear resistance available in congrete=" 10x 144x 0,253 = 364x 0x , & there fore there 15 no Shear needed from bolts.

