LICENSEE EVENT REPORT

| HT HENNEY CONTROL CONT |
|--|
| CONTROL BLOCK: |
| 0 1 G A E I H 2 2 0 0 0 0 0 0 0 0 |
| CON'T 0 1 REPORT L 6 0 5 0 0 0 3 6 6 0 1 1 2 3 8 1 8 1 2 1 5 8 1 9 7 |
| EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) [0] With the plant at steady state power of 2394 MWt while performing |
| TOT3] HNP-2-3309, HPCI TURBINE EXHAUST DIAPHRAGM PRESSURE INST. F.T.& C., |
| [0]4] 2E41-N012A was found to actuate at 10.5 psig inc. Tech Specs Table |
| [0]6] [3.3.2-2 item 4C requires actuation at = 10 psig. Redundant switches</td |
| [0]6] [2E41-N012B,C and D were operable. Neither plant operation or public |
| [0]7 [health and safety were affected. This event is repetitive as last re- |
| Total ported on Reportable Occurrence report no. 50-366/1981-096. |
| 7 8 9 SYSTEM CAUSE CAUSE COMPONENT CODE COMPONENT CODE SUBCODE |
| SEQUENTIAL SUBSTITUTE SEQUENTIAL SEQUENTIAL SUBSTITUTE SEQUENTIAL SUBSTITUTE SUB |
| CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) |
| ine cause of this event has been activibated to seep the |
| [1] [switch was immediately recalibrated per HNP-2-5279, BARKSDALE PRFSSURE] |
| SWITCH CALIBRATION, and returned to service. These switches are to be |
| replaced as part of an analog trip system. A follow-up report will be |
| |
| FACILITY STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 SURVEILLANCE Testing Solvery Description 32 Surveillance Testing |
| ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) N/A LOCATION OF RELEASE (36) N/A 44 45 |
| PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39) N/A |
| 7 8 9 11 12 13 PERSONNEL INJURIES NUMBER DESCRIPTION 41 N/A |
| 1 8 0 0 0 40 WAY |
| TYPE DESCRIPTION N/A SPDR ADOCK OSOUGHOUSE PDR ADOC |
| PUBLICITY NRC USE ONLY ISSUED DESCRIPTION (45) N/A N/A |
| 7 8 9 10 68 69 80 2 80 2 80 2 80 2 80 2 80 2 80 2 80 |

LER #: 50-366/1981-115

Licensee: Georgia Power Company Facility Name: Edwin I. Hatch

Docket #: 50-366

NARRATIVE REPORT for LER 50-366/1981-115

With the plant at steady state power of 2394 MWt while performing HNP-2-3309, HPCI TURBINE EXHAUST DIAPHRAGM PRESSURE INSTRUMENT F.T. AND C., 2E41-N012A was found to actuate at 10.5 psig increasing. Tech Specs Table 3.3.2-2 item 4C requires actuation at </= 10 psig. Redundant switches 2E41-N012B, C and D were operable and within tolerance. Neither plant operation or public health and safety were affected. This event is repetitive as last reported on Reportable Occurrence report no. 50-366/1981-096.

The cause of this event has been attributed to setpoint drift. The switch a Barksdale model D2H was immediately recalibrated and functionally tested successfully then returned to service. This switch will be replaced as part of the implementation of an analog trip system. A follow-up report will be submitted upon completion of this design change.

A generic review revealed that this type of switch is used on both units and that in this application they do not perform up to expectations. All of these switches on both units are to be replaced by the above mentioned analog trip system.