



LER SUPPLEMENTAL INFORMATION

BFRO-50- 296 / 81067 Technical Specification Involved 3.8.B.6 and 3.8.B.8  
Reported Under Technical Specification 6.7.2.b(2) \* Date Due NRC 12/16/81  
Date of Occurrence 11/16/81 Time of Occurrence 0050 Unit 3

Identification and Description of Occurrence:

Continuous air monitor 3-RM-90-249 was not sampling exhaust with fans in operation.

Conditions Prior to Occurrence:

Unit 1 at 70%.

Unit 2 at 100%.

Unit 3 in refueling outage.

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe.

None

Apparent Cause of Occurrence:

Normal wear of V-belt for the Schwitzer model 325 vacuum pump due to continuous operation.

Analysis of Occurrence:

There was no danger to the health or safety of the public, no release of activity, no damage to the plant or equipment, and no resulting significant chain of events.

Corrective Action:

Turbine building roof exhaust fans on U-3 and dampers were verified isolated. Replaced the standard V-belt for the Schwitzer model 325 vacuum pump on the 3-RM-90-249 continuous air monitor. Surveillance procedures have been revised to verify condition of drive belt to help prevent recurrence.

Failure Data:

BFRO-50-296/81063  
Retention: Period - Lifetime; Responsibility - Document Control Supervisor

\*Revision: *John W. ...*